

SEPT 1982

E83-10259

15-236-0119-679

NASA-CR-170524

THEMATIC MAPPER

THEMATIC MAPPER

THEMATIC M

ER

THEMATIC MAPPER

"Made available under NASA sponsorship
in the interest of early and wide dis-
semination of Earth Resources Survey
Program information in a volume
form for use in a classroom setting."



(E83-10259) THEMATIC MAPPER FLIGHT MODEL
PRESHIPMENT REVIEW DATA PACKAGE, VOLUME 2,
PART B: SUBSYSTEM DATA (Santa Barbara
Research Center) 287 p HC A13/MF A01

N83-26 128

Unclas


CSCL 14B G3/43 00259

Prepared for
GODDARD SPACE FLIGHT CENTER
Greenbelt, Maryland 20771
CONTRACT NAS 5-24200

FLIGHT MODEL
PRESHIPMENT REVIEW
DATA PACKAGE
VOLUME II - SUBSYSTEM DATA
PART B
Article IV - 3A

HUGHES

HUGHES AIRCRAFT COMPANY
SPACE AND COMMUNICATIONS GROUP



BEST AVAILABLE COPY

HS 236-0019-1679



Prepared for
GODDARD SPACE FLIGHT CENTER
Greenbelt, Maryland 20771
CONTRACT NAS 5-24200

SEPT 1982

FLIGHT MODEL
PRESHIPMENT REVIEW
DATA PACKAGE
VOLUME II - SUBSYSTEM DATA
PART B

Article IV - 3A

HUGHES

HUGHES AIRCRAFT COMPANY
SPACE AND COMMUNICATIONS GROUP

Hughes Ref No. D4896

ORIGINAL PAGE IS
OF POOR QUALITY

THEMATIC MAPPER
FLIGHT MODEL
PRESHIPMENT REVIEW
VOLUME II
SUBSYSTEMS
TABLE OF CONTENTS

	<u>Section</u>
1.0 INTRODUCTION	1.0
2.0 SUBSYSTEMS ACCEPTANCE DATA	
Multiplexer Assembly	2.1
Multiplexer Summarized Performance	2.1.1
Multiplexer Acceptance Data	2.1.2
Scan Mirror Assembly	2.2
Scan Mirror Summary Performance	2.2.1
Scan Mirror Acceptance Data	2.2.2
Power Supply Assembly	2.3
Power Supply Summarized Performance	2.3.1
Power Supply Acceptance Data	2.3.2
Mainframe/Top Mechanical Assembly	2.4
Mainframe/Top Mechanical Summarized Performance	2.4.1
Mainframe/Top Mechanical Acceptance Data	2.4.2
Aft Optics Assembly	2.5
Aft Optics Summarized Performance	2.5.1
Aft Optics Acceptance Data	2.5.2
Focal Plane Assembly	2.6
Focal Plane Summarized Performance	2.6.1
Focal Plane Acceptance Data	2.6.2
Radiative Cooler	2.7
Radiative Cooler Summarized Performance	2.7.1
Radiative Cooler Acceptance Data	2.7.2

ORIGINAL PAGE IS
OF POOR QUALITY

THEMATIC MAPPER
FLIGHT MODEL
PRE SHIPMENT REVIEW
VOLUME II
SUBSYSTEMS

TABLE OF CONTENTS
(Continued...)

	<u>Section</u>
Radiative Cooler Door Assembly	2.8
Radiative Cooler Door Summarized Performance	2.8.1
Radiative Cooler Door Acceptance Data	2.8.2
Top Optical Assembly	2.9
Top Optical Summarized Performance	2.9.1
Top Optical Acceptance Data	2.9.2
Telescope Assembly	2.10
Telescope Summarized Performance	2.10.1
Telescope Acceptance Data	2.10.2
Relay Optics	2.11
Relay Summarized Performance	2.11.1
Relay Acceptance Data	2.11.2
Electronics Module	2.12
Electronics Summarized Performance	2.12.1
Electronics Acceptance Data	2.12.2
Cable Harness	2.13
Cable Harness Summarized Performance	2.13.1
Cable Harness Acceptance Data	2.13.2

ORIGINAL PAGE IS
OF POOR QUALITY

2.0 Subsystems Acceptance Data

Each of the major subsystems of the Flight Model Thematic Mapper was reviewed as an entity prior to integration into the system. The intent of this section is to present for each major subsystem, acceptance data for the subsystem (test results); reference lists of the configuration status; and reference lists of Non-Conforming Material Reports, Failure Reports (with copies), and Requests for Deviation/Waiver (with copies).

The acceptance data for each subsystem (where applicable) is contained in the Appendix to this report, as referenced in the first subsection for each subsystem.

The second subsection for each subsystem contains a tabular summary of the "as designed" and "as built" configuration lists, showing all applicable drawings, specifications, or standards. (An "as built" configuration list for the total system is included in Volume I and is also included herein immediately following this page). This is followed by a listing of all items against the subsystem, with copies of NCRM's, RT's, and RD/W's.

SUMMARY
AS-BUILT CONFIGURATION LIST
TM FLIGHT S/N 003

IND LVL	PART NO.	NOMENCLATURE	CURRENT REVISION	ACCEP. REVISION	AS-BUILT REVISION	SERIAL NUMBER
1	51065	THEMATIC MAPPER ASSY	J 4257A 4487A 4557A 4573A 4643A 4658A D143R1 D144 D146 D148 D155 D158 D161 D162 D163 D164 D165 W166 W169 W170 W171R1 W173	J 4257A 4487A 4557A 4573A 4643A 4658A D143R1 D144 D146 D148 D155 D158 D161 D162 D163 D164 D165 W166 W169 W170 W171R1 W173	J 4257A 4487A 4557A 4573A 4643A 4658A D143R1 D144 D146 D148 D155 D158 D161 D162 D163 D164 D165 W166 W169 W170 W171R1 W173	003
2	50840	MAIN FRAME ASSY	E	E	E	003
2	52347	ELECTRONICS MODULE ASSY	D 4588A	B 4091A 4113A 4242A 4293A	B 4091A 4113A 4242A 4293A	201

ORIGINAL PAGE IS
OF POOR QUALITY

D L	PART NO.	NOMENCLATURE	CURRENT REVISION	ACCEPT. REVISION	AS-BUILT REVISION	SERIAL NUMBER
3	3533003-100	MULTIPLEXER ASSY	C 43009 43074 65661 65662 W124 W125	C 43074 65661 65662 W124 W125	C 43009 43074 65661 65662 W124 W125	003
3	50869	POWER SUPPLY ASSY	D 2015A 2039A 4347A D030 D068 W074 W092 W093 W101	D 2015A 2039A 4347A D030 D068 W074 W092 W093 W101	D 2015A 2039A 4347A D030 D068 W074 W092 W093 W101	004
3	52348	CABLE ROUTING ASSY	F 3844A	F 3844A	F 3844A	005
2	52532	OPTICAL ASSY	F 3174A 4100A 4187A 4266A 4488A 4559A 4656A D-151 D-154 W-148	F 3174A 4100A 4187A 4266A 4488A 4559A 4656A D-151 D-154 W-148	F 3174A 4100A 4187A 4266A 4488A 4559A 4656A D-151 D-154 W-148	003
3	51512	AFT OPTICS ASSY	E 3646A 3925A 3959A 4585A	D 3646A 3896A 3925A 3959A 4134A	D 3646A 3896A 3925A 3959A 4134A	001

ORIGINAL PAGE IS
OF POOR QUALITY

ND VL	PART NO.	NOMENCLATURE	CURRENT REVISION	ACCEPT. REVISION	AS-BUILT REVISION	SERIAL NUMBER
4	50795	PRIME FOCAL PLANE ASSY	J W126	II 3934A 3968A 3982A W126	II 3934A 3968A 3982A W126	201
3	51200	RADIATIVE COOLER ASSY	E 3922A 4201A 4216A 4269A SB-W032 W144 W147 W149 W151	E 3922A 4201A 4216A 4269A SB-W032 W144 W147 W149 W151	E 3922A 4201A 4216A 4269A SB-W032 W144 W147 W149 W151	003
4	50973	COLD FOCAL PLANE ASSY	B 2870A 3895A 4173A SB-D004 W102R1 W109 W111 W134 W135	B 2870A 3895A 4173A SB-D004 W102R1 W109 W111 W134 W135	B 2870A 3895A 4173A SB-D004 W102R1 W109 W111 W134 W135	201
3	51337	TELESCOPE ASSY	D 3866A 3917A W129 W136	D 3866A 3917A W129 W136	D 3866A 3917A W129 W136	002

ORIGINAL PAGE IS
OF POOR QUALITY

QD L	PART NO.	NOMENCLATURE	CURRENT REVISION	ACCEPT. REVISION	AS-BUILT REVISION	SERIAL NUMBER
---------	----------	--------------	---------------------	---------------------	----------------------	------------------

52534

RELAY OPTICS ASSY

D
1145A
4097A

D
1145A
4097A

D
1145A
4097A

003

3533002-100

SCAN MIRROR ASSY

E

D
13121
13122
64358
64363
64369
64374
W020

D
13121
13122
64358
64363
64369
64374
W020

004

ORIGINAL PAGE IS
OF POOR QUALITY

ORIGINAL PAGE IS
OF POOR QUALITY

SECTION 2.6
FOCAL PLANE ASSEMBLIES

ORIGINAL PAGE IS
OF POOR QUALITY

2.6.1

Section 2.6.1

Focal Plane Assemblies

Performance Data

The acceptance performance (test) data for the Focal Plane Assemblies is contained in Appendix D of this report (Vol. IV, Part D).

ORIGINAL PAGE IS
OF POOR QUALITY

2.6.2

2.6.2

Acceptance Data

ORIGINAL PAGE IS
OF POOR QUALITY

2.6.2.1

2.6.2.1

Configuration Lists

The "as built" configuration list for the Cooled and
Prime Focal Plane Assemblies are included in the listing
for the overall system.

AS-BUILT CONFIGURATION LIST

COLD FOCAL PLANE ASSY

P/N 50973, S/N 201, FLIGHT

ND VL	PART NO.	NOMENCLATURE	CURRENT REVISION	ACCEPT. REVISION	AS-BUILT REVISION	SERIAL NUMBER
1	50973	COLD FOCAL PLANE/COOLER CABLE ASSY	B + 2870A 3895A SB-D004 W-102R1 W-109 W-111* W-134 W-135 4173A	B + 2870A 3895A SB-D004 W-102R1 W-109 W-111* W-134 W-135 4173A	B + 2870A 3895A SB-D004 W-102R1 W-109 W-111* W-134 W-135 4173A	201
2	50955	COOLED FOCAL PLANE/COLD- FINGER ASSY	E + 2444A 3121A	E + 2444A 3121A	E + 2444A 3121A	201
3	50956	SUBSTRATE, COLD FOCAL PLANE	D + W-142	C + W-142	D + W-142	013
4	50958	DETECTOR ARRAY, BANDS 5 & 7	B + W-122* W-128* W-132 W-133	B + W-122* W-128* W-132 W-133	B + W-122* W-128* W-132 W-133	088 112
5	50959	DETECTOR ARRAY, BAND 6	B	B	B	120
6	50968	PRINTED WIRING BOARD, DISTRIBUTION	B	A + 6895 8161	A + 6895 8161	201
7	50970	FLEXIBLE PRINTED WIRING ASSY, COOLER CABLE BAND 5	C	B + 9015 9645 2198A	B + 9015 9645 2198A	102
8	50974	FLEXIBLE PRINTED WIRING ASSY, COOLER CABLE BAND 6	D	C + 9647 2199A	C + 9647 2199A	103
9	50992	FLEXIBLE PRINTED WIRING ASSY, COOLER CABLE BAND 7	C	B + 9646 2200A	B + 9646 2200A	201

ORIGINAL PAGE IS
OF POOR QUALITY


* Indicates waiver is active but no longer applicable to the hardware presently being used on this unit.

P/N 50973

2 of 2

D L	PART NO.	NOMENCLATURE	CURRENT REVISION	ACCEPT. REVISION	AS-BUILT REVISION	SERIAL NUMBER
	51393	FLEXIBLE PRINTED WIRING ASSY, CABLE HEATER & SENSOR	C + 3941A	B + 9648 22G1A 3941A	B + 9648 2201A 3941A	103
	51750	CLAMP, CABLE, INNER-HEATER & SENSOR	B	B	B	
	51751	CLAMP, CABLE, MIDDLE-HEATER & SENSOR	B	B	B	
	52752	CLAMP, CABLE, INNER-BAND 5&7	B	B	B	
	51753	CLAMP, CABLE, MIDDLE AND OUTER-BANDS 5 & 7	B	B	B	
	51754	CLAMP, CABLE, INNER-BAND 6	B	B	B	
	51755	CLAMP, CABLE, MIDDLE AND OUTER-BAND 6	B	B	B	
	51766	CLAMP, CABLE, OUTER-HEATER & SENSOR	B	A	B	


Quality Assurance

 3/10/82
Configuration Management Office

ORIGINAL PAGE IS
OF POOR QUALITY

AS-BUILT CONFIGURATION LIST

PRIME FOCAL PLANE ASSY
P/N 50795, S/N 201, FLIGHT

IND VL	PART NO.	NOMENCLATURE	CURRENT REVISION	ACCEPT. REVISION	AS-BUILT REVISION	SERIAL NUMBER
1	50795	SILICON FOCAL PLANE ASSY	H + 3934A 3968A 3982A W-126	H + 3934A 3968A 3982A W-126	H + 3934A 3968A 3982A W-126	201
2	50797	SILICON DETECTOR & PREAMP ASSY-BAND 2	E + W115	E + W115	E + W115	401
2	50797	SILICON DETECTOR & PREAMP ASSY-BAND 3	E + W112 W116	E + W112 W116	E + W112 W116	401
2	50797-1	SILICON DETECTOR & PREAMP ASSY-BAND 1	E + W123	E + W123	E + W123	401
2	50797-1	SILICON DETECTOR & PREAMP ASSY-BAND 4	E + W114 W117 W118	E + W114 W117 W118	E + W114 W117 W118	401
3	51015	SILICON PREAMP ASSY	D + 2950A	D + 2950A	D + 2950A	103 203 207 209
3	51015-1	SILICON PREAMP ASSY (S/N 207-1)	D + 2950A W119	D + 2950A W119	D + 2950A W119	102-1 206-1 207-1 208-1
4	50799-1	SUBSTRATE ASSY, SILICON PREAMP FIRST STAGE	C	C	C	018 027 035 043
4	50799-2	SUBSTRATE ASSY, SILICON PREAMP FIRST STAGE	C	C	C	010 016 030 024

ORIGINAL PAGE IS
OF POOR QUALITY

PART NO.	NOMENCLATURE	CURRENT REVISION	ACCEPT. REVISION	AS-BUILT REVISION	SERIAL NUMBER
50807	LED SOURCE, SILICON FOCAL PLANE ASSY	H + D027	H + D027	H + D027	201

J. H. Branda 12-18-81

Quality Assurance

E. Dergara 12-18-81

Configuration Data Management Office

ORIGINAL PAGE IS
OF POOR QUALITY

ORIGINAL PAGE IS
OF POOR QUALITY

PRIME FOCAL PLANE ASSEMBLY

Listing of Liens

FOCAL PLANE ASSEMBLIES
PRIME FOCAL PLANE ASSEMBLIES
P/N 50795

ORIGINAL PAGE IS
 OF POOR QUALITY

Failure Reports Number

Open	Closed
	F0527
	F0560
	F0581
	F0620
	F1717
	F2240
	F2241
	F2662
	F2663
	F2666
	F2668
	F2669
	S8014
	S8058
	S8201
	S8202
	S8206(Spare)
	S8211(Spare)
	S8212(Spare)
	S8227
	S8228(Spare)
	S8229
	S8231(Spare)
	S8317
	S8318
	S8322
	S8323
	S8324
	S8330
	S8341
	S8342
	S8401(Spare)
	S8440

Deviations

Waivers

D-128	W-112
D-142	W-114
	W-115
	W-116
	W-117
	W-119
	W-120
	W-126
	W-143
	W-148
	W-154
	W-155
	W-157
	W-158

ORIGINAL PAGE IS
OF POOR QUALITY

PRIME FOCAL PLANE ASSY.

P/N 50795

FLIGHT
Failure Report
No.

PROTOFLIGHT
Failure Report
No.

ENGINEER
Failure Report
No.

Open	Closed	Open	Closed	Open	Closed
	F0527		F0561 S8016		F1766
	F0560		F0569 S8017		F2697
	F0581		F0570 S8019		
	F0620		F0596 S8020		
	F1717		F0609 S8039		
	F2240		F0611 S8040		
	F2241		F0612 S8041		
	F2262		F0613 S8053		
	F2263		F1702 S8054		
	F2666		F1706 S8055		
	F2668		F1721 S8056		
	F2669		F1723 S8059		
	S8014		F1724 S8060		
	S8058		F1752 S8062		
	S8201		F1768 S8063		
	S8202		F1771 S8065		
	S8206(Spare)		F1784 S8066		
	S8211(Spare)		F1785 S8067		
	S8212(Spare)		F1786 S8070		
	S8227		F1790 S8071		
	S8228(Spare)		F1795 S8072		
	S8229		F1798 S8077		
	S8231(Spare)		F1799 S8078		
	S8317		F1800 S8079		
	S8318		F2388		
	S8322		F2389		
	S8323		F2390		
	S8324		F2648		
	S8330		F2673		
	S8341		F2674		
	S8342		F2712		
	S8401(Spare)		F2796		
	S8440		S8000		
			S8001		
			S8002		
			S8003		
			S8004		

HUGHES

SPACE AND COMMUNICATION GROUP FAILURE REPORT

F 052

1. PROGRAM NAME AND NUMBER TECHNICAL MAPPER		2. CLA V011		3. MODEL ALL		4. TEST TYPE RECEIVED		5. DATE OBSERVED		6. NO. OF PARTS	
7. HARDWARE LEVEL WHEN FAILURE WAS OBSERVED		<input type="checkbox"/> SPACECRAFT <input type="checkbox"/> SYSTEM		<input type="checkbox"/> SUBSYSTEM <input type="checkbox"/> UNIT		<input type="checkbox"/> ASSEMBLY <input type="checkbox"/> SUBASSEMBLY		<input type="checkbox"/> MODULE <input type="checkbox"/> MECHANISM		<input type="checkbox"/> CARD <input checked="" type="checkbox"/> PART	
8. EQUIPMENT IDENTIFICATION		NAME		PART NUMBER		LTV		MANUFACTURER			
9. EQUIPMENT		RADIOMETER									
10. UNIT		PRIME FOCAL PLANE		50795							
11. <input type="checkbox"/> ASSEMBLY <input type="checkbox"/> SUBASSEMBLY											
12. <input type="checkbox"/> MODULE <input type="checkbox"/> MECHANISM <input type="checkbox"/> CARD											
13. OTHER		SILICON PHOTODIODE DETECTOR		50803		ALL		HPCL DIV			
14. TEST WHEN FAILURE WAS OBSERVED		<input type="checkbox"/> DEVELOPMENT <input type="checkbox"/> QUALIFICATION <input type="checkbox"/> INTERGRATION <input type="checkbox"/> LAUNCH OPERATIONS		<input type="checkbox"/> ACCEPTANCE <input type="checkbox"/> SYSTEM							
15. ENVIRONMENT WHEN FAILURE WAS OBSERVED		<input type="checkbox"/> AMBIENT <input type="checkbox"/> RADIATION <input type="checkbox"/> TEMPERATURE <input type="checkbox"/> THERMAL VAC <input type="checkbox"/> MSL AT		<input type="checkbox"/> SHOCK <input type="checkbox"/> VIBRATION <input type="checkbox"/> ALTITUDE <input type="checkbox"/> HUMIDITY <input type="checkbox"/> OTHER							
16. DESCRIPTION OF FAILURE		HIGH RESISTANCE BACKSIDE CONTACT AT INTERFACE BETWEEN SILICON DETECTOR & QUARTZ SUBSTRATE									
17. TEST PROCEDURE		PARA		18. OPERATOR JL Canal		19. DATE 12-22-79		20. CONTINUATION SHEET NO.			
21. VARIATION AND FAILURE ANALYSIS		Hi resistance determined by HPL Die Si to be due to oxide growth on backside of detector. See attached IDC. Letter to E. L. Kahn dated July 27, 1979.									
22. FOLLOWING PROCEDURES REQUIRED FOR REPEAT TEST		New detectors will be fabricated in parts/fly									
23. AUTHORIZATION		ORG		DATE		24. CONTINUATION SHEET NO.		25. CAUSE		26. REMARKS	
27. ACTION TAKEN		See attached IDC #13156 dated 2 May 1979									
28. LIST ALL PARTS REPLACED		PART NUMBER		CMT SYN		PART LOT NO.		DATE CODE		MSR	
29. REPAIR BY		ORG		DATE		30. RETESTED BY		ORG		DATE	
31. CAUSE AND CORRECTIVE ACTION		OXIDE GROWTH ON BARE SILICON CAUSED HI RESISTANCE CONTACT. NEW DETECTORS WILL BE FABRICATED WITH A CHROME/GOLD BACKSIDE METALLIZATION AND THE DETECTORS WILL BE MOUNTED TO THE CHROME/GOLD METALLIZED QUARTZ SUBSTRATES USING WADSWORTH 3020 CONDUCTIVE EPOXY (SM-B019) APPLIED PER SP 80141.									
32. DOCUMENT EXPLAINING CORRECTIVE ACTION		32. PRO CLOSURE									
33. BASIC CAUSE OF VERIFIED FAILURE		<input checked="" type="checkbox"/> DESIGN <input type="checkbox"/> TEST EQUIP. <input type="checkbox"/> MSL PROCEDURE <input type="checkbox"/> WORKING CONDITION <input type="checkbox"/> UNKNOWN		<input type="checkbox"/> ENVIRONMENTAL <input type="checkbox"/> TEST PROC. <input type="checkbox"/> ASBY/PAS ERROR <input type="checkbox"/> WORKMANSHIP <input type="checkbox"/> WEAR/OUT		<input type="checkbox"/> DEFECTIVE PARTS <input type="checkbox"/> TEST SET-UP		<input type="checkbox"/> CRITICAL <input type="checkbox"/> MAJOR <input type="checkbox"/> MINOR		<input type="checkbox"/> SAFETY	
34. FAILURE TYPE		<input checked="" type="checkbox"/> PRIMARY <input type="checkbox"/> INDUCED <input type="checkbox"/> UNKNOWN <input type="checkbox"/> NO FAILURE		35. FAILURE CLASSIFICATION							
36. RESPONSIBLE ENGINEER		ORG 3886 DATE 10-15-79		37. SPACECRAFT SYSTEM ENG.		ORG 3886 DATE 12-21-79		38. CUSTOMER OR SUPPLIER		DATE 10/16/80	
39. RELIABILITY		ORG 3886 DATE 10-15-79		40. CUSTOMER OR SUPPLIER							

Don into 50795 from 7PA

ORIGINAL PAGE IS
OF POOR QUALITY

HUGHES

HUGHES AIRCRAFT COMPANY

SPACE AND COMMUNICATION GROUP
FAILURE REPORT

F 056

1. PROGRAM NAME AND NUMBER TM HS 236		2. GLA	3. MODEL PLT	4. TIME OBSERVED	5. DATE SERVED MO 11 DA 12
6. HARDWARE LEVEL WHEN FAILURE WAS OBSERVED <input type="checkbox"/> AIRCRAFT <input type="checkbox"/> SUBSYSTEM <input checked="" type="checkbox"/> ASSEMBLY <input type="checkbox"/> MODULE <input type="checkbox"/> CARD <input type="checkbox"/> SYSTEM <input type="checkbox"/> SUBASSEMBLY <input type="checkbox"/> MECHANISM <input type="checkbox"/> PART					
EQUIPMENT IDENTIFICATION: NAME PART NUMBER CN MANUFACTURER					
7. SUBSYSTEM					
8. UNIT Silicon Preamp Assy.					
9. <input checked="" type="checkbox"/> ASSEMBLY <input type="checkbox"/> SUBASSEMBLY					
10. <input type="checkbox"/> MODULE <input type="checkbox"/> MECHANISM <input type="checkbox"/> CARD					
11. OTHER					
12. TEST WHEN FAILURE WAS OBSERVED <input checked="" type="checkbox"/> DEVELOPMENT <input type="checkbox"/> QUALIFICATION <input type="checkbox"/> INTEGRATION <input type="checkbox"/> LAUNCH OPERATIONS <input type="checkbox"/> IN-PROCESS <input type="checkbox"/> ACCEPTANCE <input type="checkbox"/> SYSTEM					
13. ENVIRONMENT WHEN FAILURE WAS OBSERVED <input checked="" type="checkbox"/> ACCELERATION <input type="checkbox"/> RADIATION <input type="checkbox"/> TEMPERATURE <input type="checkbox"/> THERMAL VAC <input type="checkbox"/> HRS. AT <input type="checkbox"/> OTHER <input type="checkbox"/> DECORPH <input type="checkbox"/> VIBRATION <input type="checkbox"/> AXIS FOR <input type="checkbox"/> USE TYPE					
14. DESCRIPTION OF FAILURE Ch 1 and 7 were pegged at -25V. Ch's 2, 3, 5, & 6 exceed midpoint noise spec.					
15. TEST PROCEDURES 16306		16. PARA 4.7	18. ORIGINATOR Joe Kleban	19. ORG 3213	20. DATE 11/12/81
17. VERIFICATION AND FAILING ANALYSIS No components were overhauled.					
21. FOLLOWING REPAIRS/TESTS REQUIRED: Replace FETs in circuit per 16306 para 4.7					
22. ACTION TAKEN File released and retested successfully per 16306 para 4.7					
23. LIST ALL PARTS REPLACED PART NUMBER CMT SYN PART LOT NO. DATE CODE MSN PROGRAM DEFECT ANALYSIS NO. 52597					
24. RESPONSE BY ORG DATE 25. TESTED BY ORG DATE 21-22 11/15/81					
26. CAUSE AND CORRECTIVE ACTION FETs were initiated prior to the test. FR should not have been written since FR was not required against FET failure on first test.					
27. DOCUMENT IMPLEMENTING CORRECTIVE ACTION					
28. BASIC CAUSE OF VERIFIED FAILURE <input type="checkbox"/> DESIGN <input type="checkbox"/> TEST EQUIP. <input type="checkbox"/> MFG. PROCEDURE <input type="checkbox"/> WIRING ERROR <input type="checkbox"/> UNKNOWN <input type="checkbox"/> ENVIRONMENTAL <input type="checkbox"/> TEST PROC. <input type="checkbox"/> ASSEMBLY/FAB ERROR <input type="checkbox"/> ROUGH HANDLING <input type="checkbox"/> DEFECT CODE <input checked="" type="checkbox"/> DEFECTIVE PARTS <input type="checkbox"/> TEST SET-UP <input type="checkbox"/> WORKMANSHIP <input type="checkbox"/> WEAR-OUT					
29. FAILURE TYPE <input checked="" type="checkbox"/> PRIMARY <input type="checkbox"/> SECONDARY <input type="checkbox"/> UNKNOWN <input type="checkbox"/> NO FAILURE					
30. FAILURE CLASSIFICATION <input type="checkbox"/> CRITICAL <input type="checkbox"/> MAJOR <input type="checkbox"/> MINOR <input type="checkbox"/> SAFETY					
31. RESPONSIBLE ENGINEER Joe Kleban					
32. SPACECRAFT SYSTEM ENGR. Joe Kleban					
33. RELIABILITY 51-41 11-78-8					
34. CUSTOMER OR SUPPLIER 51/81					

ORIGINAL PAGE IS
OF POOR QUALITY

HUGHES
HUGHES AIRCRAFT COMPANY

SPACE AND COMMUNICATION GROUP
FAILURE REPORT

F 0581

HS 236

1. PROGRAM NAME AND NUMBER THEMATIC MAPPER		2. QLA	3. MODE FLIGHT	4. TIME OBSERVED 1400	5. DATE OBSERVED NOV 21 1979
6. HARDWARE LEVEL WHEN FAILURE WAS OBSERVED <input type="checkbox"/> SPACECRAFT <input type="checkbox"/> SUBSYSTEM <input type="checkbox"/> ASSEMBLY <input type="checkbox"/> MODULE <input type="checkbox"/> CARD <input type="checkbox"/> SYSTEM <input type="checkbox"/> UNIT <input checked="" type="checkbox"/> SUBASSEMBLY <input type="checkbox"/> MICAM <input type="checkbox"/> PART					
EQUIPMENT IDENTIFICATION					
7. SUBSYSTEM		NAME		PART NUMBER	EPN
8. UNIT					
9. <input type="checkbox"/> ASSEMBLY <input checked="" type="checkbox"/> SUBASSEMBLY		POSITION INDICATOR PICKOFF ASSEMBLY		52083	201-207
10. <input type="checkbox"/> MODULE <input type="checkbox"/> MICAM <input type="checkbox"/> CARD					
11. OTHER					
12. TEST WHEN FAILURE WAS OBSERVED <input type="checkbox"/> DEVELOPMENT <input type="checkbox"/> QUALIFICATION <input type="checkbox"/> INTEGRATION <input type="checkbox"/> LAUNCH OPERATIONS <input type="checkbox"/> PROGRESS <input checked="" type="checkbox"/> ACCEPTANCE <input type="checkbox"/> SYSTEM					
13. ENVIRONMENT WHEN FAILURE WAS OBSERVED <input checked="" type="checkbox"/> ACCIDENT <input type="checkbox"/> RADIATION <input type="checkbox"/> TEMPERATURE <input type="checkbox"/> THERMAL VAC <input type="checkbox"/> HCS AT <input type="checkbox"/> OTHER <input type="checkbox"/> ECU/RFI <input type="checkbox"/> VIBRATION <input type="checkbox"/> AXIS FOR <input type="checkbox"/> TYPE					
14. DESCRIPTION OF FAILURE THE PICKOFF ASSEMBLY IS A FIXTURE MADE UP OF A LIGHT EMITTING DIODE AND A PHOTOTRANSISTOR, BETWEEN WHICH A SHUTTER FLAP MAY PASS. AS PER TEST PROCEDURE 16660 PARA 3.5.2 WITH 25% RATED L.E.D. CURRENT, PHOTOTRANSISTOR IRRADIANCE WAS INSUFFICIENT FOR TURN-ON IN SPECIFIED CIRCUIT.					
15. TEST PROCEDURE 16660		16. ORIGINATOR PARA 3.5.2 J. A. BANACH	17. DATE 22-13	18. TIME 1400 7 1979	19. CONTINUATION SHEET USED
20. VERIFICATION AND FAILURE ANALYSIS LED current used for test to low. Based upon bel review of part application, test current could be increased to 35% rated LED current and with confidence that operation over time would be assured with worst case degradation.					
21. FOLLOWING REMOVED (TEST PROCEDURE) REPAIR/RETEST NOT REQUIRED (CAUSE) Retest using 35% rated LED current.					
22. AUTHORIZATION ORG DATE					
23. APPROVAL/TEST ACTION TAKEN Test procedure changed to test with 35% rated LED current.					
24. QA REVIEW					
25. QA RETEST					
26. LIST ALL PARTS REPLACED PART NUMBER CRT SYN PART LOT NO. DATE CODE MFG PROBABLE DEFECT ANALYSED NO.					
27. REWORK BY ORG DATE					
28. RETESTED BY ORG DATE					
29. CAUSE AND CORRECTIVE ACTION Cause - Insufficient LED drive current. Corrective action - Test procedure changed to increase LED drive current to 35% rated. See Revision B of Spec 16660.					
30. PRE CLOSURE					
31. CONTINUATION SHEET USED					
32. DOCUMENT REPLEMENTING CORRECTIVE ACTION ECR 1237/01 to Rev Bot 16660.					
33. BASIC CAUSE OF VERIFIED FAILURE <input type="checkbox"/> DESIGN <input type="checkbox"/> TEST EQUIP. <input type="checkbox"/> MFG. PROCEDURE <input type="checkbox"/> WIRING ERROR <input type="checkbox"/> UNKNOWN <input type="checkbox"/> ENVIRONMENTAL <input checked="" type="checkbox"/> TEST PROC. <input type="checkbox"/> ASSEMBLY ERROR <input type="checkbox"/> ROUGH HANDLING <input type="checkbox"/> DEFECT CODE <input type="checkbox"/> DEFECTIVE PARTS <input type="checkbox"/> TEST SET-UP <input type="checkbox"/> WORKMANSHIP <input type="checkbox"/> CLEAN-OUT					
34. FAILURE TYPE <input type="checkbox"/> PRIMARY <input type="checkbox"/> UNKNOWN <input checked="" type="checkbox"/> SECONDARY <input type="checkbox"/> INDUCED <input type="checkbox"/> NO FAILURE		35. FAILURE CLASSIFICATION <input type="checkbox"/> CRITICAL <input checked="" type="checkbox"/> MINOR <input type="checkbox"/> SAFETY			
36. RESPONSIBLE ENGINEER J. A. Banach		37. SPACECRAFT SYSTEM ENGR J. L. Crisp		DATE 22-13 11/21/80	

ORIGINAL PAGE 10
OF POOR QUALITY

HUGHES

HUGHES AIRCRAFT COMPANY

SPACE AND COMMUNICATION GROUP
FAILURE REPORT

F 0621

1. PROGRAM NAME AND NUMBER TM HS236		2. QLA	3. MODEL FLT	4. TIME OBSERVED	5. DATE OBSERVED 9 12 88
6. HARDWARE LEVEL WHEN FAILURE WAS OBSERVED <input type="checkbox"/> SPACECRAFT <input type="checkbox"/> SUBSYSTEM <input checked="" type="checkbox"/> ASSEMBLY <input type="checkbox"/> MODULE <input type="checkbox"/> CARD		<input type="checkbox"/> SYSTEM <input type="checkbox"/> UNIT <input type="checkbox"/> SUBASSEMBLY <input type="checkbox"/> MOUNT <input type="checkbox"/> PART			
EQUIPMENT IDENTIFICATION					
7. SUBSYSTEM Silver Beam Asy.		PART NUMBER 51015-1		S/N 201	
8. UNIT Power Section Asy.					
9. <input checked="" type="checkbox"/> ASSEMBLY <input type="checkbox"/> SUBASSEMBLY					
10. <input type="checkbox"/> MODULE <input type="checkbox"/> MOUNT <input type="checkbox"/> CARD					
11. OTHER					
12. TEST WHEN FAILURE WAS OBSERVED <input type="checkbox"/> DEVELOPMENT <input type="checkbox"/> IN-PROCESS <input type="checkbox"/> QUALIFICATION <input type="checkbox"/> ACCEPTANCE <input checked="" type="checkbox"/> INTEGRATION <input type="checkbox"/> SYSTEM <input type="checkbox"/> LAUNCH OPERATIONS					
13. ENVIRONMENT WHEN FAILURE WAS OBSERVED <input checked="" type="checkbox"/> AMBIENT <input type="checkbox"/> RADIATION <input type="checkbox"/> TEMPERATURE <input type="checkbox"/> THERMAL VAC <input type="checkbox"/> MAG. AT <input type="checkbox"/> OTHER					
14. DESCRIPTION OF FAILURE Channel 1 does not meet transient spec. and channel 4 does not meet transient spec.					
15. TEST PROCEDURE 16306		PARA 4.6	16. ORIGINATOR Joe Kleeburn	ORG 2213	DATE 8/5/88
18. VERIFICATION AND FAILURE ANALYSIS SHIELD ADJUSTMENT DOES NOT AFFECT PWR STRESSES. RESON VALUES WERE WITHIN SELECT RANGE SPECIFIED. NORM. POWER WAS APPLIED. NO OVERSTRESS WAS POSSIBLE.		19. FAILED ITEM NAME AND PART NUMBER			
20. FOLLOWING REPAIR/TEST REQUIRED REPAIR/TEST NOT REQUIRED (SCALE) Adjust crystal/shield on channels 1 & 4 and return per 16306 Para 4.6 after replacing feedback resistor.		21. AUTHORIZATION W. H. H. H.			
23. REMOVED/TEST ACTION TAKEN Adjusted crystal/shield on channels 1 & 4 and returned per 16306 Para 4.6 after replacing feedback resistor.		24. OR RETURN		25. OR RETEST	
23. LIST ALL PARTS REPLACED		PART NUMBER			
CMT SYN		PART LOT NO.		DATE CODE	
WPR		PROBABLE DEFECT		ANALYSIS ACQ.	
27. REWORK BY		DATE		28. RETEST BY	
ORG		DATE		ORG	
30. CAUSE AND CORRECTIVE ACTION 20 Crystal/shield not adjusted correctly. Resistor not able to be brought in spec with shield adjustment. Operator instructed to make sure proper adjustments are made before final testing.		31. CONTINUATION SHEET USED			
32. DOCUMENT IMPLEMENTING CORRECTIVE ACTION		33. CONTINUATION SHEET USED			
34. BASIC CAUSE OF VERIFIED FAILURE <input type="checkbox"/> DESIGN <input type="checkbox"/> TEST EQUIP. <input type="checkbox"/> MFG. PROCEDURE <input type="checkbox"/> WIRING ERROR <input type="checkbox"/> UNKNOWN		<input type="checkbox"/> ENVIRONMENTAL <input type="checkbox"/> TEST PROC. <input type="checkbox"/> AGENT/PAS ERROR <input type="checkbox"/> ROUGH HANDLING <input type="checkbox"/> DEFECT CODE			
<input type="checkbox"/> DEFECTIVE PARTS <input type="checkbox"/> TEST SET-UP <input type="checkbox"/> WORKMANSHIP <input type="checkbox"/> WEAR-OUT					
35. FAILURE TYPE <input checked="" type="checkbox"/> PRIMARY <input type="checkbox"/> SECONDARY <input type="checkbox"/> UNKNOWN		36. FAILURE CLASSIFICATION <input type="checkbox"/> CRITICAL <input checked="" type="checkbox"/> MINOR		<input type="checkbox"/> MAJOR <input type="checkbox"/> SAFETY	
37. RESPONSIBLE ENGINEER W. H. H. H.		DATE 2/23 9-17-80		38. SPACECRAFT SYSTEM ENGINEER W. H. H. H.	
39. RELIABILITY 51-47		DATE 10-21-80		40. CUSTOMER OR SUPPLIER 10/21/80	

ORIGINAL PAGE IS
OF POOR QUALITY

HUGHES
HUGHES AIRCRAFT COMPANY

SPACE AND COMMUNICATION GROUP
FAILURE REPORT

F 1717

1. PROGRAM NAME AND NUMBER TM HS 236		2. QLA	3. MODEL FLT	4. TIME OBSERVED 3:14 PM	5. DATE OBSERVED AUG 9 80
6. HARDWARE LEVEL WHICH FAILURE WAS OBSERVED		<input type="checkbox"/> DISCREPANT <input type="checkbox"/> SYSTEM	<input type="checkbox"/> DISASSEMBLY <input type="checkbox"/> UNIT	<input checked="" type="checkbox"/> ASSEMBLY <input type="checkbox"/> MODULE	<input type="checkbox"/> CARD <input type="checkbox"/> PART
7. EQUIPMENT IDENTIFICATION NAME Silicon Assembly		PART NUMBER 51015		SN 103	MANUFACTURER OK
8. UNIT HALF-BAND					
9. ASSEMBLY <input type="checkbox"/> DISASSEMBLY					
10. <input type="checkbox"/> MODULE <input checked="" type="checkbox"/> ICAM <input type="checkbox"/> CARD					
11. OTHER					
12. TEST WHEN FAILURE WAS OBSERVED <input type="checkbox"/> DEVELOPMENT <input type="checkbox"/> QUALIFICATION <input type="checkbox"/> INTEGRATION <input type="checkbox"/> LAUNCH OPERATIONS		<input checked="" type="checkbox"/> EVALUATION			
13. ENVIRONMENT WHICH FAILURE WAS OBSERVED <input checked="" type="checkbox"/> AMBIENT <input type="checkbox"/> RADIATION <input type="checkbox"/> TEMPERATURE <input type="checkbox"/> THERMAL VAC <input type="checkbox"/> VIBRATION <input type="checkbox"/> ACID FOG <input type="checkbox"/> MIN TYPE <input type="checkbox"/> OTHER					
14. D. COPIES OF FAILURE Requirements of paragraph 4.6 (Frequency response) and paragraph 4.7 (Wideband noise) are out of tolerance in 2 places.					
15. TEST PROCEDURE 16306		16. ORIGINATOR M.C. DAVISON	17. DATE 12213 18-8-80	18. CONTINUATION SHEET USED	
19. VERIFICATION AND FAILURE ANALYSIS The unit tested was mis-identified. It is really SN 103					
20. FOLLOWING REPAIR/TEST REQUIRED REPAIR/TEST NOT REQUIRED BECAUSE Repair per supplement 4					
21. AUTHORIZATION M. Randall ORG 2122 DATE 8/8/80 CONTINUATION SHEET USED					
22. REPAIR/TEST ACTION TAKEN Failure Report 58066 was moved against SN 103. Halfband SN 103 was repaired and tested per supplement 4. No correction of any other components needed.					
23. LIST ALL PARTS REPLACED PART NUMBER 50799					
24. CAUSE AND CORRECTIVE ACTION Workmanship. FETs removed during removal of Bandpass filter. Repair was due to excessive stress in assembly substitution. Subsequent testing has been changed to test a theory in substitution.					
25. BASIC CAUSE OF FAILURE <input type="checkbox"/> DESIGN <input type="checkbox"/> TEST EQUIP <input type="checkbox"/> MFG. PROCEDURE <input type="checkbox"/> WIRING ERROR <input type="checkbox"/> UNKNOWN <input type="checkbox"/> ENVIRONMENTAL <input type="checkbox"/> TEST PROC. <input type="checkbox"/> ASSEMBLY/FAB ERROR <input type="checkbox"/> ROUGH HANDLING <input type="checkbox"/> DEFECT CODE <input type="checkbox"/> DEFECTIVE PARTS <input type="checkbox"/> TEST SET-UP <input type="checkbox"/> WORKMANSHIP <input type="checkbox"/> WEAR-OUT					
26. FAILURE TYPE <input type="checkbox"/> PRIMARY <input type="checkbox"/> UNKNOWN <input type="checkbox"/> NO FAILURE					
27. RESPONSIBLE ENGINEER M. Randall ORG 2122 DATE 7-1-81 28. SPACECRAFT SYSTEM ENGR M. Randall ORG 2261 DATE 81076					

ORIGINAL PAGE IS
OF POOR QUALITY

HUGHES
HUGHES AIRCRAFT COMPANY

SPACE AND COMMUNICATION GROUP
FAILURE REPORT

F 2

1. PROGRAM NAME AND NUMBER		TM RS 236		2. QLA	3. MODEL	4. TIME OBSERVED	5. DATE OBSERVED	NO. OF	DA
6. HARDWARE LEVEL WHERE FAILURE WAS OBSERVED		<input type="checkbox"/> SPACECRAFT <input type="checkbox"/> SUBSYSTEM <input checked="" type="checkbox"/> ASSEMBLY <input type="checkbox"/> MODULE <input type="checkbox"/> CARD		<input type="checkbox"/> UNIT <input type="checkbox"/> SUBASSEMBLY <input type="checkbox"/> MECHANISM <input type="checkbox"/> PART					
EQUIPMENT IDENTIFICATION:									
7. SUBSYSTEMS				NAME		PART NUMBER		S/N	
8. UNIT									
9. <input type="checkbox"/> ASSEMBLY <input checked="" type="checkbox"/> SUBASSEMBLY				HALF BAND LEVEL ASSY		51015 -1		102 SBRC	
10. <input type="checkbox"/> MODULE <input type="checkbox"/> MECHANISM <input type="checkbox"/> CARD									
11. OTHER									
12. TEST WHEN FAILURE WAS OBSERVED				<input type="checkbox"/> DEVELOPMENT <input type="checkbox"/> QUALIFICATION <input type="checkbox"/> INTEGRATION <input type="checkbox"/> LAUNCH OPERATIONS					
				<input checked="" type="checkbox"/> IN-PROCESS <input type="checkbox"/> ACCEPTANCE <input type="checkbox"/> SYSTEM					
13. ENVIRONMENT WHEN FAILURE WAS OBSERVED				<input checked="" type="checkbox"/> MAGNETIC <input type="checkbox"/> RADIATION <input type="checkbox"/> TEMPERATURE <input type="checkbox"/> THERMAL VAC <input type="checkbox"/> HRS AT					
				<input type="checkbox"/> EMC/RFI <input type="checkbox"/> VIBRATION <input type="checkbox"/> ALTITUDE <input type="checkbox"/> MIN <input type="checkbox"/> TYPE <input type="checkbox"/> OTHER					
14. DESCRIPTION OF FAILURE									
CHANNELS 1 & 2 IN-BAND NOISE EXCEEDS LIMIT OF 2.4 PA IS: APPROX 3.5 PA. REF. ORIGINAL ER'S 1798, 1 GENERATED FOR NHA. FULL BAND ASSY NO. 50797									
15. TEST PROCEDURE				16597		4.7		16. ORIGINATOR	
						SBRC		DATE 3/6/81	
17. VERIFICATION AND FAILURE ANALYSIS									
18. PARALLEL TESTS IN-100 AND PART NUMBER									
23. FOLLOWING REPAIR/RETEST REQUIRED REPAIR/RETEST NOT REQUIRED BECAUSE									
Replace FETs and retest per 16597 para 4.7									
FET CH1 REPLACED BY AHP SUP 45 - OTHER FETs REPLACED SUP # 6. OP									
21. AUTHORIZATION									
22. REPAIR/RETEST ACTION TAKEN									
FETs replaced and tested good per 16597 para 4.7									
No other components were overhauled.									
25. LIST ALL PARTS REPLACED									
PART NUMBER CKT SYM PART LOT NO. DATE CODE MFR PROBABLE DEFECT ANALYSIS									
52597									
27. REPAIR BY									
28. RETESTED BY									
33. CAUSE AND CORRECTIVE ACTION									
Workmanship. FETs damaged during disassembly of band level assy.									
Band level assy redesigned so that it will not have to be opened after operator cautioned to use more care.									
33. FRD CLOSURE									
32. DOCUMENT IMPLEMENTING CORRECTIVE ACTION									
34. BASIC CAUSE OF VERIFIED FAILURE									
<input type="checkbox"/> DESIGN <input type="checkbox"/> TEST EQUIP. <input type="checkbox"/> MFG. PROCEDURE <input type="checkbox"/> WIRING ERROR <input type="checkbox"/> UNKNOWN									
<input type="checkbox"/> ENVIRONMENTAL <input type="checkbox"/> TEST PROC. <input type="checkbox"/> ASSY/PAS ERROR <input type="checkbox"/> ROUGH HANDLING <input type="checkbox"/> DEFECT CODE									
<input type="checkbox"/> OBSOLETE PARTS <input type="checkbox"/> TEST SET-UP <input checked="" type="checkbox"/> WORKMANSHIP <input type="checkbox"/> WEAR-OUT									
35. FAILURE TYPE									
<input type="checkbox"/> PRIMARY <input type="checkbox"/> UNKNOWN <input type="checkbox"/> NO FAILURE									
36. FAILURE CLASSIFICATION									
<input type="checkbox"/> CRITICAL <input type="checkbox"/> MAJOR <input checked="" type="checkbox"/> MINOR <input type="checkbox"/> SAFETY									
37. RESPONSIBLE ENGINEER									
38. SPACECRAFT SYSTEM ENGR.									
39. RELIABILITY									
40. CUSTOMER OR SUPPLIER									

ORIGINAL PAGE IS
OF POOR QUALITY

HUGHES
HUGHES AIRCRAFT COMPANY

SPACE AND COMMUNICATION GROUP
FAILURE REPORT

F 2241

1. PROGRAM NAME AND NUMBER T-1 H5236		2. QLA	3. CODE 27	4. TIME OBSERVED 72	5. DATE OBSERVED 6/2/81
6. HARDWARE LEVEL WHICH FAILURE WAS OBSERVED <input type="checkbox"/> SPACECRAFT <input type="checkbox"/> SYSTEM <input type="checkbox"/> SUBSYSTEM <input type="checkbox"/> UNIT <input checked="" type="checkbox"/> ASSEMBLY <input type="checkbox"/> DISASSEMBLY <input type="checkbox"/> MODULE <input type="checkbox"/> MECHANISM <input type="checkbox"/> CARD <input type="checkbox"/> PART					
EQUIPMENT IDENTIFICATION					
7. SUBSYSTEM		NAME		PART NUMBER	SN
8. UNIT					
9. <input type="checkbox"/> ASSEMBLY <input checked="" type="checkbox"/> DISASSEMBLY		HALF BAND LEVEL ASSY		57015	203 SERC
10. <input type="checkbox"/> MODULE <input type="checkbox"/> MECHANISM <input type="checkbox"/> CARD					
11. OTHER					
12. TEST WHEN FAILURE WAS OBSERVED <input type="checkbox"/> DEVELOPMENT <input checked="" type="checkbox"/> PRODUCTION		<input type="checkbox"/> QUALIFICATION <input type="checkbox"/> ACCEPTANCE		<input type="checkbox"/> INTEGRATION <input type="checkbox"/> SYSTEM	<input type="checkbox"/> LAUNCH OPERATIONS
13. ENVIRONMENT WHEN FAILURE WAS OBSERVED <input type="checkbox"/> ELEVATION <input type="checkbox"/> EMISSION <input type="checkbox"/> RADIATION <input type="checkbox"/> VIBRATION <input type="checkbox"/> TEMPERATURE <input type="checkbox"/> AXIS FOR <input type="checkbox"/> THERMAL VAC <input type="checkbox"/> HRS. AT <input type="checkbox"/> TYPE <input type="checkbox"/> OTHER					
14. DESCRIPTION OF FAILURE CHANNELS 12 & 8 WIDEBAND NOISE EXCEEDS LIMIT OF 2.4 PA. # REFERENCE ORIGINAL FR'S 1798, 1771, 1786, 1799 GENERATED FOR N.H.A. FULL BAND ASSY NO. 50797					
15. TEST PROCEEDING 16597		16. ORIGINATOR 47	17. ORIGINATOR JOY ZOOH	18. ORG SERC	19. DATE 6/2/81
18. VERIFICATION AND FAILURE ANALYSIS					
19. FAILED ITEM NAME AND PART NUMBER					
20. <input checked="" type="checkbox"/> FOLLOWING OPERATIONAL TEST REQUIRED <input type="checkbox"/> FOLLOWING TEST NOT REQUIRED (CHANGE) Roller FETA and Test PA 16597 Rev. 02 FETA WERE REPLACED BY AFR SUP 4 WHICH INSTALLED A NEW SUBSTRATE WITH NEW FETA/ATTEN 13 AND 14 Substrate replaced and tested per para 16597 para 4.7. No other components were mentioned.					
21. AUTHORIZATION 2122 6/2/81					
22. CONTINUATION SHEET USED					
23. LIST ALL PARTS REPLACED					
PART NUMBER	QTY	SYM	PART LOT NO.	DATE CODE	MSR
PROBABLE DEFECT					
ANAL. SER. NO.					
24. REWORK BY					
25. RETESTED BY					
26. CAUSE AND CORRECTIVE ACTION Workmanship. FETA damaged during disassembly of Bend lead ring. Vibration continued to use of more than Bend level required so that it will not have to be taken apart for excess stress in substrate.					
27. DOCUMENT IMPLEMENTING CORRECTIVE ACTION					
28. BASIC CAUSE OF VERIFIED FAILURE <input type="checkbox"/> DESIGN <input type="checkbox"/> ENVIRONMENTAL <input type="checkbox"/> DEFECTIVE PARTS <input type="checkbox"/> TEST EQUIP. <input type="checkbox"/> TEST PROC. <input type="checkbox"/> TEST SET-UP <input type="checkbox"/> MFG. PROCEDURE <input type="checkbox"/> ASSY/FAB ERROR <input type="checkbox"/> WORKMANSHIP <input type="checkbox"/> WIRING ERROR <input type="checkbox"/> ROUGH HANDLING <input type="checkbox"/> WEAR-OUT <input type="checkbox"/> UNKNOWN <input type="checkbox"/> DEFECT CODE					
29. FAILURE TYPE <input type="checkbox"/> PRIMARY <input checked="" type="checkbox"/> SECONDARY <input type="checkbox"/> UNKNOWN <input type="checkbox"/> NO FAILURE					
30. FAILURE CLASSIFICATION <input type="checkbox"/> CRITICAL <input type="checkbox"/> MAJOR <input type="checkbox"/> MINOR <input type="checkbox"/> SAFETY					
31. RESPONSIBLE ENGINEER 2122 6/2/81					
32. SPACECRAFT SYSTEM ENG 224 6/2/81					

ORIGINAL PAGE IS
OF POOR QUALITY

HUGHES

HUGHES AIRCRAFT COMPANY

SPACE AND COMMUNICATION GROUP
FAILURE REPORT

F 2662

1. PROGRAM NAME AND NUMBER T.M.		2. CLA	3. MODEL FLT	4. TIME OBSERVED 6:30 PM	5. DATE OBSERVED 2 19 1981
6. HARDWARE LEVEL WHEN FAILURE WAS OBSERVED <input type="checkbox"/> SPACECRAFT <input type="checkbox"/> SYSTEM <input type="checkbox"/> SUBSYSTEM <input type="checkbox"/> UNIT <input checked="" type="checkbox"/> ASSEMBLY <input checked="" type="checkbox"/> SUBASSEMBLY <input type="checkbox"/> MODULE <input type="checkbox"/> SCAM <input type="checkbox"/> CARD <input type="checkbox"/> PART					
7. SUBSYSTEM					
8. UNIT					
9. <input type="checkbox"/> ASSEMBLY <input checked="" type="checkbox"/> SUBASSEMBLY S: FPA HALF BAND 51015-1 208-1 SBRC					
10. <input type="checkbox"/> MODULE <input type="checkbox"/> SCAM <input type="checkbox"/> CARD					
11. OTHER					
12. TEST WHEN FAILURE WAS OBSERVED <input type="checkbox"/> DEVELOPMENT <input type="checkbox"/> QUALIFICATION <input type="checkbox"/> INTEGRATION <input type="checkbox"/> LAUNCH OPERATIONS <input type="checkbox"/> IN-PROCESS <input checked="" type="checkbox"/> ACCEPTANCE <input type="checkbox"/> SYSTEM					
13. ENVIRONMENT WHEN FAILURE WAS OBSERVED <input checked="" type="checkbox"/> AMBIENT <input type="checkbox"/> RADIATION <input type="checkbox"/> TEMPERATURE <input type="checkbox"/> THERMAL VAC <input type="checkbox"/> POS. AT <input type="checkbox"/> OTHER <input type="checkbox"/> ESD/EMI <input type="checkbox"/> VIBRATION <input type="checkbox"/> AXIS FOR <input type="checkbox"/> MM <input type="checkbox"/> TYPE					
14. DESCRIPTION OF FAILURE CHANNEL 8 NOISE OUT OF SPEC. S/B 2.4 PA MAX OBSERVED VALUE IS 2.5 PA.					
15. TEST PROCEDURE 16306 PARA 4.7 16. ORIGINATOR A.C. JAVISON ORG 2213 DATE 21 22 10/14/81 17. CONTINUATION SHEET USED <input type="checkbox"/>					
18. VERIFICATION AND FAILURE ANALYSIS Failure due to a noisy test detector. The operation of many components occurred. NO HARDWARE WAS NOT INVOLVED.					
19. PARTS LISTED NAME AND PART NUMBER					
20. <input checked="" type="checkbox"/> FOLLOWING RECORD/TEST REQUIRED OR REMOVED/TEST NOT REQUIRED BECAUSE Halfband noise increased while connected to a test detector. In this case the test detector was contributing more than the proper 10 dB noise that a good test detector does. 21. AUTHORIZATION W. J. J. J. ORG 2213 DATE 21 22 10/14/81 22. CONTINUATION SHEET USED <input type="checkbox"/>					
23. REWORK/RETEST ACTION TAKEN Halfband was used in band looking 35N 21. The Halfband 208-1 was connected to band looking 35N 21. The noise of band looking 35N 21 was measured and found to be 2.4 PA well within the spec. of 2.4 PA. 24. ORG 2213 DATE 21 22 10/14/81 25. CONTINUATION SHEET USED <input type="checkbox"/>					
26. LIST ALL PARTS REPLACED PART NUMBER CRT SYM PART LOT NO. DATE CODE VPR PROBABLE DEFECT ANALYSIS NO.					
27. REWORK BY ORG DATE 28. RETESTED BY ORG DATE 29. CONTINUATION SHEET USED <input type="checkbox"/>					
30. CAUSE AND CORRECTIVE ACTION The test detector should have been changed and the halfband tested. Personnel have been instructed to do so in the future. 31. PRO CLOSURE 11/17/81					
32. DOCUMENT IMPLEMENTING CORRECTIVE ACTION					
33. BASIC CAUSE OF VERIFIED FAILURE <input type="checkbox"/> DESIGN <input checked="" type="checkbox"/> TEST EQUIP. <input type="checkbox"/> MPQ. PROCEDURE <input type="checkbox"/> WIRING ERROR <input type="checkbox"/> UNKNOWN <input type="checkbox"/> ENVIRONMENTAL <input type="checkbox"/> TEST PROC. <input type="checkbox"/> ASSEY/PAG ERROR <input type="checkbox"/> ROUGH HANDLING <input type="checkbox"/> DEFECT CODE <input type="checkbox"/> DEFECTIVE PARTS <input type="checkbox"/> TEST SET-UP <input type="checkbox"/> WORKMANSHIP <input type="checkbox"/> WEAR-OUT					
34. FAILURE TYPE <input type="checkbox"/> PRIMARY <input type="checkbox"/> UNKNOWN <input checked="" type="checkbox"/> NO FAILURE <input checked="" type="checkbox"/> INDUCED					
35. FAILURE CLASSIFICATION <input type="checkbox"/> CRITICAL <input checked="" type="checkbox"/> MINOR <input type="checkbox"/> SAFETY <input type="checkbox"/> MAJOR					
36. RESPONSIBLE ENGINEER W. J. J. J. ORG 2213 DATE 21 22 10/14/81 37. SPACECRAFT SYSTEM ENGR. W. J. J. J. ORG 2213 DATE 21 22 10/14/81					
38. RELIABILITY 208-1 ORG 51-4 DATE 11/17/81 39. CUSTOMER OR SUPPLIER 208-1 DATE 11/17/81					

ORIGINAL PAGE IS
OF POOR QUALITY

HUGHES

HUGHES AIRCRAFT COMPANY

SPACE AND COMMUNICATION GROUP
FAILURE REPORT

F 266

1. PROGRAM NAME AND NUMBER TM VO11		2. SLA	3. MODEL FLIGHT	4. TIME OBSERVED 1075	5. DATE OBSERVED 12-10-81
6. HARDWARE LEVEL CIRCUIT BOARD <input type="checkbox"/> SPACECRAFT <input type="checkbox"/> SUBSYSTEM <input type="checkbox"/> ASSEMBLY <input type="checkbox"/> MODULE <input type="checkbox"/> CARD <input type="checkbox"/> SYSTEM <input type="checkbox"/> UNIT <input checked="" type="checkbox"/> SUBASSEMBLY <input type="checkbox"/> MECHAN <input type="checkbox"/> PART					
7. SUBSYSTEM IDENTIFICATION NAME: PART NUMBER: SIZE: MANUFACTURER:					
8. UNIT					
9. <input type="checkbox"/> ASSEMBLY <input checked="" type="checkbox"/> SUBASSEMBLY 510154 203					
10. <input type="checkbox"/> MODULE <input type="checkbox"/> MECHAN <input type="checkbox"/> CARD					
11. OTHER					
12. TEST WHEN FAILURE WAS OBSERVED <input type="checkbox"/> DEVELOPMENT <input type="checkbox"/> QUALIFICATION <input type="checkbox"/> INTEGRATION <input type="checkbox"/> LAUNCH OPERATIONS <input type="checkbox"/> PRODUCTION <input checked="" type="checkbox"/> ACCEPTANCE <input type="checkbox"/> SYSTEM					
13. ENVIRONMENT WHEN FAILURE WAS OBSERVED <input checked="" type="checkbox"/> AMBIENT <input type="checkbox"/> RADIATION <input type="checkbox"/> TEMPERATURE <input type="checkbox"/> THERMAL VAC <input type="checkbox"/> HRS. AT <input type="checkbox"/> OTHER <input type="checkbox"/> SHOCK <input type="checkbox"/> VIBRATION <input type="checkbox"/> AXIS FOR <input type="checkbox"/> USE <input type="checkbox"/> TYPE					
14. DESCRIPTION OF FAILURE CH. 7 TRANSIENT RESPONSE IS 2% LOWER AFTER 30ms AND 1.75% LOWER AFTER 60ms					
15. TEST NUMBER 110306		16. PART NUMBER 146	17. ORIGINATOR C. R. Jones		18. DATE 12-11-81
19. VERIFICATION AND FAILURE ANALYSIS Failure is in performance only; no hardware were subjected to over-stress.					
20. FOLLOWING REPAIR/TEST REQUIRED <input checked="" type="checkbox"/> REPAIR/TEST NOT REQUIRED BECAUSE Replace resistor Ch. 7 and circuit per 16306 para 4.6					
21. AUTHORIZATION [Signature] 21-22 15-11-81 <input type="checkbox"/> CONTINUE <input type="checkbox"/> STOP USE					
22. REPAIR/TEST ACTION USED Replaced resistor Ch. 7 and circuit manually per 16306 para 4.6					
23. LIST ALL PARTS REPLACED PART NUMBER: CXT SYS: PART LOT NO: DATE CODE: MFR: PROBABLE DEFECT: ANALYSIS NO: 52595					
24. REMARKS BY: C. R. Jones 21-22 15-11-81 <input type="checkbox"/> CONTINUE <input type="checkbox"/> STOP USE					
25. CAUSE AND CORRECTIVE ACTION Transient response changed after replacement of a cross-talk shield. Transient response in sensitive portion of shield and could not be brought into spec with new shield. Transient could not be controlled with selection of resistor as required. DISTRIBUTED CAPACITANCE OF RESISTOR TO GROUND CHANGED WHEN CROSSTALK					
26. PROS CLOSURE [Signature] 5/18/81					
27. DOCUMENT IMPLEMENTING CORRECTIVE ACTION					
28. BASIC CAUSE OF VERIFIED FAILURE <input type="checkbox"/> DESIGN <input type="checkbox"/> TEST EQUIP <input type="checkbox"/> MFG. PROCEDURE <input type="checkbox"/> WIRING ERROR <input type="checkbox"/> UNKNOWN <input type="checkbox"/> ENVIRONMENTAL <input type="checkbox"/> TEST PROC. <input type="checkbox"/> ASSEMBLY ERROR <input type="checkbox"/> ROUGH HANDLING <input type="checkbox"/> DEFECT CODE <input checked="" type="checkbox"/> DEFECTIVE PARTS <input type="checkbox"/> TEST SET UP <input type="checkbox"/> WORKMANSHIP <input type="checkbox"/> WEAR-OUT					
29. FAILURE TYPE <input checked="" type="checkbox"/> PRIMARY <input type="checkbox"/> SECONDARY <input type="checkbox"/> UNKNOWN <input type="checkbox"/> NO FAILURE					
30. FAILURE CLASSIFICATION <input type="checkbox"/> CRITICAL <input type="checkbox"/> MINOR <input type="checkbox"/> SAFETY <input type="checkbox"/> MODERATE					
31. RESPONSIBLE ENGINEER [Signature] 21-22 15/11/81 2261 810					

ORIGINAL PAGE IS
OF POOR QUALITY

HUGHES

HUGHES AIRCRAFT COMPANY

SPACE AND COMMUNICATION GROUP
EQUIPMENT CHECKOUT
FAILURE REPORT
CONTINUATION SHEET

2663 CONT. SHE
FR SERIAL NO. LETTER
A

*LABEL FIRST CONTINUATION SHEET USED 'A', SECOND 'B', AND SO ON

IDENTIFY ENTRIES BY REFERENCING FR BLOCK NUMBER IN COLUMN, DATE EACH ENTRY.

ADDITIONAL FR
CONTINUATION
SHEET(S) USED

30 SHIELD WAS CHANGED OUT. CROSSTALK SHIELD IS A PART OF
THE GROUND PLANE. THE NEW RESISTOR MATCHED THE ELEM
CHARACTERISTICS OF THE CIRCUIT TO CORRECT TRANSIENT
RESPONSE.

Approved by (GSFC) 8-12-81

ORIGINAL PAGE IS
OF POOR QUALITY

HUGHES

HUGHES AIRCRAFT COMPANY

SPACE AND COMMUNICATION GROUP
FAILURE REPORT

F 2668

1. PROGRAM NAME AND NUMBER		TM VO11		2. SLA	3. MODEL	FLT	4. TIME OBSERVED	4:30A	5. DATE OBSERVED	8-29-81	
6. HARDWARE LEVEL		<input type="checkbox"/> SPACECRAFT		<input type="checkbox"/> SUBSYSTEM		<input type="checkbox"/> ASSEMBLY		<input type="checkbox"/> MODULE		<input type="checkbox"/> CARD	
7. SUBSYSTEM		<input type="checkbox"/> SYSTEM		<input type="checkbox"/> UNIT		<input checked="" type="checkbox"/> SUBASSEMBLY		<input type="checkbox"/> MICAM		<input type="checkbox"/> PART	
8. COMPONENT IDENTIFICATION		NAME		PART NUMBER		SN		MANUFACTURER			
9. UNIT											
10. <input type="checkbox"/> ASSEMBLY <input checked="" type="checkbox"/> SUBASSEMBLY		Band 4		50797		401		SBRG			
11. OTHER											
12. TEST WHEN FAILURE WAS OBSERVED		<input checked="" type="checkbox"/> DEVELOPMENT		<input type="checkbox"/> QUALIFICATION		<input type="checkbox"/> INTEGRATION		<input type="checkbox"/> LAUNCH OPERATIONS			
13. ENVIRONMENT WHEN FAILURE WAS OBSERVED		<input checked="" type="checkbox"/> ACCELERATION		<input type="checkbox"/> RADIATION		<input type="checkbox"/> TEMPERATURE		<input type="checkbox"/> THERMAL VAC		<input type="checkbox"/> H2O AT	
14. DESCRIPTION OF FAILURE		CHANNEL 16 FAILS TO RESPOND TO OPTICAL STIMULUS.									
15. TEST PROCEDURE		16597		PAGE 1 N/A		16. ORIGINATOR		N.C. DAVISON		2213	
17. VERIFICATION AND FAILURE ANALYSIS											
18. FOLLOWING RECORD/TEST REQUIRED		REWORK AND RETEST FOR SUPPLEMENT 1									
19. AUTHORIZATION											
20. REWORK/RETEST ACTION TAKEN		Reworked and tested for supplement 1 successfully.									
21. LIST ALL PARTS REPLACED		PART NUMBER		CMT SYM		PART LOT NO.		DATE CODE		WPR	
22. Rework		BY		DATE		20. RETESTED BY		DATE			
23. CAUSE AND CORRECTIVE ACTION		Detector stage was damaged during early out of plane									
24. BASIC CAUSE OF VERIFIED FAILURE		<input type="checkbox"/> DESIGN		<input type="checkbox"/> TEST EQUIP		<input type="checkbox"/> MFG. PROCEDURE		<input type="checkbox"/> WIRING ERROR		<input type="checkbox"/> UNKNOWN	
25. FAILURE TYPE		<input checked="" type="checkbox"/> PRIMARY		<input type="checkbox"/> SECONDARY		<input type="checkbox"/> UNKNOWN		<input type="checkbox"/> CRITICAL		<input checked="" type="checkbox"/> MINOR	
26. RESPONSIBLE ENGINEER		J. H. K. K. K.		DATE		12/1/81		13. SPACECRAFT SYSTEM ENGR.		DATE	

ORIGINAL PAGE IS
OF POOR QUALITY

HUGHES

HUGHES AIRCRAFT COMPANY

SPACE AND COMMUNICATION GROUP

FAILURE REPORT

F 26

1. PROGRAM NAME AND NUMBER T.M.		2. GLA		3. MODEL		4. TIME OBSERVED 2:30		5. DATE OBSERVED NO 3 2	
6. HAZARDOUS LEVEL WHEN FAILURE WAS OBSERVED <input type="checkbox"/> SPACECRAFT <input type="checkbox"/> SYSTEM		<input type="checkbox"/> SUBSYSTEM <input type="checkbox"/> UNIT		<input type="checkbox"/> ASSEMBLY <input checked="" type="checkbox"/> SUBASSEMBLY		<input type="checkbox"/> MODULE <input type="checkbox"/> MICAS		<input type="checkbox"/> CARD <input type="checkbox"/> PART	
8. EQUIPMENT IDENTIFICATION:									
7. SUBSYSTEM									
8. UNIT									
9. <input type="checkbox"/> ASSEMBLY <input checked="" type="checkbox"/> SUBASSEMBLY									
10. <input type="checkbox"/> MODULE <input type="checkbox"/> MICAS <input type="checkbox"/> CARD									
11. OTHER									
12. TEST WHEN FAILURE WAS OBSERVED <input type="checkbox"/> DEVELOPMENT <input type="checkbox"/> IN-PROCESS <input type="checkbox"/> QUALIFICATION <input checked="" type="checkbox"/> ACCEPTANCE <input type="checkbox"/> INTEGRATION <input type="checkbox"/> SYSTEM <input type="checkbox"/> LAUNCH OPERATIONS									
13. ENVIRONMENT WHEN FAILURE WAS OBSERVED <input checked="" type="checkbox"/> SHOCK <input type="checkbox"/> RADIATION <input type="checkbox"/> TEMPERATURE <input type="checkbox"/> THERMAL VAC <input type="checkbox"/> MAG AT <input type="checkbox"/> OTHER									
14. DESCRIPTION OF FAILURE CH. 3 TRANSIENT RESP. IS 1.25% @ 60K SEC. S/B 6190 @ 60K SEC. RECOMMEND USE AS IS.									
15. TEST 16306 PARA 46 16. ORIGINATOR N.C. JAVISON ORG 2213 DATE 12-81 17. CONTIN SHEET									
18. INVESTIGATION AND FAILURE ANALYSIS									
19. FAILED ITEM NAME AND PART NUMBER									
20. <input checked="" type="checkbox"/> FOLLOW-UP REQUIRED (RETEST REQUIRED) (RETEST NOT REQUIRED) DUE TO Further review is not considered until schedule effective at this time.									
21. AUTHORIZATION [Signature] ORG 2213 DATE 12/1/81 22. CONTIN SHEET									
23. REWORK/RETEST ACTION TAKEN									
24. CAUSE AND CORRECTIVE ACTION This channel was rework a matter of time and time was the best transient response strength. There is no need to use or is rather than subject the hardware to any further rework. Waves W-119 attached.									
25. LIST ALL PARTS REPLACED									
26. REWORK BY ORG DATE 27. RETESTED BY ORG DATE									
28. BASIC CAUSE OF VERIFIED FAILURE <input checked="" type="checkbox"/> DESIGN <input type="checkbox"/> TEST EQUIP. <input type="checkbox"/> MFG. PROCEDURE <input type="checkbox"/> WIRING ERROR <input type="checkbox"/> UNKNOWN <input type="checkbox"/> ENVIRONMENTAL <input type="checkbox"/> TEST PROC. <input type="checkbox"/> ASSEMBLY ERROR <input type="checkbox"/> ROUGH HANDLING <input type="checkbox"/> DEFECT CODE <input type="checkbox"/> DEFECTIVE PARTS <input type="checkbox"/> TEST SET-UP <input type="checkbox"/> WORKMANSHIP <input type="checkbox"/> WEAR-OUT									
29. FAILURE TYPE <input checked="" type="checkbox"/> PRIMARY <input type="checkbox"/> UNKNOWN <input checked="" type="checkbox"/> INDUCED <input type="checkbox"/> NO FAILURE									
30. SPACE PART SYSTEM ENGR [Signature] ORG 2241 DATE 11/17									
31. RELIABILITY [Signature] ORG 151-41 DATE 11-18-81									
32. CUSTOMER OR SUPPLIER [Signature]									

ORIGINAL PAGE IS
OF POOR QUALITY
Program Instruction 010

F2669

REQUEST FOR DEVIATION/VALUER
(SEE VIL 510-10 ON SET FOR INSTRUCTIONS)

DATE PREPARED

PROCESSING ACTIVITY NO.

1. ORIGINATOR NAME AND ADDRESS David M. Randall SBRC, 75 Coronar Dr., Goleta, Ca. 93117				2. DEVIATION <input type="checkbox"/> MINOR <input checked="" type="checkbox"/> MAJOR <input type="checkbox"/> CRITICAL	
3. REQUEST FOR DEVIATION/VALUER a. MOD. TYPE F b. MOD. CODE 11323 c. MOD. TYPE TM d. MOD. CODE W-119				4. BASE LINE AFFECTED <input checked="" type="checkbox"/> FUNC. <input type="checkbox"/> ALLO. <input type="checkbox"/> PROG. <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO	
5. OTHER SYSTEMS/CORRELATION ITEMS AFFECTED <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO				6. DRAWINGS AFFECTED a. MOD. CODE 11323 b. DRAWING NO. 51015 c. REV. D d. MOD. NO. 2950-A	
7. TITLE OF DEVIATION/VALUER Permission to use Halfband SN 207-1				8. CONTRACT NO. & LINE ITEM NAS 5-24200	
9. DESCRIPTION OF DEVIATION/VALUER Radiometer				10. CD NO. II	
11. NAME OF PART OR SUB-ASSEMBLY AFFECTED 51015				12. PART NO. OR TYPE DESIGN 207-1	
13. EFFECT ON INTEGRATED LOGISTIC SUPPORT, INTERFACES, ETC. None				14. EFFECT ON DELIVERY SCHEDULE Greater than 4 months if not approved.	
15. DESCRIPTION OF DEVIATION/VALUER Permission to use Halfband SN 207-1 with transient response meeting to 1.75% by 60 msec on channel 1 vs a specification of $\pm 1.0\%$ by 60 msec.					

16. REASON FOR DEVIATION/VALUER

This unit had been rework a number of times and this was the best result. Halfband has since been assembled into Band 2 Band Level Assy. Rework at this time is not considered cost or schedule effective.

17. APPROVAL a. APPROVAL RECOMMENDED b. APPROVAL c. DISAPPROVED		18. APPROVAL a. APPROVAL b. DISAPPROVED	
19. APPROVAL a. APPROVAL b. DISAPPROVED		20. APPROVAL a. APPROVAL b. DISAPPROVED	
21. APPROVAL a. APPROVAL b. DISAPPROVED		22. APPROVAL a. APPROVAL b. DISAPPROVED	
23. APPROVAL a. APPROVAL b. DISAPPROVED		24. APPROVAL a. APPROVAL b. DISAPPROVED	
25. APPROVAL a. APPROVAL b. DISAPPROVED		26. APPROVAL a. APPROVAL b. DISAPPROVED	
27. APPROVAL a. APPROVAL b. DISAPPROVED		28. APPROVAL a. APPROVAL b. DISAPPROVED	
29. APPROVAL a. APPROVAL b. DISAPPROVED		30. APPROVAL a. APPROVAL b. DISAPPROVED	
31. APPROVAL a. APPROVAL b. DISAPPROVED		32. APPROVAL a. APPROVAL b. DISAPPROVED	
33. APPROVAL a. APPROVAL b. DISAPPROVED		34. APPROVAL a. APPROVAL b. DISAPPROVED	
35. APPROVAL a. APPROVAL b. DISAPPROVED		36. APPROVAL a. APPROVAL b. DISAPPROVED	
37. APPROVAL a. APPROVAL b. DISAPPROVED		38. APPROVAL a. APPROVAL b. DISAPPROVED	
39. APPROVAL a. APPROVAL b. DISAPPROVED		40. APPROVAL a. APPROVAL b. DISAPPROVED	
41. APPROVAL a. APPROVAL b. DISAPPROVED		42. APPROVAL a. APPROVAL b. DISAPPROVED	
43. APPROVAL a. APPROVAL b. DISAPPROVED		44. APPROVAL a. APPROVAL b. DISAPPROVED	
45. APPROVAL a. APPROVAL b. DISAPPROVED		46. APPROVAL a. APPROVAL b. DISAPPROVED	
47. APPROVAL a. APPROVAL b. DISAPPROVED		48. APPROVAL a. APPROVAL b. DISAPPROVED	
49. APPROVAL a. APPROVAL b. DISAPPROVED		50. APPROVAL a. APPROVAL b. DISAPPROVED	
51. APPROVAL a. APPROVAL b. DISAPPROVED		52. APPROVAL a. APPROVAL b. DISAPPROVED	
53. APPROVAL a. APPROVAL b. DISAPPROVED		54. APPROVAL a. APPROVAL b. DISAPPROVED	
55. APPROVAL a. APPROVAL b. DISAPPROVED		56. APPROVAL a. APPROVAL b. DISAPPROVED	
57. APPROVAL a. APPROVAL b. DISAPPROVED		58. APPROVAL a. APPROVAL b. DISAPPROVED	
59. APPROVAL a. APPROVAL b. DISAPPROVED		60. APPROVAL a. APPROVAL b. DISAPPROVED	
61. APPROVAL a. APPROVAL b. DISAPPROVED		62. APPROVAL a. APPROVAL b. DISAPPROVED	
63. APPROVAL a. APPROVAL b. DISAPPROVED		64. APPROVAL a. APPROVAL b. DISAPPROVED	
65. APPROVAL a. APPROVAL b. DISAPPROVED		66. APPROVAL a. APPROVAL b. DISAPPROVED	
67. APPROVAL a. APPROVAL b. DISAPPROVED		68. APPROVAL a. APPROVAL b. DISAPPROVED	
69. APPROVAL a. APPROVAL b. DISAPPROVED		70. APPROVAL a. APPROVAL b. DISAPPROVED	
71. APPROVAL a. APPROVAL b. DISAPPROVED		72. APPROVAL a. APPROVAL b. DISAPPROVED	
73. APPROVAL a. APPROVAL b. DISAPPROVED		74. APPROVAL a. APPROVAL b. DISAPPROVED	
75. APPROVAL a. APPROVAL b. DISAPPROVED		76. APPROVAL a. APPROVAL b. DISAPPROVED	
77. APPROVAL a. APPROVAL b. DISAPPROVED		78. APPROVAL a. APPROVAL b. DISAPPROVED	
79. APPROVAL a. APPROVAL b. DISAPPROVED		80. APPROVAL a. APPROVAL b. DISAPPROVED	
81. APPROVAL a. APPROVAL b. DISAPPROVED		82. APPROVAL a. APPROVAL b. DISAPPROVED	
83. APPROVAL a. APPROVAL b. DISAPPROVED		84. APPROVAL a. APPROVAL b. DISAPPROVED	
85. APPROVAL a. APPROVAL b. DISAPPROVED		86. APPROVAL a. APPROVAL b. DISAPPROVED	
87. APPROVAL a. APPROVAL b. DISAPPROVED		88. APPROVAL a. APPROVAL b. DISAPPROVED	
89. APPROVAL a. APPROVAL b. DISAPPROVED		90. APPROVAL a. APPROVAL b. DISAPPROVED	
91. APPROVAL a. APPROVAL b. DISAPPROVED		92. APPROVAL a. APPROVAL b. DISAPPROVED	
93. APPROVAL a. APPROVAL b. DISAPPROVED		94. APPROVAL a. APPROVAL b. DISAPPROVED	
95. APPROVAL a. APPROVAL b. DISAPPROVED		96. APPROVAL a. APPROVAL b. DISAPPROVED	
97. APPROVAL a. APPROVAL b. DISAPPROVED		98. APPROVAL a. APPROVAL b. DISAPPROVED	
99. APPROVAL a. APPROVAL b. DISAPPROVED		100. APPROVAL a. APPROVAL b. DISAPPROVED	

DD FORM 1694

HUGHES

HUGHES AIRCRAFT COMPANY
SPACE AND COMMUNICATIONS GROUP
81 SEGUNDO, CALIFORNIA

SPACE AND COMMUNICATIONS GROUP FAILURE REPORT

ORIGINAL PAGE 13
OF POOR QUALITY

S 801

1. PROGRAM NAME AND NUMBER V011		2. GLA		3. MODEL FLIGHT		4. TIME OBSERVED 1:32 P.M.		5. DATE OBSERVED MO 6 DA 13 YR 8	
6. HARDWARE LEVEL WHEN FAILURE WAS OBSERVED		<input type="checkbox"/> SPACECRAFT <input type="checkbox"/> SYSTEM		<input type="checkbox"/> SUBSYSTEM <input type="checkbox"/> UNIT		<input type="checkbox"/> ASSEMBLY <input type="checkbox"/> SUBASSEMBLY		<input type="checkbox"/> MODULE <input type="checkbox"/> MICAM <input checked="" type="checkbox"/> CARD <input type="checkbox"/> PART	
EQUIPMENT IDENTIFICATION:									
7. SUBSYSTEM		NAME		PART NUMBER		S/N		MANUFACTURER	
8. UNIT									
9. <input type="checkbox"/> ASSEMBLY <input type="checkbox"/> SUBASSEMBLY									
10. <input type="checkbox"/> MODULE <input type="checkbox"/> MICAM <input checked="" type="checkbox"/> CARD		(BAND 2)		50904		201		SBRC	
11. OTHER									
12. TEST WHEN FAILURE WAS OBSERVED		<input type="checkbox"/> DEVELOPMENT <input checked="" type="checkbox"/> IN-PROCESS		<input type="checkbox"/> QUALIFICATION <input type="checkbox"/> ACCEPTANCE		<input type="checkbox"/> INTEGRATION <input type="checkbox"/> SYSTEM		<input type="checkbox"/> LAUNCH OPERATIONS	
13. ENVIRONMENT WHEN FAILURE WAS OBSERVED		<input checked="" type="checkbox"/> AMBIENT <input type="checkbox"/> EMC/RFI		<input type="checkbox"/> RADIATION <input type="checkbox"/> VIBRATION		<input type="checkbox"/> TEMP AXIS FOR		<input type="checkbox"/> THERMAL VAC HRS AT <input type="checkbox"/> OTHER	
14. DESCRIPTION OF FAILURE NO SIGNAL CH'S 3, 4, 7, 8, 11, 12, 15, 16. JUMPER FROM R98 TO U1-PIN18 INCORRECTLY CONNECTED TO U1-PIN42. ETC. FOR CHANNELS 4, 7, 8, 11, 12, 15 & 16. JUMPERS NOT TO PRINT.									
15. TEST PROCEDURE		16368		16. OPERATOR 431		17. DATE 6-16-81		18. CONTINUAL SHEET USED <input type="checkbox"/>	
19. VERIFICATION AND FAILURE ANALYSIS MISPLACED JUMPER WIRES (WORKMANSHIP ERROR). NO OVERSTRESS ACCURRED SEE AVO DATED 11/19/81. (ATTACHED)									
20. FOLLOWING REWORK/RETEST REQUIRED <input type="checkbox"/> Rework/Retest Not Required Because INSTALL JUMPER WIRES TO PRINT									
21. AUTHORIZATION ORG DATE									
22. REWORK/RETEST ACTION TAKEN JUMPER WIRES PROPERLY INSTALLED PER E.O. 9678									
23. LIST ALL PARTS REPLACED PART NUMBER CKT SYM PART LOT NUMBER DATE CODE MANUFACTURER PROBABLE DEFECT ANALYSIS N/A									
NONE									
27. REWORK BY ORG DATE 28. RETESTED BY ORG DATE									
29. CAUSE AND CORRECTIVE ACTION WORKMANSHIP ERROR (JUMPER WIRES NOT INSTALLED TO PRINT). PERSONNEL READVISED TO BE CAREFUL WHEN INSTALLING JUMPER WIRES. Inspection supervisor notified of inspection error. Will review all effective E.O. prior to installation.									
30. DOCUMENT IMPLEMENTING CORRECTIVE ACTION E.O. 9678 DETAILS JUMPER WIRE INSTALLATION ATTACHED									
31. BASIC CAUSE OF VERIFIED FAILURE <input type="checkbox"/> DESIGN <input type="checkbox"/> ENVIRONMENTAL <input type="checkbox"/> DEFECTIVE PARTS <input type="checkbox"/> TEST EQUIPMENT <input type="checkbox"/> TEST PROCEDURE <input type="checkbox"/> TEST SET-UP <input checked="" type="checkbox"/> MFG. PROCEDURE <input type="checkbox"/> ASSY/FAB ERROR <input checked="" type="checkbox"/> WORKMANSHIP <input type="checkbox"/> WIRING ERROR <input type="checkbox"/> ROUGH HANDLING <input type="checkbox"/> WEAR-OUT <input type="checkbox"/> UNKNOWN									
32. FAILURE TYPE <input checked="" type="checkbox"/> PRIMARY <input type="checkbox"/> INDUCED <input type="checkbox"/> UNKNOWN <input type="checkbox"/> NO FAILURE									
33. RESPONSIBLE ENGINEER 11/11/81									
34. RELIABILITY 51-11 11-13-81									
35. FAILURE CLASSIFICATION <input type="checkbox"/> CRITICAL <input type="checkbox"/> MAJOR <input checked="" type="checkbox"/> MINOR <input type="checkbox"/> SAFETY									
36. DATE 11/19/81									

AVOID VERBAL ORDERS

TO Lloyd O'Connell, Mgr. ReliabilityDATE November 19, 1981FROM Dee Evans, Reliability EngineerSUBJECT FR #8014After carefully reviewing schematic in conjunction with subject failure #8014,I comfortably feel that no overstress has occurred to any components regarding
subject failure.Dee Evans, *Dee Evans*
Reliability Engineer

HUGHESHUGHES AIRCRAFT COMPANY
SPACE AND COMMUNICATIONS GROUP
EL SEGUNDO, CALIFORNIASPACE AND COMMUNICATIONS GROUP
FAILURE REPORTORIGINAL PAGE IS
OF POOR QUALITY**S** 8058

1. PROGRAM NAME AND NUMBER TM VO11		2. GLA	3. MODEL FLIGHT	4. TIME OBSERVED 4:27 p.m.	5. DATE OBSERVED MO 12 DA 11 YR 8
6. HARDWARE LEVEL WHEN FAILURE WAS OBSERVED <input type="checkbox"/> SPACECRAFT <input type="checkbox"/> SUBSYSTEM <input type="checkbox"/> ASSEMBLY <input type="checkbox"/> MODULE <input type="checkbox"/> CARD <input type="checkbox"/> SYSTEM <input type="checkbox"/> UNIT <input checked="" type="checkbox"/> SUBASSEMBLY <input type="checkbox"/> MICAM <input type="checkbox"/> PART					
EQUIPMENT IDENTIFICATION:		NAME	PART NUMBER	S/N	MANUFACTURER
7. SUBSYSTEM					
8. UNIT					
9. <input type="checkbox"/> ASSEMBLY <input checked="" type="checkbox"/> SUBASSEMBLY			51015-1	102-1	
10. <input type="checkbox"/> MODULE <input type="checkbox"/> MICAM <input type="checkbox"/> CARD					
11. OTHER					
12. TEST WHEN FAILURE WAS OBSERVED <input type="checkbox"/> DEVELOPMENT <input type="checkbox"/> IN-PROCESS <input type="checkbox"/> QUALIFICATION <input checked="" type="checkbox"/> ACCEPTANCE <input type="checkbox"/> INTEGRATION <input type="checkbox"/> SYSTEM <input type="checkbox"/> LAUNCH OPERATIONS					
13. ENVIRONMENT WHEN FAILURE WAS OBSERVED <input checked="" type="checkbox"/> AMBIENT <input type="checkbox"/> RADIATION <input type="checkbox"/> TEMP <input type="checkbox"/> THERMAL VAC HRS AT <input type="checkbox"/> OTHER <input type="checkbox"/> EMC/RFI <input type="checkbox"/> VIBRATION AXIS FOR MIN TYPE					
14. DESCRIPTION OF FAILURE CHANNEL NO. 1 OUTPUT PEGGED AT -25V TRANSIENT RESPONSE - 170 ON CHANNELS 1 & 3					
15. TEST PROCEDURE 16306		16. PARA 46-4.7	18. ORIGINATOR N.C. DAVISON	19. ORG 2213	20. DATE 12-11-80
17. CONTINUATION SHEET USED					
18. VERIFICATION AND FAILURE ANALYSIS FET damaged during rework of Band 1 SN 101. No structure of any components occurred as a result.					
19. FOLLOWING REWORK/RETEST REQUIRED <input type="checkbox"/> Rework/Retest Not Required Because		10. FAILED ITEM NAME AND PART NUMBER			
Replace FET per supplement #5.					
21. AUTHORIZATION <i>[Signature]</i>		22. ORG 222	23. DATE 12/11/80	24. CONTINUATION SHEET USED	
25. Rework/Retest Action Taken FET replaced per supplement 5 and tested good per 16306		26. CA REASON REPAIR			
27. LIST ALL PARTS REPLACED		CKT SYM	PART LOT NUMBER	DATE CODE	MANUFACTURER
52597					
28. PROBABLE DEFECT		ANALYSIS NO.			
29. Rework By		ORG	DATE	30. Retested By	ORG
31. Cause and Corrective Action FET on ch 1, Halfband 51015-1 SN 102 was removed from Band level Org Band 1 SN 101 due to excess stress in quartz substitution. The FET on ch 1 was damaged in the process and was replaced. The Band level Org has been redesigned to use different quartz tubing and adhesives so that stress in quartz substitution will be acceptable.		32. FRG CLOSURE <i>[Signature]</i>			
33. DOCUMENT IMPLEMENTING CORRECTIVE ACTION		34. CONTINUATION SHEET USED			
35. BASIC CAUSE OF VERIFIED FAILURE <input checked="" type="checkbox"/> ENVIRONMENTAL <input type="checkbox"/> DEFECTIVE PARTS		36. TEST EQUIPMENT <input type="checkbox"/> TEST PROCEDURE <input type="checkbox"/> TEST SET-UP		37. MFG. PROCEDURE <input type="checkbox"/> ASSY/FAB ERROR <input checked="" type="checkbox"/> WORKMANSHIP	
38. FAILURE TYPE <input type="checkbox"/> PRIMARY <input checked="" type="checkbox"/> INDUCED		39. UNKNOWN <input type="checkbox"/> NO FAILURE		40. WIRING ERROR <input type="checkbox"/> ROUGH HANDLING <input type="checkbox"/> WEAR-OUT	
41. RESPONSIBLE ENGINEER <i>[Signature]</i>		42. DATE 12/11/80		43. SPACECRAFT SYSTEM ENGINEER <i>[Signature]</i>	
44. RELIABILITY <i>[Signature]</i>		45. ORG 51-4		46. DATE 12-11-80	
47. CUSTOMER OR SUPPLIER		48. DATE			

HUGHES

HUGHES AIRCRAFT COMPANY
SPACE AND COMMUNICATIONS GROUP
EL SEGUNDO, CALIFORNIA

PRE-AMP - MAIN AHR, OP. # 2600
POST-AMP - MAIN AHR, OP. # 1300

SPACE AND COMMUNICATIONS GROUP

FAILURE REPORT

ORIGINAL PAGE IS
OF POOR QUALITY

S 8201

ORIGINATOR	1. PROGRAM NAME AND NUMBER V411 TM		2. GLA		3. MODEL FLIGHT		4. TIME OBSERVED FIRST SHIFT		5. DATE OBSERVED MO 11 DA 03 YR 81	
	6. HARDWARE LEVEL WHEN FAILURE WAS OBSERVED <input type="checkbox"/> SPACECRAFT <input type="checkbox"/> SYSTEM		<input type="checkbox"/> SUBSYSTEM <input type="checkbox"/> UNIT		<input checked="" type="checkbox"/> ASSEMBLY <input type="checkbox"/> SUBASSEMBLY		<input type="checkbox"/> MODULE <input type="checkbox"/> MICAM		<input type="checkbox"/> CARD <input type="checkbox"/> PART	
	EQUIPMENT IDENTIFICATION:									
	7. SUBSYSTEM		NAME		PART NUMBER		S/N		MANUFACTURER	
ENGINEERING EVALUATION	8. UNIT									
	9. <input checked="" type="checkbox"/> ASSEMBLY <input type="checkbox"/> SUBASSEMBLY		PRE-AMP BAND 1		50797		401		SBRG	
	10. <input type="checkbox"/> MODULE <input type="checkbox"/> MICAM <input type="checkbox"/> CARD									
	11. OTHER									
ENGINEERING EVALUATION	12. TEST WHEN FAILURE WAS OBSERVED <input type="checkbox"/> DEVELOPMENT <input type="checkbox"/> IN-PROCESS		<input type="checkbox"/> QUALIFICATION <input checked="" type="checkbox"/> ACCEPTANCE		<input type="checkbox"/> INTEGRATION <input type="checkbox"/> SYSTEM		<input type="checkbox"/> LAUNCH OPERATIONS			
	13. ENVIRONMENT WHEN FAILURE WAS OBSERVED <input type="checkbox"/> AMBIENT <input type="checkbox"/> EMC/RFI		<input type="checkbox"/> RADIATION <input type="checkbox"/> VIBRATION		<input checked="" type="checkbox"/> TEMP 15 °K AXIS FOR _____ MIN TYPE _____		<input type="checkbox"/> THERMAL VAC		HRS AT _____ <input type="checkbox"/> OTHER	
	14. DESCRIPTION OF FAILURE CHS 2, 4, 6, 8 10, 12, 14, 16 NEAREST NEIGHBORS > -40dB, NON-NEIGHBORS AVERAGE > -60dB. SEE DATA SHEET									
	15. TEST PROCEDURE 16597		PARA 4.8		16. ORIGINATOR C. R. Lane		ORG 2213		DATE 11-03-81	
ENGINEERING EVALUATION	18. VERIFICATION AND FAILURE ANALYSIS Diagnostic testing revealed that ground plane on bron channel halfband 1 was not connected to signal return. No action of any component.									
	19. FOLLOWING REWORK/RETEST REQUIRED <input checked="" type="checkbox"/> REWORK/RETEST NOT REQUIRED BECAUSE Repair per MCO 277772									
	20. AUTHORIZED BY [Signature]									
	21. REWORK/RETEST ACTION TAKEN Repair per MCO 277772									
MANUFACTURING AND TEST	22. LIST ALL PARTS REPLACED									
	PART NUMBER	CKT SYM	PART LOT NUMBER	DATE CODE	MANUFACTURER	PROBABLE DEFECT	ANALYSIS NUMBER			
	27. REWORK BY		ORG	DATE	28. RETESTED BY		ORG	DATE	29. CONTINUATION SHEET USED <input type="checkbox"/>	
	30. CAUSE AND CORRECTIVE ACTION Cause is unknown. Work to determine if a mechanical wiring test can be done at halfband level is underway.									
ENGINEERING/RELIABILITY	31. CRISTAL FOR CHANNEL 2 ACCEPTABLE PER W123 (COPY ATTACHED)									
	32. DOCUMENT IMPLEMENTING CORRECTIVE ACTION W123 (COPY ATTACHED)									
	33. BASIC CAUSE OF VERIFIED FAILURE <input type="checkbox"/> DESIGN <input type="checkbox"/> ENVIRONMENTAL <input type="checkbox"/> DEFECTIVE PARTS		<input type="checkbox"/> TEST EQUIPMENT <input type="checkbox"/> TEST PROCEDURE <input type="checkbox"/> TEST SET-UP		<input type="checkbox"/> MFG. PROCEDURE <input type="checkbox"/> ASSY/FAB ERROR <input type="checkbox"/> WORKMANSHIP		<input type="checkbox"/> WIRING ERROR <input type="checkbox"/> ROUGH HANDLING <input type="checkbox"/> WEAR-OUT		<input checked="" type="checkbox"/> UNKNOWN DEFECT CODE	
	34. FAILURE TYPE <input type="checkbox"/> PRIMARY <input checked="" type="checkbox"/> INDUCED		<input type="checkbox"/> UNKNOWN <input type="checkbox"/> NO FAILURE		35. FAILURE CLASSIFICATION <input type="checkbox"/> CRITICAL <input checked="" type="checkbox"/> MAJOR		<input type="checkbox"/> MINOR <input type="checkbox"/> SAFETY			
37. REPORTING ENGINEER [Signature]		ORG 2122	DATE 11/20/81	38. SPACECRAFT SYSTEM ENGINEER [Signature]		ORG 22-41	DATE 12/10/81			
39. RELIABILITY 0: Ground		ORG 51-41	DATE 12-18-81	40. CUSTOMER OR SUPPLIER [Signature]						

Program Instruction 010

ORIGINAL PAGE IS
OF POOR QUALITY 201

REQUEST FOR DEVIATION/WAIVER
(SEE MIL-STD-883 OR 883 FOR INSTRUCTIONS)

DATE PREPARED

PROCURING ACTIVITY NO.

1. ORIGINATOR NAME AND ADDRESS David M. Randall SBRC, 75 Coromar Dr., Goleta, Ca. 93117				2. <input type="checkbox"/> DEVIATION <input checked="" type="checkbox"/> WAIVER	
				3. <input type="checkbox"/> MINOR <input checked="" type="checkbox"/> MAJOR <input type="checkbox"/> CRIT	
4. DESIGNATION FOR DEVIATION/WAIVER				5. BASE LINE AFFECTED	
6. MODEL/TYPE F	7. WFR. CODE 11323	8. SYS. DESIG. TM	9. DERIVATIVE NO. W-123	<input checked="" type="checkbox"/> FUNCTIONAL	<input type="checkbox"/> ALLOCATED
				<input type="checkbox"/> PRODUCE	<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO
10. SPECIFICATIONS AFFECTED-TEST PLAN				11. DRAWINGS AFFECTED	
WFR. CODE SPEC. DOC. NO. SCH				WFR. CODE	NUMBER
				11323	50797
12. SYSTEM				REV.	NO. NO.
				E	
13. TEST PLAN					
14. TITLE OF DEVIATION/WAIVER Permission to use Band 1 Band Level Assy SN 401				15. CONTRACT NO. & LINE NAS 5-24200	
16. CONFIGURATION ITEM NO./MODULE				17. CLASSIFICATION OF DEFECT	
Radiometer				18. CD NO. II	19. DEFECT CLASSIFICATION <input checked="" type="checkbox"/> MINOR <input type="checkbox"/> MAJOR <input type="checkbox"/> CRIT
20. NAME OF PART OR LARGEST ASSEMBLY AFFECTED Band 1 Band Level Assy		21. PART NO. OR TYPE DESIGN 50797-E		22. LOT NO. 401	23. QTY 1
24. EFFECT ON COST/PRICE Greater than \$100.00-if not approved.		25. EFFECT ON DELIVERY SCHEDULE Six weeks		26. RECURRING DEVIATION/WAIVER <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO	
27. EFFECT ON INTEGRATED LOGISTIC SUPPORT, INTERPACK, ETC. None					
28. DESCRIPTION OF DEVIATION/WAIVER					

Band 1 has a number of channels with transient/frequency response discrepancies as defined by FR 8440. Attached is a copy of FR 8440 and transient response plots for all channels. Channel two has average crosstalk between non-neighbors of -59dB vs a specification of ≤ -60 dB.

29. NEED FOR DEVIATION/WAIVER

Band 1 has been bonded into the FPA assy and discrepancies are not considered sig enough to warrant rework on a cost/schedule impact basis.

30. REA <i>DM Randall</i> 11/20/81		SYS ENGR <i>LH Chao</i>		QA <i>TH Miller</i>	
31. PRODUCTION EFFECTIVITY BY SERIAL NUMBER 003 51065 SERNO 003 ONLY		PE <i>David H. Hines</i>		CMO <i>Eric</i> 38	
32. <i>FX-Rhitey</i> 11/23/81		Minor - System		Major/Critical - Program Manager	
33. APPROVAL		<input checked="" type="checkbox"/> APPROVED		<input type="checkbox"/> DISAPPROVED	
34. DATE		12-17-8		<i>Paul R. Kurnett</i>	
DL #1694					

HUGHES

HUGHES AIRCRAFT COMPANY
SPACE AND COMMUNICATIONS GROUP
EL SEGUNDO, CALIFORNIA

SPACE AND COMMUNICATIONS GROUP

FAILURE REPORT

ORIGINAL PAGE IS
OF POOR QUALITY

S 8227

1. PROGRAM NAME AND NUMBER TM 1011 PL 1162		2. QLA		3. MODEL FLIGHT		4. TIME OBSERVED DAY SHIFT		5. DATE OBSERVED MO 8 DA 25 YR 81	
6. HARDWARE LEVEL WHEN FAILURE WAS OBSERVED <input type="checkbox"/> SPACECRAFT <input type="checkbox"/> SYSTEM		<input type="checkbox"/> SUBSYSTEM <input type="checkbox"/> UNIT		<input type="checkbox"/> ASSEMBLY <input type="checkbox"/> SUBASSEMBLY		<input type="checkbox"/> MODULE <input type="checkbox"/> MICAM		<input type="checkbox"/> CARD <input type="checkbox"/> PART	
EQUIPMENT IDENTIFICATION: NAME PART NUMBER S/N MANUFACTURER									
7. SUBSYSTEM									
8. UNIT									
9. <input checked="" type="checkbox"/> ASSEMBLY <input type="checkbox"/> SUBASSEMBLY PANEL 3 RST AMP SD904-3 201 SPP									
10. <input type="checkbox"/> MODULE <input type="checkbox"/> MICAM <input type="checkbox"/> CARD									
11. OTHER									
12. TEST WHEN FAILURE WAS OBSERVED <input type="checkbox"/> DEVELOPMENT <input checked="" type="checkbox"/> IN-PROCESS <input type="checkbox"/> QUALIFICATION <input type="checkbox"/> ACCEPTANCE <input type="checkbox"/> INTEGRATION <input type="checkbox"/> SYSTEM <input type="checkbox"/> LAUNCH OPERATIONS									
13. ENVIRONMENT WHEN FAILURE WAS OBSERVED <input type="checkbox"/> AMBIENT <input type="checkbox"/> RADIATION <input checked="" type="checkbox"/> TEMP 15.0 <input type="checkbox"/> THERMAL VAC <input type="checkbox"/> HRS AT <input type="checkbox"/> VIBRATION <input type="checkbox"/> MIN TYPE <input type="checkbox"/> OTHER									
14. DESCRIPTION OF FAILURE CHANNEL 4 FAILED TO MEET THE PRE-GAIN RESISTOR (R90) SELECTION REQUIREMENTS WITHOUT USING A COMPONENT OUTSIDE THE SELECT RANGE. LIMITS 2.61K TO 5.90K. VALUE 2.49.									
15. TEST PROCEDURE 16597		16. PART 4.5		17. ORIGINATOR N.C. JAVISON		18. ORG 2213		19. DATE 8-25-81	
20. VERIFICATION AND FAILURE ANALYSIS CONDITION VERIFIED AT TEST/SELECT STEP. NO PARTS OVERSTRESSED BY THE USE OF THIS RESISTOR VALUE.									
21. <input type="checkbox"/> FOLLOWING REWORK/RETEST REQUIRED <input checked="" type="checkbox"/> REWORK/RETEST NOT REQUIRED BECAUSE AN OUT-OF-RANGE VALUE IS ADVISORILY REQUIRED TO MEET GAIN SPECIFICATIONS.									
22. REWORK/RETEST ACTION TAKEN NONE									
23. LIST ALL PARTS REPLACED PART NUMBER CKT SYM PART LOT NUMBER DATE CODE MANUFACTURER PROBABLE DEFECT ANALYSIS NUMBER									
N/A									
27. REWORK BY N/A ORG DATE 28. RETESTED BY N/A ORG DATE									
29. CAUSE AND CORRECTIVE ACTION RANGE SPECIFIED IN 16597 NOT BROAD ENOUGH TO PERMIT ADJUSTMENT. P.O. TO SPEC IS REQUIRED TO INCREASE SELECT RANGE RANGE WAS: 2.61K TO 5.90K CHANGE TO: 2.21K TO 12.7K									
30. DOCUMENT IMPLEMENTING CORRECTIVE ACTION P.O. 3442 A-EFFECTIVITY 54003 sup									
31. BASIC CAUSE OF VERIFIED FAILURE <input type="checkbox"/> DESIGN <input type="checkbox"/> ENVIRONMENTAL <input type="checkbox"/> DEFECTIVE PARTS <input type="checkbox"/> TEST EQUIPMENT <input type="checkbox"/> TEST PROCEDURE <input type="checkbox"/> TEST SET-UP <input type="checkbox"/> MFG. PROCEDURE <input type="checkbox"/> ASSY/FAB ERROR <input type="checkbox"/> WORKMANSHIP <input type="checkbox"/> WIRING ERROR <input type="checkbox"/> ROUGH HANDLING <input type="checkbox"/> WEAR-OUT									
32. FAILURE TYPE <input type="checkbox"/> PRIMARY <input type="checkbox"/> INDUCED <input type="checkbox"/> UNKNOWN <input checked="" type="checkbox"/> NO FAILURE									
33. FAILURE CLASSIFICATION <input type="checkbox"/> CRITICAL <input type="checkbox"/> MAJOR <input checked="" type="checkbox"/> MINOR <input type="checkbox"/> SAFETY									
34. TEST/RETEST ENGINEER 10/26/81 2213 8/26/81 2213 8/10/81									
35. CUSTOMER OR SUPPLIER									

HUGHESHUGHES AIRCRAFT COMPANY
SPACE AND COMMUNICATIONS GROUP
EL SEGUNDO, CALIFORNIA

SPACE AND COMMUNICATIONS GROUP

FAILURE REPORT

MAIN ALR OFN# 2300

ORIGINAL PAGE 1
OF FOUR QUALIT**S 8229**

1. PROGRAM NAME AND NUMBER VOII T.M.		2. GLA	3. MODEL FLIGHT	4. TIME OBSERVED N/A	5. DATE OBSERVED MO 12 DA 01 YR 8
6. HARDWARE LEVEL WHEN FAILURE WAS OBSERVED <input type="checkbox"/> SPACECRAFT <input type="checkbox"/> SUBSYSTEM <input type="checkbox"/> ASSEMBLY <input type="checkbox"/> MODULE <input type="checkbox"/> CARD <input type="checkbox"/> SYSTEM <input checked="" type="checkbox"/> SUBASSEMBLY <input type="checkbox"/> MICAM <input type="checkbox"/> PART					
EQUIPMENT IDENTIFICATION:					
7. SUBSYSTEM		NAME		PART NUMBER	S/N
8. UNIT					
9. <input type="checkbox"/> ASSEMBLY <input checked="" type="checkbox"/> SUBASSEMBLY (1/2 BAND)		51015		212-1	3BRC
10. <input type="checkbox"/> MODULE <input type="checkbox"/> MICAM <input type="checkbox"/> CARD					
11. OTHER					
12. TEST WHEN FAILURE WAS OBSERVED <input type="checkbox"/> DEVELOPMENT <input checked="" type="checkbox"/> IN-PROCESS <input type="checkbox"/> QUALIFICATION <input type="checkbox"/> ACCEPTANCE <input type="checkbox"/> INTEGRATION <input type="checkbox"/> SYSTEM <input type="checkbox"/> LAUNCH OPERATIONS					
13. ENVIRONMENT WHEN FAILURE WAS OBSERVED <input checked="" type="checkbox"/> AMBIENT <input type="checkbox"/> EMC/RFI <input type="checkbox"/> RADIATION <input type="checkbox"/> VIBRATION <input type="checkbox"/> TEMP <input type="checkbox"/> THERMAL VAC <input type="checkbox"/> HRS AT <input type="checkbox"/> OTHER					
14. DESCRIPTION OF FAILURE CHANNELS 1 & 2 EXHIBIT EXCESSIVE NOISE AFTER REPEATED CHANGES OF FETS.					
15. TEST PROCEDURE 16306		16. PARA 4.7	17. ORIGINATOR A.C. DAVISON	18. ORG 7213	19. DATE 12-01-81
20. VERIFICATION AND FAILURE ANALYSIS Hybrid put on NCAR 392547 and sent to reliability for failure analysis. See IDC 12-60-01/82-037 (ATTACHED)					
21. FAILED ITEM NAME AND PART NUMBER 50860 SN 215					
22. <input checked="" type="checkbox"/> FOLLOWING REWORK/RETEST REQUIRED <input type="checkbox"/> Rework/Retest Not Required Because Replace Hybrid for ch. 1 & 2 (U-1)					
23. AUTHORIZATION [Signature]					
24. CONTINUATION SHEET USED <input type="checkbox"/>					
25. REWORK/RETEST ACTION TAKEN Hybrid replaced and unit held good for support of 1.					
26. CONTINUATION SHEET USED <input type="checkbox"/>					
27. LIST ALL PARTS REPLACED					
PART NUMBER	CRT SYM	PART LOT NUMBER	DATE CODE	MANUFACTURER	PROBABLE DEFECT
50860			SN 215		
28. CONTINUATION SHEET USED <input type="checkbox"/>					
29. REWORK BY [Signature]					
30. DATE 1-11-82					
31. TESTED BY [Signature]					
32. DATE 2-13-82					
33. CONTINUATION SHEET USED <input type="checkbox"/>					
34. CAUSE AND CORRECTIVE ACTION FAILURE ANALYSIS CONCLUDES THAT THIS WAS A RANDOM FAILURE. NO CORRECTIVE ACTION IS DEEMED APPROPRIATE (REFERENCE IDC 12-60-01/82-037, COPY ATTACHED) (REFERENCE IDC 12-60-01/82-042 COPY ATTACHED)					
35. F10 CLOSURE					
36. CONTINUATION SHEET USED <input type="checkbox"/>					
37. DOCUMENT IMPLEMENTING CORRECTIVE ACTION IDC 12-60-01/82-037, COPY ATTACHED					
38. BASIC CAUSE OF VERIFIED FAILURE <input type="checkbox"/> DESIGN <input type="checkbox"/> ENVIRONMENTAL <input type="checkbox"/> DEFECTIVE PARTS <input type="checkbox"/> TEST/EQUIPMENT <input type="checkbox"/> TEST PROCEDURE <input type="checkbox"/> TEST SET-UP <input type="checkbox"/> MFG. PROCEDURE <input type="checkbox"/> ASSY/FAB ERROR <input type="checkbox"/> WORKMANSHIP <input type="checkbox"/> WIRING ERROR <input type="checkbox"/> ROUGH HANDLING <input type="checkbox"/> WEAR-OUT <input type="checkbox"/> UNKNOWN					
39. FAILURE TYPE <input checked="" type="checkbox"/> PRIMARY <input type="checkbox"/> INDUCED <input type="checkbox"/> UNKNOWN <input type="checkbox"/> NO FAILURE <input type="checkbox"/> CRITICAL <input type="checkbox"/> MAJOR <input type="checkbox"/> MINOR <input type="checkbox"/> SAFETY					
40. RESPONSIBLE ENGINEER [Signature]					
41. DATE 1/6/82					
42. SPACECRAFT SYSTEM ENGINEER [Signature]					
43. DATE 2/6/82					
44. REPAIRABILITY [Signature]					
45. DATE 7-6-82					
46. CUSTOMER OR SUPPLIER [Signature]					
47. DATE 7-6-82					

ORIGINAL PAGE IS
OF POOR QUALITY

58229

HUGHES AIRCRAFT COMPANY

INTERDEPARTMENTAL CORRESPONDENCE



TO: L. Holthausen
FROM: SARC

CC: J. Adams
L. O'Connell

DATE: 14 July 1982
REF: 12-60-01/82-042

SUBJECT: Rationale for
Failure Classification

FROM: J. Hazenko
SLCC: 604
EXT: 21218

MAIL JTA: 8253
ORG. CODE: 12-60-0

Silicon Preamplifier P/N 1950594/50860 serial number 215 was failure analyzed on 30 June 1982 (ref. IDC 12-60-01/82-037). The hybrid was found to be noisy on channel B. It was determined that transistor Q3 (2N4405) was defective. The failure was classified as random since no previous failures of this type had been seen. Below is a list of "Flight" Silicon Preamplifiers previously returned for retest and the disposition of some.

SILICON PREAMPLIFIER PART NUMBER 1950594/50860

<u>PART NUMBER</u>	<u>APPROXIMATE RETEST DATE</u>	<u>DISPOSITION</u>
116	10 NOVEMBER 1980	RETESTED. MEETS SPECIFICATION.
154	10 NOVEMBER 1980	OPEN PIN 10-13. MISSING WIRE BOND.
169	3 AUGUST 1981	RETESTED. MEETS SPECIFICATION.
193	11 MARCH 1982	OPEN PIN 10-13. WIRE BOND PIN 10-1 FUSED OPEN.
97	30 JUNE 1982	RETESTED. MEETS SPECIFICATION.
202	30 JUNE 1982	RETESTED. MEETS SPECIFICATION.
81	30 JUNE 1982	RETESTED. MEETS SPECIFICATION.
206	30 JUNE 1982	RETESTED. MEETS SPECIFICATION.
165	30 JUNE 1982	RETESTED. MEETS SPECIFICATION.
169	30 JUNE 1982	CHANNEL B OPEN.

(Note that serial #'s 165 and 169 were submitted twice for retest)

As seen from the data above, none of the Silicon Preamplifiers exhibited failures related to the 2N4405 transistor; thus, as previously stated it is assumed that the failure mode for Silicon Preamplifier serial # 215 may be classified as random.

JH/dlc

ORIGINAL PAGE IS
OF POOR QUALITY

58229

HUGHES AIRCRAFT COMPANY

INTERDEPARTMENTAL CORRESPONDENCE



TO: L. Holthausen
FROM: SBRC

CC: D. Adams
L. O'Connor

DATE: 14 July 1982
REF: 12-60-01/82-042

SUBJECT: Rationale for
Failure Classification

FROM: J. Hazenko

GLD: 604

EXT: 21218

MAIL STA.: 8253

ORG. CODE: 12-60

Silicon Preamplifier P/N 1950594/50860 serial number 215 was failure analyzed on 30 June 1982 (ref. IDC 12-60-01/82-037). The hybrid was found to be noisy on channel B. It was determined that transistor Q3 (2N4405) was defective. The failure was classified as random since no previous failures of this type had been seen. Below is a list of "Flight" Silicon Preamplifiers previously returned for retest and the disposition of same.

SILICON PREAMPLIFIER PART NUMBER 1950594/50860

<u>PART NUMBER</u>	<u>APPROXIMATE RETEST DATE</u>	<u>DISPOSITION</u>
116	10 NOVEMBER 1980	RETESTED. MEETS SPECIFICATION.
154	10 NOVEMBER 1980	OPEN PIN 10-13. MISSING WIRE BOND
169	3 AUGUST 1981	RETESTED. MEETS SPECIFICATION.
193	11 MARCH 1982	OPEN PIN 10-13. WIRE BOND PIN 10 FUSED OPEN.
97	30 JUNE 1982	RETESTED. MEETS SPECIFICATION.
202	30 JUNE 1982	RETESTED. MEETS SPECIFICATION.
81	30 JUNE 1982	RETESTED. MEETS SPECIFICATION.
206	30 JUNE 1982	RETESTED. MEETS SPECIFICATION.
166	30 JUNE 1982	RETESTED. MEETS SPECIFICATION.
169	30 JUNE 1982	CHANNEL B OPEN.

(Note that serial #'s 166 and 169 were submitted twice for retest)

As seen from the data above, none of the Silicon Preamplifiers exhibited failure related to the 2N4405 transistor; thus, as previously stated it is assumed that the failure mode for Silicon Preamplifier serial # 215 may be classified as random.

HUGHES AIRCRAFT COMPANY

ORIGINAL PAGE IS
OF POOR QUALITY

58229

INTERDEPARTMENTAL CORRESPONDENCE



TO: L. Woltheusen
ORG: SBRC

CC: D. Adams
L. O'Connell

DATE: 30 June 1982
REF: 12-60-01/82-037

SUBJECT: Failure Analysis
of Silicon
Preamplifier Hybrid

FROM: J. Mazenko
CLASS: 604
EXT: 21218
MAIL STA.: 8253
ORD. CODE: 12-60-01

SILICON PREAMPLIFIER

PART NUMBER: 1950594/50860
SERIAL NUMBER: 215
DATE CODE: 2880

The above hybrid was retested per SBRC Spec. #16099 and found to be out of spec. on Channel B for spectral noise at both 10 KHZ and 20 KHZ.


The hybrid passed fine leak, gross leak and pind test. Upon delidding the cause of failure was determined to be Q3 a 2N4405. Q3 was replaced with a dice from lot 8-7066 (the same lot as used in the original hybrid build). The hybrid was then retested and found to be within spec. The test results are shown below.

Spec limit $\leq 1.7 \text{ nV/}\sqrt{\text{HZ}}$ (Paragraph 1.6 of Spec #16099)

<u>FREQUENCY</u>	<u>DATA 7/24/80</u>	<u>DATA 6/10/82</u>	<u>Q3 REPLACED 6/29/82</u>
10 KHZ	1.3 nV	2.3 nV	1.5 nV
20 KHZ	1.4 nV	1.8 nV	1.4 nV

Since no other failures of this type have been seen this may be assumed to be a random failure.

JM:mle


J. J. Mazenko
Manager Technical Staff
Technical Support Laboratory
Engineering Services & Support Division

ORIGINAL PAGE IS
OF POOR QUALITY

58229

ASSEMBLY HISTORY RECORD SUPPLEMENT				SHEET 1 OF 3	
PART NUMBER	QUANTITY	DRAWING NO.	REVISIONS	PREPARED BY	SUPPLEMENT NO. 1 TO
51015-1	212	51015	D	J. Wells	AIR DATED 10-19-81
PURPOSE OF SUPPLEMENT - INCORPORATES NEW ASSY DRAWING REVISION 1 FOR EDS 11; REWORK 11; OTHER U.I. EXPLAIN:			SUPPLEMENT RELEASE DATE 12-17-81 DATE TO PRODUCTION - UPON RECEIPT, ENTER SUPPLEMENT NO. AND RECEIPT DATE ON FRONT SHEET OF AIR - INITIAL THE ENTRY.		
QUALITY APPROVAL J. Wells SPECIAL INSPECTION AFQA			QUALITY APPROVAL J. Wells SPECIAL INSPECTION AFQA		
NOTES: SAME AS ORIGINAL AIR <div style="border: 1px solid black; padding: 5px; display: inline-block;"> STATIC SENSITIVE ITEM HANDLE PER 389913 </div>					
OPER NO.	S/C NO.	INSTRUCTIONS	PERFORMED BY		REMARKS
			OPER	INSP	
		PURPOSE:			
2301	21-21	Kit (1 ea.) Hybrid (Item 6) per B/P & ABC/TR.			
2302	51-14	Kit Inspect Operation #2301 per B/P & ABC/TR. f			
2303	22-73	1) Remove Hybrid U1 (Item 6) from preamp assy. (Bag and identify removed part.) Submit to inspection.			

58229

ASSEMBLY HISTORY RECORD CONTINUATION SHEET						SHEET 2 OF 3
PART NUMBER	SERIAL OR LOT NUMBER	ASSEMBLY NAME	CONTINUATION OF: AIR DATED 10-19-81 AHR SUPPLEMENT NO. 1			
51015-1	212	SILICON PRE-AMP ASSY				
OPER NO.	S/C NO.	INSTRUCTIONS	PERFORMED BY OPER INSP	DATE	REMARKS	
2303	22-73	Continued				
		3) Install Hybrid (Item 6) at U1 to preamp assy per B/P and Note 3. NOTE: Observe correct pin location. (Ref. zone 5D)	JRC	1-11		
				1-12-82		
2304	51-14	Inspect operation #2303 per B/P. Put removed Hybrid on R.C.M.R. Record W.C.M.R. # 342549.	[H] [INS]	1-10-82		
2305	MCI	HANDATORY CUSTOMER INSPECTION STATIC SENSITIVE ITEM HANDLE PER EPC0113	[CNS] [GWS]	1/13/82		
2306	22-13	1) Notify Q.A. & A.F. before testing. NOTIFIED AF Dept 1/14/82 CALLED ALL TEST EQUIPMENT TO AIRMAN PRIOR TO TESTING	[H] [INS]	1/14/82	REF FR 8206 M COMMENT 510614	
		* NOTE: Attach test data to AHR.		1/14/82	SEE REF TEST ON COMMENT 54182	
2307	51-14	* NOTE: Spot bonding of Hybrid will be performed on airin				

58229

4.7 Wideband noise

ORIGINAL PAGE IS
OF POOR QUALITY


Limit: 2.4 PA

Ch	Meter	Gain*	Pre-Amp Output	N.B. Noise	REF
1.	.84 V	350	2.40 mV	2.1 PA	1.15 x 10 ⁹
2.	.84		2.40	2.2	1.10
3.	.69		1.97	2.3	.85
4.	.72		2.06	2.3	.90
5.	.76		2.17	2.1	1.05
6.	.76		2.17	2.2	.97
7.	.66		1.89	1.9	1.00
8.	.70		2.00	2.1	.96

Gain is based on Gain Factor (in dB) - Based on Noise Floor
- Noise Gain (in dB) For The 2.4 PA Noise
Converted from dB to Gain

$$\log \left\{ \left[\frac{3.81}{2.87} \cdot (26.91) + 27.79 \right] \right\} = 350$$

Design Engineer William C. Smith III Date: FEB. 27, 1982
TEST Engineer C. R. Lane Date: 2-22-82



SIZE A	CODE IDENT NO. 11323	NUMBER 16306
SCALE	REV	SHEET 12

ORIGINAL PAGE IS
OF POOR QUALITY

58229

MODEL EFFECTIVITY	REVISIONS			
	SYM	DESCRIPTION	DATE	APPROVED
		INITIALLY RELEASED 9-5-78		
FIRST USE	D	Completely revised and retyped to incorporate new system specs & update test procedures. As required by ECR TM1103/01.	12-6-79	
ER. No. 2 & SUBQ.	E	Incorporated EO 1610	80-8-29	
51065 SER. No 002 & Subq.	F	Paragraph 4.6 added: Transient response---- gold wires are not damaged. as req by ECR TM 1913/01.	80-09-12	
1065 NCC3 SUBQ.	G	Incorporated E. O. 2149A	12-2-80	
025 SN E & SEQ	H	INCORPORATED EO 2960A.	81-4-20	
065 S/N & SUBQ	J	Changed by Revision Notice per ECR No. TM 2339/01	81-5-22	

MAIN AHR
OP. No. 2300
AFTER TRYING
3 (THREE) DIFFERENT
FET'S ON CH. 1,2
NO CHANGE IN EXCESSIVE
NOISE.

RECOMMEND INSTALL
NEW HYBRID PREAMP.

CR. Lane 12-01-81

REF SUP-1 FOR DEPARTMENT OF HYBRID
REF. FILE 8229
REVISION STATUS THIS PRINT
NOT MAINTAINED AFTER
NOV 23 1981
DO NOT USE THIS PRINT
UNLESS YOUR ORDER OR INSTRUCTIONS
SPECIFY THE REVISION LEVEL SHOWN

EO
2364A

William C. Clanton III 12-1-81

CONTRACT NO. NAS 5-24200		SANTA BARBARA RESEARCH CENTER A Subsidiary of Hughes Aircraft Company GOLETA, CALIFORNIA	
PROPOSED CHECKED APPROVED APPROVED	11-1-71 11-1-74 11/8/79	TITLE TEST PROCEDURE FOCAL PLANE PREAMP ASSEMBLY	
SIZE A	CODE IDENT NO. 11323	NUMBER 16306	

58229

4.7 Wideband noise

ORIGINAL PAGE IS
OF POOR QUALITY

Limit: 2.4 pA

Ch	Meter	Gain*	Pre-Amp Output	N.B. Noise	<u>Res</u>
1.	<u>** V</u>	<u> </u>	<u> </u> mV	<u> </u> pA	<u>1.15 X 10⁹</u>
2.	<u>**</u>	<u> </u>	<u> </u>	<u> </u>	<u>1.10</u>
3.	<u>.66</u>	<u>343</u>	<u>1.92</u>	<u>2.3 pA</u>	<u>CH 3, 4, 85</u>
4.	<u>* .68</u>	<u>343</u>	<u>1.98</u>	<u>2.2 pA</u>	<u>.90</u> <u>1.05 CH</u>
5.	<u>.77</u>	<u>343</u>	<u>2.24</u>	<u>2.1</u>	<u>1.07 CH</u>
6.	<u>NO</u>	<u>RESPONSE</u>	<u> </u>	<u> </u>	<u>.97</u>
7.	<u>NO</u>	<u>RESPONSE</u>	<u> </u>	<u> </u>	<u>1.00</u>
8.	<u>.73</u>	<u>343</u>	<u>2.13</u>	<u>2.2 pA</u>	<u>98.96</u> <u>CH</u>

$$10^{\frac{1}{2}} \left[\frac{7.26}{\sqrt{2}} - \frac{(-15.88)}{\sqrt{2}} + \frac{27.55}{\sqrt{2}} \right] = 343$$

Design Engineer _____ Date: _____
 Tech. Engineer C. R. Lane Date: 11-25-81
 J.E. Engineer CH 4 IS 2.2 pA W.B.N WITH WIRE PULLED
1212 CH 1, 2 V. NOISEY - NO WRITTEN DATA - CH 6, 7 Date: 12/02/81
NO RESPONSE

- * CH. 4 DATA WITH DETECTOR WIRE PULLED - NEED NEW DETECTOR
- ** CH. 1-2 VERY NOISY - NEED NEW FET'S
- CH. 6-7 TRY NEW DETECTORS

SIZE A	CODE IDENT NO. 11323	NUMBER 16806
SCALE	REV	SHEET 12

4.7 Wideband noise

ORIGINAL PAGE IS
OF POOR QUALITY

58229

Ch	Meter	Gain*	Pre-Amp Output		R.F.B.
1.	1.35V		3.94 mV	3.4 pA	1.15 X 10 ⁹ Ω
2.	2.40V NOISEY (VERY)				1.10
3.					.85
4.	NO RESPONSE				.90
5.					1.05
6.	PEGGED				.92
7.	.70	343	2.04	2.0	1.00
3.					.96

* Gain = Test Amp-Out Put (in dB) - Post Amp Input (in dB)
- Scope Gain (in dB) For The 100V/div Scale
Converted From dB to Gain

$$\log \left\{ \left[\frac{7.26}{(-15.88)} + 27.55 \right] \right\} = 343$$

Design Engineer

Date:

TEST

Engineer C. R. Lane

Date: 12-01-81

Q.A. Engineer

P. G. Ryan

Date: 12/02/91

CH. 1,2 NEW FET

CH 4,6 NEW DETECTOR

INITIAL TEST AFTER REWORK ON
CH. 1,2,4,6,7

SIZE A	CCDC IDENT NO 11323	NUMBER 18405
SCALE	REV	SHEET 12

HUGHES

HUGHES AIRCRAFT COMPANY
SPACE AND COMMUNICATIONS GROUP
EL SEGUNDO, CALIFORNIA

MAIN AMR - CP#2600

ORIGINAL PAGE IS
OF POOR QUALITY

SPACE AND COMMUNICATIONS GROUP

FAILURE REPORT

S 831

ORIGINATOR	1. PROGRAM NAME AND NUMBER TM 1011		2. GLA		3. MODEL FLIGHT		4. TIME OBSERVED 3:30 AM		5. DATE OBSERVED MO 8 DA 26 YR 8	
	6. HARDWARE LEVEL WHEN FAILURE WAS OBSERVED <input type="checkbox"/> SPACECRAFT <input type="checkbox"/> SUBSYSTEM <input type="checkbox"/> ASSEMBLY <input type="checkbox"/> MODULE <input type="checkbox"/> CARD		<input type="checkbox"/> SYSTEM <input type="checkbox"/> UNIT <input checked="" type="checkbox"/> SUBASSEMBLY <input type="checkbox"/> MICAM <input type="checkbox"/> PART							
	EQUIPMENT IDENTIFICATION:									
	7. SUBSYSTEM		NAME		PART NUMBER		S/N		MANUFACTURER	
	8. UNIT				50904-3		201			
	9. <input type="checkbox"/> ASSEMBLY <input checked="" type="checkbox"/> SUBASSEMBLY BOARD #3				50797		201		SERC	
	10. <input type="checkbox"/> MODULE <input type="checkbox"/> MICAM <input type="checkbox"/> CARD									
	11. OTHER									
	12. TEST WHEN FAILURE WAS OBSERVED <input type="checkbox"/> DEVELOPMENT <input type="checkbox"/> QUALIFICATION <input type="checkbox"/> INTEGRATION <input type="checkbox"/> LAUNCH OPERATIONS		<input type="checkbox"/> V4-PROCESS <input checked="" type="checkbox"/> ACCEPTANCE <input type="checkbox"/> SYSTEM							
	13. ENVIRONMENT WHEN FAILURE WAS OBSERVED <input type="checkbox"/> AMBIENT <input type="checkbox"/> RADIATION <input checked="" type="checkbox"/> TEMP 15.0 <input type="checkbox"/> THERMAL VAC <input type="checkbox"/> HRS AT <input type="checkbox"/> OTHER		<input type="checkbox"/> EMC/RFI <input type="checkbox"/> VIBRATION <input type="checkbox"/> AXIS FOR <input type="checkbox"/> MIN TYPE							
14. DESCRIPTION OF FAILURE CHANNEL 4 NOISE IS 2.6 PA; CHANNEL 9 NOISE IS 2.9 PA. SPECIFICATION 16597 REQUIREMENT IS 2.4 PA OR LESS. NO CONTINUATION SHEET USED										
15. TEST PROCEDURE 16597 PARA 47 ORIGINATOR H.C. DAVISON II ORG 2215 DATE 8-28-81 CONTINUATION SHEET USED										
ENGINEERING EVALUATION	16. VERIFICATION AND FAILURE ANALYSIS									
	17. FAILED ITEM NAME AND PART NUMBER									
	18. <input type="checkbox"/> FOLLOWING REWORK/RETEST REQUIRED <input checked="" type="checkbox"/> REWORK/RETEST NOT REQUIRED BECAUSE FR to be closed via waiver W-116									
	21. AUTHORIZED BY [Signature] ORG 2122 DATE 11/9/81									
	22. REWORK/RETEST ACTION TAKEN									
	23. LIST ALL PARTS REPLACED									
	24. CONTINUATION SHEET USED									
	25. CONTINUATION SHEET USED									
	26. CONTINUATION SHEET USED									
	27. REWORK BY ORG DATE 28. RETESTED BY ORG DATE 29. CONTINUATION SHEET USED									
MANUFACTURING AND TEST	30. CAUSE AND CORRECTIVE ACTION The noise on channel 4 has been high since the unit was built and is a function of the noise of the TET/Detector combi. Channel 9 became noisy due to a change in the Si detector. The effect of the change is being studied and a life test is being conducted on a detector with a similar defect. The transient response settling time between units are at 30us									
	31. FRB CLOSURE									
	32. DOCUMENT IMPLEMENTING CORRECTIVE ACTION (COPY ATTACHED)									
	33. BASIC CAUSE OF VERIFIED FAILURE <input type="checkbox"/> DESIGN <input type="checkbox"/> ENVIRONMENTAL <input type="checkbox"/> DEFECTIVE PARTS									
	34. TEST EQUIPMENT <input type="checkbox"/> TEST PROCEDURE <input type="checkbox"/> TEST SET-UP									
	35. MFG. PROCEDURE <input type="checkbox"/> ASSY/FAB ERROR <input type="checkbox"/> WORKMANSHIP									
	36. WIRING ERROR <input type="checkbox"/> ROUGH HANDLING <input type="checkbox"/> WEAR-OUT									
	37. FAILURE TYPE <input type="checkbox"/> PRIMARY <input type="checkbox"/> SECONDARY <input checked="" type="checkbox"/> UNKNOWN <input type="checkbox"/> NO FAILURE									
	38. FAILURE CLASSIFICATION <input type="checkbox"/> CRITICAL <input type="checkbox"/> MINOR <input type="checkbox"/> SAFETY									
	39. SPACECRAFT SYSTEM ENGINEER [Signature] ORG 2241 DATE 12/18/81									
ENGINEERING/RELIABILITY	40. RELIABILITY [Signature] ORG 5141 DATE 12-18-81									
	41. CUSTOMER OR SUPPLIER									

HUGHES

HUGHES AIRCRAFT COMPANY

SPACE AND COMMUNICATION GROUP
EQUIPMENT CHECKOUT
FAILURE REPORT
CONTINUATION SHEET

ORIGINAL PAGE IS
OF POOR QUALITY

58317 CONT. SHEET
PR SERIAL NO. LETTER

*LABEL FIRST CONTINUATION SHEET USED 'A', SECOND 'B', AND SO ON

IDENTIFY ENTRIES BY REFERENCING PR BLOCK NUMBER IN COLUMN, DATE EACH ENTRY.

ADDITIONAL P
CONTINUATION
SHEET(S) USED

14 The following channels do not meet the settling time requirements

Limit	15%	10%	
Channel	30 μ s	60 μ s	1% by
1	2.0%	1.2%	35 μ s
2	2.0	.1	35
3	1.8	0	33
4	2.4	.2	35
6	1.8	0	35
8	2.6	.2	50
10	2.6	.4	45
12	1.8	.5	48
14	2.0	.2	35
15	2.0	.2	35
16	2.0	.4	50

30 and all are settled within 1% by ± 50 μ s. This is the best that can be expected with the present design.

ORIGINAL PAGE IS
OF POOR QUALITY

Program Instruction 010

REQUEST FOR DEVIATION/WAIVER
ISSUE - IL-STD-400 OR 401 FOR INSTRUCTIONS

DATE PREPARED

PENDING ACTIVITY NO.

11-10-81

1. ORIGINATOR NAME AND ADDRESS David M. Randall
SBRC, 75 Coromar Drive, Culeta, Ca. 93117

2. ☐ DEVIATION ☒ WAIVER
3. ☐ MINOR ☒ MAJOR ☐ CRITICAL

4. DEVIATION OR WAIVER NO. 11323
5. DATE LINE AFFECTED
6. OTHER SYSTEMS/COMPONENTS AFFECTED
7. DRAWINGS AFFECTED
8. TEST PLAN
9. TYPE OF DEVIATION/WAIVER
10. CONTRACT NO. & LINE ITEM
11. DESCRIPTION OF DEVIATION/WAIVER
12. CD NO.
13. DEFECT NO.
14. DEFECT CLASSIFICATION
15. LOT NO.
16. QTY
17. RECEIVING ORGANIZATION
18. EFFECT ON DELIVERY SCHEDULE

Permission to use Band 3 Band Level Assy SN 201
Radiometer
Band Level Assy 50797
Greater than \$100,000-if not approved.
NONE

19. EFFECT ON DELIVERY SCHEDULE
3 to 4 months if not approved

Permission to use Band 3 Band Level Assy SN 201 with Ch 4 noise of 2.6 pA and Ch 9 noise of 2.9 pA vs a spec of <2.4 pA and Channels 1, 2, 3, 4, 6, 8, 10, 12, 14, 15 & 16 not meeting transient response settling time requirement of <1.52 by 30 ms. Copy of FR 8317 attached.

24. NEED FOR DEVIATION/WAIVER

Noise performance of Ch 4 & 9 will still allow system signal to noise performance to be met and all channels have transient responses that settle to 1% by <50ms. The rework required to correct the discrepancies described above is not considered cost or schedule effective.

25. AUTHORIZATION EFFECTIVE TO SERIAL NUMBER 003

26. APPROVALS
27. DISAPPROVALS
28. APPROVED
29. DISAPPROVED

DD FORM 1694

HUGHESHUGHES AIRCRAFT COMPANY
SPACE AND COMMUNICATIONS GROUP
EL SEGUNDO, CALIFORNIA

AHR Oper 2600 PHN 50797 BAND 1

SPACE AND COMMUNICATIONS GROUP
FAILURE REPORT**S** 8318

ORIGINATOR	1. PROGRAM NAME AND NUMBER	TM VOIL PL1162		2. GLA	3. MODEL	4. TIME OBSERVED	5. DATE OBSERVED
	6. HARDWARE LEVEL WHEN FAILURE WAS OBSERVED	<input type="checkbox"/> SPACECRAFT <input type="checkbox"/> SUBSYSTEM <input type="checkbox"/> ASSEMBLY <input checked="" type="checkbox"/> SUBASSEMBLY <input type="checkbox"/> MODULE <input type="checkbox"/> MICAM <input type="checkbox"/> CARD <input type="checkbox"/> PART					
	7. SUBSYSTEM	NAME		PART NUMBER	S/N	MANUFACTURER	
	8. UNIT						
	9. <input type="checkbox"/> ASSEMBLY <input checked="" type="checkbox"/> SUBASSEMBLY	FEM BAND 1 PRE-AMP 50797		401	SBRL		
	10. <input type="checkbox"/> MODULE <input type="checkbox"/> MICAM <input type="checkbox"/> CARD						
	11. OTHER						
	12. TEST WHEN FAILURE WAS OBSERVED	<input type="checkbox"/> DEVELOPMENT <input type="checkbox"/> IN-PROCESS <input type="checkbox"/> QUALIFICATION <input checked="" type="checkbox"/> ACCEPTANCE <input type="checkbox"/> INTEGRATION <input type="checkbox"/> SYSTEM <input type="checkbox"/> LAUNCH OPERATIONS					
	13. ENVIRONMENT WHEN FAILURE WAS OBSERVED	<input type="checkbox"/> AMBIENT <input type="checkbox"/> RADIATION <input type="checkbox"/> VIBRATION <input checked="" type="checkbox"/> TEMP 16 °C <input type="checkbox"/> THERMAL VAC <input type="checkbox"/> WRS AT <input type="checkbox"/> OTHER					
	14. DESCRIPTION OF FAILURE	CH'S 1, 5, 9, 13 EXHIBIT OUT OF SPEC TRANSIENT / FREQUENCY RESPONSE AND HIGH NOISE					
ENGINEERING EVALUATION	15. TEST PROCEDURE	16. PARA	17. ORIGINATOR	18. ORG	19. DATE	20. CONTINUATION SHEET USED	
	16597	4.6	C.R. Lane	2213	09-07-81	<input type="checkbox"/>	
	10. VERIFICATION AND FAILURE ANALYSIS	Wingmaster testing determined this S: Detector to be at fault.					
	21. FOLLOWING REWORK/RETEST REQUIRED	Replace Detector					
	21. REWORK/RETEST NOT REQUIRED BECAUSE						
	21. AUTHORIZATION	22. ORG	23. DATE	24. CONTINUATION SHEET USED			
	21. AUTHORIZATION	22. ORG	23. DATE	24. CONTINUATION SHEET USED			
	21. AUTHORIZATION	22. ORG	23. DATE	24. CONTINUATION SHEET USED			
	21. AUTHORIZATION	22. ORG	23. DATE	24. CONTINUATION SHEET USED			
	21. AUTHORIZATION	22. ORG	23. DATE	24. CONTINUATION SHEET USED			
MANUFACTURING AND TEST	25. REWORK/RETEST ACTION TAKEN	Detector replaced and Bench Read and Easy scheduled successfully; discussion during this testing concluded on FR of 19440 (COPY ATTACHED)					
	26. LIST ALL PARTS REPLACED	CRT SYM	PART LOT NUMBER	DATE CODE	MANUFACTURER	PROBABLE DEFECT	ANALYSIS NUMBER
	50803		1033-29				
	27. Rework by	ORG	DATE	28. RETESTED BY	ORG	DATE	29. CONTINUATION SHEET USED
	30. CAUSE AND CORRECTIVE ACTION	Cause of failure in work order. Detector Okay is presently scheduled to undergo life testing followed by analysis to determine cause. UNIT ACCEPTABLE PER DW123					
	31. DOCUMENT IMPLEMENTING CORRECTIVE ACTION	W123 (COPY ATTACHED)					
	32. BASIC CAUSE OF VERIFIED FAILURE	<input type="checkbox"/> DESIGN <input type="checkbox"/> ENVIRONMENTAL <input type="checkbox"/> DEFECTIVE PARTS		<input type="checkbox"/> TEST EQUIPMENT <input type="checkbox"/> TEST PROCEDURE <input type="checkbox"/> TEST SET-UP		<input type="checkbox"/> MFG. PROCEDURE <input type="checkbox"/> ASSY/FAB ERROR <input type="checkbox"/> WORKMANSHIP	
	33. FAILURE TYPE	<input type="checkbox"/> PRIMARY <input type="checkbox"/> INDUCED		<input type="checkbox"/> UNKNOWN <input type="checkbox"/> NO FAILURE		<input type="checkbox"/> WIRING ERROR <input type="checkbox"/> REWORK HANDLING <input type="checkbox"/> WEAR-OUT	
	34. RESPONSIBLE ENGINEER	J. Randall		2/22		DATE 11/18/81	
	35. RELIABILITY	51-41		DATE 12-18-81		DATE 12/18/81	
ENGINEERING/RELIABILITY	36. FAILURE CLASSIFICATION	<input type="checkbox"/> CRITICAL <input checked="" type="checkbox"/> MAJOR <input type="checkbox"/> MINOR <input type="checkbox"/> SAFETY		37. DATE			
	38. FAILURE CLASSIFICATION	<input type="checkbox"/> CRITICAL <input checked="" type="checkbox"/> MAJOR <input type="checkbox"/> MINOR <input type="checkbox"/> SAFETY		39. DATE			

Program Instruction 010

58318

ORIGINAL PAGE
OF POOR QUALITYREQUEST FOR DEVIATION/WAIVER
(SEE MIL-STD-440 OR 442 FOR INSTRUCTIONS)

DATE PREPARED

PROCURING ACTIVITY NO.

1. ORIGINATOR NAME AND ADDRESS David M. Randall SBRC, 75 Coronado Dr., Goleta, Ca. 93117				2. <input type="checkbox"/> DEVIATION <input checked="" type="checkbox"/> WAIVER	
				3. <input type="checkbox"/> MINOR <input checked="" type="checkbox"/> MAJOR <input type="checkbox"/> CRITICAL	
4. DESIGNATION FOR DEVIATION/WAIVER				5. BASIC LINE AFFECTED	
6. MODEL TYPE F	7. MFR. CODE 11323	8. SYS. DESIG. TM	9. DEV/WAIVER NO. W-123	<input checked="" type="checkbox"/> FUNCTIONAL <input type="checkbox"/> ALLOCATED <input type="checkbox"/> PROBABLY	6. OTHER SYSTEMS/COMPONENTS AFFECTED <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO
7. SPECIFICATIONS AFFECTED-TEST PLAN				8. DRAWINGS AFFECTED	
MFR. CODE SPEC./DOC. NO. SCR				MFR. CODE NUMBER REV. MOD. NO.	
9. SYSTEM				11323 50797 E	
10. TEST PLAN					
11. TITLE OF DEVIATION/WAIVER Permission to use Band 1 Band Level Assy SN 401				12. CONTRACT NO. & LINE NAS 5-24200	
13. CONFIGURATION ITEM NOMENCLATURE Radiometer				14. DEFECT CLASSIFICATION <input checked="" type="checkbox"/> MINOR <input type="checkbox"/> MAJOR <input type="checkbox"/> CRITICAL	
15. NAME OF PART OR LOWEST ASSEMBLY AFFECTED Band 1 Band Level Assy				16. PART NO. OR TYPE DESIGNATION 50797-Z	
17. LOT NO. 401				18. QTY 1	
19. EFFECT ON COST/PRICE Greater than \$100.00-if not approved.				20. EFFECT ON DELIVERY SCHEDULE Six weeks	
21. EFFECT ON INTEGRATED LOGISTIC SUPPORT, INTERFACE, ETC. None				22. RECURRING DEVIATION/WAIVER <input checked="" type="checkbox"/> YES <input type="checkbox"/> NO	
23. DESCRIPTION OF DEVIATION/WAIVER					

Band 1 has a number of channels with transient/frequency response discrepancies as defined by FR 8440. Attached is a copy of FR 8440 and transient response plots for all channels. Channel two has average crosstalk between non-neighbors of -59dB vs a specification of ≤ -60 dB.

24. NEED FOR DEVIATION/WAIVER

Band 1 has been bonded into the FPA assy and discrepancies are not considered significant enough to warrant rework on a cost/schedule impact basis.

REQ *DM Randall* 11/20/81 SYS ENGR *LH Engr*RE *Johnnie*
QA *Johnnie*
PE *Johnnie*

25. PRODUCTION EFFECTIVITY BY SERIAL NUMBER

003

51065 SERNO 003 ONLY

CNO *Johnnie* 3426. *Johnnie* 11/23/81Minor - System Engineer
Major/Critical - Program Manager27. ☐ APPROVAL DISAPPROVED☒ APPROVED☐ DISAPPROVED

28. APPROVAL ACTIVITY

Johnnie 12.17.8

DD

594

ORIGINAL PAGE IS
OF POOR QUALITY

HUGHES

HUGHES AIRCRAFT COMPANY
SPACE AND COMMUNICATIONS GROUP
EL SEGUNDO, CALIFORNIA

SPACE AND COMMUNICATIONS GROUP
FAILURE REPORT

S 8322

1. PROGRAM NAME AND NUMBER T.M. VO11		2. GLA	3. MODEL FLIGHT	4. TIME OBSERVED 4:00 P.M.	5. DATE OBSERVED MO 9 OA 28 YR 81
6. HARDWARE LEVEL WHEN FAILURE WAS OBSERVED <input type="checkbox"/> SPACECRAFT <input type="checkbox"/> SUBSYSTEM <input checked="" type="checkbox"/> ASSEMBLY <input type="checkbox"/> MODULE <input type="checkbox"/> CARD		7. SUBSYSTEM			
EQUIPMENT IDENTIFICATION:		PART NUMBER		S/N	
8. UNIT		PART NUMBER		S/N	
9. <input checked="" type="checkbox"/> ASSEMBLY <input type="checkbox"/> SUBASSEMBLY <input type="checkbox"/> MODULE <input type="checkbox"/> MICAM <input type="checkbox"/> CARD		PART NUMBER		S/N	
10. OTHER		PART NUMBER		S/N	
11. TEST WHEN FAILURE WAS OBSERVED <input type="checkbox"/> DEVELOPMENT <input type="checkbox"/> IN-PROCESS <input type="checkbox"/> QUALIFICATION <input type="checkbox"/> ACCEPTANCE <input type="checkbox"/> INTEGRATION <input type="checkbox"/> SYSTEM <input type="checkbox"/> LAUNCH OPERATIONS		12. ENVIRONMENT WHEN FAILURE WAS OBSERVED <input type="checkbox"/> AMBIENT <input type="checkbox"/> RADIATION <input type="checkbox"/> VIBRATION <input type="checkbox"/> TEMP. <input type="checkbox"/> THERMAL VAC. <input type="checkbox"/> HRS AT <input type="checkbox"/> OTHER			
13. DESCRIPTION OF FAILURE CHANNELS 1, 5, 9, 13 & 15 HAVE NON-NEAREST NEIGHBORS - 58 dB FOR CROSSTALK. SPEC. REQUIREMENT: - 60 dB		14. TEST PROCEDURE 16597			
15. VERIFICATION AND FAILURE ANALYSIS		16. CONTINUATION SHEET USED			
17. REWORK/RETEST ACTION TAKEN		18. CONTINUATION SHEET USED			
19. CAUSE AND CORRECTIVE ACTION Crosstalk discrepancies are small and are within reason for the state of the art under which this hardware was built and tested. The transient response within time discrepancies are most likely due to crosstalk signals being picked up by other channels. A small amount of crosstalk is normal and should not be a concern.		20. CONTINUATION SHEET USED			
21. BASIC CAUSE OF VERIFIED FAILURE <input type="checkbox"/> DESIGN <input type="checkbox"/> ENVIRONMENTAL <input type="checkbox"/> DEFECTIVE PARTS <input type="checkbox"/> TEST EQUIPMENT <input type="checkbox"/> TEST PROCEDURE <input type="checkbox"/> TEST SET-UP <input type="checkbox"/> MFG. PROCEDURE <input type="checkbox"/> ASSY/FAB ERROR <input type="checkbox"/> WORKMANSHIP <input type="checkbox"/> VERIFYING ERROR <input type="checkbox"/> ROUGH HANDLING <input type="checkbox"/> WEAR-OUT <input type="checkbox"/> UNKNOWN		22. CONTINUATION SHEET USED			
23. FAILURE TYPE <input type="checkbox"/> PRIMARY <input type="checkbox"/> INDUCED <input type="checkbox"/> UNKNOWN <input type="checkbox"/> NO FAILURE		24. CONTINUATION SHEET USED			
25. RESPONSIBLE ENGINEER W117 (COPY ATTACHED)		26. CONTINUATION SHEET USED			
27. DATE 12/15/81		28. DATE 12/15/81			
29. DATE 12/15/81		30. DATE 12/15/81			

HUGHES AIRCRAFT COMPANY

ORIGINAL PAGE IS
OF POOR QUALITY

58322 CONT. SM
LETTER
FR SERIAL NO. 1

* LABEL FIRST CONTINUATION SHEET USED 'A', SECOND 'B', AND SO ON

IDENTIFY ENTRIES BY REFERENCING FA BLOCK NUMBER IN COLUMN, DATE EACH ENTRY.

ADDITIONAL P
CONTINUATION
SHEET(S) USED

14

Time	1.5%	1.0%	1.8 hr
2.5	30 μ s	60 μ s	
1.3	2.0	2.0	90 μ s
1.4	2.0	1.8	50
1.5	2.0	1.5	3.3
1.6	1.9	0	3.2

ORIGINAL PAGE IS
OF POOR QUALITY

Program Instruction 010

REQUEST FOR DEVIATION/VAIVER
FORM 418-100-0000 (10-81) (INSTRUCTIONS)

DATE PREPARED

11-10-81

PROCURING ACTIVITY NO.

58322

1. ORIGINATOR NAME AND ADDRESS David M. Randall

SHRC, 75 Coronado Dr. Colton, Ca. 93117

2. ☐ DEVIATION ☒ VAIVER
3. ☐ MINOR ☒ MAJOR ☐ CRITICAL

4. DES. SECTION FOR DEVIATION/VAIVER
A. WORK ORDER NO. 11323 B. SYS. OFFICER TM C. SPEC. NO. W-117
5. BASE LINE AFFECTED ☒ PLANNED ☐ UNPLANNED ☐ OTHER
6. OTHER SYSTEMS/CONFIGURATION ITEMS AFFECTED ☐ YES ☒ NO

7. SPECIFIC ACTIONS AFFECTED TEST PLAN
A. SYSTEM B. ITEM C. TEST PLAN
8. DRAWINGS AFFECTED
A. DRAWING NO. B. REV. C. REV. D. REV. E. REV. F. REV. G. REV. H. REV. I. REV. J. REV. K. REV. L. REV. M. REV. N. REV. O. REV. P. REV. Q. REV. R. REV. S. REV. T. REV. U. REV. V. REV. W. REV. X. REV. Y. REV. Z. REV. AA. REV. AB. REV. AC. REV. AD. REV. AE. REV. AF. REV. AG. REV. AH. REV. AI. REV. AJ. REV. AK. REV. AL. REV. AM. REV. AN. REV. AO. REV. AP. REV. AQ. REV. AR. REV. AS. REV. AT. REV. AU. REV. AV. REV. AW. REV. AX. REV. AY. REV. AZ. REV. BA. REV. BB. REV. BC. REV. BD. REV. BE. REV. BF. REV. BG. REV. BH. REV. BI. REV. BJ. REV. BK. REV. BL. REV. BM. REV. BN. REV. BO. REV. BP. REV. BQ. REV. BR. REV. BS. REV. BT. REV. BU. REV. BV. REV. BW. REV. BX. REV. BY. REV. BZ. REV. CA. REV. CB. REV. CC. REV. CD. REV. CE. REV. CF. REV. CG. REV. CH. REV. CI. REV. CJ. REV. CK. REV. CL. REV. CM. REV. CN. REV. CO. REV. CP. REV. CQ. REV. CR. REV. CS. REV. CT. REV. CU. REV. CV. REV. CW. REV. CX. REV. CY. REV. CZ. REV. DA. REV. DB. REV. DC. REV. DD. REV. DE. REV. DF. REV. DG. REV. DH. REV. DI. REV. DJ. REV. DK. REV. DL. REV. DM. REV. DN. REV. DO. REV. DP. REV. DQ. REV. DR. REV. DS. REV. DT. REV. DU. REV. DV. REV. DW. REV. DX. REV. DY. REV. DZ. REV. EA. REV. EB. REV. EC. REV. ED. REV. EE. REV. EF. REV. EG. REV. EH. REV. EI. REV. EJ. REV. EK. REV. EL. REV. EM. REV. EN. REV. EO. REV. EP. REV. EQ. REV. ER. REV. ES. REV. ET. REV. EU. REV. EV. REV. EW. REV. EX. REV. EY. REV. EZ. REV. FA. REV. FB. REV. FC. REV. FD. REV. FE. REV. FF. REV. FG. REV. FH. REV. FI. REV. FJ. REV. FK. REV. FL. REV. FM. REV. FN. REV. FO. REV. FP. REV. FQ. REV. FR. REV. FS. REV. FT. REV. FU. REV. FV. REV. FW. REV. FX. REV. FY. REV. FZ. REV. GA. REV. GB. REV. GC. REV. GD. REV. GE. REV. GF. REV. GG. REV. GH. REV. GI. REV. GJ. REV. GK. REV. GL. REV. GM. REV. GN. REV. GO. REV. GP. REV. GQ. REV. GR. REV. GS. REV. GT. REV. GU. REV. GV. REV. GW. REV. GX. REV. GY. REV. GZ. REV. HA. REV. HB. REV. HC. REV. HD. REV. HE. REV. HF. REV. HG. REV. HH. REV. HI. REV. HJ. REV. HK. REV. HL. REV. HM. REV. HN. REV. HO. REV. HP. REV. HQ. REV. HR. REV. HS. REV. HT. REV. HU. REV. HV. REV. HW. REV. HX. REV. HY. REV. HZ. REV. IA. REV. IB. REV. IC. REV. ID. REV. IE. REV. IF. REV. IG. REV. IH. REV. II. REV. IJ. REV. IK. REV. IL. REV. IM. REV. IN. REV. IO. REV. IP. REV. IQ. REV. IR. REV. IS. REV. IT. REV. IU. REV. IV. REV. IW. REV. IX. REV. IY. REV. IZ. REV. JA. REV. JB. REV. JC. REV. JD. REV. JE. REV. JF. REV. JG. REV. JH. REV. JI. REV. JJ. REV. JK. REV. JL. REV. JM. REV. JN. REV. JO. REV. JP. REV. JQ. REV. JR. REV. JS. REV. JT. REV. JU. REV. JV. REV. JW. REV. JX. REV. JY. REV. JZ. REV. KA. REV. KB. REV. KC. REV. KD. REV. KE. REV. KF. REV. KG. REV. KH. REV. KI. REV. KJ. REV. KK. REV. KL. REV. KM. REV. KN. REV. KO. REV. KP. REV. KQ. REV. KR. REV. KS. REV. KT. REV. KU. REV. KV. REV. KW. REV. KX. REV. KY. REV. KZ. REV. LA. REV. LB. REV. LC. REV. LD. REV. LE. REV. LF. REV. LG. REV. LH. REV. LI. REV. LJ. REV. LK. REV. LL. REV. LM. REV. LN. REV. LO. REV. LP. REV. LQ. REV. LR. REV. LS. REV. LT. REV. LU. REV. LV. REV. LW. REV. LX. REV. LY. REV. LZ. REV. MA. REV. MB. REV. MC. REV. MD. REV. ME. REV. MF. REV. MG. REV. MH. REV. MI. REV. MJ. REV. MK. REV. ML. REV. MM. REV. MN. REV. MO. REV. MP. REV. MQ. REV. MR. REV. MS. REV. MT. REV. MU. REV. MV. REV. MW. REV. MX. REV. MY. REV. MZ. REV. NA. REV. NB. REV. NC. REV. ND. REV. NE. REV. NF. REV. NG. REV. NH. REV. NI. REV. NJ. REV. NK. REV. NL. REV. NM. REV. NN. REV. NO. REV. NP. REV. NQ. REV. NR. REV. NS. REV. NT. REV. NU. REV. NV. REV. NW. REV. NX. REV. NY. REV. NZ. REV. OA. REV. OB. REV. OC. REV. OD. REV. OE. REV. OF. REV. OG. REV. OH. REV. OI. REV. OJ. REV. OK. REV. OL. REV. OM. REV. ON. REV. OO. REV. OP. REV. OQ. REV. OR. REV. OS. REV. OT. REV. OU. REV. OV. REV. OW. REV. OX. REV. OY. REV. OZ. REV. PA. REV. PB. REV. PC. REV. PD. REV. PE. REV. PF. REV. PG. REV. PH. REV. PI. REV. PJ. REV. PK. REV. PL. REV. PM. REV. PN. REV. PO. REV. PP. REV. PQ. REV. PR. REV. PS. REV. PT. REV. PU. REV. PV. REV. PW. REV. PX. REV. PY. REV. PZ. REV. QA. REV. QB. REV. QC. REV. QD. REV. QE. REV. QF. REV. QG. REV. QH. REV. QI. REV. QJ. REV. QK. REV. QL. REV. QM. REV. QN. REV. QO. REV. QP. REV. QQ. REV. QR. REV. QS. REV. QT. REV. QU. REV. QV. REV. QW. REV. QX. REV. QY. REV. QZ. REV. RA. REV. RB. REV. RC. REV. RD. REV. RE. REV. RF. REV. RG. REV. RH. REV. RI. REV. RJ. REV. RK. REV. RL. REV. RM. REV. RN. REV. RO. REV. RP. REV. RQ. REV. RR. REV. RS. REV. RT. REV. RU. REV. RV. REV. RW. REV. RX. REV. RY. REV. RZ. REV. SA. REV. SB. REV. SC. REV. SD. REV. SE. REV. SF. REV. SG. REV. SH. REV. SI. REV. SJ. REV. SK. REV. SL. REV. SM. REV. SN. REV. SO. REV. SP. REV. SQ. REV. SR. REV. SS. REV. ST. REV. SU. REV. SV. REV. SW. REV. SX. REV. SY. REV. SZ. REV. TA. REV. TB. REV. TC. REV. TD. REV. TE. REV. TF. REV. TG. REV. TH. REV. TI. REV. TJ. REV. TK. REV. TL. REV. TM. REV. TN. REV. TO. REV. TP. REV. TQ. REV. TR. REV. TS. REV. TU. REV. TV. REV. TW. REV. TX. REV. TY. REV. TZ. REV. UA. REV. UB. REV. UC. REV. UD. REV. UE. REV. UF. REV. UG. REV. UH. REV. UI. REV. UJ. REV. UK. REV. UL. REV. UM. REV. UN. REV. UO. REV. UP. REV. UQ. REV. UR. REV. US. REV. UT. REV. UY. REV. UZ. REV. VA. REV. VB. REV. VC. REV. VD. REV. VE. REV. VF. REV. VG. REV. VH. REV. VI. REV. VJ. REV. VK. REV. VL. REV. VM. REV. VN. REV. VO. REV. VP. REV. VQ. REV. VR. REV. VS. REV. VT. REV. VU. REV. VV. REV. VW. REV. VX. REV. VY. REV. VZ. REV. WA. REV. WB. REV. WC. REV. WD. REV. WE. REV. WF. REV. WG. REV. WH. REV. WI. REV. WJ. REV. WK. REV. WL. REV. WM. REV. WN. REV. WO. REV. WP. REV. WQ. REV. WR. REV. WS. REV. WT. REV. WY. REV. WZ. REV. XA. REV. XB. REV. XC. REV. XD. REV. XE. REV. XF. REV. XG. REV. XH. REV. XI. REV. XJ. REV. XK. REV. XL. REV. XM. REV. XN. REV. XO. REV. XP. REV. XQ. REV. XR. REV. XS. REV. XT. REV. XU. REV. XV. REV. XW. REV. XX. REV. XY. REV. XZ. REV. YA. REV. YB. REV. YC. REV. YD. REV. YE. REV. YF. REV. YG. REV. YH. REV. YI. REV. YJ. REV. YK. REV. YL. REV. YM. REV. YN. REV. YO. REV. YP. REV. YQ. REV. YR. REV. YS. REV. YT. REV. YU. REV. YV. REV. YW. REV. YX. REV. YZ. REV. ZA. REV. ZB. REV. ZC. REV. ZD. REV. ZE. REV. ZF. REV. ZG. REV. ZH. REV. ZI. REV. ZJ. REV. ZK. REV. ZL. REV. ZM. REV. ZN. REV. ZO. REV. ZP. REV. ZQ. REV. ZR. REV. ZS. REV. ZT. REV. ZU. REV. ZV. REV. ZW. REV. ZX. REV. ZY. REV. ZZ.

9. TITLE OF DEVIATION/VAIVER Permission to use Band 4 Band Level Assy SN 201
10. CONTRACT NO. & LINE ITEM NAS 5-24200

11. IDENTIFICATION OF DEVIATION/VAIVER Radiometer
12. CD NO. II
13. TARGET NO. I
14. EFFECT CLASSIFICATION ☒ MINOR ☐ MAJOR ☐ CRITICAL

15. NAME OF BASE OF DEVIATION/VAIVER AFFECTED Band Level Assy
16. PART NO. OF TYPE DESIGN 50797
17. LINE NO. 201
18. EFFECT ON DELIVERY ☐ YES ☒ NO

19. EFFECT ON COST/PRICE Greater than \$100,000-if not approved.
20. EFFECT ON INTEGRATED LOGISTIC SUPPORT, INTERFACE, ETC. Thru to four months if not approved.

21. EFFECT ON DELIVERY NONE
22. EFFECT ON INTEGRATED LOGISTIC SUPPORT, INTERFACE, ETC. NONE

23. DESCRIPTION OF DEVIATION/VAIVER

Permission to use Band 4 Band Level Assy SN 201 with Channels 9, 13, 14 15 & 16 exceeding transient response settling time specification, and Channels 1, 5, 9, 13 & 15 have -56dB crosstalk vs a specification of -60dB.

Channel	30µs	60µs	12µs
5	2.0%	1.0%	60µs
13	2.0	2.0	90µs
14	2.0	.8	50µs
15	2.0	.5	13µs
16	1.0	0	12µs

24. ALSO FOR DEVIATION/VAIVER

The rework required to correct the discrepancies noted above is not considered cost or schedule effective.

REA *[Signature]* SYS ENGR *[Signature]*

RE *[Signature]*
QA *[Signature]*
PE *[Signature]*

25. PREPARED EFFECTIVELY BY SPECIAL REQUEST 003

[Signature] 11/16/81
Minor - System Engineering
Major/Critical - Program Manager

26. APPROVAL, RECOMMENDED ☐ APPROVED ☒ DISAPPROVED ☐
27. SIGNATURE *[Signature]* DATE *[Date]*

HUGHESHUGHES AIRCRAFT COMPANY
SPACE AND COMMUNICATIONS GROUP
1. SEQUOIA, CALIFORNIA

AHR 50797 3/N 401 Band 4

Oper 2600

SPACE AND COMMUNICATIONS GROUP

FAILURE REPORTORIGINAL PAGE IS
OF POOR QUALITY**S 8323**

1. PROGRAM NAME AND NUMBER T.M. VO11		2. GLA VO11	3. MODEL FLIGHT	4. TIME OBSERVED 12:45 PM	5. DATE OBSERVED MO 9 DA 20 YR 81
6. HARDWARE LEVEL WHEN FAILURE WAS OBSERVED <input type="checkbox"/> SPACECRAFT <input type="checkbox"/> SYSTEM		<input type="checkbox"/> SUBSYSTEM <input type="checkbox"/> UNIT	<input type="checkbox"/> ASSEMBLY <input checked="" type="checkbox"/> SUBASSEMBLY	<input type="checkbox"/> MODULE <input type="checkbox"/> MICAM	<input type="checkbox"/> CARD <input type="checkbox"/> PART
EQUIPMENT IDENTIFICATION:					
7. SUBSYSTEM		NAME		PART NUMBER	S/N
8. UNIT		NAME		PART NUMBER	S/N
9. <input type="checkbox"/> ASSEMBLY <input checked="" type="checkbox"/> SUBASSEMBLY		NAME		PART NUMBER	S/N
10. <input type="checkbox"/> MODULE <input type="checkbox"/> MICAM <input type="checkbox"/> CARD		NAME		PART NUMBER	S/N
11. OTHER		NAME		PART NUMBER	S/N
12. TEST WHEN FAILURE WAS OBSERVED <input type="checkbox"/> DEVELOPMENT <input type="checkbox"/> IN-PROCESS		<input type="checkbox"/> QUALIFICATION <input checked="" type="checkbox"/> ACCEPTANCE		<input type="checkbox"/> INTEGRATION <input type="checkbox"/> SYSTEM	
13. ENVIRONMENT WHEN FAILURE WAS OBSERVED <input checked="" type="checkbox"/> AMBIENT <input type="checkbox"/> EMC/RF		<input type="checkbox"/> RADIATION <input type="checkbox"/> VIBRATION		<input type="checkbox"/> TEMP <input type="checkbox"/> THERMAL VAC	
14. DESCRIPTION OF FAILURE		NO CONTINUITY BETWEEN J2-16 AND J2-10. ON EVEN SIDE OF PRE-AMP ASSY			
15. TEST PROCEDURE		16.597	17. PARA 4.9	18. OPERATOR ALICE JAVISON	19. CONTINUATION SHEET USED
20. VERIFICATION AND FAILURE ANALYSIS		NO CONTINUITY BETWEEN PIN 13 OF U3 HYBRID AND OTHER PINS (6, 10, 24) DESIGNATED AS SIGNAL GROUND, CLEARLY INDICATING THAT U3 HAS FAILED.			
21. FOLLOWING REWORK/RETEST REQUIRED <input checked="" type="checkbox"/> Rework/Retest Not Required Because		Hybrid S/N 193			
22. REWORK/RETEST ACTION TAKEN		Hybrid replaced and tested good. No continuity of any components. Then, as a check, ground the other pins.			
23. LIST ALL PARTS REPLACED		CXT SYM	PART LOT NUMBER	DATE CODE	MANUFACTURER
50860 (REMOVED)			S/N 193		HAC
INSTALLED			S/N 160		
24. REWORK BY		ORG	DATE	25. RETESTED BY	ORG
26. CAUSE AND CORRECTIVE ACTION		PART SENT FOR FAILURE ANALYSIS. FAILURE MAY BE A MISSING BAND WIRE FROM PIN 13 TO SUBSTRATE (SEE ATTACHED MEMO, HS236-7598). CORRECTIVE ACTION WAS TO REPLACE HYBRID. FAILURE OF THIS TYPE CANNOT GO UNDETECTED BECAUSE CONTINUITY BETWEEN PIN 13 AND THE SUBSTRATE IS TESTED BY TEST PROCEDURE 16597. MANUFACTURING HAS BEEN ADVISED. CAUSE UNKNOWN - SEE ATTACHED IDC 82/12-60-02-106 MEMO			
27. DOCUMENT IMPLEMENTING CORRECTIVE ACTION		NONE REQ'D			
28. BASIC CAUSE OF VERIFIED FAILURE <input type="checkbox"/> DESIGN <input type="checkbox"/> ENVIRONMENTAL <input type="checkbox"/> DEFECTIVE PARTS		<input type="checkbox"/> TEST EQUIPMENT <input type="checkbox"/> TEST PROCEDURE <input type="checkbox"/> TEST SET-UP		<input type="checkbox"/> MFG. PROCEDURE <input type="checkbox"/> ASSEMBLY ERROR <input type="checkbox"/> WORKMANSHIP	
29. FAILURE TYPE <input checked="" type="checkbox"/> PRIMARY <input type="checkbox"/> INDUCED		<input type="checkbox"/> UNKNOWN <input type="checkbox"/> NO FAILURE		<input type="checkbox"/> WIRING ERROR <input type="checkbox"/> ROUGH HANDLING <input type="checkbox"/> WEAR-OUT	
30. RESPONSIBLE ENGINEER		DATE		31. SPACE/FACTOR SYSTEM ENGINEER	
A. Hunter		2122 11-3-81		22-41 3/15/81	
32. RELIABILITY		DATE		33. TEST OVER FOR SUPPLIER	
51-11		11-02-81		11-02-81	

ORIGINAL PAGE IS
OF POOR QUALITY

HUGHES

HUGHES AIRCRAFT COMPANY
SPACE AND COMMUNICATIONS GROUP
EL SEGUNDO, CALIFORNIA

SPACE AND COMMUNICATIONS GROUP

**FAILURE REPORT
CONTINUATION SHEET**

FR SERIAL NO.
58323
CONTINUATION SHEET LETTER
A

*LABEL FIRST CONTINUATION SHEET USED 'A', SECOND 'B', AND SO ON

IDENTIFY ENTRIES BY REFERENCING FR BLOCK NUMBER IN COLUMN, DATE EACH ENTRY.

ADDITIONAL FR
CONTINUATION
SHEET(S) USED ☐

30 HS 236-7598 WAS WRITTEN PRIOR TO RETURNING THE
DEVICE FOR FAILURE ANALYSIS. THE HYPOTHESIS AT THAT
TIME (10-26-81) WAS THAT THE CAUSE WAS THE SAME
AS NOTED ON 50860 S/N BB, WHICH WAS A MISSING
BOND WIRE. FAILURE ANALYSIS AS DOCUMENTED IN
IDC 82/12-60-02-101 SHOWS THE CAUSE TO BE UNDETER-
MINATE. OF THE THREE POTENTIAL CAUSES LISTED, THE REVERSAL
OF HYBRID ON THE PC BOARD IS RULED OUT BECAUSE
A FUNCTIONAL TEST PRECEDED THE CONTINUITY
CHECK OF TP 16597 PARA 4.9. THIS ALSO RULED OUT
THE POSSIBILITY OF APPLICATION OF POTENTIAL BETWEEN
PINS 10 AND 13 AS THE UNIT WAS IN NORMAL
TEST/OPERATING CONFIGURATION AT THE TIME
FAILURE WAS NOTED.

THE FAILURE WAS FIRST NOTED AT THIS POINT OF THE
TEST PROCEDURE BECAUSE THERE IS NO RECEIVING TEST
INSPECTION FOR THIS FUNCTION. SOURCE INSPECTION IS UTILIZED
AND DATA IS FORWARDED TO THE USER. THE POSSIBILITY OF
REVERSAL IN TEST FIXTURE AT SUPPLIER'S FACILITY IS ONE
ONE OF SEVERAL ~~FAVORABLE~~ POSSIBLE METHODS OF
INDUCING THIS FAILURE. THEREFORE, CAUSE UNKNOWN
IS CHECKED IN ITEM 34.

THE LAST 50860 WAS DELIVERED ON 11-24-80.

A MISSING BOND BETWEEN PINS 10 & 13 RESULTED IN
A CHANGE TO THE MANUFACTURING TEST PROCEDURE
JUST PRIOR TO 8-19-81. THIS TEST PROCEDURE CHECKS
CONTINUITY BETWEEN ALL GROUND RETURN PINS. THE
MANUFACTURER HAS BEEN ADVISED OF THE FAILURE THAT
IS REPORTED HERE AND ~~FAVORABLE~~ THE USERS AT
SBRC HAVE ALSO BEEN ALERTED. THIS SHOULD PRELU-
RECURRANCE OF SIMILAR PROBLEMS ON FUTURE
PROCUREMENTS.

INGERS AIRCRAFT COMPANY

ORIGINAL PAGE IS
OF POOR QUALITY

58323

INTERDEPARTMENTAL CORRESPONDENCE



TO: L. Nolthausen
FROM: SBAC
SUBJECT: Failure Verification
OF Thematic Mapper
Silicon Preamp
Hybrid

cc: L. O'Connell
F. Carle
R. Nelson
E. Furuya

DATE: 11 March 1982
REF: 82/12-60-02-101

FROM: J. Mazenko
BLOC: 604 MAIL STA. 8253
EXT: 21218 ORG CODE: 12-60-01


Thematic Mapper Silicon Preamplifier Hybrid P/N 50860/1950594-100 was returned to the author for failure verification and analysis. The results of the investigation are given below.

Initial Failure Indication - Open between pins 10 and 13 (Detector Return B)

Failure was confirmed by Electrical Test. The hybrid was then subjected to Pind Test, Fine Leak Test and Gross Leak Test. The hybrid passed all of these tests. The hybrid was then decapped for visual inspection. Visual inspection revealed that the wire bond which connects the two conductor traces on the hybrid substrate (see attached photographs) joining pin 10 to pin 13 was fused open.

The actual cause of failure is indeterminate. However, several potential causes are listed below.

1. Reversal of hybrid in test fixture.
2. Reversal of hybrid on PC board.
3. Improper potential applied to pin 10 or 13 during probing or trouble shooting of PC board.


J. Mazenko
Manager Technical Staff
Technical Support Laboratory
Engineering Services & Support Division

ORIGINAL PAGE IS
OF POOR QUALITY

HUGHES

HUGHES AIRCRAFT COMPANY
SPACE AND COMMUNICATIONS GROUP
EL SEGUNDO, CALIFORNIA

**SPACE AND COMMUNICATIONS GROUP
FAILURE REPORT**

S 8324

1. PROGRAM NAME AND NUMBER V011 TM		2. GLA	3. MODEL FLIGHT	4. TIME OBSERVED 1ST SHIFT	5. DATE OBSERVED MO 10 DA 01 YR 81
6. HARDWARE LEVEL WHEN FAILURE WAS OBSERVED <input type="checkbox"/> SPACECRAFT <input type="checkbox"/> SYSTEM <input type="checkbox"/> SUBSYSTEM <input type="checkbox"/> UNIT <input checked="" type="checkbox"/> ASSEMBLY <input type="checkbox"/> SUBASSEMBLY <input type="checkbox"/> MODULE <input type="checkbox"/> MICAM <input type="checkbox"/> CARD <input type="checkbox"/> PART					
EQUIPMENT IDENTIFICATION:					
7. SUBSYSTEM		NAME		PART NUMBER	S/N
8. UNIT					
9. <input checked="" type="checkbox"/> ASSEMBLY <input type="checkbox"/> SUBASSEMBLY		Bonded Bonding		50797	401
10. <input type="checkbox"/> MODULE <input type="checkbox"/> MICAM <input type="checkbox"/> CARD					
11. OTHER					
12. TEST WHEN FAILURE WAS OBSERVED <input type="checkbox"/> DEVELOPMENT <input type="checkbox"/> IN-PROCESS <input type="checkbox"/> QUALIFICATION <input type="checkbox"/> ACCEPTANCE <input type="checkbox"/> INTEGRATION <input type="checkbox"/> SYSTEM <input type="checkbox"/> LAUNCH OPERATIONS					
13. ENVIRONMENT WHEN FAILURE WAS OBSERVED <input type="checkbox"/> AMBIENT <input type="checkbox"/> EMC/RF <input type="checkbox"/> RADIATION <input type="checkbox"/> VIBRATION <input checked="" type="checkbox"/> TEMP 15 °C <input type="checkbox"/> THERMAL VAC HRS AT <input type="checkbox"/> OTHER					
14. DESCRIPTION OF FAILURE CH'S 1, 5, 9 FREQUENCY RESPONSE OUT SPEC. CH 1: -3.1 dB, CH 5: -3.05 dB, CH 9: -3.06 dB AT 52K Hz. Should be -3.0/-0.5 dB CH'S 2, 3, 6, 11, 12, 13 EXCEED TRANSMITTANCE RESPONSE SPEC. AT 300 MHz					
15. TEST PROCEDURE 16597		PARA 4.6.48	16. ORIGINATOR C. R. Lee	ORG 2213	DATE 10-06-81
17. VERIFICATION AND FAILURE ANALYSIS					
18. FAILED ITEM NAME AND PART NUMBER					
19. <input type="checkbox"/> FOLLOWING REWORK/RETEST REQUIRED <input checked="" type="checkbox"/> REWORK/RETEST NOT REQUIRED BECAUSE FR to be closed via waiver W-115 Failure is one of not meeting specification; therefore no components have been overhauled					
20. AUTHORIZATION [Signature]		ORG 2122	DATE 11/9/81	21. CONTINUATION <input checked="" type="checkbox"/> SHEET USED	
22. REWORK/RETEST ACTION TAKEN		23. QA Rework			
		24. QA RETEST			
25. LIST ALL PARTS REPLACED		CKT SYM	PART LOT NUMBER	DATE CODE	MANUFACTURER
PART NUMBER					PROBABLE DEFECT
					ANALYSIS NUMBER
27. REWORK BY		ORG	DATE	28. RETESTED BY	ORG
					DATE
29. CAUSE AND CORRECTIVE ACTION Frequency response and constant discrepancy are small and are within reason for the state of the art under which this hardware was built and tested. The transient response within time discrepancies are most likely due to constant shielding being pushed closed together during case of Bond Level. Operator cautioned to use care not to move shield.		30. CONTINUATION <input type="checkbox"/> SHEET USED			
31. DOCUMENT IMPLEMENTING CORRECTIVE ACTION W115 (COPY ATTACHED)		32. FAILURE CLASSIFICATION <input type="checkbox"/> UNKNOWN <input type="checkbox"/> DEFECT CODE			
33. BASIC CAUSE OF VERIFIED FAILURE <input type="checkbox"/> DESIGN <input type="checkbox"/> ENVIRONMENTAL <input type="checkbox"/> DEFECTIVE PARTS <input type="checkbox"/> TEST EQUIPMENT <input type="checkbox"/> TEST PROCEDURE <input type="checkbox"/> TEST SET-UP <input type="checkbox"/> MFG. PROCEDURE <input type="checkbox"/> ASSY/FAB ERROR <input checked="" type="checkbox"/> WORKMANSHIP <input type="checkbox"/> VARIING ERROR <input type="checkbox"/> ROUGH HANDLING <input type="checkbox"/> WEAR-OUT		34. FAILURE TYPE <input type="checkbox"/> PRIMARY <input checked="" type="checkbox"/> INDICED <input type="checkbox"/> UNKNOW <input type="checkbox"/> NO FAILURE			
35. FAILURE TYPE 11.2		36. FAILURE CLASSIFICATION <input type="checkbox"/> MINOR <input checked="" type="checkbox"/> MAJOR <input type="checkbox"/> SAFETY		37. SPACECRAFT SYSTEM ENGINEER [Signature]	
37. RESUBMIT ENGINEER [Signature]		ORG 101101		DATE 11/12/81	

HUGHES

HUGHES AIRCRAFT COMPANY

SPACE AND COMMUNICATION GROUP
EQUIPMENT CHECKOUT
FAILURE REPORT
CONTINUATION SHEET

ORIGINAL PAGE 19
OF POOR QUALITY

5 8324 CONT.
PR SERIAL NO. LETTER

*LABEL FIRST CONTINUATION SHEET USED 'A', SECOND 'B', AND SO ON

IDENTIFY ENTRIES BY REFERENCING PR BLOCK NUMBER IN COLUMN, DATE EACH ENTRY.

ADDITIONAL
CONTINUA
SHEET(S) U

14 CH'S 5,7,9 DO NOT MEET -60dB NON-NEIGHBORS AVER
REQUIREMENTS FOR CROSS TALK: 5, -57dB; 7, -57dB; 9, -58dB
15 16597 PARA. 4.6, 4.8
16 C.R. Lenz 22-13 10-01-81

1	1	20.1	10.0	3.0	1.0
2	2	2.5	1.5	1.5	1.0
3	3	1.5	1.2		
4	4	2.2	1.0		
5	5	2.2	1.2		
6	6	2.5	1.2		
7	7	1.5	1.2		
8	8	2.0	1.5		
9	9	1.2	1.5		

14	Channel	30dB	60dB	170 dB	70dB
2		10.7	1.2		12.7
6		1.5	1.9		80
7		0	1.5		3.5
8		2.0	1.2		92
9		1.2	1.5		90
11		1.2	1.7		90
12		2.0	1.7		95
13		1.4	1.7		

H 5 P 5824

1955: 131-132

2.	<input type="checkbox"/> DEVIATION	<input checked="" type="checkbox"/> DANGER
3.	<input type="checkbox"/> MINOR	<input checked="" type="checkbox"/> MAJOR
		<input type="checkbox"/> CRITICAL

NAS 5-24200

Permission to use Band 2 Band Level Assy SN 401 with Ch 1, 5, 9 & 13 not meeting frequency response of 2-1dB @ 32KHZ (-3.1dB, -3.05dB & -3.06dB respectively); Ch 5, 7 & 9 have non-neighbor crosstalk of -59dB, -59dB & -58dB respectively vs a spec of <60dB; and Ch 2, 6, 7, 8, 9, 11, 12 & 13 do not meet settling time requirements. Copy of FR 8324 attached.

20. 4446 : 08 26 VIA 104: 94: 46B

The rework required to correct the discrepancies noted above is not considered cost or schedule effective.

REA *[Signature]* SYS ENGR

RE- 100-100000-1000 1000
QA 100-100000-1000
PE 100-100000-1000

003

76 J. H. [unclear] 11/16/81

☒ APPROVED
[Signature] 12.17.8

HUGHES

HUGHES AIRCRAFT COMPANY
SPACE AND COMMUNICATIONS GROUP
EL SEGUNDO, CALIFORNIA

SPACE AND COMMUNICATIONS GROUP FAILURE REPORT

ORIGINAL PAGE IS
OF POOR QUALITY

S 8341

1. PROGRAM NAME AND NUMBER VO11		2. GLA		3. MODEL FLIGHT		4. TIME OBSERVED 11:30 a.m.		5. DATE OBSERVED MO 10 DA 26 YR 8	
6. HARDWARE LEVEL WHEN FAILURE WAS OBSERVED <input type="checkbox"/> SPACECRAFT <input type="checkbox"/> SYSTEM		<input type="checkbox"/> SUBSYSTEM <input type="checkbox"/> UNIT		<input type="checkbox"/> ASSEMBLY <input type="checkbox"/> SUBASSEMBLY		<input type="checkbox"/> MODULE <input type="checkbox"/> MICAM		<input checked="" type="checkbox"/> CARD <input type="checkbox"/> PART	
EQUIPMENT IDENTIFICATION:									
7. SUBSYSTEM		NAME		PART NUMBER		S/N		MANUFACTURER	
8. UNIT									
9. <input checked="" type="checkbox"/> ASSEMBLY <input type="checkbox"/> SUBASSEMBLY		BAND 1 POST AMP		S0904-1		101		SGRC	
10. <input type="checkbox"/> MODULE <input type="checkbox"/> MICAM <input type="checkbox"/> CARD									
11. OTHER									
12. TEST WHEN FAILURE WAS OBSERVED <input type="checkbox"/> DEVELOPMENT <input checked="" type="checkbox"/> IN-PROCESS		<input type="checkbox"/> QUALIFICATION <input type="checkbox"/> ACCEPTANCE		<input type="checkbox"/> INTEGRATION <input type="checkbox"/> SYSTEM		<input type="checkbox"/> LAUNCH OPERATIONS			
13. ENVIRONMENT WHEN FAILURE WAS OBSERVED <input type="checkbox"/> AMBIENT <input type="checkbox"/> EMC/RFI		<input type="checkbox"/> RADIATION <input type="checkbox"/> VIBRATION		<input checked="" type="checkbox"/> TEMP 15.0 AXIS FOR MIN TYPE OTHER		<input type="checkbox"/> THERMAL VAC		HRS AT 1	
14. DESCRIPTION OF FAILURE		TRANSIENT RESPONSE VERY BAD							
15. TEST PROCEDURE 16597		PARA		16. ORIGINATOR N. C. DAVISON		ORG 2213		DATE 10-26-81	
17. CONTINUATION SHEET USED									
18. VERIFICATION AND FAILURE ANALYSIS		RESISTORS R72 (ROLLOFF 24.3K - 259) AND R88 (GAIN 6.34K - 283) ARE REVERSED. NO OVERSTRESS OCCURRED. REF HS236-7743 COPY ATTACHED.							
19. FOLLOWING REWORK/RETEST REQUIRED <input type="checkbox"/> REWORK/RETEST NOT REQUIRED BECAUSE		REVERSE R72 AND R88 AND RETURN TO FINAL TEST.							
20. AUTHORIZATION		N. C. DAVISON		ORG 2213		DATE 10-26-81		17. CONTINUATION SHEET USED	
21. REWORK/RETEST ACTION TAKEN		R72 (ROLLOFF, 24.3K) AND R88 (GAIN, 6.34K) WERE INSTALLED IN THEIR PROPER LOCATIONS. NO OVERSTRESS OCCURRED.							
22. LIST ALL PARTS REPLACED		CXT SYM		PART LOT NUMBER		DATE CODE		MANUFACTURER	
23. PROBABLE DEFECT		ANALYSIS NUM							
24. NONE (NO OVERSTRESS OCCURRED AS A RESULT OF THE RESISTOR INTERCHANGE) REF HS236-7743 DATED 11-20-81 (COPY ATTACHED)									
25. REWORK BY		ORG		DATE		26. RETESTED BY		ORG	
27. CAUSE AND CORRECTIVE ACTION		WORKMANSHIP ERROR WHEN MOVING SELECT RESISTORS FROM STANDOFFS TO THE BOARD. PERSONNEL HAVE BEEN REMOVED TO USE CARE WHEN REMOVING AND REINSTALLING COMPONENTS		30. CONTINUATION SHEET USED		31. CONTINUATION SHEET USED		32. CONTINUATION SHEET USED	
33. DOCUMENT IMPLEMENTING CORRECTIVE ACTION		NEW RPD'S HS 236-7743 COPY ATTACHED							
34. BASIC CAUSE OF VERIFIED FAILURE <input type="checkbox"/> DESIGN <input type="checkbox"/> ENVIRONMENTAL <input type="checkbox"/> DEFECTIVE PARTS		<input type="checkbox"/> TEST EQUIPMENT <input type="checkbox"/> TEST PROCEDURE <input type="checkbox"/> TEST SET-UP		<input type="checkbox"/> MFG. PROCEDURE <input type="checkbox"/> ASSY/FAB ERROR <input checked="" type="checkbox"/> WORKMANSHIP		<input type="checkbox"/> WIRING ERROR <input type="checkbox"/> ROUGH HANDLING <input type="checkbox"/> WEAR-OUT		35. UNKNOWN	
36. FAILURE TYPE <input type="checkbox"/> PRIMARY <input checked="" type="checkbox"/> INDUCED		<input type="checkbox"/> UNKNOWN <input checked="" type="checkbox"/> NO FAILURE		37. FAILURE CLASSIFICATION <input type="checkbox"/> CRITICAL <input type="checkbox"/> MAJOR <input checked="" type="checkbox"/> MINOR		<input type="checkbox"/> SAFETY		38. DEFECT CODE	
39. RESPONSIBLE ENGINEER U. Huber		ORG 51-11		DATE 11-13-81		39. SPACECRAFT SYSTEM ENGINEER W. J. Engel		ORG 22-4	
40. RELIABILITY		ORG 51-11		DATE 11-13-81		40. CUSTOMER OR SUPPLIER		DATE 11/17/81	

ORIGINAL PAGE IS
OF POOR QUALITY

SANTA BARBARA RESEARCH CENTER
A Subsidiary of Hughes Aircraft Company
INTERNAL MEMORANDUM

234/

TO: L. O'Connell

CC: See Distribution List

DATE: 20 November 1981

REF: HS 236-7743

REAE 81/64

FROM: A. Huber

SUBJECT: Subject: FR: S8341
(Band 1 Postamplifier Bd,
50904, Flt)

BLDG. B-11 MAIL STA. 102
EXT. 6246

FR: S8341, Dated October 26, 1981

The failure was encountered during retest of Band 1, Channel 15, after select resistors were removed from standoffs and placed directly onto the board. It was found that the pregain resistor R88(6.34K) and rolloff resistor R72 (24.3K) were interchanged. The resistors were subsequently removed and reinstalled in their proper locations. Figure 1 illustrates the postamplifier pregain and rolloff stages. In general no overstress will occur as a result of an interchange of pregain and postgain resistors. The postamplifier has been designed so that any intermediate amplifier stage can saturate without causing a condition of overstress.

Andrew E. Huber
A. Huber

AH: jc

HUGHESHUGHES AIRCRAFT COMPANY
SPACE AND COMMUNICATIONS GROUP
EL SEGUNDO, CALIFORNIAMAIN AHR
OP. No. 1900
SPACE AND COMMUNICATIONS GROUP
FAILURE REPORTORIGINAL PAGE IS
OF POOR QUALITY**S 8342**

ORIGINATOR	1. PROGRAM NAME AND NUMBER UO11 TM		2. GLA		3. MODEL FLIGHT		4. TIME OBSERVED FIRST SHOT		5. DATE OBSERVED MO 10 DA 24 YR 8	
	6. HARDWARE LEVEL WHEN FAILURE WAS OBSERVED <input type="checkbox"/> SPACECRAFT <input type="checkbox"/> SYSTEM		<input type="checkbox"/> SUBSYSTEM <input type="checkbox"/> UNIT		<input checked="" type="checkbox"/> ASSEMBLY <input type="checkbox"/> SUBASSEMBLY		<input type="checkbox"/> MODULE <input type="checkbox"/> MICAM		<input type="checkbox"/> CARD <input type="checkbox"/> PART	
	EQUIPMENT IDENTIFICATION:									
	7. SUBSYSTEM		NAME		PART NUMBER		S/N		MANUFACTURER	
	8. UNIT									
	9. <input checked="" type="checkbox"/> ASSEMBLY <input type="checkbox"/> SUBASSEMBLY				50795		201		SBRC	
	10. <input type="checkbox"/> MODULE <input type="checkbox"/> MICAM <input type="checkbox"/> CARD									
	11. OTHER									
	12. TEST WHEN FAILURE WAS OBSERVED <input type="checkbox"/> DEVELOPMENT <input type="checkbox"/> IN-PROCESS		<input type="checkbox"/> QUALIFICATION <input type="checkbox"/> ACCEPTANCE		<input type="checkbox"/> INTEGRATION <input type="checkbox"/> SYSTEM		<input type="checkbox"/> LAUNCH OPERATIONS			
	13. ENVIRONMENT WHEN FAILURE WAS OBSERVED <input checked="" type="checkbox"/> AMBIENT <input type="checkbox"/> EMC/RF		<input type="checkbox"/> RADIATION <input type="checkbox"/> VIBRATION		<input type="checkbox"/> TEMP AXIS FOR MIN TYPE		<input type="checkbox"/> THERMAL VAC HRS AT		<input type="checkbox"/> OTHER	
14. DESCRIPTION OF FAILURE BAND 4, CH. 16 WIDE BAND NOISE IS 2.8 PA SHOULD BE 2.4 PA										
ENGINEERING EVALUATION	15. TEST PROCEDURE 16597		16. ORIGINATOR C. R. Lane		17. CONTINUATION SHEET USED <input type="checkbox"/>		18. VERIFICATION AND FAILURE ANALYSIS di detector noise increased			
	19. FOLLOWING REWORK/RETEST REQUIRED <input checked="" type="checkbox"/> REWORK/RETEST NOT REQUIRED BECAUSE effective R/W-118		20. FAILED ITEM NAME AND PART NUMBER 50803							
	21. AUTHORIZATION [Signature]		22. CA REASON NONE - PROCEED WITH WAIVER W-118		23. CA RETEST					
	24. LIST ALL PARTS REPLACED PART NUMBER		CKT SYM		PART LOT NUMBER		DATE CODE		MANUFACTURER	
MANUFACTURING AND TEST	27. REWORK BY		ORG		DATE		28. RETESTED BY		ORG	
	29. CAUSE AND CORRECTIVE ACTION Cause of increase in di detector noise is unknown. Analysis indicates that the system level radiometric sensitivity requirements will still be met.									
	30. DOCUMENT IMPLEMENTING CORRECTIVE ACTION W-118 (COPY ATTACHED)									
	31. BASIC CAUSE OF VERIFIED FAILURE <input type="checkbox"/> DESIGN <input type="checkbox"/> ENVIRONMENTAL <input type="checkbox"/> DEFECTIVE PARTS		<input type="checkbox"/> TEST EQUIPMENT <input type="checkbox"/> TEST PROCEDURE <input type="checkbox"/> TEST SET-UP		<input type="checkbox"/> MFG. PROCEDURE <input type="checkbox"/> ASSY/FAB ERROR <input type="checkbox"/> WORKMANSHIP		<input type="checkbox"/> WIRING ERROR <input type="checkbox"/> ROUGH HANDLING <input type="checkbox"/> WEAR-OUT		32. UNKNOWN DEFECT CODE	
	33. FAILURE TYPE <input type="checkbox"/> PRIMARY <input checked="" type="checkbox"/> INDUCED		<input type="checkbox"/> UNKNOWN <input type="checkbox"/> NO FAILURE		34. FAILURE CLASSIFICATION <input type="checkbox"/> CRITICAL <input type="checkbox"/> MAJOR <input checked="" type="checkbox"/> MINOR		<input type="checkbox"/> SAFETY			
	35. RESPONSIBLE ENGINEER [Signature]		DATE 2/21/82		36. SPACECRAFT SYSTEM ENGINEER [Signature]		DATE 2/24/82			
	37. RELIABILITY 16597		DATE 2-23-82		38. CUSTOMER OR SUPPLIER SAIC		DATE			

Program Instruction 010

ORIGINAL PAGE IS
OF POOR QUALITY

REQUEST FOR DEVIATION/WAIVER
(SEE MIL-STD-460 OR 461 FOR INSTRUCTIONS)

DATE PREPARED

PROCURING ACTIVITY NO.

2/17/82

58342

1. ORIGINATOR NAME AND ADDRESS David M. Randall SBRC, 75 Coromar Dr, Goleta, Ca. 93117				2. <input type="checkbox"/> DEVIATION <input checked="" type="checkbox"/> WAIVER	
				3. <input checked="" type="checkbox"/> MINOR <input type="checkbox"/> MAJOR <input type="checkbox"/> CRITICAL	
4. DESIGNATION FOR DEVIATION/WAIVER				5. BASE LINE AFFECTED	
a. MODEL/TYPE F	b. MFR CODE 11323	c. SYS. DESIG. TM	d. DEV/WAIVER NO. W-118	<input checked="" type="checkbox"/> FUNCTIONAL <input type="checkbox"/> ALLOCATED <input type="checkbox"/> PHYS. UCT	
6. OTHER SYSTEMS/CONFIGURATIONS ITEMS AFFECTED				<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO	
7. SPECIFICATIONS AFFECTED-TEST PLAN				8. DRAWINGS AFFECTED	
a. SYSTEM b. ITEM c. TEST PLAN				a. MFR. CODE 11323 b. NUMBER 50795 c. REV. H d. DOR. NO. -	
9. TITLE OF DEVIATION/WAIVER Permission to use PFPA with Band 4 Ch 16 noise of 2.8 pA				10. CONTRACT NO. & LINE ITEM NAS 5-24200	
11. CONFIGURATION - NEW NOMENCLATURE Radiometer				12. CD NO. II	
13. NAME OF PART OR LATEST ASSEMBLY AFFECTED Band 4 Band Level Assy				14. DEFECT CLASSIFICATION <input checked="" type="checkbox"/> MINOR <input type="checkbox"/> MAJOR <input type="checkbox"/> CRITICAL	
15. PART NO. OR TYPE DESIGN 50797-E				16. LOT NO. 401	
17. QTY 1				18. RECEIVING DEVIATION/WAIVER <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO	
19. EFFECT ON COST/PRICE Greater than \$100,000-if not approved.				20. EFFECT ON DELIVERY SCHEDULE Eight weeks if not approved.	
21. EFFECT ON INTEGRATED LOGISTIC SUPPORT, INTERFACE, ETC. None					
22. DESCRIPTION OF DEVIATION/WAIVER Permission to use Flight PFPA with Band 4 Ch #16 noise of 2.8 pA. (Ref. FR 58342) Specification is < 2.4pA. Analysis indicates that the Radiometric sensitivity requirements will still be met at the systems level.					

14. NEED FOR DEVIATION/WAIVER

The alternative is to take the FPA Assy apart; take Band 4 apart and replace the detector. This operation is risky and since the reason the detector became noisy is unknown, there is no assurance that the replacement detector will perform any better or be more reliable.

2/17/82 REA <i>[Signature]</i> SYS ENGR <i>[Signature]</i>		RE <i>[Signature]</i> 2/17/82 QA <i>[Signature]</i> 2/18/82 PE <i>[Signature]</i> 2/18/82	
3. PRODUCTION EFFECTIVITY BY SERIAL NUMBER 003 51065 SN 003 ONLY		CMR <i>[Signature]</i> 3-8-82	
4. AUTHORITY AUTHORIZING SIGNATURE <i>[Signature]</i> 2/18/82		5. TITLE Minor - System Engineer Major/Critical - Program Manager	
6. APPROVAL, DISAPPROVAL <input type="checkbox"/> APPROVAL RECOMMENDED		<input checked="" type="checkbox"/> APPROVED <input type="checkbox"/> DISAPPROVED SIGNATURE <i>[Signature]</i> DATE 2/23/82	
7. GOVERNMENT ACTIVITY NASA GSFC		8. D. SEC 16 1694	

HUGHES

REF. AMR. 50904-1 OPERATION 1300

SPACE AND COMMUNICATIONS GROUP

FAILURE REPORT

S. 8441

1. HANDMADE (LEVEL NUMBER) PART NUMBER		2. GRA		3. MODEL		4. TIME OBSERVED		5. DATE OBSERVED	
TM PL1122				FLIGHT		2:51 p.m.		MO 11 DA 12 YR 8	
6. HANDMADE (LEVEL NUMBER) PART NUMBER WAS OBSERVED		7. SPARE PART SYSTEM		8. SUBSYSTEM		9. ASSEMBLY		10. MODULE	
		SYSTEM		SUBSYSTEM		ASSEMBLY		MODULE	
		SYSTEM		SUBSYSTEM		ASSEMBLY		MODULE	
EQUIPMENT IDENTIFICATION		NAME		PART NUMBER		S/N		MANUFACTURER	
1. SUBSYSTEM									
2. ASSEMBLY									
3. MODULE									
4. CARD									
5. OTHER									
12. TEST WORK FAILURE WAS OBSERVED		13. DEVELOPMENT		14. QUALIFICATION		15. INTEGRATION		16. LAUNCH OPERATIONS	
		IN PROCESS		ACCEPTANCE		SYSTEM			
17. ENVIRONMENTAL WORKING FAILURE WAS OBSERVED		18. AMOUNT		19. RADIATION		20. TEMP		21. THERMAL H/C	
		ENVIRONMENTAL		VIBRATION		AND FOR		NHS AT	
22. DISCUSSION OF FAILURE		SEE CONTINUATION SHEET (THREE ENTRIES.)							
23. PART NUMBER		24. PART NAME		25. PART NUMBER		26. PART NAME		27. PART NUMBER	
76597		46/4.8		N. C. DAVISON		2213		11/12/81	
28. CONTINUED SHEET USED		29. CONTINUED SHEET USED		30. CONTINUED SHEET USED		31. CONTINUED SHEET USED		32. CONTINUED SHEET USED	
33. FOLLOWING TESTS WERE PERFORMED		34. TEST RESULTS		35. TEST RESULTS		36. TEST RESULTS		37. TEST RESULTS	
TO DETERMINE CAUSE OF FAILURE		FAILURE WAS NOT REPRODUCED BECAUSE		FAILURE WAS NOT REPRODUCED BECAUSE		FAILURE WAS NOT REPRODUCED BECAUSE		FAILURE WAS NOT REPRODUCED BECAUSE	
		FAILURE WAS NOT REPRODUCED BECAUSE		FAILURE WAS NOT REPRODUCED BECAUSE		FAILURE WAS NOT REPRODUCED BECAUSE		FAILURE WAS NOT REPRODUCED BECAUSE	
38. PART NUMBER		39. PART NAME		40. PART NUMBER		41. PART NAME		42. PART NUMBER	
NONE									
43. PART NUMBER		44. PART NAME		45. PART NUMBER		46. PART NAME		47. PART NUMBER	
48. PART NUMBER		49. PART NAME		50. PART NUMBER		51. PART NAME		52. PART NUMBER	
53. PART NUMBER		54. PART NAME		55. PART NUMBER		56. PART NAME		57. PART NUMBER	
58. PART NUMBER		59. PART NAME		60. PART NUMBER		61. PART NAME		62. PART NUMBER	
63. PART NUMBER		64. PART NAME		65. PART NUMBER		66. PART NAME		67. PART NUMBER	
68. PART NUMBER		69. PART NAME		70. PART NUMBER		71. PART NAME		72. PART NUMBER	
73. PART NUMBER		74. PART NAME		75. PART NUMBER		76. PART NAME		77. PART NUMBER	
78. PART NUMBER		79. PART NAME		80. PART NUMBER		81. PART NAME		82. PART NUMBER	
83. PART NUMBER		84. PART NAME		85. PART NUMBER		86. PART NAME		87. PART NUMBER	
88. PART NUMBER		89. PART NAME		90. PART NUMBER		91. PART NAME		92. PART NUMBER	
93. PART NUMBER		94. PART NAME		95. PART NUMBER		96. PART NAME		97. PART NUMBER	
98. PART NUMBER		99. PART NAME		100. PART NUMBER		101. PART NAME		102. PART NUMBER	
103. PART NUMBER		104. PART NAME		105. PART NUMBER		106. PART NAME		107. PART NUMBER	
108. PART NUMBER		109. PART NAME		110. PART NUMBER		111. PART NAME		112. PART NUMBER	
113. PART NUMBER		114. PART NAME		115. PART NUMBER		116. PART NAME		117. PART NUMBER	
118. PART NUMBER		119. PART NAME		120. PART NUMBER		121. PART NAME		122. PART NUMBER	
123. PART NUMBER		124. PART NAME		125. PART NUMBER		126. PART NAME		127. PART NUMBER	
128. PART NUMBER		129. PART NAME		130. PART NUMBER		131. PART NAME		132. PART NUMBER	
133. PART NUMBER		134. PART NAME		135. PART NUMBER		136			

~~REF AIRR SOUTH / OPERATIONS CUBO, CUBO THERMISTOR 1500~~

ONE'S AIRCRAFT COMPANY

CONTINUATION SHEET

• SERIAL NO.

ADDITIONAL
CONTINUATION
SHEET(S) USE

74 PER PARAGRAPH 4.6 THE FOLLOWING CHANNELS WERE OUT OF SPEC FOR TRANSIENT RESPONSE SETTLING TIMES:

14 PER PARAGRAPH 4.6 THE FOLLOWING CHANNELS WERE OUT OF
SPEC FOR FREQUENCY RESPONSE AT THE FOLLOWING POINT

74. PER PARAGRAPH 4.3; CROSSTALK: CH. 2 AVERAGE - 3.0
OF NON-NEIGHBORS IS -59 dB; SHOULD BE
≤ -60 dB.

Program Identification 010

DATE PREPARED

ORIGINAL PAGE IS
OF POOR QUALITY

REQUEST FOR DEVIATION/WAIVER
(SEE 412-100-000-001 FOR INSTRUCTIONS)

PREPARING ACTIVITY NO.

1. REQUESTOR NAME AND ADDRESS David M. Randall SBRU, 75 Colorado Dr., Colton, Ca. 93117				2. DEVIATION <input type="checkbox"/> MINOR <input checked="" type="checkbox"/> MAJOR <input type="checkbox"/> CRITICAL	
3. BASE LINE AFFECTED				4. OTHER SYS (CH/COM/INT) AFFECTED	
5. MODEL TYPE F	6. WFR CODE 11323	7. SYL. DESIG. TN	8. DEVIATION NO. W-123	9. FUMG. TYPICAL <input type="checkbox"/>	10. ALLU. CATED <input type="checkbox"/>
11. SPECIFICATIONS AFFECTED-TEST PLAN				12. UNAWARING AFFECTED	
13. WFR CODE				14. MSGR	15. REV.
16. TEST PLAN				17. 11323	18. 50797
19. EFFECT ON COST/PRICE Greater than \$100.00-if not approved.				20. EFFECT ON DELIVERY SCHEDULE Six weeks	
21. EFFECT ON INTEGRATED LOGISTICS SUPPORT, MAINTENANCE, ETC. None				22. DESCRIPTION OF DEVIATION/WAIVER	

Band 1 has a number of channels with transient/frequency response discrepancies as defined by FR 8440. Attached is a copy of FR 8440 and transient response plots for all channels. Channel two has average crosstalk between non-neighbors of -59dB vs a specification of <-60dB.

23. NEED FOR DEVIATION/WAIVER

Band 1 has been bonded into the FPA Assy and discrepancies are not considered significant enough to warrant rework on a cost/schedule impact basis.

24. REQUESTOR SIGNATURE <i>David M. Randall</i>	25. DATE 11/20/81	26. SYS ENGR <i>John L. Brown</i>	27. QA <i>John L. Brown</i>	28. PS <i>John L. Brown</i>
29. PREPARING ACTIVITY NO. 003				
30. 51065 SERVO CO'S ONLY				
31. SIGNATURE <i>John L. Brown</i>		32. DATE 11/23/81		
33. APPROVAL, DISAPPROVED <input type="checkbox"/>		34. APPROVED <input checked="" type="checkbox"/>		
35. DATE 11/23/81		36. DATE 12/17/81		

DD FORM 1694

REQUEST FOR DEVIATION/WAIVER
(SEE MIL-STD-480 OR 481 FOR INSTRUCTIONS)

DATE PREPARED

3-18-82

ORIGINAL PAGE IS
OF POOR QUALITY

PROPOSED ACTIVITY NO.

1. ORIGINATOR NAME AND ADDRESS David M. Randall SBRC, 75 Coromar Dr., Goleta, Ca. 93117				2. <input checked="" type="checkbox"/> DEVIATION <input type="checkbox"/> WAIVER			
				3. <input checked="" type="checkbox"/> MINOR <input type="checkbox"/> MAJOR <input type="checkbox"/> CRITICAL			
4. DESIGNATION FOR DEVIATION/WAIVER				5. BASE LINE AFFECTED			
6. MODEL/TYPE S	7. MFR. CODE 11323	8. SYS. DESIG. TM	9. DEV/WAIVER NO. D-142	<input checked="" type="checkbox"/> FUNCTIONAL	<input type="checkbox"/> ALLO. CATED	<input type="checkbox"/> PROD. UCT	10. OTHER SYSTEMS/CONFIGURATION ITEMS AFFECTED <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO
7. SPECIFICATIONS AFFECTED-TEST PLAN				8. DRAWINGS AFFECTED			
MFR. CODE				MFR. CODE			
SPEC. / CDC. NO.				NUMBER			
SCN				REV.			
6. SYSTEM				NON. NO.			
7. ITEM				11323			
8. TEST PLAN				50797			
				E			
9. TITLE OF DEVIATION/WAIVER Permission to use Ag Epoxy Bonds				12. CONTRACT INT. & LINE ITEM NAS 5-24200			
11. CONFIGURATION ITEM NOMENCLATURE Radiometer				13. DEFECT NO.			
				II			
15. NAME OF PART OR LONEST ASSEMBLY AFFECTED Short Band Level Assy				16. PART NO. OR TYPE DESIG. 50797			
17. LOT NO. 501				18. QTY 1			
19. RECURRING DEVIATION/WAIVER <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO							
20. EFFECT ON COST/PRICE Greater than \$100,000 if not approved.				21. EFFECT ON DELIVERY SCHEDULE Three to Four months if not approved.			
22. EFFECT ON INTEGRATED LOGISTIC SUPPORT, INTERFACE, ETC. None							
23. DESCRIPTION OF DEVIATION/WAIVER							

This deviation requests permission to use Ag epoxy to make the electrical connection on alignment channel A and channels 5, 7 & 15 without making a thermal compression bond first. The bonding area is chipped away on the alignment channel and 5, 7 & 15 have Ag epoxy on their bonding pads which precludes the making of a T.C. bond.

24. NEED FOR DEVIATION/WAIVER

We do not have another basic halfband to replace the present one with the discrepant bonding areas. To rework this halfband or to build another halfband is not considered cost or schedule effective.

25. PRODUCTION EFFECTIVITY BY SERIAL NUMBER

Spare

26. SUBMITTING OFFICE AUTHORIZING SIGNATURE

J. H. Engel 3/18/82

27. APPROVAL/DISAPPROVAL

☐ APPROVAL RECOMMENDED

☒ APPROVED

☐ DISAPPROVED

28. GOVERNMENT ACTIVITY

NASA GSFC

SIGNATURE

E. B. Smith

DATE

3/19/82

DD FORM 1694

Carol W. Smith

8-11-7

SANTA BARBARA RESEARCH CENTER

A Subsidiary of Hughes Aircraft Company

INTERNAL MEMORANDUM

TO: L. O'Connell

CC: W.D. Adams
L. Altman
G. Gritt
D. Randall
T. Sciacca

DATE: 19 March 1982

REF: HS 236-7901

PE 62:82

FROM: A. Perline


SUBJECT: Use of Silver Epoxy for
Electrical Connections
(Ref. Deviation D-142)

BLDG. B-11 MAIL STA. 39
EXT. 6106

The undersigned has completed a review of the use of silver epoxy for electrical connections on the spare silicon detector and preamplifier assembly (P/N 50797).

The results are as follows:

1. The bonding will be performed in accordance with SP 80141. Paragraph 6.1 specifies intended use is to achieve electrical conductivity between electrically conductive parts.
2. This bond will be used on three leads only.
3. The wire is 0.001 in diameter and has a loop height of 0.010 in max. The inertia of this loop is extremely small and will pose no problems in vibration. This problem was reviewed at the time of replacement of platinum wires with gold in the CFPA.


A. Perline, Reliability Engineer
Thematic Mapper Program

AP:jc

ORIGINAL PAGE IS
OF POOR QUALITY

ORIGINAL PAGE IS
OF POOR QUALITY

REQUEST FOR DEVIATION/WAIVER
(SEE MIL-STD-480 OR 481 FOR INSTRUCTIONS)

DATE PREPARED

PROCURING ACTIVITY NO.

1. ORIGINATOR NAME AND ADDRESS Don C. Campbell SBRC, 75 Coromar Dr., Goleta CA 93117				2. <input checked="" type="checkbox"/> DEVIATION <input type="checkbox"/> WAIVER	
				3. <input checked="" type="checkbox"/> MINOR <input type="checkbox"/> MAJOR <input type="checkbox"/> CRITICAL	
4. DESIGNATION FOR DEVIATION/WAIVER				5. BASE LINE AFFECTED	
a. MODEL/TYPE FLT	b. MFR. CODE 11323	c. SYS. DESIG. TM	d. DEV/WAIVER NO. D-128	<input type="checkbox"/> FUNC-TIONAL <input type="checkbox"/> ALLO-CATED <input type="checkbox"/> PROD-UCT	6. OTHER SYSTEMS/CONFIGURATION ITEMS AFFECTED <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO
7. SPECIFICATIONS AFFECTED-TEST PLAN				8. DRAWINGS AFFECTED	
a. SYSTEM 11323	b. MFR. CODE SP80057	c. SPEC./DOC. NO. D	d. SCH 11323	e. MFR. CODE 50797	f. REV. E
9. TEST PLAN				10. CONTRACT NO. & LINE ITEM HAS 5-24200	
11. TITLE OF DEVIATION/WAIVER AUTHORIZATION TO MODIFY WIRE BOND CONNECTION				12. CD NO. II	
13. CONFIGURATION ITEM NOMENCLATURE PRIME FOCAL PLANE DETECTOR ARRAY				14. DEFECT NO. 1	
15. NAME OF PART OR LARGEST ASSEMBLY AFFECTED SILICON DETECTOR				16. DEFECT CLASSIFICATION <input checked="" type="checkbox"/> MINOR <input type="checkbox"/> MAJOR <input type="checkbox"/> CRITICAL	
17. PART NO. OR TYPE DESIG. 50803-G				18. LOT NO. 1	
19. QTY 1				20. RECURRING DEVIATION/WAIVER <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO	
21. EFFECT ON COST/PRICE \$20,000				22. EFFECT ON DELIVERY SCHEDULE 2 Weeks	
23. EFFECT ON INTEGRATED LOGISTIC SUPPORT, INTERFACE, ETC. NONE					
24. DESCRIPTION OF DEVIATION/WAIVER THIS DEVIATION REQUESTS PERMISSION TO DISCONNECT SILICON DETECTOR, CHANNEL #9 DETECTOR LEAD AT THE DETECTOR LEAD TO DETECTOR SUBSTRATE CONNECTION OF #50797 BAND 3 S/N 401. TEST FOR WIDEBAND NOISE CHARACTERISTICS (DETECTOR OUT OF CIRCUIT), RECONNECT CHANNEL 9 DETECTOR LEAD AND USING STEVEN C. CA... AT THE ELECTRICAL WIRE BOND SITE					

24. NEED FOR DEVIATION/WAIVER

NOISE MEASUREMENTS MADE ON CHANNEL 9 OF #50797 BAND 3 S/N 401 INDICATED A POTENTIAL EXCESS NOISE CONDITION WHICH COULD AFFECT FINAL SYSTEM PERFORMANCE. THIS ACTION IS NECESSARY TO ACCURATELY DETERMINE THE SOURCE OF NOISE AND ITS EFFECT ON FOCAL PLANE PERFORMANCE.

REA

SYS ENG

R.E. *[Signature]*

D.E.

P.E. *[Signature]* 15 Oct 81

C-ED *[Signature]* 10-20-81

25. PRODUCTION EFFECTIVITY BY SERIAL NUMBER

51065 SERNO 003 ONLY

26. SUBMITTING ACTIVITY AUTHORIZING SIGNATURE

27. APPROVAL/DISAPPROVAL

a. <input type="checkbox"/> APPROVAL RECOMMENDED	b. <input checked="" type="checkbox"/> APPROVED <input type="checkbox"/> DISAPPROVED
c. GOVERNMENT ACTIVITY	d. SIGNATURE <i>[Signature]</i> DATE <i>[Signature]</i>

DD FORM 1694 Engineering Reliability Quality Production Test

Program Instruction 010

ORIGINAL PAGE 11
OF POOR QUALITY

REQUEST FOR DEVIATION/WAIVER
(SEE MIL-STD-460 OR 461 FOR INSTRUCTIONS)

DATE PREPARED
10/19/81

PROCURING ACTIVITY NO.

1. ORIGINATOR NAME AND ADDRESS SBRC, 75 Coromar Dr. Goleta, Ca. 93117				2. <input type="checkbox"/> DEVIATION <input checked="" type="checkbox"/> WAIVER			
				3. <input checked="" type="checkbox"/> MINOR <input type="checkbox"/> MAJOR <input type="checkbox"/> CRITICAL			
4. DESIGNATION FOR DEVIATION/WAIVER				5. BASE LINE AFFECTED			
6. MODEL TYPE F	7. MFR. CODE 11323	8. SYS. DESIG. W-112	9. DEV/WAIVER NO.	<input type="checkbox"/> FUNC. TIONAL	<input type="checkbox"/> ALLO- CATED	<input type="checkbox"/> PROD- UCT	10. OTHER SYSTEMS/CONFIG- URATION ITEMS AFFECTED
				11. YES <input type="checkbox"/> NO <input type="checkbox"/>			
12. SPECIFICATIONS AFFECTED-TEST PLAN				13. DRAWINGS AFFECTED			
MFR. CODE SPEC./DOC. NO. SN				MFR. CODE NUMBER REV. MOD. NO.			
				11323 50795 H -			
14. SYSTEM							
15. ITEM							
16. TEST PLAN							
17. TITLE OF DEVIATION/WAIVER Permission to continue thru FPA assy 50795 with Band 3 Ch 9 Wide Band Noise of 2.9 pA.				18. CONTRACT NO. & LINE ITEM NAS 5-24200			
19. CONFIGURATION ITEM IDENTIFICATION Radiometer				20. IDENTIFICATION OF DEFECT			
				21. CD NO. II	22. DEFECT NO.	23. DEFECT CLASSIFICATION	
						<input checked="" type="checkbox"/> MINOR <input type="checkbox"/> MAJOR <input type="checkbox"/> CRITICAL	
24. NAME OF PART OR LOWEST ASSEMBLY AFFECTED Band 3 Band Level Assy				25. PART NO. OR TYPE DESIGN 50797-E	26. LOT NO. 401	27. QTY 1	28. RECURRING DEVIATION/WAIVER
							<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO
29. EFFECT ON COST/PRICE \$45,000 if not approved				30. EFFECT ON DELIVERY SCHEDULE Two weeks if not approved.			
31. EFFECT ON INTEGRATED LOGISTIC SUPPORT, INTERFAC, ETC. None							
32. DESCRIPTION OF DEVIATION/WAIVER This waiver requests permission to reconnect detector lead Band 3 Ch #9 via silver epoxy, test and assemble into F-1 PFFA assy 50795 with Ch 9 wide band noise of 2.9 pA.							

33. NEED FOR DEVIATION/WAIVER

The alternative is to take the band level assy apart and replace the detector array. This operation is risky and since the reason the detector became noisy is unknown, there is no assurance that replacing the detector will result in better performance or reliability

34. REQUESTED BY D.M. Randall 10/19/81	35. SYSTEMS ENGINEER J.L. Engel	36. QUALITY ASSURANCE R. T. Williams 10/19/81
37. PRODUCTION EFFECTIVITY BY SERIAL NUMBER 003 51065 SN 003 ONLY	38. CMO B. D. Dore	
39. SIGNATURE J.L. Engel 10/10/81	40. SIGNATURE B. D. Dore	
41. APPROVAL, DISAPPROVAL		
42. <input type="checkbox"/> APPROVAL RECOMMENDED <input checked="" type="checkbox"/> APPROVED <input type="checkbox"/> DISAPPROVED		
43. GOVERNMENT ACTIVITY NASA GSFC		
44. SIGNATURE George B. Kirt 10/20/81		
45. DD FORM 1694		

ORIGINAL PAGE IS
OF POOR QUALITY

ORIGINAL PAGE IS
OF POOR QUALITY

HUGHES

INTERDEPARTMENTAL CORRESPONDENCE

TO: R. J. Wilberzon
CRG: 51-41
SUBJECT: Bonding of Gold Wire

CC: E. C. Long
J. M. Keffer
L. O'Connell

DATE: 15 October 1981
REF: 7621-21/276

FROM: K. M. Boyle
ORG: 76-21-27

ELC: 3767 MAIL STA: R1
LOC: EQ EXT: 52

A recent problem when bonding a 1 mil gold wire to gold plated quartz has resulted in an electrically noisy bond joint. It has been suggested that the silver-filled epoxy used in accordance with SM 80140 be mechanically removed and fresh epoxy applied to form a better bond. Because of the small surface area involved and the thinness of the wire, it would be difficult to completely remove all of the cured epoxy. Questions arose as to the integrity of such a secondary bond on top of a cured adhesive.

In this instance, there should be no problems with this bonded joint. The only load on the wire is its weight. The bondline will be mainly an epoxy/epoxy coupling as opposed to an optimum epoxy/gold bond. However, this mechanical bond should be adequate for this application.

There may be some degradation in the thermal transfer capabilities, but it is doubtful that it could be measured. This repair procedure is strictly recommended for this problem and should not be used in general practice.

K.M. Boyle
K. M. Boyle

J. T. Chou
J. T. Chou, Head
Adhesives and Dielectrics Section

/cs

Program Instruction 010

DATE PREPARED

PROCURING ACTIVITY NO.13. DESCRIPTION OF DEVIATION/WAIVER

4. NEED FOR DEVIATION #41VER

25. PRODUCTION EFFECTIVITY BY SERIAL NUMBER

003 51065 SV 003 è SUBG

100-443887-100

L. C. ... 10/28/31

Minor - System Engineering
Major/Critical - Program Manager

17 APPROVAL 215 APPROVAL

☐ APPROVAL RECOMMENDED

☒ APPROVED ☐ DISAPPROVED

6-20185451-4121-9

NAJZ GJEL

DD FORM 1624

1968

ORIGINAL PAGE IS
OF POOR QUALITY

Program Instruction 0100

REWORK FOR DISCREPANCY

DATE RECEIVED
11-19-81

REWORKING TIME: 12-17-81

1. ORIGINATOR'S NAME AND ADDRESS SHRC, 75 Commerce Drive, Colton, Ca. 93117				2. <input type="checkbox"/> DEVIATION <input checked="" type="checkbox"/> WAIVER	
3. <input type="checkbox"/> MINOR <input checked="" type="checkbox"/> MAJOR <input type="checkbox"/> CRITICAL				4. <input type="checkbox"/> OTHER SYSTEMS/COMPONENTS AFFECTED	
5. MODEL NAME F 11323		6. SYS. DESIG. FM		7. DEVICED NO. W-115	
8. BASE LINE AFFECTED		9. <input checked="" type="checkbox"/> CABLE AFFECTED <input type="checkbox"/> CABLE AFFECTED		10. <input type="checkbox"/> PROD. UCT. <input type="checkbox"/> YES <input type="checkbox"/> NO	
11. <input type="checkbox"/> TEST PLAN		12. <input type="checkbox"/> TEST PLAN		13. <input type="checkbox"/> TEST PLAN	
14. <input type="checkbox"/> TEST PLAN		15. <input type="checkbox"/> TEST PLAN		16. <input type="checkbox"/> TEST PLAN	
17. <input type="checkbox"/> TEST PLAN		18. <input type="checkbox"/> TEST PLAN		19. <input type="checkbox"/> TEST PLAN	
20. <input type="checkbox"/> TEST PLAN		21. <input type="checkbox"/> TEST PLAN		22. <input type="checkbox"/> TEST PLAN	
23. <input type="checkbox"/> TEST PLAN		24. <input type="checkbox"/> TEST PLAN		25. <input type="checkbox"/> TEST PLAN	
26. <input type="checkbox"/> TEST PLAN		27. <input type="checkbox"/> TEST PLAN		28. <input type="checkbox"/> TEST PLAN	
29. <input type="checkbox"/> TEST PLAN		30. <input type="checkbox"/> TEST PLAN		31. <input type="checkbox"/> TEST PLAN	
32. <input type="checkbox"/> TEST PLAN		33. <input type="checkbox"/> TEST PLAN		34. <input type="checkbox"/> TEST PLAN	
35. <input type="checkbox"/> TEST PLAN		36. <input type="checkbox"/> TEST PLAN		37. <input type="checkbox"/> TEST PLAN	
38. <input type="checkbox"/> TEST PLAN		39. <input type="checkbox"/> TEST PLAN		40. <input type="checkbox"/> TEST PLAN	
41. <input type="checkbox"/> TEST PLAN		42. <input type="checkbox"/> TEST PLAN		43. <input type="checkbox"/> TEST PLAN	
44. <input type="checkbox"/> TEST PLAN		45. <input type="checkbox"/> TEST PLAN		46. <input type="checkbox"/> TEST PLAN	
47. <input type="checkbox"/> TEST PLAN		48. <input type="checkbox"/> TEST PLAN		49. <input type="checkbox"/> TEST PLAN	
50. <input type="checkbox"/> TEST PLAN		51. <input type="checkbox"/> TEST PLAN		52. <input type="checkbox"/> TEST PLAN	
53. <input type="checkbox"/> TEST PLAN		54. <input type="checkbox"/> TEST PLAN		55. <input type="checkbox"/> TEST PLAN	
56. <input type="checkbox"/> TEST PLAN		57. <input type="checkbox"/> TEST PLAN		58. <input type="checkbox"/> TEST PLAN	
59. <input type="checkbox"/> TEST PLAN		60. <input type="checkbox"/> TEST PLAN		61. <input type="checkbox"/> TEST PLAN	
62. <input type="checkbox"/> TEST PLAN		63. <input type="checkbox"/> TEST PLAN		64. <input type="checkbox"/> TEST PLAN	
65. <input type="checkbox"/> TEST PLAN		66. <input type="checkbox"/> TEST PLAN		67. <input type="checkbox"/> TEST PLAN	
68. <input type="checkbox"/> TEST PLAN		69. <input type="checkbox"/> TEST PLAN		70. <input type="checkbox"/> TEST PLAN	
71. <input type="checkbox"/> TEST PLAN		72. <input type="checkbox"/> TEST PLAN		73. <input type="checkbox"/> TEST PLAN	
74. <input type="checkbox"/> TEST PLAN		75. <input type="checkbox"/> TEST PLAN		76. <input type="checkbox"/> TEST PLAN	
77. <input type="checkbox"/> TEST PLAN		78. <input type="checkbox"/> TEST PLAN		79. <input type="checkbox"/> TEST PLAN	
80. <input type="checkbox"/> TEST PLAN		81. <input type="checkbox"/> TEST PLAN		82. <input type="checkbox"/> TEST PLAN	
83. <input type="checkbox"/> TEST PLAN		84. <input type="checkbox"/> TEST PLAN		85. <input type="checkbox"/> TEST PLAN	
86. <input type="checkbox"/> TEST PLAN		87. <input type="checkbox"/> TEST PLAN		88. <input type="checkbox"/> TEST PLAN	
89. <input type="checkbox"/> TEST PLAN		90. <input type="checkbox"/> TEST PLAN		91. <input type="checkbox"/> TEST PLAN	
92. <input type="checkbox"/> TEST PLAN		93. <input type="checkbox"/> TEST PLAN		94. <input type="checkbox"/> TEST PLAN	
95. <input type="checkbox"/> TEST PLAN		96. <input type="checkbox"/> TEST PLAN		97. <input type="checkbox"/> TEST PLAN	
98. <input type="checkbox"/> TEST PLAN		99. <input type="checkbox"/> TEST PLAN		100. <input type="checkbox"/> TEST PLAN	

Permission to use Band 2 Band Level Assy SN 401

NAS 5-24200

11. <input type="checkbox"/> RADIOMETER		12. <input type="checkbox"/> BAND LEVEL ASSY		13. <input type="checkbox"/> BAND LEVEL ASSY	
14. <input type="checkbox"/> BAND LEVEL ASSY		15. <input type="checkbox"/> BAND LEVEL ASSY		16. <input type="checkbox"/> BAND LEVEL ASSY	
17. <input type="checkbox"/> BAND LEVEL ASSY		18. <input type="checkbox"/> BAND LEVEL ASSY		19. <input type="checkbox"/> BAND LEVEL ASSY	
20. <input type="checkbox"/> BAND LEVEL ASSY		21. <input type="checkbox"/> BAND LEVEL ASSY		22. <input type="checkbox"/> BAND LEVEL ASSY	
23. <input type="checkbox"/> BAND LEVEL ASSY		24. <input type="checkbox"/> BAND LEVEL ASSY		25. <input type="checkbox"/> BAND LEVEL ASSY	
26. <input type="checkbox"/> BAND LEVEL ASSY		27. <input type="checkbox"/> BAND LEVEL ASSY		28. <input type="checkbox"/> BAND LEVEL ASSY	
29. <input type="checkbox"/> BAND LEVEL ASSY		30. <input type="checkbox"/> BAND LEVEL ASSY		31. <input type="checkbox"/> BAND LEVEL ASSY	
32. <input type="checkbox"/> BAND LEVEL ASSY		33. <input type="checkbox"/> BAND LEVEL ASSY		34. <input type="checkbox"/> BAND LEVEL ASSY	
35. <input type="checkbox"/> BAND LEVEL ASSY		36. <input type="checkbox"/> BAND LEVEL ASSY		37. <input type="checkbox"/> BAND LEVEL ASSY	
38. <input type="checkbox"/> BAND LEVEL ASSY		39. <input type="checkbox"/> BAND LEVEL ASSY		40. <input type="checkbox"/> BAND LEVEL ASSY	
41. <input type="checkbox"/> BAND LEVEL ASSY		42. <input type="checkbox"/> BAND LEVEL ASSY		43. <input type="checkbox"/> BAND LEVEL ASSY	
44. <input type="checkbox"/> BAND LEVEL ASSY		45. <input type="checkbox"/> BAND LEVEL ASSY		46. <input type="checkbox"/> BAND LEVEL ASSY	
47. <input type="checkbox"/> BAND LEVEL ASSY		48. <input type="checkbox"/> BAND LEVEL ASSY		49. <input type="checkbox"/> BAND LEVEL ASSY	
50. <input type="checkbox"/> BAND LEVEL ASSY		51. <input type="checkbox"/> BAND LEVEL ASSY		52. <input type="checkbox"/> BAND LEVEL ASSY	
53. <input type="checkbox"/> BAND LEVEL ASSY		54. <input type="checkbox"/> BAND LEVEL ASSY		55. <input type="checkbox"/> BAND LEVEL ASSY	
56. <input type="checkbox"/> BAND LEVEL ASSY		57. <input type="checkbox"/> BAND LEVEL ASSY		58. <input type="checkbox"/> BAND LEVEL ASSY	
59. <input type="checkbox"/> BAND LEVEL ASSY		60. <input type="checkbox"/> BAND LEVEL ASSY		61. <input type="checkbox"/> BAND LEVEL ASSY	
62. <input type="checkbox"/> BAND LEVEL ASSY		63. <input type="checkbox"/> BAND LEVEL ASSY		64. <input type="checkbox"/> BAND LEVEL ASSY	
65. <input type="checkbox"/> BAND LEVEL ASSY		66. <input type="checkbox"/> BAND LEVEL ASSY		67. <input type="checkbox"/> BAND LEVEL ASSY	
68. <input type="checkbox"/> BAND LEVEL ASSY		69. <input type="checkbox"/> BAND LEVEL ASSY		70. <input type="checkbox"/> BAND LEVEL ASSY	
71. <input type="checkbox"/> BAND LEVEL ASSY		72. <input type="checkbox"/> BAND LEVEL ASSY		73. <input type="checkbox"/> BAND LEVEL ASSY	
74. <input type="checkbox"/> BAND LEVEL ASSY		75. <input type="checkbox"/> BAND LEVEL ASSY		76. <input type="checkbox"/> BAND LEVEL ASSY	
77. <input type="checkbox"/> BAND LEVEL ASSY		78. <input type="checkbox"/> BAND LEVEL ASSY		79. <input type="checkbox"/> BAND LEVEL ASSY	
80. <input type="checkbox"/> BAND LEVEL ASSY		81. <input type="checkbox"/> BAND LEVEL ASSY		82. <input type="checkbox"/> BAND LEVEL ASSY	
83. <input type="checkbox"/> BAND LEVEL ASSY		84. <input type="checkbox"/> BAND LEVEL ASSY		85. <input type="checkbox"/> BAND LEVEL ASSY	
86. <input type="checkbox"/> BAND LEVEL ASSY		87. <input type="checkbox"/> BAND LEVEL ASSY		88. <input type="checkbox"/> BAND LEVEL ASSY	
89. <input type="checkbox"/> BAND LEVEL ASSY		90. <input type="checkbox"/> BAND LEVEL ASSY		91. <input type="checkbox"/> BAND LEVEL ASSY	
92. <input type="checkbox"/> BAND LEVEL ASSY		93. <input type="checkbox"/> BAND LEVEL ASSY		94. <input type="checkbox"/> BAND LEVEL ASSY	
95. <input type="checkbox"/> BAND LEVEL ASSY		96. <input type="checkbox"/> BAND LEVEL ASSY		97. <input type="checkbox"/> BAND LEVEL ASSY	
98. <input type="checkbox"/> BAND LEVEL ASSY		99. <input type="checkbox"/> BAND LEVEL ASSY		100. <input type="checkbox"/> BAND LEVEL ASSY	

Permission to use Band 2 Band Level Assy SN 401 with Ch 1, 5, 9 & 13 not meeting frequency response of $\geq -30dB$ @ 52KHz ($-3.1dB$, $-3.05dB$ & $-3.06dB$ respectively); Ch 5, 7 & 9 have non-neighbor crosstalk of $-59dB$, $-59dB$ & $-58dB$ respectively vs a spec of $-60dB$; and Ch 2, 6, 7, 8, 9, 11, 12 & 13 do not meet settling time requirements. Copy of FR 8324 attached.

2A. NEED FOR DEVIATION/WAIVER

The rework required to correct the discrepancies noted above is not considered cost or schedule effective.

RE: <i>[Signature]</i> 11/18/81	
QA: <i>[Signature]</i> 11/18/81	
PE: <i>[Signature]</i> 11/18/81	
11/18/81	
Minor - System Engineering Major/Critical - Program Manager	
12.17.81	
DD 1694	

ORIGINAL PAGE IS
OF POOR QUALITY

Program Instruction 018

458

REQUEST FOR DEVIATION/WAIVER
(SEE MIL-STD-883C OR JST FOR INSTRUCTIONS)

DATE PREPARED

11-10-81

PROCURING ACTIVITY NO.

ORIGINATOR NAME AND ADDRESS David M. Randall

SDRC, 75 Coronar Dr. Colton, Ca. 93117

1. ☐ DEVIATION ☒ WAIVER
2. ☐ MINOR ☒ MAJOR ☐ CRITICAL

DESIGNATION FOR DEVIATION/WAIVER

1. SPEC. NO. 11323 2. SYS. SPEC. TM 3. INFORMATION NO. W-117

4. DATE TIME AFFECTED

☒ PLANNED ☐ UNPLANNED ☐ UNPLANNED

5. OTHER SYSTEMS/COMPONENTS AFFECTED
☐ YES ☒ NO

6. SPECIFICATION AFFECTED TEST PLAN

7. SYSTEM

8. ITEM

9. TEST PLAN

10. DRAWINGS AFFECTED

11. DRAWING NO. 11323 12. DRAWING REV. 50797

13. DRAWING REV. E

14. DRAWING REV. -

15. TITLE OF DEVIATION/WAIVER

Permission to use Band 4 Band Level Assy SN 201

16. CONTRACT NO. & LINE ITEM

NAS 5-24200

17. COMPENSATION FROM GOVERNMENT USE

Radiometer

18. CO. NO.

II

19. EFFECT NO.

1

20. EFFECT CLASSIFICATION

☒ MINOR ☐ MAJOR ☐ CRITICAL

21. NAME OF USER OF DEVIATION/WAIVER

Band Level Assy

22. PART NO. OR TYPE DESIGN

50797

23. DATE TIME AFFECTED

201

24. EFFECT NO.

1

25. EFFECT CLASSIFICATION

☐ YES ☒ NO

26. EFFECT ON COST/PRICE

Greater than \$100,000-if not approved.

27. EFFECT ON DELIVERY SCHEDULE

Three to four months if not approved.

28. EFFECT ON INTEGRATED LOGISTIC SUPPORT, INTERFACE, ETC.

NONE

29. DESCRIPTION OF DEVIATION/WAIVER

Permission to use Band 4 Band Level Assy SN 201 with Channels 5, 13, 14 15 & 16 exceeding transient response settling time specification, and Channels 1, 5, 9, 13 & 15 have -58dB crosstalk vs a specification of -60dB.

Channel	30µs	60µs	1% by
5	2.0%	1.0%	60µs
13	2.0	2.0	90µs
14	2.0	.8	50µs
15	2.0	.5	33µs
16	1.0	0	32µs

30. NEED FOR DEVIATION/WAIVER

The rework required to correct the discrepancies noted above is not considered cost or schedule effective.

REA *David M. Randall* SYS ENGR *J. L. Cengel*

PE *David M. Randall* 11/10/81
QA *David M. Randall* 11/10/81
PE *David M. Randall* 11/10/81

31. NUMBER OF EFFECTS OF DEVIATION/WAIVER

003

32. NAME OF USER OF DEVIATION/WAIVER

David M. Randall 11/16/81

Minor - System Engineering
Major/Critical - Program Manager

33. APPROVAL RECOMMENDED

☒ APPROVED

☐ DISAPPROVED

34. APPROVAL DATE

SIGNATURE

David M. Randall 12-17-81

DD FORM 1694

ORIGINAL PAGE IS
OF POOR QUALITY

Program Instruction 310

REQUEST FOR DEVIATION/VALUER
SEE VIL 310-10 OR 310-11 FOR INSTRUCTIONS

DATE PREPARED

PROCESSING ACTIVITY

1. ORIGINATOR NAME AND ADDRESS David M. Randall S2RC, 75 Coronar Dr., Coleta, Ca. 93117				2. <input type="checkbox"/> DEVIATION <input checked="" type="checkbox"/> DRIVER	
3. <input type="checkbox"/> MINOR <input checked="" type="checkbox"/> MAJOR <input type="checkbox"/> CRITIC				4. <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO	
5. DESCRIPTION FOR DEV. AT ON-VALUER F 11323 TM W-119		6. BASE LINE AFFECTED <input checked="" type="checkbox"/> PLUMB <input type="checkbox"/> ALLO-CATED <input type="checkbox"/> P400- VIBRAL		7. OTHER SYSTEMS/COMP- PARTS ITEMS AFFECTED <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO	
8. TEST PLAN		9. DRAWINGS AFFECTED		10. CONTRACT NO. & LINE	
MFR. CODE		MFR. CODE		REV.	
SPEC. DOC. NO.		NUMBER		HQR. NO.	
11323		51015		D 2950-A	
11. TITLE OF DEV. AFFECTED Permission to use Halfband SN 207-1				12. CONTRACT NO. & LINE NAS 5-24200	
13. DESCRIPTION OF DEV. AFFECTED Radiometer				14. EFFECT CLASSIFICATION <input type="checkbox"/> MINOR <input checked="" type="checkbox"/> MAJOR <input type="checkbox"/> CRITIC	
15. NAME OF DEV. OR ASSY. AFFECTED 51015				16. PART NO. OR DEV. 207-1	
17. EFFECT ON DELIVERY SCHEDULE Greater than 1200.00 if not approved				18. RECORDING DEVIATION/VALUER <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO	
19. EFFECT ON INTEGRATED LOGISTIC SUPPORT, INTERFACES, ETC. None				20. EFFECT ON DELIVERY SCHEDULE Greater than 4 months if not approved.	
21. DESCRIPTION OF DEVIATION/VALUER Permission to use Halfband SN 207-1 with transient response meeting to 1.25% by 60 usec on channel 1 vs a specification of $\pm 1.0\%$ by 60 usec.					

22. REASON FOR DEVIATION/VALUER

This unit had been rework a number of times and this was the best result.
Halfband has since been assembled into Band 2 Band Level Assy. Rework at
this time is not considered cost or schedule effective.

23. APPROVAL/RECOMMENDATION BY SERIAL NUMBER 003		24. APPROVAL/RECOMMENDATION BY SERIAL NUMBER 003	
25. APPROVAL/RECOMMENDATION BY SERIAL NUMBER 003		26. APPROVAL/RECOMMENDATION BY SERIAL NUMBER 003	
27. APPROVAL/RECOMMENDATION BY SERIAL NUMBER 003		28. APPROVAL/RECOMMENDATION BY SERIAL NUMBER 003	
29. APPROVAL/RECOMMENDATION BY SERIAL NUMBER 003		30. APPROVAL/RECOMMENDATION BY SERIAL NUMBER 003	
31. APPROVAL/RECOMMENDATION BY SERIAL NUMBER 003		32. APPROVAL/RECOMMENDATION BY SERIAL NUMBER 003	
33. APPROVAL/RECOMMENDATION BY SERIAL NUMBER 003		34. APPROVAL/RECOMMENDATION BY SERIAL NUMBER 003	
35. APPROVAL/RECOMMENDATION BY SERIAL NUMBER 003		36. APPROVAL/RECOMMENDATION BY SERIAL NUMBER 003	
37. APPROVAL/RECOMMENDATION BY SERIAL NUMBER 003		38. APPROVAL/RECOMMENDATION BY SERIAL NUMBER 003	
39. APPROVAL/RECOMMENDATION BY SERIAL NUMBER 003		40. APPROVAL/RECOMMENDATION BY SERIAL NUMBER 003	
41. APPROVAL/RECOMMENDATION BY SERIAL NUMBER 003		42. APPROVAL/RECOMMENDATION BY SERIAL NUMBER 003	
43. APPROVAL/RECOMMENDATION BY SERIAL NUMBER 003		44. APPROVAL/RECOMMENDATION BY SERIAL NUMBER 003	
45. APPROVAL/RECOMMENDATION BY SERIAL NUMBER 003		46. APPROVAL/RECOMMENDATION BY SERIAL NUMBER 003	
47. APPROVAL/RECOMMENDATION BY SERIAL NUMBER 003		48. APPROVAL/RECOMMENDATION BY SERIAL NUMBER 003	
49. APPROVAL/RECOMMENDATION BY SERIAL NUMBER 003		50. APPROVAL/RECOMMENDATION BY SERIAL NUMBER 003	
51. APPROVAL/RECOMMENDATION BY SERIAL NUMBER 003		52. APPROVAL/RECOMMENDATION BY SERIAL NUMBER 003	
53. APPROVAL/RECOMMENDATION BY SERIAL NUMBER 003		54. APPROVAL/RECOMMENDATION BY SERIAL NUMBER 003	
55. APPROVAL/RECOMMENDATION BY SERIAL NUMBER 003		56. APPROVAL/RECOMMENDATION BY SERIAL NUMBER 003	
57. APPROVAL/RECOMMENDATION BY SERIAL NUMBER 003		58. APPROVAL/RECOMMENDATION BY SERIAL NUMBER 003	
59. APPROVAL/RECOMMENDATION BY SERIAL NUMBER 003		60. APPROVAL/RECOMMENDATION BY SERIAL NUMBER 003	
61. APPROVAL/RECOMMENDATION BY SERIAL NUMBER 003		62. APPROVAL/RECOMMENDATION BY SERIAL NUMBER 003	
63. APPROVAL/RECOMMENDATION BY SERIAL NUMBER 003		64. APPROVAL/RECOMMENDATION BY SERIAL NUMBER 003	
65. APPROVAL/RECOMMENDATION BY SERIAL NUMBER 003		66. APPROVAL/RECOMMENDATION BY SERIAL NUMBER 003	
67. APPROVAL/RECOMMENDATION BY SERIAL NUMBER 003		68. APPROVAL/RECOMMENDATION BY SERIAL NUMBER 003	
69. APPROVAL/RECOMMENDATION BY SERIAL NUMBER 003		70. APPROVAL/RECOMMENDATION BY SERIAL NUMBER 003	
71. APPROVAL/RECOMMENDATION BY SERIAL NUMBER 003		72. APPROVAL/RECOMMENDATION BY SERIAL NUMBER 003	
73. APPROVAL/RECOMMENDATION BY SERIAL NUMBER 003		74. APPROVAL/RECOMMENDATION BY SERIAL NUMBER 003	
75. APPROVAL/RECOMMENDATION BY SERIAL NUMBER 003		76. APPROVAL/RECOMMENDATION BY SERIAL NUMBER 003	
77. APPROVAL/RECOMMENDATION BY SERIAL NUMBER 003		78. APPROVAL/RECOMMENDATION BY SERIAL NUMBER 003	
79. APPROVAL/RECOMMENDATION BY SERIAL NUMBER 003		80. APPROVAL/RECOMMENDATION BY SERIAL NUMBER 003	
81. APPROVAL/RECOMMENDATION BY SERIAL NUMBER 003		82. APPROVAL/RECOMMENDATION BY SERIAL NUMBER 003	
83. APPROVAL/RECOMMENDATION BY SERIAL NUMBER 003		84. APPROVAL/RECOMMENDATION BY SERIAL NUMBER 003	
85. APPROVAL/RECOMMENDATION BY SERIAL NUMBER 003		86. APPROVAL/RECOMMENDATION BY SERIAL NUMBER 003	
87. APPROVAL/RECOMMENDATION BY SERIAL NUMBER 003		88. APPROVAL/RECOMMENDATION BY SERIAL NUMBER 003	
89. APPROVAL/RECOMMENDATION BY SERIAL NUMBER 003		90. APPROVAL/RECOMMENDATION BY SERIAL NUMBER 003	
91. APPROVAL/RECOMMENDATION BY SERIAL NUMBER 003		92. APPROVAL/RECOMMENDATION BY SERIAL NUMBER 003	
93. APPROVAL/RECOMMENDATION BY SERIAL NUMBER 003		94. APPROVAL/RECOMMENDATION BY SERIAL NUMBER 003	
95. APPROVAL/RECOMMENDATION BY SERIAL NUMBER 003		96. APPROVAL/RECOMMENDATION BY SERIAL NUMBER 003	
97. APPROVAL/RECOMMENDATION BY SERIAL NUMBER 003		98. APPROVAL/RECOMMENDATION BY SERIAL NUMBER 003	
99. APPROVAL/RECOMMENDATION BY SERIAL NUMBER 003		100. APPROVAL/RECOMMENDATION BY SERIAL NUMBER 003	

DD 7-1694

ORIGINAL PAGE IS
OF POOR QUALITY

Program Instruction 010

REQUEST FOR DEVIATION/WAIVER
(SEE MIL-STD-883A OR -81 FOR INSTRUCTIONS)

DATE PREPARED

PROCURING ACTIVITY NO. 1180

1. ORIGINATOR NAME AND ADDRESS David M. Randall SBRC, 75 Coromar Dr., Goleta, Ca. 93117				2. <input type="checkbox"/> DEVIATION <input checked="" type="checkbox"/> WAIVER	
				3. <input checked="" type="checkbox"/> MINOR <input type="checkbox"/> MAJOR <input type="checkbox"/> CRITICAL	
4. DESIGNATION FOR DEVIATION/WAIVER				5. BASE LINE AFFECTED	
6. MODEL/TYPE F	7. MFR. CODE 11323	8. SYS. DESIG. 1M	9. DEV/WAIVER NO. W-120	<input checked="" type="checkbox"/> FUNC- TIONAL	<input type="checkbox"/> ALLO- CATED
				<input type="checkbox"/> PROD- UCT	
10. OTHER SYSTEMS/CONFIG- URATION ITEMS AFFECTED				<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO	
11. SPECIFICATIONS AFFECTED-TEST PLAN				12. DRAWINGS AFFECTED	
13. MFR. CODE				14. MFR. CODE	
15. SPEC. DOC. NO.				16. NUMBER	
17. SCN				18. REV.	
19. MFR. CODE				20. NOR. NO.	
21. SYSTEM				22. ITEM	
23. TEST PLAN				24. CONTRACT NO. & LINE ITEM	
25. TITLE OF DEVIATION/WAIVER Permission to use Band 4 Postamp SN 201				26. NAS 5-24200	
27. CONFIGURATION ITEM NOMENCLATURE Radiometer				28. CD NO. II	
29. NAME OF PART OR LOWEST ASSEMBLY AFFECTED Band 4 Postamplifier				30. DEFECT NO. 201	
31. PART NO. OR TYPE DESIGN 50904-4				32. QTY 1	
33. EFFECT ON COST/PRICE None if approved.				34. DEFECT CLASSIFICATION <input checked="" type="checkbox"/> MINOR <input type="checkbox"/> MAJOR <input type="checkbox"/> CRITICAL	
35. EFFECT ON DELIVERY SCHEDULE None if approved.				36. RECURRING DEVIATION/WAIVER <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO	
37. EFFECT ON INTEGRATED LOGISTIC SUPPORT, INTERFACE, ETC. None				38. DESCRIPTION OF DEVIATION/WAIVER	
39. NEED FOR DEVIATION/WAIVER				40. APPROVAL/RECOMMENDATION	

Permission to use Band 4 Postamp with Ch 6 frequency response -2.24 dB down vs a specification of -2.5 to -3.0 dB down at 52KHZ.

This parameter is in violation of a unit level specification; not a system specification. Rework to the Postamp PWB may result in a lifted pad. The Band 4 Band Level Assy has been bonded into LED bracket and can no longer be cooled to allow reselection of resistors. Rework is not considered necessary since Wide Band Noise of Channel 6 is 2.1pA.

REA	SYS ENGR	1/17/81	RE	QA	PE
21. PRODUCTION EFFECTIVITY BY SERIAL NUMBER			22. APPROVAL/RECOMMENDATION		
23. APPROVAL/RECOMMENDATION			24. APPROVAL/RECOMMENDATION		
25. APPROVAL/RECOMMENDATION			26. APPROVAL/RECOMMENDATION		
27. APPROVAL/RECOMMENDATION			28. APPROVAL/RECOMMENDATION		
29. APPROVAL/RECOMMENDATION			30. APPROVAL/RECOMMENDATION		
31. APPROVAL/RECOMMENDATION			32. APPROVAL/RECOMMENDATION		
33. APPROVAL/RECOMMENDATION			34. APPROVAL/RECOMMENDATION		
35. APPROVAL/RECOMMENDATION			36. APPROVAL/RECOMMENDATION		
37. APPROVAL/RECOMMENDATION			38. APPROVAL/RECOMMENDATION		
39. APPROVAL/RECOMMENDATION			40. APPROVAL/RECOMMENDATION		
41. APPROVAL/RECOMMENDATION			42. APPROVAL/RECOMMENDATION		
43. APPROVAL/RECOMMENDATION			44. APPROVAL/RECOMMENDATION		
45. APPROVAL/RECOMMENDATION			46. APPROVAL/RECOMMENDATION		
47. APPROVAL/RECOMMENDATION			48. APPROVAL/RECOMMENDATION		
49. APPROVAL/RECOMMENDATION			50. APPROVAL/RECOMMENDATION		
51. APPROVAL/RECOMMENDATION			52. APPROVAL/RECOMMENDATION		
53. APPROVAL/RECOMMENDATION			54. APPROVAL/RECOMMENDATION		
55. APPROVAL/RECOMMENDATION			56. APPROVAL/RECOMMENDATION		
57. APPROVAL/RECOMMENDATION			58. APPROVAL/RECOMMENDATION		
59. APPROVAL/RECOMMENDATION			60. APPROVAL/RECOMMENDATION		
61. APPROVAL/RECOMMENDATION			62. APPROVAL/RECOMMENDATION		
63. APPROVAL/RECOMMENDATION			64. APPROVAL/RECOMMENDATION		
65. APPROVAL/RECOMMENDATION			66. APPROVAL/RECOMMENDATION		
67. APPROVAL/RECOMMENDATION			68. APPROVAL/RECOMMENDATION		
69. APPROVAL/RECOMMENDATION			70. APPROVAL/RECOMMENDATION		
71. APPROVAL/RECOMMENDATION			72. APPROVAL/RECOMMENDATION		
73. APPROVAL/RECOMMENDATION			74. APPROVAL/RECOMMENDATION		
75. APPROVAL/RECOMMENDATION			76. APPROVAL/RECOMMENDATION		
77. APPROVAL/RECOMMENDATION			78. APPROVAL/RECOMMENDATION		
79. APPROVAL/RECOMMENDATION			80. APPROVAL/RECOMMENDATION		
81. APPROVAL/RECOMMENDATION			82. APPROVAL/RECOMMENDATION		
83. APPROVAL/RECOMMENDATION			84. APPROVAL/RECOMMENDATION		
85. APPROVAL/RECOMMENDATION			86. APPROVAL/RECOMMENDATION		
87. APPROVAL/RECOMMENDATION			88. APPROVAL/RECOMMENDATION		
89. APPROVAL/RECOMMENDATION			90. APPROVAL/RECOMMENDATION		
91. APPROVAL/RECOMMENDATION			92. APPROVAL/RECOMMENDATION		
93. APPROVAL/RECOMMENDATION			94. APPROVAL/RECOMMENDATION		
95. APPROVAL/RECOMMENDATION			96. APPROVAL/RECOMMENDATION		
97. APPROVAL/RECOMMENDATION			98. APPROVAL/RECOMMENDATION		
99. APPROVAL/RECOMMENDATION			100. APPROVAL/RECOMMENDATION		

DD FORM 1694

ORIGINAL PAGE IS
OF POOR QUALITY

Program Instruction 010

REQUEST FOR DEVIATION/WAIVER
(SEE MIL-STD-480 OR 481 FOR INSTRUCTIONS)

DATE PREPARED

PROCESSING ACTIVITY NO.

1. ORIGINATOR NAME AND ADDRESS DAVID M. RANDALL SBRC, 75 Coromar Dr., Goleta, Ca. 93117				2. <input type="checkbox"/> DEVIATION <input checked="" type="checkbox"/> WAIVER	
				3. <input type="checkbox"/> MINOR <input checked="" type="checkbox"/> MAJOR <input type="checkbox"/> CRITICAL	
4. DESIGNATION FOR DEVIATION/WAIVER				5. BASE LINE AFFECTED	
6. MODEL/TYPE F	7. MFR. CODE 11323	8. SYS. DESIG. TM	9. DEV/WAIVER NO. W-126	<input checked="" type="checkbox"/> FUNCTIONAL <input type="checkbox"/> ALLOCATED <input type="checkbox"/> PRODUCT	
10. SPECIFICATIONS AFFECTED - TEST PLAN				11. OTHER SYSTEMS/CONFIGURATION ITEMS AFFECTED	
12. MFR. CODE				13. YES <input type="checkbox"/> NO <input checked="" type="checkbox"/>	
14. SPEC. DOC. NO.					
15. SCM					
16. SYSTEM					
17. ITEM					
18. TEST PLAN					
19. TITLE OF DEVIATION/WAIVER Permission to use PFPA with Band 1 misaligned.				20. CONTRACT NO. & LINE ITEM NAS 5-24200	
21. CONFIGURATION ITEM NOMENCLATURE Radiometer				22. CLASSIFICATION OF DEFECT	
23. NAME OF PART OR LOWEST ASSEMBLY AFFECTED Si Focal Plane Assy				24. DEFECT CLASSIFICATION	
25. PART NO. OR TYPE DESIGN 50795				<input checked="" type="checkbox"/> MINOR <input type="checkbox"/> MAJOR <input type="checkbox"/> CRITICAL	
26. LOT NO. 003				27. DEFECT NO.	
28. QTY 1				29. RECURRING DEVIATION/WAIVER	
30. EFFECT ON COST/PRICE Greater than \$50,000 if not approved.				31. YES <input type="checkbox"/> NO <input checked="" type="checkbox"/>	
32. EFFECT ON DELIVERY SCHEDULE Four weeks if not approved.					
33. EFFECT ON INTEGRATED LOGISTIC SUPPORT, INTERFACE, ETC. Misalignment must be taken into consideration.					
34. DESCRIPTION OF DEVIATION/WAIVER					

Band 1 is located .102961 "to .102977" from Band 2 in the "Y" dimension vs a drawing requirement of .10200" \pm .000150". This will result in a misregistration of .24 JFOV; this misregistration will have to be taken in to consideration by ground processing of TM data.

24. NEED FOR DEVIATION/WAIVER

To correct this misregistration will require the removal and realignment of Band 1 Band Level Assy. This is a difficult and risky operation. It is not considered cost or schedule effective to repair.

25. PRODUCTION EFFECTIVITY BY SERIAL NUMBER 003 51065 SN 003 ONLY		26. AUTHORIZING SIGNATURE JL Engel	
27. APPROVAL/DISAPPROVAL		28. TITLE Minor - System Engineering Major/Critical - Program Manager	
29. APPROVAL RECOMMENDED <input checked="" type="checkbox"/>		30. APPROVED <input checked="" type="checkbox"/> DISAPPROVED <input type="checkbox"/>	
31. GOVERNMENT ACTIVITY Randolf D - TM		32. SIGNATURE D. W. Hester	
DD FORM 1694		TFS 12/17/81 CCR #0335	

ORIGINAL PAGE IS
OF POOR QUALITY

Program Instruction 010

REQUEST FOR DEVIATION/WAIVER
(SEE 416-STD-40 OR 41 FOR INSTRUCTIONS)

DATE PREPARED
3-10-82

PROCURING ACTIVITY NO.

1. ORIGINATOR NAME AND ADDRESS Santa Barbara Research Center 75 Coromar Drive, Goleta, CA 93117				2. <input type="checkbox"/> DEVIATION <input checked="" type="checkbox"/> WAIVER	
3. <input checked="" type="checkbox"/> MINOR <input type="checkbox"/> MAJOR <input type="checkbox"/> CRITICAL				4. OTHER SYSTEMS/CONFIGURATION ITEMS AFFECTED <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO	
5. DESIGNATION FOR DEVIATION/WAIVER					
6. MODEL/TYPE F-1	7. MFR. CODE 11323	8. SYS. DESIG. TM	9. DEV/WAIVER NO. W-143	10. <input type="checkbox"/> FUNCTIONAL <input checked="" type="checkbox"/> ALLOCATED <input type="checkbox"/> PRODUCE	11. <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO
12. SPECIFICATIONS AFFECTED-TEST PLAN					
13. DRAWINGS AFFECTED					
14. SYSTEM		15. MFR. CODE		16. REV.	17. NO. NO.
		11323		52733	C 3942A
18. TEST PLAN					
19. TITLE OF DEVIATION/WAIVER No planning for EO 8842 - Baffle Assy					
20. CONTRACT NO. & LINE ITEM NAS 5-24200					
21. CONFIGURATION ITEM IDENTIFICATION Thematic Mapper Assembly					
22. CLASSIFICATION OF DEFECT <input checked="" type="checkbox"/> MINOR <input type="checkbox"/> MAJOR <input type="checkbox"/> CRITICAL					
23. NAME OF PART OR LOWEST ASSEMBLY AFFECTED Baffle Assembly		24. PART NO. OR TYPE DESIG. 52733 -C		25. LOT NO. 1	26. JTY I
27. EFFECT ON COST/PRICE		28. EFFECT ON DELIVERY SCHEDULE 2 weeks if disapproved			
29. EFFECT ON INTEGRATED LOGISTIC SUPPORT, INTERFACE, ETC.					

23. DESCRIPTION OF DEVIATION/WAIVER

There exists no planning to incorporate EO 8842. This EO invokes the same changes as EO 8181 (superseded by EO 8842) but adds clarifying notes to provide specific clearances enabling assembly at the next higher level, adds the marking specification number to the drawing, and adds a requirement for bonding material test specimens.

EO 8181 has been covered by planning, and incorporated into the F-1 hardware. Even though the added notes for clearance were not invoked on the planning, their intent was accomplished as evidenced by the ability to have installed the Baffle Assembly into its next assembly.

QA records show hardness test data for the bonding material, although the test was not referenced in the planning.

24. REASONS FOR DEVIATION/WAIVER

The hardware has been built to the full intent of EO 8842, even though the planning did not specifically call out that EO. The records show that the Baffle Assembly is suitable for flight use.

25. PRODUCTION EFFECTIVITY BY SERIAL NUMBER 51065 SN 003 only		26. SIGNATURE OF AUTHORIZING SIGNATURE <i>J. H. Engel</i> 3/10/82		27. TITLE Minor - System Signaling Major/Critical - Program Manager	
28. APPROVAL/RECOMMENDATION <input type="checkbox"/> APPROVAL RECOMMENDED		29. APPROVAL/RECOMMENDATION <input checked="" type="checkbox"/> APPROVED <input type="checkbox"/> DISAPPROVED			
30. GOVERNMENT ACTIVITY NASA GSFC		31. SIGNATURE <i>George B. Lunt</i>		32. DATE 3/11/82	
DD FORM 1694					

ORIGINAL PAGE IS
OF POOR QUALITY

Program Instruction 010

REQUEST FOR DEVIATION/WAIVER
(SEE MIL-STD-460 OR 461 FOR INSTRUCTIONS)

DATE PREPARED

27 March 1982

PROCURING ACTIVITY NO.

1. ORIGINATOR NAME AND ADDRESS

Santa Barbara Research Center
75 Coromar Drive, Goleta, CA 93117

2. ☐ DEVIATION ☒ WAIVER
3. ☒ MINOR ☐ MAJOR ☐ CRITICAL

4. DESIGNATION FOR DEVIATION/WAIVER

a. MODEL/TYPE Flight b. MFR. CODE 11323 c. SYS. DESIG. TM d. DEV/WAIVER NO. W-148

5. BASE LINE AFFECTED

☒ FUNCTIONAL ☐ ALLOCATED ☐ PRODUCT

6. OTHER SYSTEMS/CONFIGURATION ITEMS AFFECTED

☐ YES ☒ NO

7. SPECIFICATIONS AFFECTED-TEST PLAN

a. SYSTEM b. ITEM 11323 c. TEST PLAN d. SPEC./DOC. NO. TP32015-506 e. SCH Rev D

8. DRAWINGS AFFECTED

a. MFR. CODE b. NUMBER c. REV. d. NOR. NO.

9. TITLE OF DEVIATION/WAIVER

Waiver on tolerance of Prime Focal Plane to scan direction alignment NAS-5 2400

11. CONFIGURATION ITEM NOMENCLATURE

IAO6R test

12. CD NO.

13. DEFECT NO.

14. DEFECT CLASSIFICATION

☒ MINOR ☐ MAJOR ☐ CRITICAL

15. NAME OF PART OR LARGEST ASSEMBLY AFFECTED

IAO6R test

16. PART NO. OR TYPE DESIGN.

52532

17. LOT NO.

N/A

18. QTY

1

19. RECURRING DEVIATION/WAIVER

☐ YES ☒ NO

20. EFFECT ON COST/PRICE

None

21. EFFECT ON DELIVERY SCHEDULE

None

22. EFFECT ON INTEGRATED LOGISTIC SUPPORT, INTERFACE, ETC.

None

23. DESCRIPTION OF DEVIATION/WAIVER

Scan direction to prime focal plane array angle is 0.74mrad. The IAO6 test procedure targets ± 0.5 mrad. [Paragraphs 1.1 and 5.1.14]
This deviation will not affect our ability to meet the relevant system level specifications on band to band registration. An angle of 0.74mrad corresponds to an along track BBR error of 0.06 IFOV between bands 1 and 4 (spec. is ± 0.2 IFOV) and 0.12 between bands 1 and 5 (spec. is ± 0.3 IFOV).

24. NEED FOR DEVIATION/WAIVER

Avoid schedule delay and risks involved in rotating optical assembly.

RE W.D. Miller for 11/11/82
QA W.D. Miller
PE W.D. Miller for L. ALTA

25. PRODUCTION EFFECTIVITY BY SERIAL NUMBER

26. SUBMITTING ACTIVITY/AUTHORIZING SIGNATURE

W.D. Miller for J. Engel

TITLE

Minor - System Engineering
Major/Critical - Program Manager

27. APPROVAL/DISAPPROVAL

☐ APPROVAL RECOMMENDED

☒ APPROVED

☐ DISAPPROVED

28. GOVERNMENT ACTIVITY

SIGNATURE

DATE

DD FORM 1694

Per O. Winters 3/27/82

ORIGINAL PAGE IS
OF POOR QUALITY

REQUEST FOR DEVIATION/WAIVER
(SEE MIL-STD-460 OR 481 FOR INSTRUCTIONS)

DATE PREPARED

PROCURING ACTIVITY NO.

HSP

1. ORIGINATOR NAME AND ADDRESS David M. Randall SBRC, 75 Coromar Drive, Goleta, CA 93117				2. <input type="checkbox"/> DEVIATION <input type="checkbox"/> WAIVER 3. <input type="checkbox"/> MINOR <input checked="" type="checkbox"/> MAJOR <input type="checkbox"/> CRITICAL					
4. DESIGNATION FOR DEVIATION/WAIVER				5. BASE LINE AFFECTED		6. OTHER SYSTEMS/CONFIGURATION ITEMS AFFECTED			
6. MODEL/TYPE Spare	7. MFR. CODE 11323	8. SYS. DESIG. TM	9. DEV/WAIVER NO. W-154	<input checked="" type="checkbox"/> FUNCTIONAL <input type="checkbox"/> ALLOCATED <input type="checkbox"/> PRODUCE	<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO				
7. SPECIFICATIONS AFFECTED-TEST PLAN				8. DRAWINGS AFFECTED					
MFR. CODE SPEC./DOC. NO. SN				MFR. CODE NUMBER REV. NOR. NO.					
9. SYSTEM				11323 50797 E					
10. ITEM									
11. TEST PLAN									
9. TITLE OF DEVIATION/WAIVER Permission to Use Band Level Assy SN 501-2						10. CONTRACT NO. & LINE ITEM NAS 5-24200			
11. CONFIGURATION ITEM NOMENCLATURE Radiometer				12. CD NO. II				13. DEFECT NO.	14. DEFECT CLASSIFICATION <input checked="" type="checkbox"/> MINOR <input type="checkbox"/> MAJOR <input type="checkbox"/> CRITICAL
15. NAME OF PART OR LOSEST ASSEMBLY AFFECTED Band Level Assy				16. PART NO. OR TYPE DESIGN 50797-E		17. LOT NO. 501	18. QTY 1	19. RECURRING DEVIATION/WAIVER <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO	
20. EFFECT ON COST/PRICE None if approved				21. EFFECT ON DELIVERY SCHEDULE None if approved					
22. EFFECT ON INTEGRATED LOGISTIC SUPPORT, INTERFACE, ETC. None									
23. DESCRIPTION OF DEVIATION/WAIVER Band Level Assy SN 501 has out of specification transient responses for Ch 1, 8, 10 and 14 per FR 8211. A copy of the FR and transient response plots are attached.									

24. NEED FOR DEVIATION/WAIVER

The Band Level Assy is completed and would require a high degree of risk to the quartz substrates to take apart to rework. The \$15K Si detector would have to be replaced and there is no guarantee that rework would result in better performance. Rework is not considered cost effective.

5/10/82
REA *David M. Randall* SYS ENGR

RE *William S-13*

QA *William S-13*

PE *William S-13*

25. PRODUCTION EFFECTIVITY BY SERIAL NUMBER 004 51065 SN 004 ONLY	
26. SUBMITTING ACTIVITY AUTHORIZING SIGNATURE <i>William S-13</i>	
27. APPROVAL/DISAPPROVAL <i>William S-13</i>	
<input type="checkbox"/> APPROVAL RECOMMENDED	<input type="checkbox"/> APPROVED <input type="checkbox"/> DISAPPROVED
28. GOVERNMENT ACTIVITY	SIGNATURE DATE

DD FORM 1694

FAILURE REPORT

S 8211

1. PART NAME AND NUMBER		2. GLA	3. MODEL	4. TIME OBSERVED	5. DATE OBSERVED
PL 1162 TM			SPARE	FIRST SHIFT	MO 04 0A 28 YR 82
6. HARDWARE LEVEL WHEN FAILURE WAS OBSERVED		7. SUBSYSTEM IDENTIFICATION		8. DATE OBSERVED	
<input type="checkbox"/> SPACECRAFT <input type="checkbox"/> SYSTEM		<input type="checkbox"/> SUBSYSTEM <input type="checkbox"/> UNIT		<input type="checkbox"/> ASSEMBLY <input type="checkbox"/> SUBASSEMBLY	
<input type="checkbox"/> MODULE <input type="checkbox"/> MICAM		<input type="checkbox"/> CARD <input type="checkbox"/> PART			
9. EQUIPMENT IDENTIFICATION		NAME		PART NUMBER	
10. SUBSYSTEM				S/N	
11. UNIT				MANUFACTURER	
12. ASSEMBLY		50797-2		501	
13. SUBASSEMBLY				SBRC	
14. MODULE					
15. MICAM					
16. CARD					
17. OTHER					
18. TEST WHEN FAILURE WAS OBSERVED		19. TEST WHEN FAILURE WAS OBSERVED		20. TEST WHEN FAILURE WAS OBSERVED	
<input type="checkbox"/> DEVELOPMENT <input type="checkbox"/> IN-PROCESS		<input type="checkbox"/> QUALIFICATION <input type="checkbox"/> ACCEPTANCE		<input type="checkbox"/> INTEGRATION <input type="checkbox"/> SYSTEM	
<input type="checkbox"/> LAUNCH OPERATIONS		<input type="checkbox"/> THERMAL VAC		<input type="checkbox"/> HRS AT	
21. AMBIENT		22. RADIATION		23. VIBRATION	
<input type="checkbox"/> EMC/RR		<input type="checkbox"/> AXIS FOR		<input type="checkbox"/> MIN TYPE	
24. DESCRIPTION OF FAILURE		25. TEST PROCEDURE		26. ORIGINAL	
CH. 15 NO RESPONSE, D.C. OFFSET IS ADJUSTABLE, HIGH NOISE WITH 1/2 NOISE EVIDENT. CH. 1, 8, 14, 10 OUT OF SPEC. ON TRANSIENT RESP. AFTER 30 U.S. CH. 14, 10 AT 60 U.S.		16306		C. R. Lane	
27. VERIFICATION AND FAILURE ANALYSIS		28. CONTINUATION SHEET USED		29. CONTINUATION SHEET USED	
19. FAILED ITEM NAME AND PART NUMBER		20. AUTHORIZATION		21. DATE	
22. FOLLOWING REWORK/RETEST REQUIRED		23. REWORK/RETEST ACTION TAKEN		24. QA Rework	
REWORK/RETEST NOT REQUIRED BECAUSE		25. REWORK/RETEST ACTION TAKEN		26. QA RETEST	
27. LIST ALL PARTS REPLACED		28. RETESTED BY		29. CONTINUATION SHEET USED	
PART NUMBER		DATE		30. CAUSE AND CORRECTIVE ACTION	
CMT SYM		31. PROS CLOSURE		32. DOCUMENT IMPLEMENTING CORRECTIVE ACTION	
PART LOT NUMBER		33. BASIC CAUSE OF VERIFIED FAILURE		34. TEST EQUIPMENT TEST SET-UP	
DATE CODE		35. WFG. PROCEDURE ASSY/FAB ERROR WORKMANSHIP		36. WIRING ERROR ROUGH HANDLING WEAR-OUT	
MANUFACTURER		37. FAILURE CLASSIFICATION		38. SPACECRAFT SYSTEM ENGINEER	
PROBABLE DEFECT		39. CUSTOMER OR SUPPLIER		40. DATE	
ANALYSIS NUMBER		41. DATE		42. DATE	
27. REWORK BY		28. RETESTED BY		29. CONTINUATION SHEET USED	
ORG		DATE		30. CAUSE AND CORRECTIVE ACTION	
31. PROS CLOSURE		32. DOCUMENT IMPLEMENTING CORRECTIVE ACTION		33. BASIC CAUSE OF VERIFIED FAILURE	
34. TEST EQUIPMENT TEST SET-UP		35. WFG. PROCEDURE ASSY/FAB ERROR WORKMANSHIP		36. WIRING ERROR ROUGH HANDLING WEAR-OUT	
37. FAILURE CLASSIFICATION		38. SPACECRAFT SYSTEM ENGINEER		39. CUSTOMER OR SUPPLIER	
40. DATE		41. DATE		42. DATE	
43. DATE		44. DATE		45. DATE	
46. DATE		47. DATE		48. DATE	
49. DATE		50. DATE		51. DATE	
52. DATE		53. DATE		54. DATE	
55. DATE		56. DATE		57. DATE	
58. DATE		59. DATE		60. DATE	
61. DATE		62. DATE		63. DATE	
64. DATE		65. DATE		66. DATE	
67. DATE		68. DATE		69. DATE	
70. DATE		71. DATE		72. DATE	
73. DATE		74. DATE		75. DATE	
76. DATE		77. DATE		78. DATE	
79. DATE		80. DATE		81. DATE	
82. DATE		83. DATE		84. DATE	
85. DATE		86. DATE		87. DATE	
88. DATE		89. DATE		90. DATE	
91. DATE		92. DATE		93. DATE	
94. DATE		95. DATE		96. DATE	
97. DATE		98. DATE		99. DATE	
100. DATE		101. DATE		102. DATE	

9211

ORIGINAL PAGE IS
OF POOR QUALITY

30μS
60μS
282

ODD CHANNEL 1

SHORT 2 FULL BAND

04-23-82

C.R. Lane

N.C. JAVISON, II

MAY 5, 1982

29.

621

ORIGINAL PAGE IS
OF POOR QUALITY

98% - 8 860ms
30ms

CH 8

SHORT 2

04-25-82

C. R. Lee

N. C. Davidson, II

MAY 5, 1982

28 -

ORIGINAL PAGE IS
OF POOR QUALITY

30 μ S
60 μ S

CH. 10

SHORT λ

04-28-82

C. R. Lee

N. C. JAVISON, II

MAY 5, 1982

22 Rise time 15 μ S

ORIGINAL PAGE IS
OF POOR QUALITY

998 -- 260 μ s
30 μ s

Channel 14
Short 7
4/27/72

50 μ s

N. C. Davison, II

MAY 5, 1982

SPARES				ASSEMBLY HISTORY RECORD SUPPLEMENT				SHEET 1 OF 1	
PAGE NO.	SERIAL NO.	INSTR. NO.	INSTR. DIV.	PREPARED BY	SUPPLEMENT NO.	AIR DATE	SUPPLEMENT RELEASE DATE	NOTE TO PRODUCTION: UPON RECEIPT, ENTER SUPPLEMENT NO. AND RECEIPT DATE ON FRONT SHEET OF AIR. INITIAL THE ENTRY.	
50797-2	501	50797	E	J. Wells	21-23	4/15/81	3/29/82		
SILICON DETECTOR PREAMP ASSY									
PURPOSE OF SUPPLEMENT - INCORPORATES NEW ASSY DWG REVISION 1.1 OR EOL & REVISE TO: OTHER PL EXPLAIN									
ADDITIONAL TESTING PER R.E.A.									
NOTES: 1) Same as original AIR. 2) Reason for this test is to ensure that band level assay is functionalable prior to putting assay into project stores incomplete. 3) Postamp PIB not available for testing with band level assay.									
UPR NO.	S/C NO.	INSTRUCTIONS		PERFORMED BY	OPER	HSP	DATE	REMARKS	
2601	22-1	1) Notify Q.A. & A.F. before testing					04/27/82		
		Q.A. (112) & A.F. 1122 PER							
		2) Test per spec #16306 Rev J & EO's 3864A, 3944A & 3047A.							
		*NOTE: Attach all test data to AIR.							
2602	51-1	Inspection verify test data from oper. #2601 Step #2.					11/19/82		
		...:RETURN TO MAIN AIR OPERATION #2700							

ORIGINAL PAGE IS OF POOR QUALITY

ORIGINAL PAGE IS OF POOR QUALITY

ORIGINAL PAGE IS
OF POOR QUALITY

4.5 Response for each focal plane channel at the following frequencies:

	1 kHz	2 kHz	5 kHz	10 kHz
Ch 1	<u>-3</u> db	<u>-1.0</u> db	<u>-3.7</u> db	<u>-8.1</u> db
23	<u>-3</u>	<u>-.8</u>	<u>-3.5</u>	<u>-7.8</u>
35	<u>-2.3</u>	<u>-1.0</u>	<u>-3.9</u>	<u>-8.3</u>
47	<u>-.2</u>	<u>-.8</u>	<u>-3.7</u>	<u>-7.9</u>
59	<u>.01</u>	<u>-.1</u>	<u>-.9</u>	<u>-3.3</u>
71	<u>-.2</u>	<u>-.8</u>	<u>-3.3</u>	<u>-7.4</u>
713	<u>-.2</u>	<u>-.8</u>	<u>-3.3</u>	<u>-7.4</u>
815	_____	_____	_____	_____

	20 kHz	50 kHz
Ch 21	<u>-13.7</u> db	<u>-22.1</u> db
23	<u>-13.4</u>	<u>-21.5</u>
35	<u>-13.8</u>	<u>-21.8</u>
47	<u>-13.6</u>	<u>-21.4</u>
59	<u>-7.9</u>	<u>-16.2</u>
71	<u>-12.6</u>	<u>-20.2</u>
713	<u>-12.8</u>	<u>-20.9</u>
815	_____	_____

Test Engineer C.R. Lane

Date 04-28-82

Design Engineer _____

Date _____




Q.A. Engineer _____

Date _____

*FR 8211

SIZE A	CODE IDENT NO 11323	16006
SCALE	REV	DATE

NO. 1000 (1982) USE PREVIOUS EDITIONS

PART NO.	DATE	OPERATOR OR JNSP	PART NAME	COMMENTS, TEST DATA, ETC	ASSY/LOT SERIAL NO.	DISPOSITION	QTY
SLIP 1 760	7/12/82		EPF	VOIDS IN SILVER EPOXY ON CH 7		Repair per Print.	1
			ST	TRACE			
	7/12/82	SSB		1. Apply silver epoxy to trace of Ch 7, making sure new and bond trace in used, and cover up to and including new part of wire. Mix # 12-17-81-1 Cure Temp. 70°C Time 3 hrs.		SP 80141 REVC	1
						ORIGINAL PAGE IS OF POOR QUALITY	
SLIP 1 260	7/14/82			FR 8211. CH 15 NO RESISTANCE D.C. OFFSET IS ADJUSTABLE HIGH AMPLITUDE WITH 1/2 VOLTAGE INPUT. CH 1, 14, 15 OUT OF SPECIFICATION. RESISTANCE AFTER 30 D.S. CH 1, 14 OUT AT 60 MΩ.			
	7/30/82	SSB		(walkman 3022) 1. Apply silver epoxy to trace of Ch 15 making sure new and bond trace in used and cover up to and including new part of wire. Mix # 12-17-81-1 Cure Temp 70°C Time 3 hrs.		FR INVESTIGATION	1
	1/2/82						
	05/04/82	ORE		2. Test Ch 15 per 76.806			1

TELE
11/10/82

TELE
11/10/82

7/21/82

7/23/82

REVISIONS				
SYM	DESCRIPTION		DATE	APPR
	INITIALLY RELEASED 9-5-78			
1ST USE	D	Completely revised and retyped to incorporate new system specs & update test procedures. As required by ECR TM1103/01.	12-6-79	<i>E. S.</i>
SER. No. 22 & SUBQ. E	E	Incorporated EO 1610	80-8-29	<i>E. S.</i>
51065 SER. No. 002 & Subq.	F	Paragraph 4.6 added: Transient response---- gold wires are not damaged. as req by ECR TM 1913/01.	80-09-12	<i>m. d.</i>
51065 S/N CC3 SUBQ.	G	Incorporated E. O. 2149A	12-2-80	<i>m. d.</i>
51065 S/N 103 & SUBQ	H	INCORPORATED EO 2960A.	81-4-20	<i>m. d.</i>
51065 S/N & SUBQ J	J	Changed by Revision Notice per ECR No. TM 2339/01	81-5-22	<i>m. d.</i>

RETEST ON CHANGES

PER COMMENT
SHEET #4,
OP. No. 2 OF
30 APRIL 82
Ref F/R 8211

REVISION STATUS THIS PRINT
NOT MAINTAINED AFTER
NOV 23 1981
DO NOT USE THIS PRINT
UNLESS YOUR COPY OF INSTRUCTIONS
SPECIFY THE REVISION LEVEL SHOWN

ORIGINAL PAGE IS
OF POOR QUALITY

SEE EO 3264A

CONTRACT NO. NAS 5-24200		SANTA BARBARA RESEARCH CENTER A Subsidiary of Hughes Aircraft Company GOLETA, CALIFORNIA	
PREPARED <i>[Signature]</i>	CHECKED <i>[Signature]</i>	TITLE TEST PROCEDURE FOCAL PLANE PREAMP ASSEMBLY	
APPROVED <i>[Signature]</i>	APPROVED <i>[Signature]</i>	SIZE A	CODE IDENT NO. 11323
		NUMBER 16306	
		SCALE	SHEET 1 OF 12

4.5 Response for each focal plane channel at the following frequencies:

	1 kHz	2 kHz	5 kHz	10 kHz
Ch 1	_____ db	_____ db	_____ db	_____ db
2	_____	_____	_____	_____
3	_____	_____	_____	_____
4	_____	_____	_____	_____
5	_____	_____	_____	_____
6	_____	_____	_____	_____
7	_____	_____	_____	_____
	<u>715 -3</u>	<u>-1.0</u>	<u>-4.0</u>	<u>-8.4</u>

	20 kHz	30 kHz
Ch 1	_____ db	_____ db
2	_____	_____
3	_____	_____
4	_____	_____
5	_____	_____
6	_____	_____
7	_____	_____
	<u>815 -13.9</u>	<u>-21.9</u>

Test Engineer C. R. Lee

Date 05-04-82

Design Engineer _____

Date _____

Q. A. Engineer (118) P. J. Russell

Date 5/1/82

VERIFY CH 45 DATA COMPLETE

SIZE A	CODE IDENT NO 11323	PROJECT 10000
SCALE	REV	SHEET 0

4.6 Boosted Frequency Response:

	100 Hz Limits (db)	1 kHz ±0.5	2 kHz ±0.5	5 kHz ±0.5
Ch 1	_____ db	_____ db	_____ db	_____ db
2	_____	_____	_____	_____
3	_____	_____	_____	_____
4	_____	_____	_____	_____
5	_____	_____	_____	_____
6	_____	_____	_____	_____
7	_____	_____	_____	_____
815	0	-1	-1	.04

	10 kHz Limits (db) ±0.4 -0.6	20 kHz ±0.1 -0.9	52 kHz ±-3
Ch 1	_____ db	_____ db	_____ db
2	_____	_____	_____
3	_____	_____	_____
4	_____	_____	_____
5	_____	_____	_____
6	_____	_____	_____
7	_____	_____	_____
815	.1	.1	-2.9

Test Engineer

C. R. Lee

Date

0500Y-82

Design Engineer

ACREN 0415
PHR

Date

Q.A. Engineer

Date

5/4/82

SIZE

A

CODE

11323

16306

SCALE

1:1

5

10

10

ORIGINAL PAGE IS
OF POOR QUALITY

4.3 Transient Response

Maximum excursion from final value after time $t_0 = t$ where t_0 is the time when the response reaches 2% of final value.

30 E040404
 $t = 35\mu S$ *PER* $t = 60\mu S$
Limit = 1.3% Limit = 1.0%

Ch 1

815

50%

5%

OVERSHOOT

CH 1

Limit: 10%

4

15% 7.2%

SETTIME

CH 1

Limit: 20 μS

2

Test Engineer

3

Date

4

Design Engineer

5

Date

6

D.A. Engineer

7

Date

815

14.0 μS

1 ACCEPT CH 15

116 R.H. Pinner

5/4/82

SIZE	CODE IDENT NO	FIGURE
A	11323	16306
SCALE	REV	SHEET 11

ORIGINAL PAGE IS
OF POOR QUALITY

4.7 wideband noise

112 0: 2.4 3A

Ch	Meter	Gain*	Pre-Amp Output	N.B. Noise	<u>RFB</u>
1.	_____V	_____	_____mV	_____dB	
2.	_____	_____	_____	_____	
3.	_____	_____	_____	_____	
4.	_____	_____	_____	_____	
5.	_____	_____	_____	_____	
6.	_____	_____	_____	_____	
7.	_____	_____	_____	_____	
7.15.	<u>.83</u>	<u>378</u>	<u>2.20</u>	<u>2.1</u>	$1.05 \times 10^9 \Omega$

$$100 \left\{ \left[\frac{7.13}{-} - (-16.03) + \frac{28.39}{-} \right] \right\} = 378$$

Design Engineer _____

Date: _____

TEST

TECH. Engineer C. R. Lane

Date: 05-04-82

Q.A. _____

5/4/82

C-2

SIZE	CODE IDENT NO	NUMBER
A	11323	16706
SCALE	REV 5	SHEET 12



ORIGINAL PAGE IS
OF POOR QUALITY

REQUEST FOR DEVIATION/WAIVER
(SEE MIL-STD-440 OR JAI FOR INSTRUCTIONS)

DATE PREPARED

PROCURING ACTIVITY NO.

H-3P

1. ORIGINATOR NAME AND ADDRESS David M. Randall SBRC, 75 Coromar Drive, Goleta, CA 93117				2. <input type="checkbox"/> DEVIATION <input type="checkbox"/> WAIVER			
				3. <input type="checkbox"/> MINOR <input checked="" type="checkbox"/> MAJOR <input type="checkbox"/> CRITICAL			
4. DESIGNATION FOR DEVIATION/WAIVER				5. BASE LINE AFFECTED			
6. MODEL/TYPE Spare	7. MFR. CODE 11323	8. SYS. DESIG. TM	9. DEV/WAIVER NO. W-155	<input type="checkbox"/> FUNC. TIONAL	<input type="checkbox"/> ALLO. CATED	<input type="checkbox"/> PROD. UCT	10. OTHER SYSTEMS/CONFIG. RATION ITEMS AFFECTED
				<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO			
7. SPECIFICATIONS AFFECTED-TEST PLAN				8. DRAWINGS AFFECTED			
9. TITLE OF DEVIATION/WAIVER Permission to use band level assembly S/N 501-1				10. CONTRACT NO. & LINE ITEM NAS 5-24200			
11. CONFIGURATION ITEM NOMENCLATURE Radiometer				12. CD NO. II			
13. NAME OF PART OR LATEST ASSEMBLY AFFECTED Band Level Assy.				14. DEFECT NO. 501			
15. PART NO. OR TYPE DESIGNATION 50797-E				16. DEFECT CLASSIFICATION <input checked="" type="checkbox"/> MINOR <input type="checkbox"/> MAJOR <input type="checkbox"/> CRITICAL			
17. LOT NO. 501				18. QTY 1			
19. EFFECT ON COST/PRICE None if approved				20. RECURRING DEVIATION/WAIVER <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO			
21. EFFECT ON DELIVERY SCHEDULE None if approved							
22. EFFECT ON INTEGRATED LOGISTIC SUPPORT, INTERFACE, ETC. None							
23. DESCRIPTION OF DEVIATION/WAIVER Band level assy. S/N 501 has out of specification transient responses for Ch 1, 5 7 and 15 per FR 8212. A copy of the FR and transient response plots are attached.							

24. NEED FOR DEVIATION/WAIVER

The band level assy. is completed and would require a high degree of risk to the quartz substrates to take apart to rework. The \$15K Si detector would have to be replaced and there is no guarantee that rework would result in better performance. Rework is not considered cost effective.

5/11/82		RE <u>G. Berlin 5-13-8</u>	
REA <u>DM Randall</u>		QA <u>W. Miller 5-12-82</u>	
SYS ENGR <u>W. Berlin 5-13-82</u>		PE <u>W. Miller 5-13-82</u>	
25. PRODUCTION EFFECTIVITY BY SERIAL NUMBER 51065 SN 004 ONLY			
26. SUBMITTING ACTIVITY AUTHORIZING SIGNATURE <u>W. Berlin</u>		27. APPROVAL/DISAPPROVAL <u>Proctor Thomas</u>	
28. <input type="checkbox"/> APPROVAL RECOMMENDED		29. <input type="checkbox"/> APPROVED <input type="checkbox"/> DISAPPROVED	
30. GOVERNMENT ACTIVITY		31. SIGNATURE DATE	

DD FORM 1694

HUGHES

HUGHES AIRCRAFT COMPANY
SPACE AND COMMUNICATIONS GROUP
EL SEGUNDO, CALIFORNIA

SPACE AND COMMUNICATIONS GROUP FAILURE REPORT


ORIGINAL PAGE IS
OF POOR QUALITY

S 8212

1. PROGRAM NAME AND NUMBER PL 1162 TM		2. GLA		3. MODEL SPRE		4. TIME OBSERVED FIRST SHIFT		5. DATE OBSERVED MO 05 DA 03 YR 82	
6. HARDWARE LEVEL WHEN FAILURE WAS OBSERVED		<input type="checkbox"/> SPACECRAFT SYSTEM		<input type="checkbox"/> SUBSYSTEM UNIT		<input checked="" type="checkbox"/> ASSEMBLY SUBASSEMBLY		<input type="checkbox"/> MODULE MODULE	
		<input type="checkbox"/> CARD PART							
EQUIPMENT IDENTIFICATION									
7. SUBSYSTEM				PART NUMBER		S/N		MANUFACTURER	
8. UNIT									
9. <input checked="" type="checkbox"/> ASSEMBLY <input type="checkbox"/> SUBASSEMBLY				50797-1		501		SBRL	
10. <input type="checkbox"/> MODULE <input type="checkbox"/> ICAM <input type="checkbox"/> CARD									
11. OTHER									
12. TEST WHEN FAILURE WAS OBSERVED									
<input type="checkbox"/> DEVELOPMENT		<input type="checkbox"/> QUALIFICATION		<input type="checkbox"/> INTEGRATION		<input type="checkbox"/> LAUNCH OPERATIONS			
<input type="checkbox"/> CLPROCESS		<input type="checkbox"/> ACCEPTANCE		<input type="checkbox"/> SYSTEM					
13. ENVIRONMENT WHEN FAILURE WAS OBSERVED									
<input checked="" type="checkbox"/> AMBIENT		<input type="checkbox"/> RADIATION		<input type="checkbox"/> TEMP		<input type="checkbox"/> THERMAL VAC		HRS AT	
<input type="checkbox"/> EMC/RF		<input type="checkbox"/> VIBRATION		AXIS FOR		MOD TYPE		<input type="checkbox"/> OTHER	
14. DESCRIPTION OF FAILURE									
CH. 1, 5, 7, 15 OUT OF SPEC. TRANS. RESP. AFTER 30MS. CH. 9, 13 OUT OF SPEC. TRANS. RESP. AFTER 60MS. HALF BAND 210 (000) SHOWS 10.92 SHORT J1-16 TO J1-11 SHOULD BE > M.A. HALF BAND 211-1, 1082 SHORT J1-16									
15. TEST PROCEDURE									
CH. 1-16		16306		4.6 4.8		10. ORIGINATOR		DATE	
						C. R. Long		22-13 05-03-82	
16. VERIFICATION AND FAILURE ANALYSIS									
J1-16 to J1-11 resistance reading out of spec. All for use during test. Being made with shunting connection in other halfband.									
17. FOLLOWING REWORK/RETEST REQUIRED									
<input type="checkbox"/> Rework/Retest Not Required Because Retest without shunting connection									
18. AUTHORIZED BY									
W. M. Kendall				2121		5/10/82		19. CONTINUATION SHEET USED	
20. REWORK/RETEST ACTION TAKEN									
Retested in spec when shunting connection was out. No over stress of any components occurred.									
21. LIST ALL PARTS REPLACED									
PART NUMBER	CXT SYM	PART LOT NUMBER	DATE CODE	MANUFACTURER	PROBABLE DEFECT	ANALYSIS NUMBER			
22. REWORK BY									
		ORG		DATE		23. RETESTED BY		DATE	
24. CAUSE AND CORRECTIVE ACTION									
Test operator inadvertently had shunting connection in other halfband during test.									
Ref 21-155 for disposition of Ch. 1, 5, 7, 15.									
25. FAB CLOSURE									
26. CONTINUATION SHEET USED									
27. DOCUMENT IMPLEMENTING CORRECTIVE ACTION									
28. BASIC CAUSE OF VERIFIED FAILURE		<input type="checkbox"/> DESIGN ENVIRONMENTAL DEFECTIVE PARTS		<input type="checkbox"/> TEST EQUIPMENT TEST PROCEDURE TEST SET-UP		<input type="checkbox"/> MFG. PROCEDURE ASSY/FAB ERROR WORKMANSHIP		<input type="checkbox"/> WIRING ERROR ROUGH HANDLING WEAR-OUT	
29. FAILURE TYPE		<input type="checkbox"/> UNKNOWN		<input type="checkbox"/> NO FAILURE		30. FAILURE CLASSIFICATION		<input type="checkbox"/> CRITICAL MAJOR	
		<input checked="" type="checkbox"/> MINOR SAFETY							
31. RESPONSIBLE ENGINEER		DATE		32. SPACECRAFT SYSTEM ENGINEER		DATE			
W. M. Kendall		2121 5/10/82							
33. RELIABILITY		DATE		34. CUSTOMER OR SUPPLIER		DATE			

ORIGINAL PAGE IS
OF POOR QUALITY

8212



CHANNEL 1

LOW 2 FULL BAND

04-30-82

C. R. Li

N. C. JAVISON, 3

MAY 5, 1982

ORIGINAL PAGE IS
OF POOR QUALITY

30μS
60μS

CHANNEL 5

LONG λ FULL BAND


04-30-82

C. R. Lone

N. C. JAVISON, II

MAY 5, 1982

ORIGINAL PAGE IS
OF POOR QUALITY



CHANNEL 7

LONG λ FULL BAND

05-03-82


C. R. Lane

N. C. DAVISON, III

MAY 5, 1982

212

ORIGINAL PAGE IS
OF POOR QUALITY



CHANNEL 9

LONG λ FULL BAND

05-03-82


C.R. Lee

N. C. JAVISON, III

MAY 5, 1982

ORIGINAL PAGE IS
OF POOR QUALITY

926



ORIGINAL PAGE IS
OF POOR QUALITY

30 μ S
60 μ S

CHANNEL 15

LONG & FULLBAND

05-03-82

C. R. Lane

N. C. Davison, JR

MAY 5, 1982

ENGINEERING ORDER / REVISION NOTICE NO. _____
SHEET _____

TEST PROCEDURE
Local Phone Pre Amp Assembly

DRAWING NUMBER
16306 Rev J

DESCRIPTION OF CHANGE

DATA START TO

4.8 Ground Continuity and Isolation Data Record

To	Resistance
J1-1	6.9
J1-5	7.4
J-23	7.9
J-27	6.2

Spec Requirements

- ① < 11 ohms
- ② > 1.5 M ohms

J2-6	6.9 ohms 8.1
J2-10	8.5
J2-27	7.6
J2-31	7.2

HB S/N 211-1

READING INCORRECT. PERFORMED
WITH SHORTING PLUGS IN OTHER
HALF BAND. NEW VALUE TAKEN
5-5-82: 5.78 MΩ. IN SPEC!

Bill C. Quinn
5-5-82

J1-11	108Ω *
J1-18	9.6M
J2-15	10.2M
J2-21	11.8M

NOT ACCESSABLE IN FULL BAND
CONFIGURATION

TEST BY: *C. R. Lee* 05-03-82
TEST BY: *Bill C. Quinn* 5-5-82
CONTROL: *Bill C. Quinn* 5/3/82

SERC ENGINEERING ORDER / REVISION NOTICE NO. 3864A
SHEET 2

ITEM TITLE TEST PROCEDURE

DRAWING NUMBER

CCM PLANE SETUP ASSEMBLY

16306 REV J

DESCRIPTION OF CHANGE

Add NEW Data Sheet to Specification (at end):
4.8 Ground Continuity and Isolation Data Record

J1-16

To Reading ①

J1-1	5.3
J1-5	6.2
J1-23	5.5
J1-27	4.8

Spec Requirements

- ① < 11 ohms
- ② > 1.0 M ohms

To Reading ①

J2-6	5.3
J2-10	5.6
J2-21	5.6
J2-31	4.8

HB S/N 210

To Reading ②

J1-11	10.3 M
J1-18	10.3 M
J2-15	10.3 M
J2-21	10.4 M

10.9 Ω *

READING INCORRECT. TAKEN WITH SHORTING CONNECTORS IN OTHER HALF BAND. NEW READING TAKEN 5-5-82: 7.15 M Ω . IN SPEC!

William C. [Signature]
5-5-82

To Reading ③

Chassis	
---------	--

NOT ACCESSIBLE - IN FULL BAND CONFIGURATION

Test Engineer C. R. [Signature]
Test Supervisor _____ Date _____
Quality Control _____ Date 1/31
5/3/82

ORIGINAL PAGE IS
OF POOR QUALITY

Program Instruction 010

REQUEST FOR DEVIATION/WAIVER
(SEE MIL-STD-440 OR 461 FOR INSTRUCTIONS)

DATE PREPARED

5-10-82

PROCURING ACTIVITY NO.

1. ORIGINATOR NAME AND ADDRESS Santa Barbara Research Center 75 Coromar Drive-Goleta, CA 93117				2. <input type="checkbox"/> DEVIATION <input checked="" type="checkbox"/> WAIVER			
				3. <input checked="" type="checkbox"/> MINOR <input type="checkbox"/> MAJOR <input type="checkbox"/> CRITICAL			
4. DESIGNATION FOR DEVIATION/WAIVER				5. BASE LINE AFFECTED			
6. MODEL/TYPE F-1	7. LTR. CODE 11323	8. SYS. DESIG. TM	9. DEVIATION NO. W-156	<input type="checkbox"/> FUNCTIONAL	<input type="checkbox"/> ALLO-CAT'D	<input checked="" type="checkbox"/> PRODUCT	10. OTHER SYSTEMS/CONFIGURATION ITEMS AFFECTED <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO
7. SPECIFICATIONS AFFECTED-TEST PLAN				8. DRAWINGS AFFECTED			
9. TITLE OF DEVIATION/WAIVER Terminal Board to replace spliced cooler door motor lead				10. CONTRACT NO. & LINE ITEM NAS-5-24200			
11. CONFIGURATION ITEM IDENTIFICATION Radiometer				12. CD NO.			
13. NAME OF PART OR LARGEST ASSEMBLY AFFECTED Motor, AC-Gearhead				14. DEFECT CLASSIFICATION <input checked="" type="checkbox"/> MINOR <input type="checkbox"/> MAJOR <input type="checkbox"/> CRITICAL			
15. PART NO. OR TYPE DESIGNATION 51258				16. DEFECT NO.			
17. LOT NO.				18. QTY 1			
19. EFFECT ON COST/PRICE				20. RECURRING DEVIATION/WAIVER <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO			
21. EFFECT ON DELIVERY SCHEDULE 6 Week delay if not approved				22. EFFECT ON INTEGRATED LOGISTIC SUPPORT, INTERFACE, ETC.			

23. DESCRIPTION OF DEVIATION/WAIVER

One lead from the radiative cooler door motor contains a splice of unknown origin. The splice will be eliminated by means of an added terminal board per approved planning.

History of part will be researched, with results to be documented by 5-24-82.

24. NEED FOR DEVIATION/WAIVER

Splices are not allowed per NHB 5300-4. Use of an additional terminal board allows elimination of the splice with minimum impact on cost and schedule. The lead that had been spliced is a 28 gage wire to the brake input.

25. PRODUCTION EFFECTIVITY BY SERIAL NUMBER

51065 SN 003

26. SUBMITTING ACTIVITY AUTHORIZING SIGNATURE <i>J. Engel</i> 5/11/82		TITLE Minor - System Engineering Major/Critical - Program Manager	
27. APPROVAL/DISAPPROVAL <input type="checkbox"/> APPROVAL RECOMMENDED		<input checked="" type="checkbox"/> APPROVED <input type="checkbox"/> DISAPPROVED	
28. GOVERNMENT ACTIVITY NASA GSFC		SIGNATURE <i>George B. Lint</i> DATE 5/11/82	

DD FORM 1694

ORIGINAL PAGE IS
OF FOUR QUALITY

REQUEST FOR DEVIATION/WAIVER
(SEE MIL-STD-480 OR 481 FOR INSTRUCTIONS)

DATE PREPARED

PROCURING ACTIVITY NO.

48P

1. ORIGINATOR NAME AND ADDRESS David M. Randall SBRC, 75 Coromar Drive, Goleta, 93117				2. <input type="checkbox"/> DEVIATION <input checked="" type="checkbox"/> WAIVER 3. <input type="checkbox"/> MINOR <input checked="" type="checkbox"/> MAJOR <input type="checkbox"/> CRITICAL			
4. DESIGNATION FOR DEVIATION/WAIVER a. MODEL/TYPE SPARE b. MFR. CODE 11323 c. SYS. DESIG. TM d. DEV/WAIVER NO. W-157				5. CASE LINE AFFECTED <input checked="" type="checkbox"/> FUNCTIONAL <input type="checkbox"/> ALLOCATED <input type="checkbox"/> PRODUCTION 6. OTHER SYSTEMS/CONFIGURATION ITEMS AFFECTED <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO			
7. SPECIFICATIONS AFFECTED-TEST PLAN a. SYSTEM b. ITEM c. TEST PLAN				8. DRAWINGS AFFECTED MFR CODE NUMBER REV. ADR. NO. 11323 51015 D 2950-A			
9. TITLE OF DEVIATION/WAIVER Permission to use Halfband S/N 211-1				10. CONTRACT NO. & LINE ITEM NAS 5-24200			
11. CONFIGURATION ITEM NOMENCLATURE Radiometer				12. CD NO. II			
13. NAME OF PART OR LARGEST ASSEMBLY AFFECTED Halfband Assy.				14. DEFECT CLASSIFICATION <input type="checkbox"/> MINOR <input checked="" type="checkbox"/> MAJOR <input type="checkbox"/> CRITICAL			
15. PART NO. OR TYPE DESIG. 51015				16. LOT NO. 211-1			
17. EFFECT ON COST/PRICE None if approved				18. EFFECT ON DELIVERY SCHEDULE None if approved			
19. EFFECT ON INTEGRATED LOGISTIC SUPPORT, INTERFACE, ETC. None				20. RECURRING DEVIATION/WAIVER <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO			
21. DESCRIPTION OF DEVIATION/WAIVER Permission to use Halfband S/N 211-1 with transient response settling to 1% by 90usec vs a specification of 60usec.							

24. NEED FOR DEVIATION/WAIVER

This unit had been reworked a number of times and this was the best result. Halfband has since been assembled into spare band level assembly S/N 501-2. Rework at this time is not considered cost effective.

25. PRODUCTION EFFECTIVITY BY SERIAL NUMBER 51065 SN 004 ONLY		26. AUTHORIZING ACTIVITY AUTHORIZING SIGNATURE [Signature]		27. APPROVAL/DISAPPROVAL a. <input type="checkbox"/> APPROVAL RECOMMENDED b. <input type="checkbox"/> APPROVED <input type="checkbox"/> DISAPPROVED	
28. GOVERNMENT ACTIVITY		29. SIGNATURE		30. DATE	

DD FORM 1694

ORIGINAL PAGE IS
OF POOR QUALITY

HUGHES

HUGHES AIRCRAFT COMPANY
SPACE AND COMMUNICATIONS GROUP
EL SEGUNDO, CALIFORNIA

SPACE AND COMMUNICATIONS GROUP
FAILURE REPORT

S 8231

ORIGINATOR	1. PROGRAM NAME AND NUMBER T.M. V011/PL1162		2. GLA	3. MODEL FLIGHT	4. TIME OBSERVED 2:00 P.M.	5. DATE OBSERVED MON. DA 27, YR 1982
	6. HARDWARE LEVEL WHEN FAILURE WAS OBSERVED <input type="checkbox"/> SPACECRAFT <input type="checkbox"/> SYSTEM		<input type="checkbox"/> SUBSYSTEM <input type="checkbox"/> UNIT	<input checked="" type="checkbox"/> ASSEMBLY <input type="checkbox"/> SUBASSEMBLY	<input type="checkbox"/> MODULE <input type="checkbox"/> MICAM	<input type="checkbox"/> CARD <input type="checkbox"/> PART
	EQUIPMENT IDENTIFICATION:					
	7. SUBSYSTEM		NAME		PART NUMBER	S/N
	8. UNIT					
	9. <input checked="" type="checkbox"/> ASSEMBLY <input type="checkbox"/> SUBASSEMBLY		NAME		PART NUMBER	S/N
	10. <input type="checkbox"/> MODULE <input type="checkbox"/> MICAM <input type="checkbox"/> CARD					
	11. OTHER					
	12. TEST WHEN FAILURE WAS OBSERVED <input type="checkbox"/> DEVELOPMENT <input checked="" type="checkbox"/> IN-PROCESS		<input type="checkbox"/> QUALIFICATION <input type="checkbox"/> ACCEPTANCE	<input type="checkbox"/> INTEGRATION <input type="checkbox"/> SYSTEM	<input type="checkbox"/> LAUNCH OPERATIONS	
	13. ENVIRONMENT WHEN FAILURE WAS OBSERVED <input checked="" type="checkbox"/> AMBIENT <input type="checkbox"/> EMC/RF		<input type="checkbox"/> RADIATION <input type="checkbox"/> VIBRATION	<input type="checkbox"/> TEMP AXIS FOR	<input type="checkbox"/> THERMAL VAC HRS AT	
14. DESCRIPTION OF FAILURE CHANNEL NO. 1 FAILS TO MEET TRANSIENT RESPONSE REQUIREMENTS IS: 1.5% AFTER 60 USEC. REQUIREMENT: $\leq 1.0\%$ AFTER 60 USEC						
15. TEST PROCEDURE 16306 4.6 N.C. JAVISON 2213 11/27/82						
ENGINEERING EVALUATION	16. VERIFICATION AND FAILURE ANALYSIS					
	17. FAILED ITEM NAME AND PART NUMBER					
	18. <input type="checkbox"/> FOLLOWING REWORK/RETEST REQUIRED <input checked="" type="checkbox"/> Rework/Retest Not Required Because Further work is not likely to bring better results. The operation of a component is essential.					
	19. AUTHORIZATION				20. CONTINUATION SHEET USED	21. QA REVIEW
	22. Rework/Retest Action Taken				23. QA RETEST	
	24. LIST ALL PARTS REPLACED					
	PART NUMBER	QCT SYM	PART LOT NUMBER	DATE CODE	MANUFACTURER	PROBABLE DEFECT
	25. Rework BY					
	26. RETESTED BY					
	27. CAUSE AND CORRECTIVE ACTION The settling time is dependent upon the distribution capacitance of the feedback network. With the circuitry as it is, this is as good as can be done. Ref W-158					
ENGINEERING/RELIABILITY	28. DOCUMENT IMPLEMENTING CORRECTIVE ACTION					
	29. BASIC CAUSE OF VERIFIED FAILURE <input checked="" type="checkbox"/> DESIGN <input type="checkbox"/> ENVIRONMENTAL <input type="checkbox"/> DEFECTIVE PARTS		30. TEST EQUIPMENT <input type="checkbox"/> TEST PROCEDURE <input type="checkbox"/> TEST SET-UP		31. MFG. PROCEDURE <input type="checkbox"/> ASSY/FAB ERROR <input type="checkbox"/> WORKMANSHIP	
	32. FAILURE TYPE <input type="checkbox"/> PRIMARY <input checked="" type="checkbox"/> INDUCED		33. FAILURE CLASSIFICATION <input type="checkbox"/> UNKNOWN <input type="checkbox"/> NO FAILURE		34. FAILURE CLASSIFICATION <input type="checkbox"/> CRITICAL <input type="checkbox"/> MAJOR	
	35. RESPONSIBLE ENGINEER W. J. J. J.		36. SPACECRAFT SYSTEM ENGINEER		37. CUSTOMER OR SUPPLIER	
	38. RELIABILITY		39. DATE		40. DATE	
	41. CONTINUATION SHEET USED					
	42. CONTINUATION SHEET USED					
	43. CONTINUATION SHEET USED					
	44. CONTINUATION SHEET USED					
	45. CONTINUATION SHEET USED					

ORIGINAL PAGE IS
OF POOR QUALITY

5-31

304
6045

828 →

CHANNEL 1

HB 5/2 211-1

01-27-82

C. R. Low

N. C. JAYSON, III

JAN 27, 1982

ORIGINAL PAGE IS
OF POOR QUALITY

REQUEST FOR DEVIATION/WAIVER
(SEE MIL-STD-883C OR 121 FOR INSTRUCTIONS)

DATE PREPARED

REQUIRING ACTIVITY NO.

1. ORIGINATOR NAME AND ADDRESS David M. Randall SBRC, 75 Corcoran Drive, Colata, CA 93117				2. <input type="checkbox"/> DEVIATION <input checked="" type="checkbox"/> WAIVER 3. <input type="checkbox"/> MINOR <input checked="" type="checkbox"/> MAJOR <input type="checkbox"/> CRITICAL	
4. DESIGNATION FOR DEVIATION/WAIVER a. MODEL TYPE Spare b. MFR. CODE 11323 c. SYS. DESIG. TM d. DEV/ASSEMBLY NO. W-158				5. BASE LINE AFFECTED <input checked="" type="checkbox"/> FUNCTIONAL <input type="checkbox"/> ALLOCATED <input type="checkbox"/> PROTECT	
6. OTHER SYSTEMS/COMPONENTS AFFECTED <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO				7. DRAWINGS AFFECTED a. SYSTEM b. ITEM 11323 c. TEST PLAN d. TITLE OF DEVIATION/WAIVER Permission to use Halfband S/N 101-1	
8. SPECIFICATIONS AFFECTED-TEST PLAN a. MFR. CODE b. SPEC./DOC. NO. c. ITEM d. SYSTEM e. ITEM 11323 f. TEST PLAN g. TITLE OF DEVIATION/WAIVER Permission to use Halfband S/N 101-1				9. CONTRACT NO. & LINE ITEM HAS S-24200	
11. CONFIGURATION TYPE AND RELATIONSHIP Radiometer 12. NAME OF PART NO. LOWEST ASSEMBLY AFFECTED Halfband Assembly 13. PART NO. ON TYPE DESIGN 51015				14. DEFECT NO. II 15. DEFECT CLASSIFICATION <input checked="" type="checkbox"/> MINOR <input type="checkbox"/> MAJOR <input type="checkbox"/> CRITICAL 16. LOT NO. 101-1 17. QTY 1 18. REQUIRING DEVIATION/WAIVER <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO 19. EFFECT ON COST/PRICE None if approved 20. EFFECT ON DELIVERY SCHEDULE None if approved 21. EFFECT ON INTEGRATED LOGISTIC SUPPORT, INTERFACE, ETC. None	
22. DESCRIPTION OF DEVIATION/WAIVER Permission to use Halfband S/N 101-1 with Ch. #1 Frequency response of +. 6dB at 20KHZ vs a specification of +.1 to -.9dB					

24. NEED FOR DEVIATION/WAIVER

This unit had been reworked a number of times and this was the best result. Half-band has since been assembled into spare band level assembly S/N 501-1. Rework at this time is not considered cost effective.

REA

5/11/82
DM Randall

SYS ENGR

5-13-82

RE

A. Perlman 5-13-82

QA

5-12-82

PE

5-13-82

25. PRODUCTION EFFECTIVITY BY SERIAL NUMBER

51065 SN 006 ONLY

26. SUBMITTING ACTIVITY AUTHORIZING SIGNATURE

5/11/82
F2 Phillips

27. APPROVAL/DISAPPROVAL

ASCT PROGRAM MGR.

APPROVAL RECOMMENDED
☐ APPROVED

DISAPPROVED
☐ APPROVED ☐ DISAPPROVED

28. SUBMITTING ACTIVITY

SIGNATURE

DATE

DD FORM 1694

ORIGINAL PAGE IS
OF POOR QUALITY

SPACE AND COMMUNICATIONS GROUP FAILURE REPORT

S 8401

HUGHES AIRCRAFT COMPANY
SPACE AND COMMUNICATIONS GROUP
EL SEGUNDO, CALIFORNIA

1. PROGRAM NAME AND NUMBER TM VOII		2. CLA FLT	3. MODEL P.M.	4. TIME OBSERVED MO 6 DA 3 YR 81
5. HARDWARE LEVEL WHEN FAILURE WAS OBSERVED <input type="checkbox"/> SPACECRAFT <input type="checkbox"/> SUBSYSTEM <input type="checkbox"/> ASSEMBLY <input type="checkbox"/> MODULE <input type="checkbox"/> CARD <input type="checkbox"/> SYSTEM <input type="checkbox"/> UNIT <input checked="" type="checkbox"/> SUBASSEMBLY <input type="checkbox"/> MECAM <input type="checkbox"/> PART				
EQUIPMENT IDENTIFICATION				
7. SUBSYSTEM		PART NUMBER		MANUFACTURER
8. UNIT		S/N		
9. <input type="checkbox"/> ASSEMBLY <input checked="" type="checkbox"/> SUBASSEMBLY		S1015-1 101-1		SERC
10. <input type="checkbox"/> MODULE <input type="checkbox"/> MECAM <input type="checkbox"/> CARD				
11. OTHER				
12. TEST WHEN FAILURE WAS OBSERVED <input type="checkbox"/> DEVELOPMENT <input type="checkbox"/> QUALIFICATION <input type="checkbox"/> INTEGRATION <input type="checkbox"/> LAUNCH OPERATIONS <input checked="" type="checkbox"/> IN-PROCESS <input type="checkbox"/> ACCEPTANCE <input type="checkbox"/> SYSTEM				
13. ENVIRONMENT WHEN FAILURE WAS OBSERVED <input checked="" type="checkbox"/> AMBIENT <input type="checkbox"/> RADIATION <input type="checkbox"/> TEMP <input type="checkbox"/> THERMAL VAC <input type="checkbox"/> VIBRATION <input type="checkbox"/> AXIS FOR <input type="checkbox"/> WRS AT <input type="checkbox"/> OTHER				
14. DESCRIPTION OF FAILURE FREQUENCY RESPONSE IS +.6 dB AT 20KHz CHS SHOULD BE +.1 TO -0.9 dB. CH 1				
15. TEST PROCEDURE 16306		16. PARA 4.6	17. ORIGINATOR N.C. DAVISON	18. DATE 6-4-81
19. VERIFICATION AND FAILURE ANALYSIS				
20. FOLLOWING REMOVAL/RETEST REQUIRED <input checked="" type="checkbox"/> REMOVAL/RETEST NOT REQUIRED BECAUSE Further removal is not likely to bring better results. No existence of any component occurred.				
21. AUTHORIZATION N.C. DAVISON		22. DATE 6/4/81	23. CONTINUATION SHEET USED	
24. REMOVAL/RETEST ACTION TAKEN				
25. LIST ALL PARTS REPLACED PART NUMBER CKT SYM PART LOT NUMBER DATE CODE MANUFACTURER PROBABLE DEFECT ANALYSIS NUMBER				
26. REMOVED BY ORG DATE				
27. RETESTED BY ORG DATE				
28. CAUSE AND CORRECTIVE ACTION The frequency response plateau is independent upon the different test components for the feedback resistor. With the current supply of resistors, this is as good as can be done. Rf 11-158				
29. DOCUMENT IMPLEMENTING CORRECTIVE ACTION				
30. BASIC CAUSE OF VERIFIED FAILURE <input type="checkbox"/> DESIGN <input type="checkbox"/> ENVIRONMENTAL <input type="checkbox"/> DEFECTIVE PARTS <input type="checkbox"/> TEST EQUIPMENT <input type="checkbox"/> TEST PROCEDURE <input type="checkbox"/> TEST SET-UP <input type="checkbox"/> MFG. PROCEDURE <input type="checkbox"/> ASSEMBLY ERROR <input type="checkbox"/> WORKMANSHIP <input type="checkbox"/> WIRING ERROR <input type="checkbox"/> ROUGH HANDLING <input type="checkbox"/> WEAR-OUT <input type="checkbox"/> UNKNOWN <input type="checkbox"/> DEFECT CODE				
31. FAILURE TYPE <input checked="" type="checkbox"/> PRIMARY <input type="checkbox"/> SECONDARY <input type="checkbox"/> UNKNOWN <input type="checkbox"/> NO FAILURE <input type="checkbox"/> CRITICAL <input type="checkbox"/> MAJOR <input type="checkbox"/> MINOR <input type="checkbox"/> SAFETY				
32. TESTED BY N.C. DAVISON		33. DATE 6/10/81	34. SPACECRAFT SYSTEM ENGINEER ORG DATE	
35. RELIABILITY		36. DATE	37. CUSTOMER OR SUPPLIER DATE	

COLD FOCAL PLANE/COOLER CABLE

Listing of Liens

COLD FOCAL PLANE/COOLER CABLE
P/N 50973

ORIGINAL PAGE IS
OF POOR QUALITY

FLIGHT

Failure Reports Number

Open	Closed
S8213(Spare)	F2387
S8218(Spare)	F2664
	F2665
	F2667
	S8018
	S8205
	S8207
	S8208
	S8209(Spare)
	S8219
	S8225
	S8226
	S8230
	S8319
	S8328(Spare)
	S8340
	S8394
	S8439
	S8439
	S8443
	S8461

Deviations/Waivers

D-141	W-109
	W-110
	W-111
	W-113
	W-130
	W-132
	W-133
	W-134
	W-135
	W-142
	W-146
	W-152
	W-153
	W-161
	W-162
	W-163
	W-164

COLD FOCAL PLANE

ORIGINAL PAGE IS
OF POOR QUALITY

P/N 50973

FLIGHT
Failure Report
No.

PROTFLIGHT
Failure Report
No.

ENGINEER
Failure Report
No.

Open	Closed	Open	Closed	Open	Closed
S8213	F2387		F0592		
(Spare)	F2664		F0607		
S8218	F2665		F0608		
(Spare)	F2667		F0610		
	S8018		F0614		
	S8205		F0615		
	S8207		F0616		
	S8208		F0617		
	S8209(Spare)		F0618		
			F0623		
	S8219		F1701		
	S8225		F1704		
	S8226		F1705		
	S8230		F1722		
	S8319		F1725		
	S8328(Spare)		F1726		
	S8340		F1727		
	S8394		F1749		
	S8438		F1754		
	S8439		F1755		
	S8443		F1767		
	S8461		F1770		

ORIGINAL PAGE IS
OF POOR QUALITY

REQUEST FOR DEVIATION/WAIVER
(SEE MIL-STD-380 OR 481 FOR INSTRUCTIONS)

DATE PREPARED

2-23-82

PROCURING ACTIVITY NO.

1. ORIGINATOR NAME AND ADDRESS David M. Randall SBRC, 75 Coromar Drive, Goleta, CA 93117				2. <input checked="" type="checkbox"/> DEVIATION <input type="checkbox"/> WAIVER	
				3. <input checked="" type="checkbox"/> MINOR <input type="checkbox"/> MAJOR <input type="checkbox"/> CRITICAL	
4. DESIGNATION FOR DEVIATION/WAIVER				5. BASE LINE AFFECTED	
6. MODEL/TYPE S	7. MFR. CODE 11323	8. SYS. DESIG. TH	9. DEV/WAIVER NO. D-141	<input checked="" type="checkbox"/> FUNCTIONAL <input type="checkbox"/> ALLOCATED <input type="checkbox"/> PRODUCT	10. OTHER SYSTEMS/CONFIGURATION ITEMS AFFECTED <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO
7. SPECIFICATIONS AFFECTED-TEST PLAN				8. DRAWINGS AFFECTED	
MFR. CODE SPEC./DOC. NO. SCH				MFR. CODE NUMBER REV. NOR. NO.	
a. SYSTEM				11323 *	
b. ITEM					
c. TEST PLAN					
9. TITLE OF DEVIATION/WAIVER Permission to use cooler cables of previous design				10. CONTRACT NO. & LINE ITEM NAS 5-24200	
11. CONFIGURATION ITEM NOMENCLATURE Radiometer				12. CD NO. II	
				13. DEFECT NO.	
				14. DEFECT CLASSIFICATION <input checked="" type="checkbox"/> MINOR <input type="checkbox"/> MAJOR <input type="checkbox"/> CRITICAL	
15. NAME OF PAGE OR LOWEST ASSEMBLY AFFECTED Spare (CFPA Assy)		16. PART NO. OR TYPE DESIGN 50973-B		17. LOT NO. 301	18. QTY 1
19. EFFECT ON COST/PRICE Greater than \$100,000 if not approved		20. EFFECT ON DELIVERY SCHEDULE Greater than six months if not approved			
21. EFFECT ON INTEGRATION/TESTING SUPPORT, INTERFACE, ETC. NONE					

23. DESCRIPTION OF DEVIATION/WAIVER

Permission to use cooler cables of a design that does not incorporate the latest artwork change. This artwork change enlarged the pad area around the solder pads at the distribution board end of the cable. The cables that will be used are of the same design as those used successfully on PF and F.

*Drawings Affected

SN	Number	Rev	NOR. No.
202	51393	C	3941A
301	50970	C	--
102	50974	D	--
202	50992	C	--

24. NEED FOR DEVIATION/WAIVER

The cables that were made with the latest artwork change, that incorporated the enlarged pad areas, were not plated to the proper thickness in the solder pad areas. As a result, the pads are being dissolved by solder. To reproduce cables of this design would require a six-month delay and be quite costly.

25. PRODUCTION EFFECTIVITY BY SERIAL NUMBER 004 51025 SN 004 ONLY		26. SIGNING ACTIVITY AUTHORIZING SIGNATURE JL Engel 2/25/82		27. TITLE MGR SYSTEMS ENGR.	
28. APPROVAL/RECOMMENDATION <input type="checkbox"/> APPROVAL RECOMMENDED		29. APPROVED <input checked="" type="checkbox"/> APPROVED		30. DISAPPROVED <input type="checkbox"/> DISAPPROVED	
31. GOVERNMENT ACTIVITY NASA GSFC		32. SIGNATURE George B. Gitt		33. DATE 3/1/82	
DD FORM 1694					

CF3

H

82598 PUMP-OUT

~~152-700122~~ 681547 151

1	10/1/1910	10/1/1910
2	10/1/1910	10/1/1910

Referral to Accessible Band 7 Detector with
Biometric Band 5 Detector.

11. (Classification) Type of material Radionuclide		12. Isotope II				13. Number of 1		14. Isotope designation 140	
15. Name of test or assay method employed Coupled Foetal Plasma Assay		16. Assay no. or assay code 90973-B		17. Lot no. 201		18. CFP I		19. Packaging description (contents) yes	
20. Time to complete \$10,000 if not approved.				21. Period to return results Two weeks if not approved.					
22. Order or request for testing received from INTERNAL USE									

This waiver requests permission to proceed thru mounting, wirebonding and testing the Band 7 detector with a discrepant Band 5 detector still on the FPA. The Band 5 detector has had conductive epoxy repair of open traces on Ch 10 & 12. Channel 10 has a shared detector after epoxy repair. All other channels, including Ch 17, are proceeding to qualification.

The FPA has had numerous detector changes and further detector changes could result in loss of the entire FPA. This matter will allow evaluation of the Band 7 detector before deciding whether to replace the Band 5 detector.

1. TO: <i>SECDEF</i> 2. FROM: <i>SECDEF</i> 3. SUBJECT: <i>SECDEF</i> 4. DATE: <i>9/29/64</i> 5. TIME: <i>10:00</i> 6. BY: <i>SECDEF</i> 7. CC: <i>SECDEF</i> 8. PC: <i>SECDEF</i> 9. STG: <i>SECDEF</i> 10. STG: <i>SECDEF</i> 11. STG: <i>SECDEF</i> 12. STG: <i>SECDEF</i> 13. STG: <i>SECDEF</i> 14. STG: <i>SECDEF</i> 15. STG: <i>SECDEF</i> 16. STG: <i>SECDEF</i> 17. STG: <i>SECDEF</i> 18. STG: <i>SECDEF</i> 19. STG: <i>SECDEF</i> 20. STG: <i>SECDEF</i> 21. STG: <i>SECDEF</i> 22. STG: <i>SECDEF</i> 23. STG: <i>SECDEF</i> 24. STG: <i>SECDEF</i> 25. STG: <i>SECDEF</i> 26. STG: <i>SECDEF</i> 27. STG: <i>SECDEF</i> 28. STG: <i>SECDEF</i> 29. STG: <i>SECDEF</i> 30. STG: <i>SECDEF</i> 31. STG: <i>SECDEF</i> 32. STG: <i>SECDEF</i> 33. STG: <i>SECDEF</i> 34. STG: <i>SECDEF</i> 35. STG: <i>SECDEF</i> 36. STG: <i>SECDEF</i> 37. STG: <i>SECDEF</i> 38. STG: <i>SECDEF</i> 39. STG: <i>SECDEF</i> 40. STG: <i>SECDEF</i> 41. STG: <i>SECDEF</i> 42. STG: <i>SECDEF</i> 43. STG: <i>SECDEF</i> 44. STG: <i>SECDEF</i> 45. STG: <i>SECDEF</i> 46. STG: <i>SECDEF</i> 47. STG: <i>SECDEF</i> 48. STG: <i>SECDEF</i> 49. STG: <i>SECDEF</i> 50. STG: <i>SECDEF</i> 51. STG: <i>SECDEF</i> 52. STG: <i>SECDEF</i> 53. STG: <i>SECDEF</i> 54. STG: <i>SECDEF</i> 55. STG: <i>SECDEF</i> 56. STG: <i>SECDEF</i> 57. STG: <i>SECDEF</i> 58. STG: <i>SECDEF</i> 59. STG: <i>SECDEF</i> 60. STG: <i>SECDEF</i> 61. STG: <i>SECDEF</i> 62. STG: <i>SECDEF</i> 63. STG: <i>SECDEF</i> 64. STG: <i>SECDEF</i> 65. STG: <i>SECDEF</i> 66. STG: <i>SECDEF</i> 67. STG: <i>SECDEF</i> 68. STG: <i>SECDEF</i> 69. STG: <i>SECDEF</i> 70. STG: <i>SECDEF</i> 71. STG: <i>SECDEF</i> 72. STG: <i>SECDEF</i> 73. STG: <i>SECDEF</i> 74. STG: <i>SECDEF</i> 75. STG: <i>SECDEF</i> 76. STG: <i>SECDEF</i> 77. STG: <i>SECDEF</i> 78. STG: <i>SECDEF</i> 79. STG: <i>SECDEF</i> 80. STG: <i>SECDEF</i> 81. STG: <i>SECDEF</i> 82. STG: <i>SECDEF</i> 83. STG: <i>SECDEF</i> 84. STG: <i>SECDEF</i> 85. STG: <i>SECDEF</i> 86. STG: <i>SECDEF</i> 87. STG: <i>SECDEF</i> 88. STG: <i>SECDEF</i> 89. STG: <i>SECDEF</i> 90. STG: <i>SECDEF</i> 91. STG: <i>SECDEF</i> 92. STG: <i>SECDEF</i> 93. STG: <i>SECDEF</i> 94. STG: <i>SECDEF</i> 95. STG: <i>SECDEF</i> 96. STG: <i>SECDEF</i> 97. STG: <i>SECDEF</i> 98. STG: <i>SECDEF</i> 99. STG: <i>SECDEF</i> 100. STG: <i>SECDEF</i> 101. STG: <i>SECDEF</i> 102. STG: <i>SECDEF</i> 103. STG: <i>SECDEF</i> 104. STG: <i>SECDEF</i> 105. STG: <i>SECDEF</i> 106. STG: <i>SECDEF</i> 107. STG: <i>SECDEF</i> 108. STG: <i>SECDEF</i> 109. STG: <i>SECDEF</i> 110. STG: <i>SECDEF</i> 111. STG: <i>SECDEF</i> 112. STG: <i>SECDEF</i> 113. STG: <i>SECDEF</i> 114. STG: <i>SECDEF</i> 115. STG: <i>SECDEF</i> 116. STG: <i>SECDEF</i> 117. STG: <i>SECDEF</i> 118. STG: <i>SECDEF</i> 119. STG: <i>SECDEF</i> 120. STG: <i>SECDEF</i> 121. STG: <i>SECDEF</i> 122. STG: <i>SECDEF</i> 123. STG: <i>SECDEF</i> 124. STG: <i>SECDEF</i> 125. STG: <i>SECDEF</i> 126. STG: <i>SECDEF</i> 127. STG: <i>SECDEF</i> 128. STG: <i>SECDEF</i> 129. STG: <i>SECDEF</i> 130. STG: <i>SECDEF</i> 131. STG: <i>SECDEF</i> 132. STG: <i>SECDEF</i> 133. STG: <i>SECDEF</i> 134. STG: <i>SECDEF</i> 135. STG: <i>SECDEF</i> 136. STG: <i>SECDEF</i> 137. STG: <i>SECDEF</i> 138. STG: <i>SECDEF</i> 139. STG: <i>SECDEF</i> 140. STG: <i>SECDEF</i> 141. STG: <i>SECDEF</i> 142. STG: <i>SECDEF</i> 143. STG: <i>SECDEF</i> 144. STG: <i>SECDEF</i> 145. STG: <i>SECDEF</i> 146. STG: <i>SECDEF</i> 147. STG: <i>SECDEF</i> 148. STG: <i>SECDEF</i> 149. STG: <i>SECDEF</i> 150. STG: <i>SECDEF</i> 151. STG: <i>SECDEF</i> 152. STG: <i>SECDEF</i> 153. STG: <i>SECDEF</i> 154. STG: <i>SECDEF</i> 155. STG: <i>SECDEF</i> 156. STG: <i>SECDEF</i> 157. STG: <i>SECDEF</i> 158. STG: <i>SECDEF</i> 159. STG: <i>SECDEF</i> 160. STG: <i>SECDEF</i> 161. STG: <i>SECDEF</i> 162. STG: <i>SECDEF</i> 163. STG: <i>SECDEF</i> 164. STG: <i>SECDEF</i> 165. STG: <i>SECDEF</i> 166. STG: <i>SECDEF</i> 167. STG	
--	--

Program Instruction 010

ORIGINAL PAGE IS
OF POOR QUALITY

REQUEST FOR DEVIATION/WAIVER
(SEE MIL-STD-440 OR -41 FOR INSTRUCTIONS)

DATE PREPARED

PROCURING ACTIVITY NO.

1. ORIGINATOR NAME AND ADDRESS David M. Randall				2. <input type="checkbox"/> DEVIATION <input checked="" type="checkbox"/> WAIVER			
				3. <input checked="" type="checkbox"/> MINOR <input type="checkbox"/> MAJOR <input type="checkbox"/> CRITICAL			
4. DESIGNATION FOR DEVIATION/WAIVER				5. BASE LINE AFFECTED			
6. MODEL/TYPE F	7. MFR. CODE 11323	8. SYS. DESIG. TM	9. DEV/WAIVER NO. W-110	<input checked="" type="checkbox"/> FURTHER FUNCTIONAL	<input type="checkbox"/> ALLO- CATED	<input type="checkbox"/> PROG. UCT	10. OTHER SYSTEMS/COMPLI- RATION ITEMS AFFECTED
11. SPECIFICATIONS AFFECTED-TEST PLAN				12. DRAWINGS AFFECTED			
MFR. CODE SPEC./COC. NO. SCH				MFR. CODE NUMBER REV. MGR. NO.			
13. SYSTEM				14. TEST PLAN			
15. TEST PLAN				16. CONTRACT NO. & LINE ITEM			
17. TITLE OF DEVIATION/WAIVER Permission to test and repair discrepant Band 7 Detector.				18. NAS 5-24200			
19. CONFIGURATION TYPE/COMPLIANCE Radiometer				20. CD NO. II			
21. NAME OF PART OR LARGEST ASSEMBLY AFFECTED Cooled Focal Plane Assy				22. DEFECT NO. 50973-B			
23. LOT NO. 201				24. QTY 1			
25. EFFECT ON COST/PRICE \$30,000 if not approved.				26. EFFECT ON DELIVERY SCHEDULE Two weeks if not approved			
27. EFFECT ON INTEGRATED LOGISTIC SUPPORT, INTERFACE, ETC. None				28. REQUIRES DEVIATION/WAIVER <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO			
29. DESCRIPTION OF DEVIATION/WAIVER							

This waiver requests permission to test ~~and then repair discrepancies described in~~
~~NSR 277754 and NSR 277757. Copies of NSR's are attached. The results of~~
~~this test and physical examination of all remaining detectors in stock~~
~~(flight stores) will be reviewed with NASA prior to repair and test.~~

14. NEED FOR DEVIATION/WAIVER

The FPA has had numerous detector changes and further detector changes could result in loss of the entire FPA. This waiver will allow evaluation of the Band 7 detector before deciding whether to replace it.

REA <i>David M. Randall</i> SYS ENGR		RE <i>A. J. Wilson</i>
15. PRODUCTION EFFECTIVITY BY SERIAL NUMBER 003 51065 SN 003 ONLY		QA <i>David M. Randall</i> 10-7-81
16. EXEMPTING ACTIVITY AUTHORITY SIGNATURE <i>George B. Birt</i> 7 OCT '81		PE <i>A. J. Wilson</i>
17. APPROVAL/DISAPPROVAL		CMO <i>George B. Birt</i>
<input type="checkbox"/> APPROVAL RECOMMENDED		<input checked="" type="checkbox"/> APPROVED <input type="checkbox"/> DISAPPROVED
18. GOVERNMENT ACTIVITY NASA G.S.E.C.		SIGNATURE <i>George B. Birt</i> DATE 10/7/81
DD FORM 1694		

NOTICE OF REVISION (NOR)
(SEE MIL-STD-480 FOR INSTRUCTIONS)

W-110-R1

This revision described below has been authorized for the document listed.

1. ORIGINATOR NAME AND ADDRESS D. Randall		DATE 9 Oct. '81	WFO CODE 11323	NOB. NO. 2870A
2. TITLE OF DOCUMENT Permission to test and repair discrepant Band 7 Detector		3. WFO CODE 11323	4. DOCUMENT NUMBER 50793	
7. CONFIGURATION ITEM (OR SYSTEM) TO WHICH ECP APPLIES Cooled Focal Plane Assy.		5. REVISION LETTER (REVISION) B	6. ECP NO. (ECP) 16951	8. CLASS Minor
8. DESCRIPTION OF REVISION Test results are acceptable. Request permission to repair and retest as required.				

ORIGINAL PAGE IS
OF POOR QUALITY

REA *A. Wilkins for D. Randall*

SYS ENGR

9 Oct 81
Chasing for JENGALPE A. Wilkins

9. THIS SECTION FOR GOVERNMENT USE ONLY

A. CHECK ONE		
<input type="checkbox"/> EXISTING DOCUMENT SUPPLEMENTED BY THIS EOR MAY BE USED IN MANUFACTURE.	<input type="checkbox"/> REVISED DOCUMENT MUST BE RECEIVED BEFORE MANUFACTURER MAY INCORPORATE THIS CHANGE.	<input type="checkbox"/> CUSTODIAN OF MASTER DOCUMENT SHALL HAVE ABOVE REVISIONS AND FURNISH REVISED DOCUMENT TO:
B. ACTIVITY AUTHORIZED TO APPROVE CHANGE FOR GOVERNMENT		C. ACTIVITY ACCOMPLISHING REVISION
SIGNATURE AND TITLE <i>[Signature]</i>		DATE 10/9/81
REVISION COMPLETED (DATE)		
NASA - GSFC		

DD FORM 1695

HUGHES

HUGHES AIRCRAFT COMPANY

NONCONFORMING MATERIAL REPORT (NCMR)

NO. 211134

DATE 10/5/81

PAGE 1 OF 1

PROGRAM ID TM

V012

7PRG

PART NO.

5095D (8)

S/N 706-3316-13

162

ENG. CHANGES

NOMENCLATURE

InSA Detector Array

WORK ORDER DOC NO.

LOT SIZE

1.0

QTY. SUSP.

1.0

SUSPENDED IN

1.0 process

MANUFACTURE I.D. NO.

REF. DOCUMENTS

5095D Oper 318 Supp. 1

MRCO 27757 Oper 200

SUPPLIER

SARC

DIV. OR LOCATION

SUPPLIER CODE

P.O. NO.

ITEM NO.

R.R. NO.

ITEM NO.	QTY INSP.	QTY SUSP.	DESCRIPTION OF NONCONFORMANCE	RESP. DEPT.	PRIOR OCCUR	M.R. LEVEL	CODE
1	1	1	Hole ~ .0014" deep in end of bond pad - Ch. 9.	SARC	0	MRB	G
2	1	1	Det Return adjacent to Ch. 9 bonding pad - Redundant pad removed, 750% of main pad removed.	SARC	0	MRB	G
3	1	1	Ch 10 bond pad - pad ~ 60% removed (.0014" long - .0035" wide)	SARC	0	MRB	G

ORIGINATOR B. L. Montgomery DATE 10/5/81

QUALITY B. L. Montgomery DATE 10/5/81

ENGINEERING M. R. R. DATE 10/5/81

ITEM NO.	DISP. CODE	DISPOSITION/INSTRUCTIONS	STAMP
1	B	The Cracks. Tole not a problem if unit tests good.	
2	E	Repair per MRCO	
3	B	The Cracks. Adequate bonding pad remains if bond looks good and pull tests good.	
		DISPOSITIONAL REPORTED. THERE REMAINS CRACKS AND STRESS LINES ADJACENT TO DETECTOR RETURN & CH 9. DEFECTS NOT CONSIDERED MINOR. UNIT REQUIRES REWORK TO DP OR W	
		ALSO Ref AFDR D-60-81	

ENGINEERING M. R. R. DATE 10/5/81

QUALITY B. L. Montgomery DATE 10/5/81

ENGINEERING M. R. R. DATE 10/5/81

ITEM NO.	CAUSE OF NONCONFORMANCE	RESULTS OF CORRECTIVE ACTION INVESTIGATION	CORRECTIVE ACTION
1,2,3	Removed during removal of oxide chips - chips are due to damage during the dicing operation.	1,2,3 - Dicing procedure changed to utilize diamond saw rather than the wire saw previously used.	

SIGNATURE B. L. Montgomery DATE 10/6/81

SIGNATURE B. L. Montgomery DATE 10/6/81

RESPONSIBILITY	DEBIT VENDOR	DISP. CODE	VENDOR PACKING SHEET	QTY. R.T.V.	QTY. SCRAP	BUYER'S SIGNATURE	DATE	COPY
VENDOR	HAC	YES	NO					
<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>					

11678 CS OCT

DISTRIBUTION: 1. Original; 2. Copy; 3. Copy; 4. More

ORIGINAL PAGE IS
OF POOR QUALITYORIGINAL PAGE IS
OF POOR QUALITY

HUGHES

HUGHES AIRCRAFT COMPANY

NONCONFORMING MATERIAL REPORT (NCMR)

DATE 10/5/81

PROGRAM ID

V012

TM

7 PRG

PAGE 1 OF 1

PART NO. 50973 (B)	S/N 201	ENG. CHANGES		NOMENCLATURE CFP Assy (Band 7 wire bonding)	
WORK ORDER DOC NO.	LOT SIZE 1	QTY. SUSP. 1	SUSPENDED IN In process	HARDWARE I.D. NO.	REF. DOCUMENTS MRCO 277752 AIR 50973 Suppl 70 per 31
SUPPLIER		DIV. OR LOCATION	SUPPLIER CODE	P.O. NO.	ITEM NO. N.N. NO.

ITEM NO.	QTY INSP.	QTY SUSP.	DESCRIPTION OF NONCONFORMANCE	RESP. DEPT.	PRIOR OCCUR	M.N. LEVEL	CODE
1	1	1	Crescent band Ch. 9 - per SP80195 3; - no visible line of undisturbed metal alongside the band.	SRRC	0	MRA	G
2	1	1	Trace Ch. 9 (on band pad) ~80% open	SRRC	0	MRA	G
3	1	1	Crescent band appears to be partially over void in the bonding pad - 2 P1 - Ch. 7, Ch. 2	SRRC	0	MRA	G

ORIGINATOR A.L. Montgomery	DATE 10/5/81	QUALITY B.L. Montgomery	DATE 10/5/81	ENGINEERING [Signature]	DATE 10/5/81
ITEM NO.	DISP. CODE	DISPOSITION/INSTRUCTIONS			STAMP
1	E	Repair per MRCO			
2	E	Repair per MRCO			
3	B	The gold. Void is small and adequate trace remains, and pull test good.			10/6/81
<p>④ DISPOSITION REJECTED. THERE REMAINS EVIDENCE OF CRACKS & STRESS LINES ADJACENT TO DETECTOR RETURN & CH9. DEFECTS NOT CONSIDERED MINOR. UNIT REQUIRES REWORK TO BY</p>					

ENGINEERING [Signature]	DATE 10/5/81	QUALITY B.L. Montgomery	DATE 10/5/81	CUSTOMER ALSO REF AFDR D-060-81
ITEM NO.	CAUSE OF NONCONFORMANCE	RESULTS OF CORRECTIVE ACTION INVESTIGATION	CORRECTIVE ACTION	
1	Improperly placed wire band	Verbal instructions to the operator regarding		
2,3	Gold removed during removal of wire band.	Procedure to be followed if rework is required		
	Improperly placed wire band required removal, poor adherence of the Au to the Ti resulted in loss of gold.			

SIGNATURE A.L. Montgomery		DATE 10/5/81		SIGNATURE B.L. Montgomery		DATE 10/6/81	
RESPONSIBILITY	DEBIT VENDOR	DISP. CODE	VENDOR PACKING SHEET	QTY. R.T.V.	QTY. SCRAP	BUYERS SIGNATURE	COPY
VENDOR	HAC	YES	NO				
<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>				

11628 CS OC

DISTRIBUTION: 1. Original; 2. Copy; 3. Copy; 4. Hard

ORIGINAL PAGE IS
OF POOR QUALITY

Program Instruction 010

REQUEST FOR DEVIATION/WAIVER
(SEE MIL-STD-460 OR 481 FOR INSTRUCTIONS)

DATE PREPARED

PROCURING ACTIVITY NO.

1. ORIGINATOR NAME AND ADDRESS D.M. Randall SBRC, 75 Corowar Dr., Golata, Ca. 93117				2. <input type="checkbox"/> DEVIATION <input checked="" type="checkbox"/> WAIVER			
3. <input checked="" type="checkbox"/> MINOR <input type="checkbox"/> MAJOR <input type="checkbox"/> CRITICAL				4. DESIGNATION FOR DEVIATION/WAIVER			
5. MODEL TYPE F	6. WFR. CODE 11323	7. SYS. DESIG. TM	8. DEV/WAIVER NO. W111	9. BASE LINE AFFECTED <input checked="" type="checkbox"/> FUNCTIONAL <input type="checkbox"/> ALLOCATED <input type="checkbox"/> PRODUCT		10. OTHER SYSTEMS/CONFIGURATION ITEMS AFFECTED <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO	
11. SPECIFICATIONS AFFECTED-TEST PLAN				12. GRADINGS AFFECTED			
13. SYSTEM				14. WFR. CODE 11323			
15. ITEM				16. NUMBER 50973			
17. TEST PLAN				18. DEV. NO. 2870 A			
19. TITLE OF DEVIATION/WAIVER Permission to continue testing with discrepant Band 5 and Band 7 detectors.				20. CONTRACT NO. & LINE ITEM NAS 5-24200			
21. CONFIGURATION ITEM NOMENCLATURE Radiometer				22. CB NO. II			
23. NAME OF PART OR LATEST ASSEMBLY AFFECTED Cooled Focal Plane Assy				24. DEFECT NO. 50973-B			
25. EFFECT ON COST/PRICE \$60,000 if not approved.				26. DEFECT CLASSIFICATION <input checked="" type="checkbox"/> MINOR <input type="checkbox"/> MAJOR <input type="checkbox"/> CRITICAL			
27. EFFECT ON INTEGRATED LOGISTIC SUPPORT, INTERFACE, ETC. None				28. LOT NO. 201			
29. DESCRIPTION OF DEVIATION/WAIVER This waiver requests permission to continue testing thru determination of postamp selects with CH 10 Band 5 disconnected and silver epoxy repaired traces on the Band 7 detector.				30. QTY 1			
31. EFFECT ON DELIVERY SCHEDULE Four weeks if not approved.				32. RECURRING DEVIATION/WAIVER <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO			

14. NEED FOR DEVIATION/WAIVER

This waiver will allow the CFPA to proceed while a major waiver to allow use of FPA with discrepant Band 5 and 7 detectors is being reviewed.

REA <i>D.M. Randall</i>	SYS ENGR <i>J.H. Engel</i>	RE <i>[Signature]</i>	QA <i>[Signature]</i>	PE <i>A.J. Wilken</i>
29. PRODUCTION EFFECTIVITY BY SERIAL NUMBER C03 51065 SN C03 ONLY		CMO <i>[Signature]</i>		
30. SIGNATURE AND AUTHORITY SIGNATURE <i>J.H. Engel</i> 811016		31. MINOR - System Engineering MAJOR/CRITICAL - Program Manager		
32. APPROVAL, DISAPPROVAL <input type="checkbox"/> APPROVAL RECOMMENDED		33. APPROVED <i>[Signature]</i> <input type="checkbox"/> DISAPPROVED		
34. GOVERNMENT ACTIVITY		35. SIGNATURE <i>[Signature]</i> DATE <i>10-16-81</i>		

ORIGINAL PAGE IS
OF POOR QUALITY

Program Instruction 010

REQUEST FOR DEVIATION/WAIVER
(SEE MIL-STD-883C OR INSTRUCTIONS)

DATE PREPARED

PROCURING ACTIVITY NO.

1. ORIGINATOR NAME AND ADDRESS: David M. Randall
SBRC, 75 Coronar Dr., Goleta, Ca. 93117

2. ☒ DEVIATION ☒ WAIVER
☒ MINOR ☐ MAJOR ☐ CRITICAL

3. DESIGNATION FOR DEVIATION/WAIVER				5. BASE LINE AFFECTED		6. OTHER SYSTEMS/CONFIGURATION ITEMS AFFECTED	
a. MODEL TYPE	b. MFR. CODE	c. SYS. DESIGN.	d. DERIVATIVE NO.	<input checked="" type="checkbox"/> FUNCTIONAL	<input type="checkbox"/> ALLOCATED	<input type="checkbox"/> PRODUCT	<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO
	11323	TM	W-113				
7. SPECIFICATION AFFECTED-TEST PLAN				8. DRAWINGS AFFECTED			
a. MFR. CODE				b. NUMBER			
c. SPEC. DOC. NO.				d. REV.			
e. SN				f. MFR. NO.			
9. SYSTEM				11323			
10. ITEM				50958			
11. TEST PLAN				B			
12. TITLE OF TEST PLAN				-			

Permission to use non-conforming InSb Detectors

13. CONTRACT NO. & LINE ITEM
NAS 5-24200

14. IDENTIFICATION OF NONCONFORMANCE		15. CD NO.		16. DEFECT NO.		17. DEFECT CLASSIFICATION	
Radiometer		II				<input checked="" type="checkbox"/> MINOR <input type="checkbox"/> MAJOR <input type="checkbox"/> CRITICAL	
18. NAME OF PART OR LOOSEST ASSEMBLY AFFECTED		19. PART NO. OR TYPE DESIGN.		20. LOT NO.		21. QTY	
InSb Detector Arrays		50958-B				4	
22. EFFECT ON PRICE		23. EFFECT ON DELIVERY SCHEDULE		24. REQUIRING DEVIATION/WAIVER			
Greater than \$200,000 if not approved.		Three months if not approved.		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO			
25. EFFECT ON INTEGRATED LOGISTIC SUPPORT, INTERFACE, ETC.							
None							

26. DESCRIPTION OF DEVIATION/WAIVER

This waiver requests permission to use InSb Detector Arrays SN 906-3316-11 #114, 906-3316-11 #88, 906-3316-13 #??, and 906-3316-A-13 #102. These arrays have small oxide chips and cracks at their edges. The chips that represent potential loose particles will be bonded in place using 2216 epoxy and then tested to verify they are still good electrically. After rework of the Arrays the Array selected shall be assembled to the Cold Focal Plane Assembly and be subjected to : a base line test, 10 temperature cycles, a repeat test, then visually examined for acceptance.

*The serial number on this array cannot be read.

In addition each array will be temp cycled 10 times at the array level and inspected prior to use.

27. NEED FOR DEVIATION/WAIVER

These arrays are the only candidate arrays for replacing the discrepant Band 7 detector presently on the Flight CFPA. It will be at least three months before new detectors can be processed.

28. PRODUCT OR EFFECTIVITY BY SERIAL NUMBER		29. APPROVAL		30. DISAPPROVAL	
003 51065 SN 003 ONLY		<input checked="" type="checkbox"/> APPROVED		<input type="checkbox"/> DISAPPROVED	
31. SIGNATURE		32. SIGNATURE		33. SIGNATURE	
J. B. Engel 10/29/81		George B. Britt 11/2/81			
34. APPROVAL		35. APPROVAL		36. APPROVAL	
NASC GSFC					
DD FORM 1694					

ORIGINAL PAGE IS
OF POOR QUALITY

GENERAL FLOW OF DISCREPANT InSb Detectors

per Waiver W-113

1. The four array's will be inspected and each defect (crack) will be measured and a photo taken of the array.
2. The array's will be subjected to 10 temp. cycles ambient to liquid nitrogen.
3. Visually inspected and photographed.
4. One will be selected for mounting on the CFPA and mounted.
5. Visually inspected/photographed
6. Temperature cycled 10 times in a dewar.
7. Visually inspected/photographed.

ORIGINAL PAGE IS
OF POOR QUALITY

REQUEST FOR DEVIATION/WAIVER
(SEE HIL-STD-400 OR 481 FOR INSTRUCTIONS)

DATE PREPARED

PROCURING ACTIVITY NO.

1. ORIGINATOR NAME AND ADDRESS David M. Randall SBRC, 75 Coromar Dr., Goleta, Ca. 93117				2. <input type="checkbox"/> DEVIATION <input checked="" type="checkbox"/> WAIVER			
				3. <input checked="" type="checkbox"/> MINOR <input type="checkbox"/> MAJOR <input type="checkbox"/> CRITICAL			
4. DESIGNATION FOR DEVIATION/WAIVER				5. BASE LINE AFFECTED			
a. MODEL/TYPE Spare	b. MFR. CODE 11323	c. SYS. DESIG. TM	d. DEV/WAIVER NO. W-130	<input checked="" type="checkbox"/> FUNC. TIONAL <input type="checkbox"/> ALLO. CATED		<input type="checkbox"/> PROD. UCT	
				6. OTHER SYSTEMS/CONFIGURATION ITEMS AFFECTED <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO			
7. SPECIFICATIONS AFFECTED-TEST PLAN				8. DRAWINGS AFFECTED			
a. SYSTEM		b. ITEM		c. TEST PLAN		d. CONTRACT NO. & LINE ITEM	
						NAS 5-24200	
9. TITLE OF DEVIATION/WAIVER Permission to use Spare CFPA with damaged traces.							
11. CONFIGURATION ITEM NOMENCLATURE Radiometer				12. CD NO. II			
				13. DEFECT NO.			
				14. DEFECT CLASSIFICATION <input checked="" type="checkbox"/> MINOR <input type="checkbox"/> MAJOR <input type="checkbox"/> CRITICAL			
15. NAME OF PART OR LARGEST ASSEMBLY AFFECTED PWB, Distribution		16. PART NO. OR TYPE DESIG. 50968		17. LOT NO.		18. QTY 1	
				19. RECURRING DEVIATION/WAIVER <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO			
20. EFFECT ON COST/PRICE Greater than \$20,000-if not approved				21. EFFECT ON DELIVERY SCHEDULE 4 weeks if not approved.			
22. EFFECT ON INTEGRATED LOGISTIC SUPPORT, INTERFACE, ETC. None							
23. DESCRIPTION OF DEVIATION/WAIVER Copper traces on distribution PWB were damaged during a trimming operation. The traces are not cut thru and examination of a like defect on a spare board shows that adequate trace remains. Damage is per NCMR 392551. More than half of trace remains intact.							
24. NEED FOR DEVIATION/WAIVER To rework this board would require removal and reinstallation of 100 wire bonds. The rework to the board itself would need to be developed and if unsuccessful would result in a new procurement that would take an additional 6 to 8 weeks. There is also some risk in removing and reinstalling the wirebonds.							

24. NEED FOR DEVIATION/WAIVER


To rework this board would require removal and reinstallation of 100 wire bonds. The rework to the board itself would need to be developed and if unsuccessful would result in a new procurement that would take an additional 6 to 8 weeks. There is also some risk in removing and reinstalling the wirebonds.

25. PRODUCTION EFFECTIVITY BY SERIAL NUMBER 004		26. SUBMITTING ACTIVITY AUTHORIZING SIGNATURE <i>[Signature]</i> 1/20/82		27. APPROVAL/DISAPPROVAL	
28. GOVERNMENT ACTIVITY NASA GSFC		29. SIGNATURE <i>[Signature]</i> 1/20/82		30. DATE 1/20/82	
31. APPROVAL RECOMMENDED <input type="checkbox"/>		32. APPROVED <input checked="" type="checkbox"/>		33. DISAPPROVED <input type="checkbox"/>	
34. DD FORM 1 DEC 80 1694					

DD FORM 1 DEC 80 1694

ORIGINAL PAGE IS
OF POOR QUALITY

operation 500 H. sep. 2.
11/7/81



ORIGINAL PAGE IS OF POOR QUALITY

REQUEST FOR DEVIATION/WAIVER
(SEE MIL-STD-883C FOR INSTRUCTIONS)

DATE PREPARED

1-30-82

PROCURING ACTIVITY NO.

71

1. ORIGINATOR NAME AND ADDRESS David M. Randall SBRC, 75 Coromar Dr., Goleta, CA 93117				2. <input type="checkbox"/> DEVIATION <input checked="" type="checkbox"/> WAIVER	
				3. <input checked="" type="checkbox"/> MINOR <input type="checkbox"/> MAJOR <input type="checkbox"/> CRITICAL	
4. DESIGNATION FOR DEVIATION/WAIVER					
6. MODEL/TYPE F	9. MFR. CODE 11323	8. SYS. DESIG. TM	4. DEV/WAIVER NO. W-133	5. BASE LINE AFFECTED <input checked="" type="checkbox"/> FUNCTIONAL <input type="checkbox"/> ALLOCATED <input type="checkbox"/> PRODUCTION	
				6. OTHER SYSTEMS/CONFIGURATION ITEMS AFFECTED <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO	
7. SPECIFICATIONS AFFECTED-TEST PLAN					
MFR. CODE		SPEC./DOC. NO.		SCN	
8. DRAWINGS AFFECTED					
MFR. CODE		NUMBER		REV.	
11323		50958		B	
9. TITLE OF DEVIATION/WAIVER Permission to use non-conforming InSb Detectors					
10. CONTRACT NO. & LINE ITEM NAS 5-24200					
11. CONFIGURATION ITEM NOMENCLATURE Radiometer				12. CD NO. II	
				13. DEFECT NO.	
				14. DEFECT CLASSIFICATION <input checked="" type="checkbox"/> MINOR <input type="checkbox"/> MAJOR <input type="checkbox"/> CRITICAL	
15. NAME OF PART OR LARGEST ASSEMBLY AFFECTED InSb Detector Arrays		16. PART NO. OR TYPE DESIGN 50958-B		17. LOT NO.	
				18. QTY 4	
19. EFFECT ON COST/PRICE Greater than \$200,000 if not approved -				20. RECURRING DEVIATION/WAIVER <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO	
21. EFFECT ON DELIVERY SCHEDULE Three months if not approved					
22. EFFECT ON INTEGRATED LOGISTIC SUPPORT, INTERFACE, ETC. None					

23. DESCRIPTION OF DEVIATION/WAIVER This waiver cancels and supersedes W-113. This waiver requests permission to use InSbDetector Arrays SN 906-3316-11 #114, 906-3316-11 #88, 906-3316-13, #?*, and 906-3316-A-13 #102. These arrays have small oxide chips and cracks at their edges. The chips that represent potential loose particles will be bonded in place using 2216 epoxy and then tested to verify they are still good electrically. After rework of the Arrays, the Array selected shall be assembled to the Cold Focal Plane Assembly, tested, then visually examined for acceptance.

*The serial number on this array cannot be read.

In addition each array will be temp cycled 10 times at the array level and inspected prior to use.

24. NEED FOR DEVIATION/WAIVER

These arrays are the only candidate arrays for replacing the discrepant Band 7&5 detectors presently on the Flight CFPA. It will be at least three months before new detectors can be processed.

25. PRODUCTION EFFECTIVITY BY SERIAL NUMBER 003		RE <i>[Signature]</i> 21-1- QA <i>[Signature]</i> 21-1- PE <i>[Signature]</i>	
26. SUBMITTING ACTIVITY AUTHORIZING SIGNATURE <i>[Signature]</i>		TITLE PROGRAM MANAGER	
27. APPROVAL/DISAPPROVAL			
<input type="checkbox"/> APPROVAL RECOMMENDED		<input checked="" type="checkbox"/> APPROVED <input type="checkbox"/> DISAPPROVED	
C. GOVERNMENT ACTIVITY NASA GSFC		SIGNATURE <i>[Signature]</i> DATE 7-1-82	
DD FORM 1694			

ORIGINAL PAGE IS
OF POOR QUALITY

REQUEST FOR DEVIATION/WAIVER
(SEE MIL-STD-430 OR 481 FOR INSTRUCTIONS)

DATE PREPARED

1-27-82

PROCURING ACTIVITY NO. *41*

1. ORIGINATOR NAME AND ADDRESS David M. Randall SBRC, 75 Coromar Dr., Goleta, CA 93117				2. <input type="checkbox"/> DEVIATION <input checked="" type="checkbox"/> WAIVER	
				3. <input checked="" type="checkbox"/> MINOR <input type="checkbox"/> MAJOR <input type="checkbox"/> CRITICAL	
4. DESIGNATION FOR DEVIATION/WAIVER				5. BASE LINE AFFECTED	
6. MODEL TYPE F	7. MFR. CODE 11323	8. SYS. DESIG. TM	9. DEV/WAIVER NO. W-132	<input checked="" type="checkbox"/> FURTHER TYPICAL	<input type="checkbox"/> ALLO- CATED
				<input type="checkbox"/> PROD- UCT	
				<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO	
7. SPECIFICATIONS AFFECTED-TEST PLAN				8. OTHER SYSTEMS/CONFIG- URATION ITEMS AFFECTED	
9. MFR. CODE				10. DRAWINGS AFFECTED	
SPEC./DOC. NO.					
SON					
11. SYSTEM				12. MFR. CODE	
				11323	
13. ITEM				14. NUMBER	
				50958	
15. TEST PLAN				16. REV.	
				B	
17. TITLE OF DEVIATION/WAIVER				18. CONTRACT NO. & LINE ITEM	
Permission to use non-conforming InSb Detectors				NAS 5-24200	
19. CONFIGURATION ITEM NOMENCLATURE				20. CLASSIFICATION OF DEFECT	
Radiometer				21. DEFECT CLASSIFICATION	
				<input checked="" type="checkbox"/> MINOR <input type="checkbox"/> MAJOR <input type="checkbox"/> CRITICAL	
22. NAME OF PART OR LOWEST ASSEMBLY AFFECTED				23. DEFECT NO.	
InSb Detector Arrays				II	
24. PART NO. OR TYPE DESIG.				25. LOT NO.	
50958				2	
26. EFFECT ON COST/PRICE				27. EFFECT ON DELIVERY SCHEDULE	
Greater than \$200,000 if not approved				Two months if not approved	
28. EFFECT ON INTEGRATED LOGISTIC SUPPORT, INTERFACE, ETC.				29. RECURRING DEVIATION/WAIVER	
NONE				<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO	
30. DESCRIPTION OF DEVIATION/WAIVER					

This waiver requests permission to use InSb Detector Arrays SN 906-3316-13 #66 and #112. These arrays have small oxide chips and cracks at their edges. The chips that represent potential loose particles will be bonded in place using 2216 epoxy after the array is bonded on the FPA. Selection of these arrays is based on the following: 1.) Best available detectors from Lot 15 for workmanship (cracks and chips) per product specification 16026. 2.) All performance specifications were acceptable (i.e. 10 meg resistance).


31. NEED FOR DEVIATION/WAIVER

These arrays are the best candidate arrays for replacing the discrepant Band 7 Detector presently on the Flight CFPA. The latest lots, 19 and 20, have exhibited 1/F noise on the FPA and it will be two months before a new lot can be fabricated and qualified.

32. REASON FOR DEVIATION/WAIVER		33. APPROVAL/DISAPPROVAL	
These arrays are the best candidate arrays for replacing the discrepant Band 7 Detector presently on the Flight CFPA. The latest lots, 19 and 20, have exhibited 1/F noise on the FPA and it will be two months before a new lot can be fabricated and qualified.			
34. NEED FOR DEVIATION/WAIVER		35. APPROVAL/DISAPPROVAL	
These arrays are the best candidate arrays for replacing the discrepant Band 7 Detector presently on the Flight CFPA. The latest lots, 19 and 20, have exhibited 1/F noise on the FPA and it will be two months before a new lot can be fabricated and qualified.			
36. NEED FOR DEVIATION/WAIVER		37. APPROVAL/DISAPPROVAL	
These arrays are the best candidate arrays for replacing the discrepant Band 7 Detector presently on the Flight CFPA. The latest lots, 19 and 20, have exhibited 1/F noise on the FPA and it will be two months before a new lot can be fabricated and qualified.			
38. NEED FOR DEVIATION/WAIVER		39. APPROVAL/DISAPPROVAL	
These arrays are the best candidate arrays for replacing the discrepant Band 7 Detector presently on the Flight CFPA. The latest lots, 19 and 20, have exhibited 1/F noise on the FPA and it will be two months before a new lot can be fabricated and qualified.			
39. APPROVAL/DISAPPROVAL		40. APPROVAL/DISAPPROVAL	
<input type="checkbox"/> APPROVAL RECOMMENDED		<input checked="" type="checkbox"/> APPROVED <input type="checkbox"/> DISAPPROVED	
41. GOVERNMENT ACTIVITY		42. SIGNATURE	
NASA GSFC		George B. Bitt	
43. DATE		44. DATE	
1/28/82		1/28/82	
45. DD FORM 1694		46. DD FORM 1694	

FLR


AFTER CLEANING ON MRCO
DIMENSIONS ARE IN MILS



**ORIGINAL PAGE IS
OF POOR QUALITY**

PJR
1/27/82

NOTE: FAR FEWER TINY BLACK PARTICLES.



ORIGINAL PAGE IS
OF POOR QUALITY

REQUEST FOR DEVIATION/WAIVER
(SEE MIL-STD-460 OR 461 FOR INSTRUCTIONS)

DATE PREPARED

2-5-82

PROCURING ACTIVITY NO.

H

1. ORIGINATOR NAME AND ADDRESS David M. Randall SBRC, 75 Coromar Drive, Goleta, CA 93117				2. <input type="checkbox"/> DEVIATION <input checked="" type="checkbox"/> WAIVER	
				3. <input checked="" type="checkbox"/> MINOR <input type="checkbox"/> MAJOR <input type="checkbox"/> CRITICAL	
4. DESIGNATION FOR DEVIATION/WAIVER				5. BASE LINE AFFECTED	
a. MODEL/TYPE 7	b. MFR. CODE 11323	c. S.I.S. DESIG. TM	d. DEV/WAIVER NO. W-134	<input checked="" type="checkbox"/> FUNC. TIONAL	<input type="checkbox"/> ALLO- CATED
				<input type="checkbox"/> PROD- UCT	<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO
7. SPECIFICATIONS AFFECTED-TEST PLAN				8. DRAWINGS AFFECTED	
a. SYSTEM	b. ITEM	c. TEST PLAN	d. MFR. CODE	e. NUMBER	f. REV.
			11323	50973	B
9. TITLE OF DEVIATION/WAIVER Permission to use CFPA with void in circuit trace.				10. CONTRACT NO. & LINE ITEM NAS 5-24200	
11. CONFIGURATION ITEM NOMENCLATURE Radiometer				12. CD NO. II	
				13. DEFECT NO.	
				14. DEFECT CLASSIFICATION <input checked="" type="checkbox"/> MINOR <input type="checkbox"/> MAJOR <input type="checkbox"/> CRITICAL	
15. NAME OF PART OR LARGEST ASSEMBLY AFFECTED Cold Focal Plane Assy.		16. PART NO. OR TYPE DESIG. 50973-B		17. LOT NO. 201	18. QTY 1
19. RECURRING DEVIATION/WAIVER <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO					
20. EFFECT ON COST/PRICE Greater than \$500,000 if not approved.				21. EFFECT ON DELIVERY SCHEDULE 4 months if not approved.	
22. EFFECT ON INTEGRATED LOGISTIC SUPPORT, INTERFACE, ETC. NONE					

23. DESCRIPTION OF DEVIATION/WAIVER

This waiver requests permission to use the CFPA with a possible void in the ceramic substrate trace that goes to Band 7 detector Ch. #2.

Reference NCMR 277671

24. NEED FOR DEVIATION/WAIVER

There is a pit in the substrate that the trace goes over. This pit has been filled in with 2216 epoxy residue from repeated InSb detector replacements and the trace in the pit is thus covered and not inspectable. The trace only has to be capable of passing 3×10^{-9} amps. The trace tests good electrically,

REA <i>DM Randall</i> 2/5/82		SYS ENGR <i>Philip J. Eng</i> 2/5/82		RE <i>[Signature]</i> 2/5/82	
QA <i>[Signature]</i> 2-5-8		PE <i>[Signature]</i> 2-5-8		CNO. <i>[Signature]</i> 3-5	
25. PRODUCTION EFFECTIVITY BY SERIAL NUMBER 003 51065 SN 003 ONLY					
26. AUTHORIZING ACTIVITY AUTHORIZING SIGNATURE <i>FR Phillips</i>			TITLE PROGRAM MANAGER		
27. APPROVAL/DISAPPROVAL					
a. <input type="checkbox"/> APPROVAL RECOMMENDED			b. <input checked="" type="checkbox"/> APPROVED <input type="checkbox"/> DISAPPROVED		
c. GOVERNMENT ACTIVITY NASA GSFC.			SIGNATURE <i>George B. Litch</i> 2/9/82		

DD FORM 1694

HES
ALL COMPANY

NONCONFORMING MATERIAL REPORT (NCMR)

07 03 15

NO. 277671
DATE 1/15/82
PAGE 1 OF

PROGRAM ID V412 TM 7PRG

50973 (B)		S/N FLIGHT 201	ENG. CHANGES 2870A 3845A		NOMENCLATURE COLD FOCAL PLANE ASSY.	
DER DOC NO.	LOT SIZE 1	QTY. SUSP. 1	SUSPENDED IN INPROCESS	HARDWARE I.D. NO. 50973	REF. DOCUMENTS 50973 AHR5 CP 2538 SUPP.	
SBRC		DIV. OR LOCATION 060		SUPPLIER CODE 11323	P.O. NO.	ITEM NO. R.R. NO.

QTY NSP.	QTY SUSP.	DESCRIPTION OF NONCONFORMANCE	RESP. DEPT.	PRIOR OCCUR	M.R. LEVEL	CODE
1	1	BAND 7 CHANNEL 2 VOID IN THE TRACE GREATER THAN 50% TO UNKNOWN		1	MRS	G
1	1	BAND 7 CHANNEL 6 VOID IN THE TRACE GREATER THAN 50% TO 55%		1	MRS	G
		* VISUAL INSPECTION CANNOT DETERMINE THE AMOUNT OF TOTAL VOID IN TRACE				

FOR P. E. Ryan	DATE 1/15/82	QUALITY MD	DATE 1-15-82	ENGINEERING	DATE 1/15/82
DISPOSITION/INSTRUCTIONS				STAMP	
E The acir. There is adequate trace left to carry the signal (3.0V ² A) across the detector generator.					
WARRANT REQUIRED.				PER NASA TO COORDINATION OK TO PROCEED TO TEST TO VERIFY OPERATION OF BAND 7 CH 2.	

ING	DATE 1/15/82	QUALITY MD	DATE 1-15-82	CUSTOMER	DATE
CAUSE OF NONCONFORMANCE		RESULTS OF CORRECTIVE ACTION INVESTIGATION		CORRECTIVE ACTION	
Improvement - possibly due to process required to change staff detection		MULTIPLE PROCESS CAUSE AND C/A NOT REQ'D			
WARRANT REQUIRED					

ORIGINAL PAGE IS
OF POOR QUALITY

ORIGINAL PAGE IS
OF POOR QUALITY

REQUEST FOR DEVIATION/WAIVER
(SEE VLS-SUP-CPU OR 481 FOR INSTRUCTIONS)

DATE PREPARED

2-17-82

PROCURING ACTIVITY NO.

11-50

1. REQUESTOR NAME AND ADDRESS

David M. Randall
SBRC, 75 Coromar Drive, Goleta, CA 93117

2. ☐ DEVIATION ☒ WAIVER
3. ☐ MINOR ☒ MAJOR ☐ CRITICAL

4. DESIGNATION FOR DEVIATION/WAIVER

6. MODEL/TYPE F 7. MFR. CODE 11323 8. SYS. DESIG. TM 9. DEV/WAIVER NO. W-135

5. BASE LINE AFFECTED

☒ FUNCTIONAL ☐ ALLOCATED ☐ PRODUCT

10. OTHER SYSTEMS/CONFIGURATION ITEMS AFFECTED

☐ YES ☒ NO

11. SPECIFICATIONS AFFECTED-TEST PLAN

12. MFR. CODE 13. SPEC./DOC. NO. 14. SCN
15. SYSTEM 16. ITEM 17. TEST PLAN

8. DRAWINGS AFFECTED

18. MFR. CODE 19. NUMBER 20. REV. 21. NOR. NO.
11323 50973 B 3895A, 2870A

18. TITLE OF DEVIATION/WAIVER

Permission to use F-1 CFPA with discrepancies per FR8208

10. CONTRACT NO. & LINE IT

NAS 5-24200

19. CONFIGURATION ITEM NOMENCLATURE

Radiometer

CLASSIFICATION OF DEFECT

12. CD NO. 13. DEFECT NO. 14. DEFECT CLASSIFICATION
11 ☒ MINOR ☐ MAJOR ☐ CRITICAL

15. NAME OF PART OR LOWEST ASSEMBLY AFFECTED

CFPA

16. PART NO. OR TYPE DESIG.

50973

17. LOT NO.

201

18. QTY

1

19. RECURRING DEVIATION/WAIVER

☐ YES ☒ NO

20. EFFECT ON COST/PRICE

> 50,000 if not approved

21. EFFECT ON DELIVERY SCHEDULE

4 weeks if not approved

22. EFFECT ON INTEGRATED LOGISTIC SUPPORT, INTERFACE, ETC.

23. DESCRIPTION OF DEVIATION/WAIVER

Permission to use F-1 CFPA with discrepancies per FR 8208.
A copy of FR 8208 is attached -

24. NEED FOR DEVIATION/WAIVER

To determine selects that would improve the pulse response would require removal of the optical filter assembly and retest. This is a risky operation and there is no guaranty that the results of reselection would give in specification performance. Discrepancies are small and will not affect performance enough to warrant rework.

REA

4/12/82
DM Randall

SYS ENGR

JH Engel

RE

QA

PE

2/1/82
2/1/82
2/1/82

25. PRODUCTION EFFECTIVITY BY SERIAL NUMBER

003

26. SUBMITTING ACTIVITY AUTHORIZING SIGNATURE

FR Hullips

TITLE

Program Manager

27. APPROVAL/DISAPPROVAL

☒ APPROVAL RECOMMENDED

☒ APPROVED

☐ DISAPPROVED

28. GOVERNMENT ACTIVITY

LANDSAT-D PROJECT OFFICE

SIGNATURE

David Weinstein

DATE

2/18/82

DD FORM 1694

HUGHESHUGHES AIRCRAFT COMPANY
SPACE AND COMMUNICATIONS GROUP
EL SEGUNDO, CALIFORNIAORIGINAL PAGE IS
OF POOR QUALITY
SPACE AND COMMUNICATIONS GROUP
FAILURE REPORT

S 8208

ORIGINATOR	1. PROGRAM NAME AND NUMBER T.M. (PL 1162)		2. GLA	3. MODEL FLT-1	4. TIME OBSERVED VARIOUS	5. DATE OBSERVED MO 2 DA 11 YR 1982		
	6. HARDWARE LEVEL WHEN FAILURE WAS OBSERVED <input type="checkbox"/> SPACECRAFT <input type="checkbox"/> SUBSYSTEM <input checked="" type="checkbox"/> ASSEMBLY <input type="checkbox"/> MODULE <input type="checkbox"/> CARD		<input type="checkbox"/> SYSTEM <input type="checkbox"/> UNIT <input type="checkbox"/> SUBASSEMBLY <input type="checkbox"/> MICAM <input type="checkbox"/> PART					
	EQUIPMENT IDENTIFICATION		NAME	PART NUMBER	S/N	MANUFACTURER		
	7. SUBSYSTEM							
	8. UNIT							
	9. <input checked="" type="checkbox"/> ASSEMBLY <input type="checkbox"/> SUBASSEMBLY		CFPA IN DEWAR	50973	201	SBRC		
	10. <input type="checkbox"/> MODULE <input type="checkbox"/> MICAM <input type="checkbox"/> CARD							
	11. OTHER							
	12. TEST WHEN FAILURE WAS OBSERVED <input type="checkbox"/> DEVELOPMENT <input checked="" type="checkbox"/> IN-PROCESS <input type="checkbox"/> QUALIFICATION <input type="checkbox"/> ACCEPTANCE <input type="checkbox"/> INTEGRATION <input type="checkbox"/> SYSTEM <input type="checkbox"/> LAUNCH OPERATIONS							
	13. ENVIRONMENT WHEN FAILURE WAS OBSERVED <input type="checkbox"/> AMBIENT <input type="checkbox"/> RADIATION <input checked="" type="checkbox"/> TEMP 92.5 K <input type="checkbox"/> THERMAL VAC <input type="checkbox"/> HRS AT <input type="checkbox"/> EMC/RFI <input type="checkbox"/> VIBRATION <input type="checkbox"/> AXIS FOR <input type="checkbox"/> MIN TYPE <input type="checkbox"/> OTHER							
14. DESCRIPTION OF FAILURE		SEE CONTINUATION SHEETS A AND B.						
ENGINEERING EVALUATION	15. TEST PROCEDURE		16. PARA 4.14, 4.15	17. ORIGINATOR	18. ORG	19. DATE		
	16192			N.C. DAVISON, JR.	2213	11, 1982		
	19. VERIFICATION AND FAILURE ANALYSIS							
	20. <input type="checkbox"/> FOLLOWING REWORK/RETEST REQUIRED <input checked="" type="checkbox"/> Rework/Retest Not Required Because		Microprocessor are small and will not be replaced.					
	21. AUTHORIZATION		22. ORG		23. DATE			
	N.W. Davidson		2/21		2/5/82			
	24. REWORK/RETEST ACTION TAKEN		NONE					
	25. LIST ALL PARTS REPLACED							
	PART NUMBER		CRT SYM	PART LOT NUMBER	DATE CODE	MANUFACTURER	PROBABLE DEFECT	ANALYSIS NUMBER
	26. REWORK BY		ORG	DATE	27. RETESTED BY		ORG	DATE
ENGINEERING/RELIABILITY	28. CAUSE AND CORRECTIVE ACTION		The R.F. response microprocessor is defective. It is the microprocessor on the FRB circuitry on the FRB. It is a 16-bit microprocessor and the R.F. response is not correct. The microprocessor is small and will not be replaced. The microprocessor is small and will not be replaced. The microprocessor is small and will not be replaced.					
	29. DOCUMENT IMPLEMENTING CORRECTIVE ACTION		FRB CLOSURE					
	30. BASIC CAUSE OF VERIFIED FAILURE <input checked="" type="checkbox"/> DESIGN <input type="checkbox"/> ENVIRONMENTAL <input type="checkbox"/> TEST EQUIPMENT <input type="checkbox"/> TEST PROCEDURE <input type="checkbox"/> TEST SET-UP <input type="checkbox"/> MFG. PROCEDURE <input type="checkbox"/> ASSY/FAB ERROR <input type="checkbox"/> WORKMANSHIP <input type="checkbox"/> WIRING ERROR <input type="checkbox"/> ROUGH HANDLING <input type="checkbox"/> WEAR-OUT <input type="checkbox"/> UNKNOWN		DEFECT CODE					
	31. FAILURE TYPE <input type="checkbox"/> PRIMARY <input checked="" type="checkbox"/> INDUCED <input type="checkbox"/> UNKNOWN <input type="checkbox"/> NO FAILURE		32. FAILURE CLASSIFICATION <input type="checkbox"/> CRITICAL <input type="checkbox"/> MAJOR <input checked="" type="checkbox"/> MINOR <input type="checkbox"/> SAFETY					
	33. RESPONSIBLE ENGINEER		ORG	DATE	34. SPACECRAFT SYSTEM ENGINEER			
	1/1/82		2/21	2/5/82				
	35. RELIABILITY		ORG	DATE				

ORIGINAL PAGE IS
OF POOR QUALITY

SPACE AND COMMUNICATION GROUP
EQUIPMENT CHECKOUT
FAILURE REPORT

CONTINUATION SHEET

HUGHES

HUGHES AIRCRAFT COMPANY

S 8208 CONT. 5
FR SERIAL NO. LETTER

*LABEL FIRST CONTINUATION SHEET USED 'A', SECOND 'B', AND SO ON

IDENTIFY ENTRIES BY REFERENCING FR BLOCK NUMBER IN COLUMN, DATE EACH ENTRY.

ADDITIONAL
CONTINUATION
SHEET(S) USE

14 BAND 5 HAS THE FOLLOWING OUT OF SPEC. CONDITIONS:
PER 16192 PARAGRAPH 4.14

TRANSIENT RESPONSE SPEC: $\pm 10\%$ OVERSHOOT

CH. 4	IS	10.4%	CH. 10	IS	10.5%
CH. 6	IS	10.8%	CH. 11	IS	11.2%
CH. 7	IS	11.0%	CH. 12	IS	10.8%
CH. 9	IS	11.5%			

SETTLING TIME SPEC: SETTLED TO WITHIN 1.5% AFT
 $\pm 2\%$ + 30 μ SEC
SETTLED TO WITHIN 1.0% AFT
 $\pm 2\%$ + 60 μ SEC

CH. 10 IS + 2% AFTER 38 μ SEC
+ 1.5% AFTER 40 μ SEC
+ 1.0% AFTER 45 μ SEC

3 DB POINTS : SPEC: - 2 TO - 3 DB AT 52 KHZ

CH. 10 IS - 3.19 DB AT 52 KHZ
CH. 12 IS - 1.95 DB AT 52 KHZ

DELAY TIMES SPEC: DELAY TIMES SHALL BE WITH
 $\pm 0.5 \mu$ SEC OF EACH OTHER

ALL CHANNELS AS A POPULATION DO NOT MEET
THIS REQUIREMENT.

RISE TIME (IN μ SEC)

FALL TIME (IN μ SEC)

1	12.2	9	12.0
2	12.0	10	13.0
3	12.4	11	12.0
4	12.0	12	12.2
5	11.6	13	12.0
6	12.6	14	12.4
7	11.9	15	11.6
8	12.4	16	12.6

1	13.1	9	12.7
2	12.5	10	13.8
3	13.0	11	12.5
4	12.6	12	12.8
5	12.2	13	12.5
6	13.1	14	13.0
7	12.4	15	12.1
8	13.0	16	13.1

ORIGINAL PAGE IS
OF POOR QUALITY

HUGHES

HUGHES AIRCRAFT COMPANY

SPACE AND COMMUNICATION GROUP
EQUIPMENT CHECKOUT
FAILURE REPORT
CONTINUATION SHEET

S 8208 CONT. SHEET
FR SERIAL NO. LETTER B

*LABEL FIRST CONTINUATION SHEET USED 'A', SECOND 'B', AND SO ON

IDENTIFY ENTRIES BY REFERENCING FR BLOCK NUMBER IN COLUMN, DATE EACH ENTRY.

ADDITIONAL FR
CONTINUATION
SHEET(S) USED

14 BAND 7 HAS THE FOLLOWING OUT OF SPEC. CONDITIONS:
PER 16192 PARAGRAPH 4.14

TRANSIENT RESPONSE: SPEC: $\leq 10\%$ OVERSHOOT

CH. 6 IS 11.0%

SETTLING TIMES SPEC: SETTLED TO WITHIN 1.5%
AFTER $t_{200} + 30 \mu\text{SEC}$
SETTLED TO WITHIN 1.0%
AFTER $t_{200} + 60 \mu\text{SEC}$.

CH. 5 IS SETTLED TO 1.5% AFTER $33 \mu\text{SEC}$

CH. 5 " " " 1.0% AFTER $35 \mu\text{SEC}$

3 dB POINTS SPEC: -2 TO -3 dB AT 52 KHz

CH. 5 IS -3.25 dB AT 52 KHz

CH. 16 IS -3.32 dB AT 52 KHz

DELAY TIMES SPEC: DELAY TIMES SHALL BE WITHIN
 $\pm 0.5 \mu\text{SEC}$ OF EACH OTHER

ALL CHANNELS AS A POPULATION DO NOT MEET
THIS REQUIREMENT

RISE TIME DELAY (IN μSEC)

FALL TIME DELAY (IN μSEC)

1 12.0

9 12.9

1 12.3

9 13.4

2 12.1

10 12.5

2 12.5

10 13.2

3 11.8

11 12.4

3 12.2

11 12.9

4 12.5

12 12.3

4 12.8

12 12.7

5 12.0

13 12.2

5 12.6

13 12.6

6 12.3

14 12.4

6 12.6

14 12.8

7 12.2

15 12.3

7 12.5

15 12.8

8 12.6

16 13.0

8 13.0

16 13.4

ORIGINAL PAGE IS
OF POOR QUALITY

REQUEST FOR DEVIATION/WAIVER
(SEE MIL-STD-480 OR 481 FOR INSTRUCTIONS)

DATE PREPARED

3-4-82

PROCURING ACTIVITY NO.

1. ORIGINATOR NAME AND ADDRESS David M. Randall SBRC, 75 Coromar Dr., Goleta, CA 93117				2. <input type="checkbox"/> DEVIATION <input checked="" type="checkbox"/> WAIVER			
				3. <input checked="" type="checkbox"/> MINOR <input type="checkbox"/> MAJOR <input type="checkbox"/> CRITICAL			
4. DESIGNATION FOR DEVIATION/WAIVER				5. BASE LINE AFFECTED			
a. MODEL/TYPE F	b. MFR. CODE 11323	c. SYS. DESIG. TM	d. DEV/WAIVER NO. W-142	<input checked="" type="checkbox"/> FUNCTIONAL <input type="checkbox"/> ALLOCATED <input type="checkbox"/> PRODUCT		6. OTHER SYSTEMS/CONFIGURATION ITEMS AFFECTED <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO	
7. SPECIFICATIONS AFFECTED-TEST PLAN				8. DRAWINGS AFFECTED			
a. SYSTEM				b. ITEM			
c. TEST PLAN							
9. TITLE OF DEVIATION/WAIVER Permission to use F-1 CFPA with discrepant substrate				10. CONTRACT NO. & LINE ITEM NAS 5-24200			
11. CONFIGURATION ITEM NOMENCLATURE Radiometer				12. CD NO. II			
				13. DEFECT NO.			
				14. DEFECT CLASSIFICATION <input checked="" type="checkbox"/> MINOR <input type="checkbox"/> MAJOR <input type="checkbox"/> CRITICAL			
15. NAME OF PART OR LOWEST ASSEMBLY AFFECTED Substrate CFPA				16. PART NO. OR TYPE DESIGN 50956-D		17. LOT NO. 013	
				18. QTY 1		19. RECURRING DEVIATION/WAIVER <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO	
20. EFFECT ON COST/PRICE >2,000,000 if not approved				21. EFFECT ON DELIVERY SCHEDULE >1.5 years if not approved			
22. EFFECT ON INTEGRATED LOGISTIC SUPPORT, INTERFACE, ETC. NONE							

23. DESCRIPTION OF DEVIATION/WAIVER
This waiver requests permission to use the F-1 CFPA with the following discrepancies against its substrate:

- 1) Assembly was built to planning which was never reviewed and accepted by AF and contains no inspections of any kind.
- 2) Depositions were performed without released process procedures (none referenced in AHR).
- 3) Resistance measurement data attached to AHR indicates substrate did not meet requirement specified in Drawing Note 15.
- 4) Deposition thickness not recorded at Operation 3150.

24. REED FOR DEVIATION/WAIVER

This substrate cannot be replaced without completely rebuilding the F-1 CFPA. The CFPA has been tested successfully and a rebuild due to the above listed discrepancies is not deemed cost or schedule effective.

REA <u>DM Randall</u> 3/4/82		SYS ENGR <u>JL Engel</u>		RE <u>James</u> 3/4
				QA <u>W. J. Jones</u> 3-4-82
				PE <u>Simul. J. Jones</u> 3/4
25. PRODUCTION EFFECTIVITY BY SERIAL NUMBER 003 51065 SN CO3 ONLY				C.M.O. <u>James</u> 3-8
26. SUBMITTING ACTIVITY AUTHORIZING SIGNATURE				
27. APPROVAL/DISAPPROVAL				
<input type="checkbox"/> APPROVAL RECOMMENDED		<input checked="" type="checkbox"/> APPROVED		<input type="checkbox"/> DISAPPROVED
c. GOVERNMENT ACTIVITY NASA GSEC		SIGNATURE George B. Smith		DATE 3/9/82
DD FORM 1694				

ORIGINAL PAGE IS
OF POOR QUALITY

Attachment to Request for Deviation/Waiver No. W-142

1. Assembly Planning (AHR) was issued for use in the fall of 1978. Investigation which was performed on the Protoflight Model, which had the same problem, was accepted, however, there appears to be no documentation to support this investigation.
2. Depositions were performed per standard procedures (hand-written) with the AHR defining the amount to be evaporated, during 1978 - 1980 period. However, the evaporation lab utilizes Laboratory Procedure Instructions (LPI) which are now being changed to Manufacturing Production Engineering Instructions (MPEI). MPEI's are being released through Production Engineering under W.G. Speth.
3. Resistance Measurements recorded on attached AHR data sheet do not meet requirements specified on drawing Note 15 which says that: "Pad to Pad resistance of traces shall not exceed 3.0 ohms." The resistance of the traces is minimal and will not have a measurable affect on the detector performance. This variation is inherent in chemical evaporation processing. See Table below for actual readings.

<u>Measurement Point to Point</u>	<u>Specification</u>	<u>Before Temp Cycle</u>	<u>After Temp Cycle</u>
Hg Cd to 5-3(-)	<3 ohms	1.8	1.7
5-3(+)	"	3.4 (OT)	2.7
5-4 -	"	4.3 (UT)	3.7 (OT)
5-4(+)	"	5.1 (OT)	4.7 (OT)
5-2(-)	"	5.0 (OT)	5.0 (OT)
5-2(+)	"	4.5 (OT)	3.8 (OT)
5-1(-)	"	3.4 (OT)	2.7
5-1(+)	"	1.8	1.7
T, Top (-)	"	2.8	2.7

OT - Out of Tolerance

4. Deposition thickness was not recorded at operation 3150. In reviewing previous history the run number 1984 which was the same for the Protoflight substrate used indicates that the lab log book for Run number 1984 recorded a thickness of 2000 angstroms on October 8, 1978.

ORIGINAL PAGE IS
OF POOR QUALITY

REQUEST FOR DEVIATION/WAIVER
(SEE MIL-STD-480 OR 481 FOR INSTRUCTIONS)

DATE PREPARED

3-29-82

PROCURING ACTIVITY NO.

P

1. ORIGINATOR NAME AND ADDRESS David M. Randall SBRC, 75 Coromar Dr., Goleta, CA 93117				2. <input type="checkbox"/> DEVIATION <input checked="" type="checkbox"/> WAIVER																			
				3. <input checked="" type="checkbox"/> MINOR <input type="checkbox"/> MAJOR <input type="checkbox"/> CRITICAL																			
4. DESIGNATION FOR DEVIATION/WAIVER a. MODEL/TYPE PF, F, & S b. MFR. CODE 11323 c. SYS. DESIG. TM d. DEV/WAIVER NO. W-146				5. BASE LINE AFFECTED <input checked="" type="checkbox"/> FUNC-TIONAL <input type="checkbox"/> ALLO-CATED <input type="checkbox"/> PROD-UCT				6. OTHER SYSTEMS/CONFIGURATION ITEMS AFFECTED <input type="checkbox"/> YES <input type="checkbox"/> NO															
7. SPECIFICATIONS AFFECTED-TEST PLAN								8. DRAWINGS AFFECTED															
a. SYSTEM				b. ITEM				c. TEST PLAN				MFR. CODE NUMBER REV. NOR. NO.											
												11323 50959 8 ---											
9. TITLE OF DEVIATION/WAIVER Permission to use HCT detectors made without released planning.												10. CONTRACT NO. & LINE ITEM NAS 5-24200											
11. CONFIGURATION ITEM Nomenclature Radiometer												12. CD NO. II				13. DEFECT NO.				14. DEFECT CLASSIFICATION <input checked="" type="checkbox"/> MINOR <input type="checkbox"/> MAJOR <input type="checkbox"/> CRITICAL			
15. NAME OF PART OR LOGEST ASSEMBLY AFFECTED Det. Array Band 6, HCT								16. PART NO. OR TYPE DESIG. 50959				17. LOT NO. 4				18. QTY				19. RECURRING DEVIATION/WAIVER <input type="checkbox"/> YES <input type="checkbox"/> NO			
20. EFFECT ON COST/PRICE > 20,000,000 if not approved												21. EFFECT ON DELIVERY SCHEDULE > 1 1/2 years if not approved											
22. EFFECT ON INTEGRATED LOGISTIC SUPPORT, INTERFACE, ETC. None																							
23. DESCRIPTION OF DEVIATION/WAIVER All of the HCT detectors made for use in the PF, F, and S CFPAs were fabricated and tested without released planning and proper quality and Air Force inspections. These detectors were processed as lot #4 and bear the serial numbers V-29-G-XXX where XXX is a three digit number. This waiver requests permission to use these detectors.																							

24. NEED FOR DEVIATION/WAIVER

These detectors have been fully tested and meet all qualification test requirements. These detectors have already been incorporated in the PF & F units and replacement is not deemed to be cost or schedule effective.

25. PRODUCTION EFFECTIVITY BY SERIAL NUMBER 002		26. SUPPORTING ACTIVITY AUTHORIZING SIGNATURE J. L. ... 4/2/82 Mr. Systems Engineering	
27. APPROVAL/DISAPPROVAL <input type="checkbox"/> APPROVAL RECOMMENDED		28. APPROVAL/DISAPPROVAL <input checked="" type="checkbox"/> APPROVED <input type="checkbox"/> DISAPPROVED	
29. GOVERNMENT ACTIVITY NASA GSFC.		30. SIGNATURE George B. ... 4/5/82	
DD FORM 1694			

ORIGINAL PAGE IS
OF POOR QUALITY

REQUEST FOR DEVIATION/WAIVER
(SEE MIL-STD-460 OR -481 FOR INSTRUCTIONS)

DATE PREPARED

PROCURING ACTIVITY NO. *H*

1. ORIGINATOR NAME AND ADDRESS David M. Randall SBRC, 75 Coromar Drive, Goleta, CA 93117				2. <input type="checkbox"/> DEVIATION <input checked="" type="checkbox"/> WAIVER	
				3. <input checked="" type="checkbox"/> MINOR <input type="checkbox"/> MAJOR <input type="checkbox"/> CRITICAL	
4. DESIGNATION FOR DEVIATION/WAIVER				5. BASE LINE AFFECTED	
6. MODEL TYPE Spare	7. MFR. CODE 11323	8. SYS. DESIG. TM	9. DEV/WAIVER NO. W-152	<input checked="" type="checkbox"/> FUNCTIONAL <input type="checkbox"/> ALLOCATED <input type="checkbox"/> PRODUCT	10. OTHER SYSTEMS/CONFIGURATION ITEMS AFFECTED <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO
7. SPECIFICATIONS AFFECTED-TEST PLAN				8. DRAWINGS AFFECTED	
9. SYSTEM				10. CONTRACT NO. & LINE ITEM	
11. TITLE OF DEVIATION/WAIVER Permission to use non-conforming InSb Detectors				NAS 5-24200	
12. CONFIGURATION ITEM NOMENCLATURE Radiometer				13. DEFECT NO. 11	
14. NAME OF PART OR LARGEST ASSEMBLY AFFECTED InSb Detector Arrays				15. DEFECT CLASSIFICATION <input type="checkbox"/> MINOR <input type="checkbox"/> MAJOR <input type="checkbox"/> CRITICAL	
16. PART NO. OR TYPE DESIGN 50958-G				17. LOT NO. 3	
18. QTY 3				19. RECURRING DEVIATION/WAIVER <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO	
20. EFFECT ON COST/PRICE Greater than \$100,000 if not approved				21. EFFECT ON DELIVERY SCHEDULE 3 months if not approved	
22. EFFECT ON INTEGRATED LOGISTIC SUPPORT, INTERFACE, ETC. NONE					
23. DESCRIPTION OF DEVIATION/WAIVER					

This waiver requests permission to use InSb Detector Arrays SN 906-3316-13 #66 and 102, and 906-3316-11 #114. These arrays have oxida chips and cracks at their edges. The chips that represent potential loose particles will be bonded in place using 2216 epoxy after the array is bonded on the FPA. These arrays were on waivers 132 and 133 for use on the F-1 CFPA.

24. NEED FOR DEVIATION/WAIVER

These arrays are the best candidates for the spare CFPA. New lots of InSb detectors have not yielded good arrays and there is not any firm data that indicates good arrays will result from lot 24 presently being processed.

25. PRODUCTION EFFECTIVITY BY SERIAL NUMBER 004 51065 SN CO4 ONLY		26. SUBMITTING ACTIVITY AND SIGNATURE 4/20/82 SYSTEMS ENGINEERING	
27. APPROVAL, DISAPPROVAL <input type="checkbox"/> APPROVAL RECOMMENDED <input checked="" type="checkbox"/> APPROVED <input type="checkbox"/> DISAPPROVED		28. SIGNATURE George B. Little 4/20/82	
29. GOVERNMENT ACTIVITY NASA GSFC		30. DATE 4/20/82	
DD FORM 1694			

ORIGINAL PAGE IS
OF POOR QUALITY

REQUEST FOR DEVIATION/WAIVER
(SEE MIL-STD-480 OR 481 FOR INSTRUCTIONS)

DATE PREPARED

PROCURING ACTIVITY NO.

6 May 1982

1. ORIGINATOR NAME AND ADDRESS David M. Randall, Santa Barbara Research Center 75 Coromar Drive, Goleta, CA 93117				2. <input type="checkbox"/> DEVIATION <input checked="" type="checkbox"/> WAIVER	
				3. <input type="checkbox"/> MINOR <input checked="" type="checkbox"/> MAJOR <input type="checkbox"/> CRITICAL	
4. DESIGNATION FOR DEVIATION/WAIVER				5. BASE LINE AFFECTED	
a. MODEL/TYPE Spare	b. MFR. CODE 11323	c. SYS. DESIG. TM	d. DEV/WAIVER NO. W-153	<input checked="" type="checkbox"/> FUNC. TIONAL <input type="checkbox"/> CALLO. CATED <input type="checkbox"/> PROD. UCT	
7. SPECIFICATIONS AFFECTED-TEST PLAN				8. DRAWINGS AFFECTED	
a. SYSTEM				b. DRAWINGS AFFECTED	
b. ITEM				c. DRAWINGS AFFECTED	
c. TEST PLAN				d. DRAWINGS AFFECTED	
9. TITLE OF DEVIATION/WAIVER Permission to use InSb Detectors from Lot 24 Wafer 21				10. CONTRACT NO. & LINE ITEM NAS 5-24200	
11. CONFIGURATION ITEM NOMENCLATURE Radiometer				12. CD NO. II	
				13. DEFECT NO.	
				14. DEFECT CLASSIFICATION <input checked="" type="checkbox"/> MINOR <input type="checkbox"/> MAJOR <input type="checkbox"/> CRITICAL	
15. NAME OF PART OR LOWEST ASSEMBLY AFFECTED InSb Detector Arrays				16. PART NO. OF TYPE DESIG. 50958-B	
17. LOT NO. 24				18. QTY 20	
19. RECURRING DEVIATION/WAIVER <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO					
20. EFFECT ON COST/PRICE None if approved -				21. EFFECT ON DELIVERY SCHEDULE None if approved	
22. EFFECT ON INTEGRATED LOGISTIC SUPPORT, INTERFACE, ETC. NONE					
23. DESCRIPTION OF DEVIATION/WAIVER					

This waiver requests permission to use InSb Detectors from Lot 24 Wafer 21 without a released process specification and released planning. This waiver further requests permission to use these detectors with out of specification 5% spot scan contours and crosstalk. A copy of the test data is attached.

24. NEED FOR DEVIATION/WAIVER

Due to the urgent need for new InSb Detectors, lot 24 was processed on unreleased planning. Spotskan and crosstalk data is setup/equipment limited. The physical measurements of the detector areas are in tolerance and InSb Detectors have exhibited optical sizes within .0001" of physical measurements. Historically, InSb Detectors have not had a problem with crosstalk.

REA <i>[Signature]</i> 5/5/82	SYS ENGR <i>[Signature]</i>	RE <i>[Signature]</i> 5/6/82
QA <i>[Signature]</i> 5/6/82	PE <i>[Signature]</i> 5/6/82	CMO <i>[Signature]</i> 6/2/82
25. PRODUCTION EFFECTIVITY BY SERIAL NUMBER 004 & Subsequent		
26. SUBMITTING ACTIVITY AUTHORIZING SIGNATURE <i>[Signature]</i>		
27. APPROVAL/DISAPPROVAL		
<input type="checkbox"/> APPROVAL RECOMMENDED <input checked="" type="checkbox"/> APPROVED <input type="checkbox"/> DISAPPROVED		
28. GOVERNMENT ACTIVITY		
SIGNATURE <i>[Signature]</i> DATE 6/7/82		

DD FORM 1694

Discussion

ORIGINAL PAGE IS
OF POOR QUALITY

DATE PREPARED
6-28-82

1. **PROCURING ACTIVITY NO.**

1. ORIGINATOR NAME AND ADDRESS R. Wengler Santa Barbara Research Center 75 Coronar Drive, Coleta, CA 93117				2. <input type="checkbox"/> DEVIATION <input checked="" type="checkbox"/> WAIVER	
				3. <input type="checkbox"/> MINOR <input checked="" type="checkbox"/> MAJOR <input type="checkbox"/> CRITICAL	
4. DESIGNATION FOR DEVIATION/WAIVER				5. BASE LINE AFFECTED	
6. MODEL/TYPE F-1	7. MFR. CODE 11323	8. SYS. DESIG. TM	9. DEV/WAIVER NO. W-162	<input checked="" type="checkbox"/> FUNC-TIONAL <input type="checkbox"/> ALLO-CATED <input type="checkbox"/> PROD-UCT	10. OTHER SYSTEMS/CONFIGURATION ITEMS AFFECTED <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO
7. SPECIFICATIONS AFFECTED-TEST PLAN				8. DRAWINGS AFFECTED	
MFR. CODE		SPEC./DOC. NO.		MFR. CODE	REV. NO.
GSCF		400.8-D-210		11323	51065
H. SYSTEM		I. TEST PLAN		J. DRAWING NO.	
				EOs 4257A, 3	
9. TITLE OF DEVIATION/WAIVER Band 5 to Band 7 Misregistration				10. CONTRACT NO. & LINE ITEM NAS5-24200	
11. CONFIGURATION ITEM NOMENCLATURE Radiometer				12. CD NO.	
				13. DEFECT NO.	
				14. DEFECT CLASSIFICATION <input type="checkbox"/> MINOR <input checked="" type="checkbox"/> MAJOR <input type="checkbox"/> CRITICAL	
15. NAME OF PART OR LATEST ASSEMBLY AFFECTED CFPA		16. PART NO. OR TYPE DESIG. 50973-B		17. LOT NO.	
				18. QTY 1	
				19. REQUIRING DEVIATION/WAIVER <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO	
20. EFFECT ON COST/PRICE >>\$1,000,000				21. EFFECT ON DELIVERY SCHEDULE 1 year	
22. EFFECT ON INTEGRATED LOGISTIC SUPPORT, INTERFACE, ETC. Misalignment must be corrected for in data processing.					
23. DESCRIPTION OF DEVIATION/WAIVER Section 3.2.4 of specification GSCF 400.8-D-210 requires that bands 5 and 7 shall be registered within 0.2 pixel. Failure report F5777 states that in the F-1 system bands 5 and 7 are 26.25 IFOV's apart or registration is within 0.25 IFOV. However HS236-8026A states that the displacement from nominal position in the along scan direction is -0.132 IFOV for band 7 and +0.099 IFOV for band 5. Thus, the total misregistration is 0.231 IFOV. (HS236-8026A attached)					
24. NEED FOR DEVIATION/WAIVER To proceed with the F-1 system having the band 5 to band 7 registration exceeding the allowable tolerance by 0.031 IFOV. To correct the discrepancy would require rework of the Cooled Focal Plane.					
25. PRODUCTION EFFECTIVITY BY SERIAL NUMBER 51065 S/N 003 only					
26. SUBMITTING ACTIVITY AUTHORIZING SIGNATURE J.R. Phillips				27. APPROVAL/DISAPPROVAL Minor - System Engineering Major/Critical - Program Manager	
28. GOVERNMENT ACTIVITY <input type="checkbox"/> APPROVAL RECOMMENDED				29. SIGNATURE <input type="checkbox"/> APPROVED <input type="checkbox"/> DISAPPROVED	

DD FORM 1694
1 DEC 68

ORIGINAL PAGE IS
OF POOR QUALITY

REQUEST FOR DEVIATION/WAIVER
(SEE MIL-STD-480 OR 481 FOR INSTRUCTIONS)

DATE PREPARED

6-29-82

PROCURING ACTIVITY NO.

1. ORIGINATOR NAME AND ADDRESS SBRC, 75 Coromar Dr., Goleta, CA 93117				2. <input type="checkbox"/> DEVIATION <input checked="" type="checkbox"/> WAIVER																											
				3. <input checked="" type="checkbox"/> MINOR <input type="checkbox"/> MAJOR <input type="checkbox"/> CRITICAL																											
4. DESIGNATION FOR DEVIATION/WAIVER				5. BASE LINE AFFECTED		6. OTHER SYSTEMS/CONFIGURATION ITEMS AFFECTED																									
a. MODEL/TYPE Spare	b. MFR. CODE 11323	c. SYS. DESIG. TM	d. DEV/WAIVER NO. W-163	<input checked="" type="checkbox"/> FUNCTIONAL	<input type="checkbox"/> ALLOCATED	<input type="checkbox"/> PRODUCTION	<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO																								
7. SPECIFICATIONS AFFECTED-TEST PLAN				8. DRAWINGS AFFECTED																											
<table border="1"> <thead> <tr> <th></th> <th>MFR. CODE</th> <th>SPEC./DOC. NO.</th> <th>SCN</th> </tr> </thead> <tbody> <tr> <td>a. SYSTEM</td> <td></td> <td></td> <td></td> </tr> <tr> <td>b. ITEM</td> <td></td> <td></td> <td></td> </tr> <tr> <td>c. TEST PLAN</td> <td></td> <td></td> <td></td> </tr> </tbody> </table>					MFR. CODE	SPEC./DOC. NO.	SCN	a. SYSTEM				b. ITEM				c. TEST PLAN				<table border="1"> <thead> <tr> <th>MFR. CODE</th> <th>NUMBER</th> <th>REV.</th> <th>NOR. NO.</th> </tr> </thead> <tbody> <tr> <td>11323</td> <td>50973</td> <td>B</td> <td>3895A, 2870A</td> </tr> </tbody> </table>				MFR. CODE	NUMBER	REV.	NOR. NO.	11323	50973	B	3895A, 2870A
	MFR. CODE	SPEC./DOC. NO.	SCN																												
a. SYSTEM																															
b. ITEM																															
c. TEST PLAN																															
MFR. CODE	NUMBER	REV.	NOR. NO.																												
11323	50973	B	3895A, 2870A																												
9. TITLE OF DEVIATION/WAIVER Spare CFPA FET Offsets						10. CONTRACT NO. & LINE ITEM NAS 5-24200																									
11. CONFIGURATION ITEM NOMENCLATURE Radiometer				12. CD NO. II																											
				13. DEFECT NO.																											
				14. DEFECT CLASSIFICATION <input checked="" type="checkbox"/> MINOR <input type="checkbox"/> MAJOR <input type="checkbox"/> CRITICAL																											
15. NAME OF PART OR LOWEST ASSEMBLY AFFECTED CFPA		16. PART NO. OR TYPE DESIG. 50973		17. LOT NO. 301		18. QTY 1																									
				19. RECURRING DEVIATION/WAIVER <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO																											
20. EFFECT ON COST/PRICE \$50,000 if not approved				21. EFFECT ON DELIVERY SCHEDULE 2 months if not approved																											
22. EFFECT ON INTEGRATED LOGISTIC SUPPORT, INTERFACE, ETC. NONE																															
23. DESCRIPTION OF DEVIATION/WAIVER Permission to use CFPA with FET offsets > 10mV Band - 7 Ch 7 & 15 per FR8213																															

Ch 7 Ch 15

Offsets prior to failure - 5/5/82	9mV	9mV
Offsets time of failure - 5/24/82	12mV	14mV
Offsets most recent date - 6/25/82	10mV	12mV

Cause of change in offset is unknown; most likely due to electrical discharge.

24. NEED FOR DEVIATION/WAIVER

Focal Plane is complete. To replace FETs would require crosstalk shield to be removed. Past experience with these FETs has shown that once offsets have changed, they are stable within a few mV thereafter. No system specification will be affected. The additional offset can be easily tolerated by the preamp. Rework is not considered cost effective.

6/29/82		RE <i>[Signature]</i> 6/29/82	
QA <i>[Signature]</i> 6/29/82		PE <i>[Signature]</i> 6-29-82	
REA <i>[Signature]</i> 6/29/82		SYS ENGR <i>[Signature]</i> 6/29/82	
25. PRODUCTION EFFECTIVITY BY SERIAL NUMBER 004			
26. SUBMITTING ACTIVITY AUTHORIZING SIGNATURE <i>[Signature]</i>		TITLE SYSTEMS ENGINEERING	
27. APPROVAL/DISAPPROVAL			
a. <input type="checkbox"/> APPROVAL RECOMMENDED		b. <input type="checkbox"/> APPROVED <input type="checkbox"/> DISAPPROVED	
c. GOVERNMENT ACTIVITY		SIGNATURE DATE	

DD FORM 1694

8-11001

REQUEST FOR DEVIATION/WAIVER
(SEE MIL-STD-480 OR 481 FOR INSTRUCTIONS)

DATE PREPARED

ORIGINAL PAGE IS
OF POOR QUALITY

PRECEDENCE ACTIVITY NO.

6-30-82

1. ORIGINATOR NAME AND ADDRESS David M. Randall SBRC, 75 Coromar Dr., Goleta, CA 93117				2. <input type="checkbox"/> DEVIATION <input checked="" type="checkbox"/> WAIVER 3. <input checked="" type="checkbox"/> MINOR <input type="checkbox"/> MAJOR <input type="checkbox"/> CRITICAL			
4. DESIGNATION FOR DEVIATION/WAIVER				5. BASE LINE AFFECTED		6. OTHER SYSTEMS/CONFIGURATION ITEMS AFFECTED	
a. MODEL/TYPE Spare	b. MFR. CODE 11323	c. SYS. DESIG.	d. DEV/WAIVER NO. W-164	<input type="checkbox"/> FUNCTIONAL	<input type="checkbox"/> ALLOCATED	<input type="checkbox"/> PRODUCTION	<input type="checkbox"/> YES <input type="checkbox"/> NO
7. SPECIFICATIONS AFFECTED-TEST PLAN				8. DRAWINGS AFFECTED			
a. SYSTEM				b. DRAWINGS			
c. TEST PLAN				d. REV.			
9. TITLE OF DEVIATION/WAIVER Deleted Pull Test Spare CFPA				10. CONTRACT NO. & LINE ITEM NAS 5-24200			
11. CONFIGURATION ITEM NUMERATURE Radiometer				12. CD NO. II			
13. NAME OF PART OR LOWEST ASSEMBLY AFFECTED CFPA				14. DEFECT CLASSIFICATION <input checked="" type="checkbox"/> MINOR <input type="checkbox"/> MAJOR <input type="checkbox"/> CRITICAL			
15. PART NO. OR TYPE DESIGN. 50973-8				16. LOT NO. 301			
17. EFFECT ON COST/PRICE \$50,000 if not approved				18. QTY 1			
19. EFFECT ON INTEGRATED LOGISTIC SUPPORT, INTERFACE, ETC. NONE				20. RECURRING DEVIATION/WAIVER <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO			
21. EFFECT ON DELIVERY SCHEDULE 2 months if not approved				22. DESCRIPTION OF DEVIATION/WAIVER Permission to use spare CFPA without performing non-destructive pull test of .001" dia gold wire bonds to FETs, resistors, and capacitors. Planning calls for 10% of these bonds to be pulled to 1.5 grams.			

24. NEED FOR DEVIATION/WAIVER

The AHR operations that call for pulldtest/inspection/MCI are not signed off as completed. To do so at this time would require removal of the crosstalk shields which is difficult and risky. Past history with the PF & F FPAs shows that the risk of a poor wirebond to these components is very small.

NOTE: There were two wire bond failures on the Protoflight Unit and no failures on the Flight Unit. The Wire Bond percent defective for these two units is less than two tenths of a percent.

REA

SYS ENGR

RE

QA

PE

25. PRODUCTION EFFECTIVITY BY SERIAL NUMBER

51065 SY 004 ONLY

26. SUBMITTING ACTIVITY AUTHORIZING SIGNATURE

Minor - Systems Engineering
Major - Program Manager

27. APPROVAL/DISAPPROVAL

a. <input type="checkbox"/> APPROVAL RECOMMENDED		b. <input type="checkbox"/> APPROVED <input type="checkbox"/> DISAPPROVED	
c. GOVERNMENT ACTIVITY		d. SIGNATURE	

DD FORM 1694

ORIGINAL PAGE IS
OF POOR QUALITY

HUGHES

HUGHES AIRCRAFT COMPANY

SPACE AND COMMUNICATION GROUP
FAILURE REPORT

F 2387

1. PROGRAM NAME AND NUMBER TM VO11		2. QLA	3. MODEL FLT	4. TIME OBSERVED 1700	5. DATE OBSERVED JAN 20 1981
6. HIGHEST LEVEL OF FAILURE OBSERVED <input type="checkbox"/> SPACECRAFT <input type="checkbox"/> SUBSYSTEM <input type="checkbox"/> UNIT <input checked="" type="checkbox"/> ASSEMBLY <input type="checkbox"/> MODULE <input type="checkbox"/> CARD <input type="checkbox"/> SYSTEM <input type="checkbox"/> MICAM <input type="checkbox"/> PART					
7. EQUIPMENT IDENTIFICATION NAME PART NUMBER S/N MANUFACTURER					
8. UNIT					
9. <input type="checkbox"/> ASSEMBLY <input checked="" type="checkbox"/> SUBASSEMBLY 50973 201 SBRC					
10. <input type="checkbox"/> MODULE <input type="checkbox"/> MICAM <input type="checkbox"/> CARD					
11. OTHER					
12. TEST WHEN FAILURE WAS OBSERVED <input type="checkbox"/> DEVELOPMENT <input type="checkbox"/> QUALIFICATION <input type="checkbox"/> INTEGRATION <input type="checkbox"/> LAUNCH OPERATIONS <input checked="" type="checkbox"/> IN PROGRESS <input type="checkbox"/> ACCEPTANCE <input type="checkbox"/> SYSTEM					
13. ENVIRONMENT WHEN FAILURE WAS OBSERVED <input type="checkbox"/> AMBIENT <input type="checkbox"/> RADIATION <input checked="" type="checkbox"/> TEMPERATURE 95 °K <input type="checkbox"/> THERMAL VAC <input type="checkbox"/> HUMIDITY AT <input type="checkbox"/> OTHER <input type="checkbox"/> OSCILLATION <input type="checkbox"/> VIBRATION <input type="checkbox"/> AXIS FOR MIN TYPE					
14. DESCRIPTION OF FAILURE BAND 5 CH. 13 OFFSET 2.010; 2.013 VEC. BAND 5 CH. 4 NO RESPONSE TO INJ. FREQUENCY. BAND 7 CHANNELS 3, 7, 9 AND 12 HAVE NO RESPONSE TO INJECTED FREQUENCY					
15. TEST PROCEDURE 16192 PARA 34.46 16. ORIGINATOR N. C. JAVISON II 2213 17. DATE 1-29-81 18. CONTINUATION SHEET USED					
19. VERIFICATION AND FAILURE ANALYSIS No overcurrents occurred. Unit was in normal test configuration. Outputs are fed through high impedance circuitry limiting current to other devices.					
20. FOLLOWING REPAIR/TEST REQUIRED REPAIR/TEST KEY REQUIRED BECAUSE Work was needed per suggestion of Bands 5 detector failed; up FR 2667. Band 7 detector failed; up FR 2665.					
21. AUTHORIZATION M. R. 2121 22. DATE 1/29/81 23. CONTINUATION SHEET USED					
24. REPAIR/TEST ACTION TAKEN Work was needed per suggestion of Bands 5 detector failed; up FR 2667. Band 7 detector failed; up FR 2665.					
25. LIST ALL PARTS REPLACED PART NUMBER CKY SYM PART LOT NO. DATE CODE WPR PROBABLE DEFECT ANALYSIS NO. 50958 Band 5 906-3316A-A-89 50958 Band 7 906-3316A-13-127					
27. REPAIR BY ORG DATE 28. RETESTED BY ORG DATE 29. CONTINUATION SHEET USED					
30. CAUSE AND CORRECTIVE ACTION Cause was electrostatic discharge. Parts were sent to TSO for failure analysis. Report of this report; ref 176A. 40/1 is attached. Static discharge precautions were reviewed and recommendations were implemented.					
31. PRE CLOSURE					
32. DOCUMENT IMPLEMENTING CORRECTIVE ACTION					
33. BASIC CAUSE OF VERIFIED FAILURE <input type="checkbox"/> DESIGN <input type="checkbox"/> TEST EQUIP <input checked="" type="checkbox"/> MFG. PROCEDURE <input type="checkbox"/> WIRING ERROR <input type="checkbox"/> UNKNOWN <input type="checkbox"/> ENVIRONMENTAL <input type="checkbox"/> TEST PROC. <input type="checkbox"/> ASSY/PAS ERROR <input type="checkbox"/> ROUGH HANDLING <input type="checkbox"/> DEFECT CODE <input type="checkbox"/> DEFECTIVE PARTS <input type="checkbox"/> TEST SET-UP <input type="checkbox"/> WORKMANSHIP <input type="checkbox"/> WEAR-OUT					
34. FAILURE TYPE <input type="checkbox"/> PRIMARY <input type="checkbox"/> UNKNOWN <input type="checkbox"/> NO FAILURE <input checked="" type="checkbox"/> INQUIRY					
35. FAILURE CLASSIFICATION <input type="checkbox"/> CRITICAL <input type="checkbox"/> MINOR <input type="checkbox"/> SAFETY <input type="checkbox"/> MAJOR					
36. SPACECRAFT SYSTEM ENGR. 37. RESPONSIBLE ENGINEER M. R. 2121 38. DATE 2/2/82 39. CUSTOMER ORG 22-01 40. DATE 2/22/82					

ORIGINAL PAGE IS
OF POOR QUALITY

HUGHES

F 2387

TECHNICAL INTERNAL CORRESPONDENCE

TO: D.M. Randall
21-23

DATE: 07 July 1981
REF: 7611.40/1

SUBJECT: Failure Investigation of InSb
Photovoltaic Detector

FROM: F. Reizman
76-11-44

BLDG. 6 MAIL STA. C136
EXT. 6343

ABSTRACT:

Failure analysis was performed on a photovoltaic InSb infrared detector, which was suspected to have been damaged by electrostatic discharges. Three diode channels (out of sixteen) were electrically degraded, without visible signs of damage.

Surface metallization was removed by RF sputtering in argon. No distinguishing features were visible on the damaged diodes until sputtering had proceeded below the metal/oxide interface. Two of the three degraded diodes then showed distinguishing features, whose form and location very strongly suggest that they are sites of electrostatic damage which caused the diodes to fail.

A discussion of the analysis methods, including sputter-etching, is given in an appendix.

ORIGINAL PAGE IS
OF POOR QUALITY

F2387

I. INTRODUCTION

Several photovoltaic InSb detector chips were submitted to TSD for failure analysis. Several diodes (channels) out of sixteen in each chip had been shorted or degraded, without any visible change in their microscopic appearance. (Figure 1 shows the overall layout of the chip.) SBRC strongly suspected that the degraded performance of these diodes was due to electrostatic damage (ESD). [Ref: SBRC Internal Memo HS236-7391, dated 12 March 1981.]

Since electrical measurements of the diode characteristics could be made only at 90°K or below, TSD confined its failure analysis to optical and electron-beam microscopy.

In an attempt to locate the damage more precisely, an ultrasonic cutting probe with tungsten-carbide point was used to cut conductor traces near the diode region. After cutting the trace, the bonding pad tested "open" with respect to the substrate, both on degraded and good channels. This shows that there was no shorting through the thick oxide, but that the electrical damage was at or near the junction.

Metal and oxide coatings were stripped in an effort to find evidence relating to the cause of failure. In the following pages we describe the investigation and the results which strongly suggest ESD as the cause.

F 2387

ORIGINAL PAGE IS
OF POOR QUALITY

II. DEVICE AND COATING STRUCTURE

The device substrate is indium antimonide (InSb), which is coated in succession with:

- 1) a thin proprietary passivation layer
- 2) a thin evaporated SiO (inner rectangle)
- 3) A thicker SiO (outer area). On this thick oxide most of the conductor traces and wire-bonding pads are coated.
- 4) Thin metallization: titanium (several hundred Å) for adherence, followed by about 3000 Å of gold.
- 5) Thick metallization: consists of the thin Ti/Au above, covered by another Ti/Au double layer about twice as thick, giving a total thickness of about 1 µm. Thick metallization is confined to the area near the diode and is used to span the sheer step from thick to thin oxide.

Each diode is formed by a mesa in the central area. The mesa is oxide-covered, except for a contact window that gives access to the metallization. A rough appearance in the center of this contact window marks the thin palladium coating which improves electrical contact with the Ti/Au conductor trace. A cross-section of the chip taken through a typical diode is shown in Figure 2. This diagram is obtained mostly by interference microscopy supplemented by ordinary optical microscopy and information from SBRC. Further discussion is reserved to Appendix A.

The appearance of the of the devices as received is shown in Figures 3, 4, and 5. Figure 5, taken on the Band 5 chip, shows metal films with "frills" or "pie-crust" edges. These are formed as a result of the photoresist liftoff process that defines the metal patterns. Figures 4 and 5 also show the difficulty of getting good metal coverage over the sheer oxide step.

III. STRIPPING OF COATINGS

Optical examination, both at SBRC and TSD, showed that no visible signs of electrical damage were present. It was therefore thought necessary to remove the metallization, and possibly part of the oxide, to expose the site of the damage and have a reasonable likelihood of making it visible.

Chemical etching was at first tried, using potassium iodide to remove gold, and a preparation containing HF for the titanium. Further details are given in Appendix B. This approach failed because of formation of a bulky corrosion product on contact with InSb. As a result, no useful information was obtained from the Band 5 chip.

To avoid these difficulties, RF sputter etching was then tried. This technique subjects the sample to an RF glow discharge in argon, which removes material by ion bombardment without chemical reactions. By this relatively clean method, metallization was removed and ESD sites located. Further details about sputter-etching are given in Appendix C.

IV. RESULTS

Figures 3, 4, and 5 are representative of the diodes as they appear in the as-received condition. Careful optical examination at SBRC and TSD, and SEM examination at TSD, failed to show any systematic differences between diodes 7, 9, 12 (degraded) and the nine remaining (undamaged) diodes.

Sputter-etching was then carried out for a total of 190 minutes in several stages. After 190 minutes the optical views (Figures 6, 8) show a small amount of titanium remaining of the thick metallization. Figures 7 and 9 show roughly the same areas in SEM view. The small amount of titanium is thin enough to be penetrated by the electron beam, so that Figures 7 and 9 are basically pictures of the oxide. Nevertheless, no characteristic trace of ESD can be seen at this point. Although some oxide has been sputtered away in the unmetallized areas, the covering of titanium still preserves the oxide in the diode areas originally coated with thick metallization.

After an additional two hours of sputter-etching, however, diodes 9 and 12 have developed "new" features which do not appear in any of the others. Diode 12 now shows a notch in one edge of the mesa (Fig. 10, 11, 12), while diode 9 shows linear markings (furrows) at two mesa corners (Fig. 13, 14, 15, 16). Figure 16 should be compared to a picture of known ESD published by A. Trigonis* (Fig. 17).

The association of these features with ESD is supported by the following arguments:

1. The features are seen near the edge and corners of the mesa, where the junction reaches the surface and electric fields are strongest. Junction curvature and discontinuities in dielectric constant combine here to raise the field strength above its average value, and create local breakdown.
2. Since the surface is covered with SiO and metal, all breakdown takes place in the oxide under the electrodes. Unless enough energy is liberated to disturb the outer surface, the damage will not be visible until the metal is removed and oxide etching reaches the damaged region. Then a difference in etch rate may create an "etch pit", analogous to preferential effects in wet-chemical etching. The belated appearance of these features is therefore suggestive of a low-energy ESD.
3. No such features appeared at the same time on undamaged channels. It must be admitted that channel 7 does not show such features, so that the correspondence is not bidirectional. However, the subtle nature of ESD makes it plausible that channel 7 has damage too slight for the preferential etch to reveal, but nevertheless electrically important.

CONCLUSIONS

1. The anomalies at the edge of the mesa in channels 9 and 12 are probably associated with ESD, and to this extent the hypothesis of ESD on the failed detectors is confirmed.

* Proceedings, 1976 Reliability and Maintainability Symposium, p. 165

ORIGINAL PAGE IS
OF POOR QUALITY

F 2387

2. Sputter-etching in argon is a practical method of removing metal-
lization from InSb devices. As used in the Thin Film Lab at TSD,
however, the slow etch rate for titanium is a disadvantage. Better
vacuum technique could improve this, however, and make etch rates
for active metals closer to those for noble ones.
3. When using sputter-etching as a means for stripping coatings, it is
important in interpretation to allow for changes of surface feature
form and topography. These include the following:
 - (a) preferential attack at vertical surfaces
 - (b) formation of a groove at a mesa foot
 - (c) appearance of a raised relief image of a metal trace after
the metal is etched away. This relief is left because
oxide was etched in the bare areas, but was masked by the
metal. Chemical etching, in contrast, usually removes
metals without appreciably etching the oxide. In conse-
quence, after metal is sputter-etched off, the oxide
topography is more complex than it was before the metal
was applied.
 - (d) V-grooving of fine cracks.

ORIGINAL PAGE IS
OF POOR QUALITY

F2387

APPENDIX A:

Interferograms

The height of surface features and thickness of thin films can often be measured under the microscope by optical interferometry. This method has several advantages over profilometers (e.g., Dektak, Talysurf):

1. Thicknesses or heights are obtained in terms of a wavelength of light, whose value is fixed by nature. There is no need to calibrate.
2. Data is automatically obtained over a two-dimensional area, rather than along a linear track. A photograph can serve as a compact record of a great many local heights.
3. It is often possible to find the thickness of a transparent film if the index of refraction is known, even if there is no hole or step.

In Figure 2, an index of 1.9 was assumed for SiO_2 , and used for thickness in the central region. For the thick oxide areas, it was possible to check this value using several chipped areas near the edge where the InSb substrate was exposed. There was good agreement with measurements of the step height.

The measurements in this work were made using a Watson Interference Objective adapted to a Reichert microscope. Other companies make instruments very convenient for shop use in evaluating surface finishes or scratch depths. Figure 18 shows a typical micro-interferogram used in making measurements for Figure 2. The fringes are at intervals of $.29 \mu\text{m}$ (a half-wave of yellow light).

Somewhat related to interferometry is the Nomarski objective. While Figure 18 quantitatively shows heights, Nomarski contrast indicates slopes. Thus it is good for showing the vertical dimension in a qualitative way, making surface contour easy to visualize. Most of the optical micrographs in this report were made with Nomarski contrast.

ORIGINAL PAGE IS
OF POOR QUALITY

F2387

APPENDIX B:

Chemical Etching

Following the usual practice for silicon IC's, attempts were made to strip metallization with chemical etchants. Figure 19 shows a typical diode after removal of the external gold layers with a potassium-iodide solution. Small amounts of gold remain in several areas, while the oxide is completely untouched. The intermediate titanium protects the inner gold layer in the thick-metallization area. The inner gold could not be removed until an application of "Sapp etch" penetrated the titanium.

Unfortunately, the second application of KI etch came into contact with bare InSb in the now-open contact window. A purple-black, bulky corrosion product was formed which obscured detail near the edge of the window, an area in which ESD effects could be expected. After an unsuccessful trial on the Band 5 detector, the chemical stripping approach was abandoned.

Gold Etch

Water 250 ml
KI 25 g
I 19.1 g

"SAPP Etch" for Ti

HF 1-3 ml
HNO₂ 2-6 ml
water to make 100 ml

ORIGINAL PAGE IS
OF POOR QUALITY

F2387

APPENDIX C:

Sputter-Etching

Sputter-etching was done by RF sputtering in the Thin Film Laboratory, by D. E. Blackmon, through the cooperation of J. F. Linder.

The sputtering action is completely physical, by argon ion bombardment, so that no corrosion products are formed. The erosion or "etch" rate tends to be faster for noble metals like gold than for active metals, unless the partial pressure of oxygen in the system is very low. In a "dirty" system, active metals tend to sputter almost as slowly as oxides.

There was in fact a large difference in the sputtering rates of the gold and titanium layers. The vacuum before admission of argon was said to be about 6×10^{-6} Torr, and the argon pressure 5×10^{-3} Torr. RF voltage was 700v and power about 200 watts. We noticed considerable differences in time needed to sputter away metallization on the actual and practice samples. These differences might have been due to accidental air leaks or differences in heat sinking.

As sputtering proceeds, certain changes occur in surface topography which are different from those seen in chemical etching.

1. Vertical surfaces are eroded faster than horizontal ones, due to an angle-of-incidence effect. Ion bombardment is actually more effective at removing material if it is oblique rather than perpendicular. This results in mesa edges moving back but remaining steep. A groove was seen to appear at the foot of the mesa after prolonged sputtering, perhaps due to argon ions reflected obliquely from the mesa slope (Figures 7, 11, 12, 14).
2. A wire close to the surface of the sample can be seen to cast a sharp vertical "shadow" (Figure 20).
3. Fine cracks, originally only about $0.3 \mu\text{m}$ wide, were "gouged" out in V-groove form after prolonged sputtering (see Figure 21). Certain conical pits, of perfect geometrical form, may have similar origin by enlargement of a fine pinhole (Figure 22).

ORIGINAL PAGE IS
OF POOR QUALITY

F2307

Figures 20 and 21 show where a crack has been emphasized by sputtering, except where it crosses the "shadow" of a lead wire. This crack was produced accidentally by TSD while mounting the chip in silver-epoxy, and extends completely through the chip.

F. Reizman
F. Reizman

Approved:

S. L. Webster

S.L. Webster, Head
Component Reliability Section

ORIGINAL PAGE IS
OF POOR QUALITY

F2387




FIGURE NO. 1. - Band 7, chip layout and numbering system. This thin-oxide region, containing the diodes, is in the inner rectangle. The section line marks the typical cross-section of Figure 2. The actual size of the central rectangle is about .375 x 1.36 mm.




FIGURE NO. 2. - IR Detectors - Coating structure from interferometry.

ORIGINAL PAGE IS
OF POOR QUALITY

F2387




FIGURE NO. 3

Channels 10 and 12, as
received, Nomarski contrast.




FIGURE NO. 4

SEM of typical diode as
received, showing coverage
at step and thickened
metallization

F2387




FIGURE NO. 5

Typical diode, Band 5, as received. Clearly shows double metallization, frills at metal edge, possible continuity problem at oxide step.

ORIGINAL PAGE IS
OF POOR QUALITY




FIGURE NO. 6

(190 minutes sputter etch)
Optical micrograph showing channels 5, 7, 9, 11 (from left). Seven and nine are electrically damaged. Note remaining Ti metal in area of diode; conductor traces are now marked by raised area.

F2387




FIGURE NO. 7

(190 minutes sputter etch)
Nearly same area as Figure 6. SEM view showing channel 7 and 9 in center. Oblique view shows groove around mesa. A small amount of residual gold (inner layer) appears at foot of oxide step.




FIGURE NO. 8

(190 minutes sputter etch)
optical view showing channel 12 (damaged), 14, 16 from left. Residual gold shows dark in optical, light in SEM views.

ORIGINAL PAGE IS
OF POOR QUALITY

F 2387




FIGURE NO. 9

SEM showing nearly same area as Figure 8, channel 12 in center. The spot (arrow) on channel 12 is a small area of residual metal probably due to shielding by a dust particle during sputtering.




FIGURE NO. 10

310 minute sputter etch, channel 12 (left) and channel 14, optical with Nomarski contrast. A notch has appeared in the left side of the mesa of channel 12.

ORIGINAL PAGE IS
OF POOR QUALITY

F2387




FIGURE NO. 11

Same area as Figure 10,
SEM. Channel 12 in
center. The notch is
clearly shown; note also
a deeper groove around
the mesa than that visible
after 190 minutes.




FIGURE NO. 12

Shows the notch under
higher magnification.

ORIGINAL PAGE IS
OF POOR QUALITY

F2387




FIGURE NO. 13

Optical, channels 11, 9,
7 (from left). Note
damage on channel 9, at
left edge and upper left
corner of mesa. Nomarski
contrast.




FIGURE NO. 14

SEM showing channel 9 and
7 in center. Same features
are seen plus grooving
around mesa.

ORIGINAL PAGE IS
OF POOR QUALITY

F2387



FIGURE NO. 15

SEM showing damage at
left edge of mesa on
channel 9 (compare
Figure 14).




FIGURE NO. 16

SEM showing damage at
upper left corner of
mesa, channel 9 (Figure
14).

ORIGINAL PAGE IS
OF POOR QUALITY

F-2387




FIGURE NO. 17
Photo reprinted from
Trigonis, Ref. 1, as
an example of ESD.
Compare to Figure 16.
(Original, 4300X)

ORIGINAL PAGE IS
OF POOR QUALITY

F 2387




FIGURE NO. 18

A white-light interferogram on the as-received Band 7 chip. In the thin oxide at left, two fringe systems can be seen, from the oxide surface and one from the oxide/substrate interface.




FIGURE NO. 19

SEM of typical diode after 45 seconds KI etch. Lighter granular material is residual gold. Remaining exposed metal is Ti; thicker area is Ti/Au/Ti sandwich.

ORIGINAL PAGE IS
OF POOR QUALITY

F2387




FIGURE NO. 20

Relief shadows of a lead wire, after several stages of sputter-etching. The wire was accidentally moved between stages. Some Ti remains in the last shadow. A crack appears, crossing the shadow. (Optical, Nomarski contrast.)




FIGURE NO. 21

SEM of crack seen in Figure 3 showing V-groove enlargement in sputtered area.

F2387

ORIGINAL PAGE IS
OF POOR QUALITY




FIGURE NO. 22
Conical pit on mesa
top after 310 minutes
sputtering.

ORIGINAL PAGE IS
OF POOR QUALITY

HUGHES

HUGHES AIRCRAFT COMPANY

SPACE AND COMMUNICATION GROUP
FAILURE REPORT

F 2665

1. PROGRAM NAME AND NUMBER TM 0011		2. QLA	3. MODEL FLT	4. TIME OBSERVED 4 PM	5. DATE OBSERVED 25-20-81
6. HARDWARE LEVEL WHEN FAILURE WAS OBSERVED <input type="checkbox"/> SPACECRAFT <input type="checkbox"/> SUBSYSTEM <input type="checkbox"/> ASSEMBLY <input type="checkbox"/> MODULE <input type="checkbox"/> CARD <input type="checkbox"/> SYSTEM <input type="checkbox"/> UNIT <input checked="" type="checkbox"/> SUBASSEMBLY <input type="checkbox"/> MICAS <input type="checkbox"/> PART					
EQUIPMENT IDENTIFICATION					
7. SUBSYSTEM		NAME		PART NUMBER	SN
8. UNIT					
9. <input type="checkbox"/> ASSEMBLY <input checked="" type="checkbox"/> SUBASSEMBLY		BAND 7/CPPA		50955	201
10. <input type="checkbox"/> MODULE <input type="checkbox"/> MICAS <input type="checkbox"/> CARD				50973	5BRL
11. OTHER					
12. TEST WHEN FAILURE WAS OBSERVED <input type="checkbox"/> DEVELOPMENT <input type="checkbox"/> QUALIFICATION <input type="checkbox"/> INTEGRATION <input type="checkbox"/> LAUNCH OPERATIONS <input checked="" type="checkbox"/> PROPOSED <input type="checkbox"/> ACCEPTANCE <input type="checkbox"/> SYSTEM					
13. ENVIRONMENT WHEN FAILURE WAS OBSERVED <input type="checkbox"/> AMBIENT <input type="checkbox"/> RADIATION <input checked="" type="checkbox"/> TEMPERATURE 92° R <input type="checkbox"/> THERMAL VAC <input type="checkbox"/> HRS. AT <input type="checkbox"/> OTHER					
14. DESCRIPTION OF FAILURE		BAND 7, CHANNEL 1 INTERFERED SIGNAL FBGA. RESPONSE OUTPUT VOLTAGE OUT OF SPEC. 4.5mV AT 10Hz. CHANNEL 7 OUTPUT VOLTAGE HIGH OUT OF SPEC. 19.4mV AT 10Hz.			
15. TEST PROCEDURE 16192		16. PART NUMBER 4.6	17. ORIGINATOR C. R. Zane	18. DATE 2213 05-20-81	19. CONTINUATION SHEET USED
18. VERIFICATION AND FAILURE ANALYSIS					
19. FAILED ITEM NAME AND PART NUMBER					
20. FOLLOWING REWORK/RETEST REQUIRED REWORK/RETEST NOT REQUIRED BECAUSE Revised per supplement 5.					
21. AUTHORIZATION AM Rendell ORG 2122 DATE 7/1/81					
22. REWORK/RETEST ACTION TAKEN Revised + Retested per supplement 5. Tested good. No other components will be overhauled.					
23. LIST ALL PARTS REPLACED					
PART NUMBER	CKT SYM	PART LOT NO.	DATE CODE	MFR	PROBABLE DEFECT
50958					
27. Rework BY ORG DATE 28. RETESTED BY ORG DATE					
29. CAUSE AND CORRECTIVE ACTION 4.5mV @ 10Hz relates to a detector impedance of $67 \times 10^6 \Omega$ or a capacitance of $280 \times 10^6 \Omega$. 19.4mV @ 10Hz relates to an open detector. The open detector was caused by a crack in the S.O. coating causing the detector trace to open. Both failures are "inherent mortality" problems that cannot be detected until the detector is connected onto the PPA, wire bonded, and tested.					
32. DOCUMENT IMPLEMENTING CORRECTIVE ACTION					
34. BASIC CAUSE OF VERIFIED FAILURE <input type="checkbox"/> DESIGN <input type="checkbox"/> TEST EQUIP <input type="checkbox"/> MFG. PROCEDURE <input type="checkbox"/> HIRING ERROR <input type="checkbox"/> UNKNOWN <input checked="" type="checkbox"/> ENVIRONMENTAL <input type="checkbox"/> TEST PROC. <input type="checkbox"/> ASBY/FAB ERROR <input type="checkbox"/> ROUGH HANDLING <input type="checkbox"/> DEFECT CODE <input checked="" type="checkbox"/> DEFECTIVE PARTS <input type="checkbox"/> TEST SET-UP <input type="checkbox"/> WORKMANSHIP <input type="checkbox"/> WEAR-OUT					
35. FAILURE TYPE <input checked="" type="checkbox"/> PRIMARY <input type="checkbox"/> UNKNOWN <input type="checkbox"/> NO FAILURE					
36. FAILURE CLASSIFICATION <input type="checkbox"/> CRITICAL <input checked="" type="checkbox"/> MINOR <input type="checkbox"/> MAJOR <input type="checkbox"/> SAFETY					
37. RESPONSIBLE ENGINEER AM Rendell ORG 2122 DATE 7/1/81					
38. SPACECRAFT SYSTEM ENGR AM Rendell ORG 2261 DATE 7/2/81					
39. RELIABILITY 151-41 DATE 12-2-81					
40. CUSTOMER OR SUPPLIER					

ORIGINAL PAGE IS
OF POOR QUALITY

HUGHES

HUGHES AIRCRAFT COMPANY

SPACE AND COMMUNICATION GROUP
FAILURE REPORT

F 266

1. PROGRAM NAME AND NUMBER T-1		2. GLA	3. MODEL F1	4. TIME OBSERVED 11/11	5. DATE OBSERVED 8-27-81
6. HARDWARE LEVEL WHEN FAILURE WAS OBSERVED <input type="checkbox"/> SPACECRAFT <input type="checkbox"/> SYSTEM <input type="checkbox"/> SUBSYSTEM <input type="checkbox"/> UNIT <input checked="" type="checkbox"/> ASSEMBLY <input type="checkbox"/> MODULE <input type="checkbox"/> MICAM <input type="checkbox"/> CARD <input type="checkbox"/> PART					
7. EQUIPMENT IDENTIFICATION NAME		PART NUMBER 50973		S/N 201	MANUFACTURER
8. UNIT					
9. ASSEMBLY <input checked="" type="checkbox"/> ASSEMBLY <input type="checkbox"/> SUBASSEMBLY					
10. MODULE <input type="checkbox"/> MODULE <input type="checkbox"/> MICAM <input type="checkbox"/> CARD					
11. OTHER					
12. TEST WHEN FAILURE WAS OBSERVED <input type="checkbox"/> DEVELOPMENT <input checked="" type="checkbox"/> IN-PROCESS <input type="checkbox"/> QUALIFICATION <input type="checkbox"/> ACCEPTANCE <input type="checkbox"/> INTEGRATION <input type="checkbox"/> SYSTEM <input type="checkbox"/> LAUNCH OPERATIONS					
13. ENVIRONMENT WHEN FAILURE WAS OBSERVED <input type="checkbox"/> ACCIDENT <input type="checkbox"/> RADIATION <input type="checkbox"/> TEMPERATURE <input type="checkbox"/> VIBRATION <input type="checkbox"/> AXIS FOR MIN TYPE <input type="checkbox"/> THERMAL VAC <input type="checkbox"/> HRS. AT <input type="checkbox"/> OTHER					
14. DESCRIPTION OF FAILURE No visual out of Band 5 Ch 348. Larger than expected signals from Ch 425-44 indicating probable gain in detector circuit					
15. TEST PROCEDURE 16192		PART 4.6	16. ORIGINATOR C.R. Lane		DATE 8-22-81 DAY 24-26-81 CONTINUATION SHEET USED
17. VERIFICATION AND FAILURE ANALYSIS					
18. FAILED ITEMS REPAIR AND PART NUMBER					
19. FOLLOWING REPAIR/RETEST REQUIRED REPAIR/RETEST NOT REQUIRED CAUSE per 16192 para 4.6		Replace detector per supplement 3 and test			
20. AUTHORIZATION per 16192 para 4.6		21. AUTHORIZATION per 16192 para 4.6		22. DATE 8/22/81 CONTINUATION SHEET USED	
23. LIST ALL PARTS REPLACED PART NUMBER 50958		CKT SYM (REMOVED BAND 5 ARRAY SIN #92	PART LOT NO. (INSTALLED " " SIN #116	DATE CODE 906-3316A-11	MPR Q. Hender
24. REWORK BY ORG		DATE 10-5-81	25. RETESTED BY ORG		DATE 10-5-81 CONTINUATION SHEET USED
26. CAUSE AND CORRECTIVE ACTION Detector was damaged by discharge of static electricity. Guy, tab and test harness cable been implemented with static safe grounds.		27. FRB CLOSURE 511-21/1			
28. DOCUMENT IMPLEMENTING CORRECTIVE ACTION		29. CONTINUATION SHEET USED			
30. BASIC CAUSE OF VERIFIED FAILURE <input type="checkbox"/> DESIGN <input checked="" type="checkbox"/> ENVIRONMENTAL <input type="checkbox"/> DEFECTIVE PARTS <input type="checkbox"/> TEST EQUIP <input type="checkbox"/> TEST PROC. <input type="checkbox"/> TEST SET-UP <input checked="" type="checkbox"/> MFG. PROCEDURE <input type="checkbox"/> ASSEMBLY ERROR <input type="checkbox"/> WORKMANSHIP <input type="checkbox"/> WIRING ERROR <input type="checkbox"/> ROUGH HANDLING <input type="checkbox"/> WEAR-OUT <input type="checkbox"/> UNKNOWN <input type="checkbox"/> DEFECT CODE					
31. FAILURE TYPE <input type="checkbox"/> PRIMARY <input checked="" type="checkbox"/> INDUCED <input type="checkbox"/> UNKNOWN <input type="checkbox"/> NO FAILURE		32. FAILURE CLASSIFICATION <input type="checkbox"/> CRITICAL <input checked="" type="checkbox"/> MAJOR <input type="checkbox"/> MINOR <input type="checkbox"/> SAFETY		33. SPACECRAFT SYSTEM ENGR 122-41 DATE 5 OCT 81	
34. RESPONSIBLE ENGINEER per 16192 para 4.6		35. CUSTOMER OR SUPPLIER per 16192 para 4.6		36. DATE 10/1/81	

HUGHES

HUGHES AIRCRAFT COMPANY
SPACE AND COMMUNICATIONS GROUP
EL SEGUNDO, CALIFORNIA

SPACE AND COMMUNICATIONS GROUP FAILURE REPORT

S 8018

ORIGINAL PAGE IS
OF POOR QUALITY

1. PROGRAM NAME AND NUMBER <i>TMM</i>		2. GLA <i>VO 11</i>		3. MODEL <i>7</i>		4. TIME OBSERVED <i>11:30 AM</i>		5. DATE OBSERVED MO <i>1</i> DAY <i>2</i> YR <i>81</i>	
6. HARDWARE LEVEL WHEN FAILURE WAS OBSERVED		<input type="checkbox"/> SPACECRAFT		<input type="checkbox"/> SUBSYSTEM		<input type="checkbox"/> ASSEMBLY		<input type="checkbox"/> MODULE	
		<input type="checkbox"/> SYSTEM		<input type="checkbox"/> UNIT		<input checked="" type="checkbox"/> SUBASSEMBLY		<input type="checkbox"/> MICAM	
EQUIPMENT IDENTIFICATION:		NAME		PART NUMBER		S/N		MANUFACTURER	
7. SUBSYSTEM									
8. UNIT									
9. <input type="checkbox"/> ASSEMBLY <input checked="" type="checkbox"/> SUBASSEMBLY		<i>CTPA</i>		<i>50973</i>		<i>201</i>			
10. <input type="checkbox"/> MODULE <input type="checkbox"/> MICAM <input type="checkbox"/> CARD									
11. OTHER									
12. TEST WHEN FAILURE WAS OBSERVED		<input type="checkbox"/> DEVELOPMENT		<input type="checkbox"/> QUALIFICATION		<input type="checkbox"/> INTEGRATION		<input type="checkbox"/> LAUNCH OPERATIONS	
		<input checked="" type="checkbox"/> IN-PROCESS		<input type="checkbox"/> ACCEPTANCE		<input type="checkbox"/> SYSTEM		<input type="checkbox"/>	
13. ENVIRONMENT WHEN FAILURE WAS OBSERVED		<input checked="" type="checkbox"/> AMBIENT		<input type="checkbox"/> RADIATION		<input type="checkbox"/> TEMP		<input type="checkbox"/> THERMAL VAC	
		<input type="checkbox"/> EMC/RFI		<input type="checkbox"/> VIBRATION		AXIS FOR		HRS AT	
14. DESCRIPTION OF FAILURE		<i>Feedback loop board 5 Q13 measured open circuit when tested per requirement 1 per 1300 2803.</i>							
15. TEST PROCEDURE		<i>NONE per MRS</i>		16. ORIGINAL DATE		<i>222</i>		DATE <i>1/21/81</i>	
17. CONTINUATION SHEET USED									
18. VERIFICATION AND FAILURE ANALYSIS		<i>Visual inspection revealed a poor solder joint on 7th substrate</i>							
19. FAILED ITEM NAME AND PART NUMBER		<i>50956</i>							
20. FOLLOWING REWORK/RETEST REQUIRED		<i>Put TMM on NCR and issue per and that</i>							
<input type="checkbox"/> REWORK/RETEST NOT REQUIRED BECAUSE		<i>MERCO 288457</i>							
21. AUTHORIZATION		<i>Dr. P. D.</i>		DATE		<i>222</i>		DATE <i>1/21/81</i>	
22. REWORK/RETEST ACTION TAKEN		<i>Repaired and tested per MERCO 288457.</i>							
23. LIST ALL PARTS REPLACED		PART NUMBER		CMT SYM		PART LOT NUMBER		DATE CODE	
27. REWORK BY		ORG		DATE		28. RETESTED BY		ORG	
29. CAUSE AND CORRECTIVE ACTION		<i>Trace was scribbled thru when cleaning up spars conductive epoxy used to bond FETs to circuit board. Operator was cautioned to use more care in applying and cleaning up conductive epoxy.</i>							
30. DOCUMENT IMPLEMENTING CORRECTIVE ACTION									
31. BASIC CAUSE OF VERIFIED FAILURE		<input type="checkbox"/> DESIGN ENVIRONMENTAL DEFECTIVE PARTS		<input type="checkbox"/> TEST EQUIPMENT TEST SET-UP		<input type="checkbox"/> MFG. PROCEDURE ASSY/FAB ERROR WORKMANSHIP		<input type="checkbox"/> WIRING ERROR ROUGH HANDLING WEAR-OUT	
32. FAILURE TYPE		<input type="checkbox"/> PRIMARY <input checked="" type="checkbox"/> SECONDARY		<input type="checkbox"/> UNKNOWN		<input type="checkbox"/> NO FAILURE		<input type="checkbox"/> CRITICAL <input checked="" type="checkbox"/> MAJOR	
33. RESPONSIBLE ENGINEER		<i>Dr. P. D.</i>		DATE		<i>222</i>		DATE <i>6/24/81</i>	
34. RELIABILITY		<i>51-41</i>		DATE		<i>6-56-81</i>		DATE	
35. FAILURE CLASSIFICATION		<input type="checkbox"/> SAFETY		<input checked="" type="checkbox"/> MAJOR		<input type="checkbox"/> MINOR		<input type="checkbox"/> DEFECT CODE	
36. SPACECRAFT SYSTEM ENGINEER		<i>Dr. P. D.</i>		DATE		<i>222</i>		DATE <i>6/24/81</i>	
37. SUBCARRIER OR SUPPLIER		<i>Dr. P. D.</i>		DATE		<i>222</i>		DATE <i>6/24/81</i>	

ORIGINAL PAGE IS
OF POOR QUALITY

HUGHES

HUGHES AIRCRAFT COMPANY
SPACE AND COMMUNICATIONS GROUP
EL SEGUNDO, CALIFORNIA

SPACE AND COMMUNICATIONS GROUP
FAILURE REPORT

S 8205

MAIN TEST AND #5773

Opn# 800

1. PROGRAM NAME AND NUMBER TM PL1162		2. GLA	3. MODEL FLIGHT	4. TIME OBSERVED 1400	5. DATE OBSERVED MO 12 DA 14 YR 81
6. HARDWARE LEVEL WHEN FAILURE WAS OBSERVED <input type="checkbox"/> SPACECRAFT <input type="checkbox"/> SYSTEM		<input type="checkbox"/> SUBSYSTEM <input type="checkbox"/> UNIT	<input type="checkbox"/> ASSEMBLY <input checked="" type="checkbox"/> SUBASSEMBLY	<input type="checkbox"/> MODULE <input type="checkbox"/> MICAM	<input type="checkbox"/> CARD <input type="checkbox"/> PART
EQUIPMENT IDENTIFICATION:					
7. SUBSYSTEM # 50988		NAME PREAMP ASSY		PART NUMBER 50988	S/N 201
8. UNIT				MANUFACTURER 11323	
9. <input type="checkbox"/> ASSEMBLY <input checked="" type="checkbox"/> SUBASSEMBLY					
10. <input type="checkbox"/> MODULE <input type="checkbox"/> MICAM <input type="checkbox"/> CARD					
11. OTHER					
12. TEST WHEN FAILURE WAS OBSERVED <input type="checkbox"/> DEVELOPMENT <input checked="" type="checkbox"/> IN-PROCESS <input type="checkbox"/> QUALIFICATION <input type="checkbox"/> ACCEPTANCE <input type="checkbox"/> INTEGRATION <input type="checkbox"/> SYSTEM <input type="checkbox"/> LAUNCH OPERATIONS					
13. ENVIRONMENT WHEN FAILURE WAS OBSERVED <input checked="" type="checkbox"/> AMBIENT <input type="checkbox"/> EMC/RF <input type="checkbox"/> RADIATION <input type="checkbox"/> VIBRATION <input type="checkbox"/> TEMP AXIS FOR MIN TYPE <input type="checkbox"/> THERMAL VAC HRS AT <input type="checkbox"/> OTHER					
14. DESCRIPTION OF FAILURE DURING RECHECK OF SELECT REGISTERS AND CAPTRES FOUND CH 3 BAND 5 TO HAVE OSCILLATIONS (NO DETECTORS IN CAPRES).					
15. TEST PROCEDURE 16192		16. PARA 4.10	17. ORIGINATOR L.O. Anderson	18. ORG 22-13	19. DATE DEC 81
20. VERIFICATION AND FAILURE ANALYSIS Improper selection of C24. Removal of some components required. REMOVED COMPONENTS WERE WITHIN SELECT SPECIFICATION RANGE.		21. CONTINUATION <input type="checkbox"/> SHEET USED			
22. FOLLOWING REWORK/RETEST REQUIRED <input type="checkbox"/> Rework/retest not required because		23. PLACE R7 and C24 ON STANDOFFS FOR RESELECT.			
24. AUTHORIZATION [Signature]		25. ORG 22-1		26. DATE 12/14/81	
27. REWORK/RETEST ACTION TAKEN Rechecked and found good per supplement #2.		28. CONTINUATION <input type="checkbox"/> SHEET USED		29. TEST	
30. LIST ALL PARTS REPLACED		31. CKT SYM	32. PART LOT NUMBER	33. DATE CODE	34. MANUFACTURER
35. PROBABLE DEFECT		36. ANALYSIS NUM			
37. REWORK BY		38. ORG	39. DATE	40. RETESTED BY	41. ORG
42. CONTINUATION <input type="checkbox"/> SHEET USED		43. DATE			
44. CAUSE AND CORRECTIVE ACTION Improper selection of C24. There are small differences in capacitance between having the part on standoffs during selection and after the part has been soldered to the board. Consequently the difference is enough to require reselection.		45. FRB CLOSURE			
46. DOCUMENT IMPLEMENTING CORRECTIVE ACTION		47. CONTINUATION <input type="checkbox"/> SHEET USED			
48. BASIC CAUSE OF VERIFIED FAILURE <input type="checkbox"/> DESIGN <input type="checkbox"/> ENVIRONMENTAL <input type="checkbox"/> DEFECTIVE PARTS		49. TEST EQUIPMENT <input type="checkbox"/> TEST PROCEDURE <input type="checkbox"/> TEST SET-UP		50. MFG. PROCEDURE <input type="checkbox"/> ASSY/FAB ERROR <input type="checkbox"/> WORKMANSHIP	
51. FAILURE <input type="checkbox"/> UNKNOWN <input checked="" type="checkbox"/> NO FAILURE		52. FAILURE CLASSIFICATION <input type="checkbox"/> CRITICAL <input type="checkbox"/> MAJOR		53. MINOR SAFETY	
54. RESPONSIBLE ENGINEER [Signature]		55. ORG 22-41		56. DATE 2/22/82	
57. RELIABILITY [Signature]		58. ORG		59. DATE	

OF POOR QUALITY

HUGHESHUGHES AIRCRAFT COMPANY
SPACE AND COMMUNICATIONS GROUP
EL SEGUNDO, CALIFORNIASPACE AND COMMUNICATIONS GROUP
FAILURE REPORT**S 8207**

1. PROGRAM NAME AND NUMBER TM		2. GLA 1162		3. MODEL F-1		4. TIME OBSERVED 3:11 AM		5. DATE OBSERVED MO 2 DA 6 YR 82	
6. HARDWARE LEVEL WHEN FAILURE WAS OBSERVED <input type="checkbox"/> SPACECRAFT <input type="checkbox"/> SYSTEM		<input type="checkbox"/> SUBSYSTEM <input type="checkbox"/> UNIT		<input type="checkbox"/> ASSEMBLY <input checked="" type="checkbox"/> SUBASSEMBLY		<input type="checkbox"/> MODULE <input type="checkbox"/> MICAM		<input type="checkbox"/> CARD <input type="checkbox"/> PART	
EQUIPMENT IDENTIFICATION:									
7. SUBSYSTEM		NAME		PART NUMBER		S/N		MANUFACTURER	
8. UNIT									
9. <input type="checkbox"/> ASSEMBLY <input type="checkbox"/> SUBASSEMBLY		C7PA		50973		201		SB2C	
10. <input type="checkbox"/> MODULE <input type="checkbox"/> MICAM <input type="checkbox"/> CARD									
11. OTHER									
12. TEST WHEN FAILURE WAS OBSERVED <input type="checkbox"/> DEVELOPMENT <input checked="" type="checkbox"/> IN-PROCESS		<input type="checkbox"/> QUALIFICATION <input type="checkbox"/> ACCEPTANCE		<input type="checkbox"/> INTEGRATION <input type="checkbox"/> SYSTEM		<input type="checkbox"/> LAUNCH OPERATIONS			
13. ENVIRONMENT WHEN FAILURE WAS OBSERVED <input type="checkbox"/> AMBIENT <input type="checkbox"/> EMC/RFI		<input type="checkbox"/> RADIATION <input type="checkbox"/> VIBRATION		<input checked="" type="checkbox"/> TEMP 92.5 AXIS FOR		<input type="checkbox"/> THERMAL VAC		HRS AT	
14. DESCRIPTION OF FAILURE No output Band 7 Ch 7									
15. TEST PROCEDURE 16192									
16. VERIFICATION AND FAILURE ANALYSIS Problem determined to be an incorrectly mated cable connector. No overtones caused to any component. No out of design electrical power could have been applied. UNIT IN NORMAL TEST CONFIGURATION.									
17. CONTINUATION SHEET USED									
18. FOLLOWING REWORK/RETEST REQUIRED <input checked="" type="checkbox"/> REWORK/RETEST NOT REQUIRED BECAUSE No components failed									
19. AUTHORIZATION									
20. REWORK/RETEST ACTION TAKEN Connector was properly mated and test was continued.									
21. LIST ALL PARTS REPLACED									
22. CONTINUATION SHEET USED									
23. REWORK BY									
24. RETESTED BY									
25. CONTINUATION SHEET USED									
26. CAUSE AND CORRECTIVE ACTION Preamp board was not properly mounted in preamp housing. The board was not secured to the housing as the side of the connector to the PWB and its connector moved away when the hook cable connector was mated. Person at instruction as to proper installation of PWB in housing.									
27. NOTICE WAS ATTACHED TO THE									
28. DOCUMENT IMPLEMENTING CORRECTIVE ACTION									
29. BASIC CAUSE OF VERIFIED FAILURE <input type="checkbox"/> DESIGN <input type="checkbox"/> ENVIRONMENTAL <input type="checkbox"/> DEFECTIVE PARTS									
30. TEST EQUIPMENT <input type="checkbox"/> TEST PROCEDURE <input type="checkbox"/> TEST SET-UP									
31. MFG. PROCEDURE <input type="checkbox"/> ASSY/FAB ERROR <input type="checkbox"/> WORKMANSHIP									
32. WIRING ERROR <input type="checkbox"/> ROUGH HANDLING <input type="checkbox"/> WEAR-OUT									
33. UNKNOWN									
34. DEFECT CODE									
35. FAILURE TYPE <input type="checkbox"/> PRIMARY <input type="checkbox"/> INDUCED									
36. UNKNOWN									
37. NO FAILURE									
38. FAILURE CLASSIFICATION <input type="checkbox"/> CRITICAL <input checked="" type="checkbox"/> MAJOR									
39. SPACECRAFT SYSTEM ENGINEER									
40. CUSTOMER OR SUPPLIER									

ORIGINAL PAGE IS
OF POOR QUALITY

HUGHES

HUGHES AIRCRAFT COMPANY
SPACE AND COMMUNICATIONS GROUP
EL SEGUNDO, CALIFORNIA

SPACE AND COMMUNICATIONS GROUP

FAILURE REPORT
CONTINUATION SHEET

FR SERIAL NO.
5 8207
CONTINUATION SHEET LETTER
A

*LABEL FIRST CONTINUATION SHEET USED 'A', SECOND 'B', AND SO ON

IDENTIFY ENTRIES BY REFERENCING FR BLOCK NUMBER IN COLUMN, DATE EACH ENTRY.

ADDITIONAL FR
CONTINUATION
SHEET(S) USED

30 SURFACE OF THE HOUSING USED FOR TESTING PREPARED.
THIS NOTICE READS "SCREWS ON EITHER SIDE OF
CONNECTORS MUST BE IN PLACE TO INSURE PWB IS
HELD FIRMLY TO ALLOW PROPER CONNECTOR MATING OF

HUGHESHUGHES AIRCRAFT COMPANY
SPACE AND COMMUNICATIONS GROUP
EL SEGUNDO, CALIFORNIAORIGINAL PAGE IS
OF POOR QUALITYSPACE AND COMMUNICATIONS GROUP
FAILURE REPORT

S 8208

ORIGINATOR	1. PROGRAM NAME AND NUMBER T.M. (PL 1162)	2. GLA	3. MODEL FLT-1	4. TIME OBSERVED VARIOUS	5. DATE OBSERVED MO 2 DA 11 YR 1982
	6. HARDWARE LEVEL WHEN FAILURE WAS OBSERVED <input type="checkbox"/> SPACECRAFT <input type="checkbox"/> SUBSYSTEM <input checked="" type="checkbox"/> ASSEMBLY <input type="checkbox"/> MODULE <input type="checkbox"/> CARD <input type="checkbox"/> SYSTEM <input type="checkbox"/> UNIT <input type="checkbox"/> SUBASSEMBLY <input type="checkbox"/> MICAM <input type="checkbox"/> PART				
	EQUIPMENT IDENTIFICATION: NAME PART NUMBER S/N MANUFACTURER				
	7. SUBSYSTEM				
	8. UNIT				
	9. <input checked="" type="checkbox"/> ASSEMBLY <input type="checkbox"/> SUBASSEMBLY CFFA IN DEWAR 50973 201 SBRC				
	10. <input type="checkbox"/> MODULE <input type="checkbox"/> MICAM <input type="checkbox"/> CARD				
	11. OTHER				
	12. TEST WHEN FAILURE WAS OBSERVED <input checked="" type="checkbox"/> DEVELOPMENT <input type="checkbox"/> QUALIFICATION <input type="checkbox"/> INTEGRATION <input type="checkbox"/> LAUNCH OPERATIONS <input type="checkbox"/> IN-PROCESS <input type="checkbox"/> ACCEPTANCE <input type="checkbox"/> SYSTEM				
	13. ENVIRONMENT WHEN FAILURE WAS OBSERVED <input type="checkbox"/> AMBIENT <input type="checkbox"/> RADIATION <input checked="" type="checkbox"/> TEMP 92.5 <input type="checkbox"/> THERMAL VAC <input type="checkbox"/> MRS AT <input type="checkbox"/> OTHER <input type="checkbox"/> EMC/RR <input type="checkbox"/> VIBRATION <input type="checkbox"/> AXIS FOR <input type="checkbox"/> MIN TYPE				
14. DESCRIPTION OF FAILURE SEE CONTINUATION SHEETS A AND B.					
ENGINEERING EVALUATION	15. TEST PROCEDURE 16192 PAHA 4.14, 4.15 16. ORIGINATOR N.C. DAVISON, III 17. ORG 2213 18. DATE FEB. 11, 1982 19. CONTINUATION SHEET USED				
	20. VERIFICATION AND FAILURE ANALYSIS UNIT WAS IN NORMAL TEST CONFIGURATION. NO OVERSTRESS OCCURRED. 92				
	21. FAILED ITEM NAME AND PART NUMBER				
	22. <input type="checkbox"/> FOLLOWING REWORK/RETEST REQUIRED <input checked="" type="checkbox"/> REWORK/RETEST NOT REQUIRED BECAUSE Discrepancies are small and will not affect performance enough to warrant rework.				
	23. AUTHORIZED BY [Signature] 24. ORG 2/21/82 25. DATE 2/15/82 26. CONTINUATION SHEET USED				
	27. REWORK/RETEST ACTION TAKEN NONE				
	28. QA Rework				
	29. QA RETEST				
	30. LIST ALL PARTS REPLACED PART NUMBER CKT SYM PART LOT NUMBER DATE CODE MANUFACTURER PROBABLE DEFECT ANALYSIS NUMBER				
	31. Rework by ORG DATE 32. RETESTED BY ORG DATE 33. CONTINUATION SHEET USED				
ENGINEERING/RELIABILITY	34. CAUSE AND CORRECTIVE ACTION The pulse response discrepancies are a function of the feedback resistors on the 7PA substrate on both passivated capacitors and the frequency boost and roll-off resistors on the 7PA substrate. These discrepancies are small and will not affect performance enough to warrant rework. Waiver to use as is per waiver, 135				
	35. DOCUMENT IMPLEMENTING CORRECTIVE ACTION Waiver W 135 (COPY ATTACHED)				
	36. FRB CLOSURE				
	37. BASIC CAUSE OF VERIFIED FAILURE <input checked="" type="checkbox"/> DESIGN <input type="checkbox"/> TEST EQUIPMENT <input type="checkbox"/> MFG. PROCEDURE <input type="checkbox"/> WIRING ERROR <input type="checkbox"/> ENVIRONMENTAL <input type="checkbox"/> TEST PROCEDURE <input type="checkbox"/> ASSY/FAB ERROR <input type="checkbox"/> MAJOR <input type="checkbox"/> DEFECTIVE PARTS <input type="checkbox"/> TEST SET-UP <input type="checkbox"/> WORKMANSHIP <input type="checkbox"/> WEAR-OUT				
	38. FAILURE TYPE <input type="checkbox"/> PRIMARY <input type="checkbox"/> UNKNOWN <input type="checkbox"/> NO FAILURE <input type="checkbox"/> CRITICAL <input checked="" type="checkbox"/> SECONDARY <input type="checkbox"/> MINOR				
	39. RESPONSIBLE ENGINEER [Signature] 40. ORG 2/21/82 41. DATE 2/22/82				
	42. RELIABILITY 51-41 2-18-82 43. CUSTOMER OR SUPPLIER				
	44. [Signature] 45. DATE 2/22/82				
	46. [Signature] 47. DATE 2/22/82				
	48. [Signature] 49. DATE 2/22/82				

SPACE AND COMMUNICATION GROUP
EQUIPMENT CHECKOUT
FAILURE REPORT
CONTINUATION SHEET

ORIGINAL PAGE IS
OF POOR QUALITY

UGHES

AIRCRAFT COMPANY

S 8208 CONT. SHEET
FR SERIAL NO. LETTER A

* LABEL FIRST CONTINUATION SHEET USED 'A', SECOND 'B', AND SO ON

- IDENTIFY ENTRIES BY REFERENCING FR BLOCK NUMBER IN COLUMN, DATE EACH ENTRY.

ADDITIONAL FR
CONTINUATION
SHEET(S) USED

D 5 HAS THE FOLLOWING OUT OF SPEC. CONDITIONS:
16192 PARAGRAPH 4.14

ENT RESPONSE SPEC: $\leq 10\%$ OVERSHOOT

CH. 4	IS	10.4%	CH. 10	IS	10.5%
CH. 6	IS	10.8%	CH. 11	IS	11.2%
CH. 7	IS	11.0%	CH. 12	IS	10.8%
CH. 9	IS	11.5%			

SETTLING TIME SPEC: SETTLED TO WITHIN 1.5% AFTER
 $22\% + 30 \mu\text{Sec}$
SETTLED TO WITHIN 1.0% AFTER
 $22\% + 60 \mu\text{Sec}$

CH. 10 IS $+2\%$ AFTER $38 \mu\text{Sec}$
 $+1.5\%$ AFTER $40 \mu\text{Sec}$
 $+1.0\%$ AFTER $45 \mu\text{Sec}$

3 DB POINTS SPEC: -2 TO -3 DB AT 52 KHZ

CH. 10 IS -3.19 DB AT 52 KHZ
CH. 12 IS -1.95 DB AT 52 KHZ

DELAY TIMES SPEC: DELAY TIMES SHALL BE WITHIN
 $\pm 0.5 \mu\text{Sec}$ OF EACH OTHER

ALL CHANNELS AS A POPULATION DO NOT MEET
THIS REQUIREMENT.

RISETIME (IN μSec)

FALL TIME (IN μSec)

1 12.2	9 12.0	1 13.1	9 12.7
2 12.0	10 13.0	2 12.5	10 13.8
3 12.4	11 12.0	3 13.0	11 12.5
4 12.0	12 12.2	4 12.6	12 12.8
5 11.6	13 12.0	5 12.2	13 12.5
6 12.6	14 12.4	6 13.1	14 13.0
7 11.9	15 11.6	7 12.4	15 12.1
8 12.4	16 12.6	8 13.0	16 13.1



SPACE AND COMMUNICATION GROUP
EQUIPMENT CHECKOUT
FAILURE REPORT
CONTINUATION SHEET

ORIGINAL PAGE IS
OF POOR QUALITY

S 8208 CONT. SHEET
FR SERIAL NO. 1 LETTER B

* LABEL FIRST CONTINUATION SHEET USED 'A', SECOND 'B', AND SO ON

IDENTIFY ENTRIES BY REFERENCING FR BLOCK NUMBER IN COLUMN, DATE EACH ENTRY.

ADDITIONAL FR
CONTINUATION
SHEET(S) USED.

14	BAND 7 HAS THE FOLLOWING OUT OF SPEC. CONDITION 3: PER 16192 PARAGRAPH 4.14		
TRANSIENT RESPONSE: SPEC: $\pm 10\%$ OVER $\pm 400\text{T}$			
CH. 6 IS 11.0%			
SETTLING TIMES SPEC: SETTLED TO WITHIN 1.5% AFTER $C_{120} + 30\mu\text{SEC}$ SETTLED TO WITHIN 1.0% AFTER $C_{120} + 60\mu\text{SEC}$			
CH. 5 IS SETTLED TO 1.5% AFTER $33\mu\text{SEC}$ CH. 5 " " " 1.0% AFTER $35\mu\text{SEC}$			
3 dB POINTS SPEC: -2 TO -3 dB AT 52 KHz			
CH. 5 IS -3.25 dB AT 52 KHz CH. 16 IS -3.32 dB AT 52 KHz			
DELAY TIMES SPEC: DELAY TIMES SHALL BE WITHIN $\pm 0.5\mu\text{SEC}$ OF EACH OTHER			
ALL CHANNELS AS A POPULATION DO NOT MEET THIS REQUIREMENT			
RISETIME DELAY (IN μSEC)		FALLTIME DELAY (IN μSEC)	
1 12.0	9 12.9	1 12.3	9 13.4
2 12.1	10 12.5	2 12.5	10 13.2
3 11.8	11 12.4	3 12.2	11 12.9
4 12.5	12 12.3	4 12.8	12 12.7
5 12.0	13 12.2	5 12.6	13 12.6
6 12.3	14 12.4	6 12.6	14 12.8
7 12.2	15 12.3	7 12.5	15 12.8
8 12.6	16 13.0	8 13.0	16 13.4

58208

ST FOR DEVIATION/WAIVER
VIL-STD-APU OR 481 FOR INSTRUCTIONS)

DATE PREPARED
2-17-82

PROCURING ACTIVITY NO.

1. ORIGINATOR NAME AND ADDRESS
David M. Randall
SBRC, 75 Coromar Drive, Goleta, CA 93117

2. ☐ DEVIATION ☒ WAIVER

3. ☐ MINOR ☒ MAJOR ☐ CRITICAL

4. DESIGNATION FOR DEVIATION/WAIVER

a. MODEL/TYPE
F

b. MFR. CODE
11323

c. SYS. DESIG.
TM

d. DEV/WAIVER NO.
W-135

5. BASE LINE AFFECTED

☒ FUNCTIONAL ☐ ALLOCATED ☐ PRODUCTION

6. OTHER SYSTEMS/CONFIGURATION ITEMS AFFECTED

☐ YES ☒ NO

7. SPECIFICATIONS AFFECTED-TEST PLAN

a. SYSTEM

b. ITEM

c. TEST PLAN

8. DRAWINGS AFFECTED

a. MFR. CODE
11323

b. NUMBER
50973

c. REV.
B

d. NOR. NO.
3895A, 2870A

9. TITLE OF DEVIATION/WAIVER
Permission to use F-1 CFPA with discrepancies per FR8206

10. CONTRACT NO. & LINE 11
NAS 5-24200

11. CONFIGURATION ITEM NOMENCLATURE
Radiometer

12. CD NO.
11

13. DEFECT NO.

14. DEFECT CLASSIFICATION

☒ MINOR ☐ MAJOR ☐ CRITICAL

15. NAME OF PART OR LOWEST ASSEMBLY AFFECTED
CFPA

16. PART NO. OR TYPE DESIG.
50973

17. LOT NO.
201

18. QTY
1

19. RECURRING DEVIATION/WAIVER

☐ YES ☒ NO

20. EFFECT ON COST/PRICE
> 50,000 if not approved

21. EFFECT ON DELIVERY SCHEDULE
4 weeks if not approved

22. EFFECT ON INTEGRATED LOGISTIC SUPPORT, INTERFACE, ETC.

23. DESCRIPTION OF DEVIATION/WAIVER

Permission to use F-1 CFPA with discrepancies per FR 8208.
A copy of FR 8208 is attached -

ORIGINAL PAGE IS
OF POOR QUALITY

24. NEED FOR DEVIATION/WAIVER

To determine selects that would improve the pulse response would require removal of the optical filter assembly and retest. This is a risky operation and there is no guaranty that the results of reselection would give in specification performance. Discrepancies are small and will not affect performance enough to warrant rework.

25. PRODUCTION EFFECTIVITY BY SERIAL NUMBER
003

26. SUBMITTING ACTIVITY AUTHORIZING SIGNATURE
FR Pullips

TITLE
Program Manager

27. APPROVAL/DISAPPROVAL

a. ☒ APPROVAL RECOMMENDED

b. ☒ APPROVED ☐ DISAPPROVED

c. GOVERNMENT ACTIVITY
LANDSAT-D PROJECT OFFICE

SIGNATURE
Gundewister

DATE
2/18/82

DD FORM 1694

HUGHESHUGHES AIRCRAFT COMPANY
SPACE AND COMMUNICATIONS GROUP
EL SEGUNDO, CALIFORNIASPACE AND COMMUNICATIONS GROUP
FAILURE REPORT

SUPP#6-OP#300

ORIGINAL PAGE IS
OF POOR QUALITY**S** 8225

ORIGINATOR	1. PROGRAM NAME AND NUMBER VO11 TM		2. GLA	3. MODEL FLIGHT	4. TIME OBSERVED 3:30 P.M.	5. DATE OBSERVED MO 8 DA 11 YR 1981
	6. HARDWARE LEVEL WHEN FAILURE WAS OBSERVED <input type="checkbox"/> SPACECRAFT <input type="checkbox"/> SYSTEM		<input type="checkbox"/> SUBSYSTEM <input type="checkbox"/> UNIT	<input checked="" type="checkbox"/> ASSEMBLY <input type="checkbox"/> SUBASSEMBLY	<input type="checkbox"/> MODULE <input type="checkbox"/> MICAM	<input type="checkbox"/> CARD <input type="checkbox"/> PART
	EQUIPMENT IDENTIFICATION:					
	7. SUBSYSTEM		NAME		PART NUMBER	S/N
	8. UNIT					
	9. <input checked="" type="checkbox"/> ASSEMBLY <input type="checkbox"/> SUBASSEMBLY		COLD FPA ASSY		50973	201
	10. <input type="checkbox"/> MODULE <input type="checkbox"/> MICAM <input type="checkbox"/> CARD					SBCC
	11. OTHER					
	12. TEST WHEN FAILURE WAS OBSERVED <input type="checkbox"/> DEVELOPMENT <input checked="" type="checkbox"/> IN-PROCESS		<input type="checkbox"/> QUALIFICATION <input type="checkbox"/> ACCEPTANCE	<input type="checkbox"/> INTEGRATION <input type="checkbox"/> SYSTEM	<input type="checkbox"/> LAUNCH OPERATIONS	
	13. ENVIRONMENT WHEN FAILURE WAS OBSERVED <input type="checkbox"/> AMBIENT <input type="checkbox"/> EMC/RF		<input type="checkbox"/> RADIATION <input type="checkbox"/> VIBRATION	<input checked="" type="checkbox"/> TEMP 95.0 K AXIS FOR MIN TYPE	<input type="checkbox"/> THERMAL VAC WRS AT <input type="checkbox"/> OTHER	
ENGINEERING EVALUATION	14. DESCRIPTION OF FAILURE BAND 5 CH. 9 INPUT SHORT TO GROUND, CH. 11 NO OUTPUT SIGNAL. BAND 7 CH. 2 NO OUTPUT SIGNAL. ALL ABOVE OBSERVED DURING INJECTED SIGNAL TEST.					
	15. TEST PROCEDURE 16192		16. PARA 4.6	17. ORIGINATOR A.C. DAVISON	18. ORG 2213	19. DATE 8/11/81
	20. VERIFICATION AND FAILURE ANALYSIS NO OVERSTRESS OCCURRED. INPUTS WERE DERIVED FROM TEST EQUIPMENT. OUTPUT IS FED INTO VERY HIGH IMPEDENCE CIRCUIT, RESULTING IN VERY LOW CURRENTS AVAILABLE TO FOLLOWING CIRCUITRY. UNIT WAS IN NORMAL TEST CONFIGURATION.					
	21. FOLLOWING REWORK/RETEST REQUIRED <input type="checkbox"/> Rework/Retest Not Required Because Replace arrays per supplement #7					
	22. AUTHORITY W.M. Randall					
	23. CONTINUATION <input type="checkbox"/> SHEET USED					
	24. ORIGINATOR'S SIGNATURE (178)					
	25. QA REVIEWER'S SIGNATURE (178)					
	26. LIST ALL PARTS REPLACED PART NUMBER CXT SYM PART LOT NUMBER DATE CODE MANUFACTURER PROBABLE DEFECT ANALYSIS NUMBER					
	27. REWORK BY 50958 Bands 906-3316A-11-116 50958 Band 7 906-3316A-13-128					
ENGINEERING/RELIABILITY	28. REWORK BY ORG DATE 21/21 8/11/81					
	29. REWORK BY ORG DATE 21/21 8/11/81					
	30. CAUSE AND CORRECTIVE ACTION These arrays were damaged during A9 early in-service mission. This work was directed by NASA to ensure that detector elements would not incur opens due to poor TAV coverage of thick SiOx stud. The arrays were returned during removal from FPA and no further failure analysis was possible.					
	31. FRB CLOSURE					
	32. DOCUMENT IMPLEMENTING CORRECTIVE ACTION					
	33. CONTINUATION <input type="checkbox"/> SHEET USED					
	34. BASIC CAUSE OF VERIFIED FAILURE <input type="checkbox"/> DESIGN <input type="checkbox"/> ENVIRONMENTAL <input type="checkbox"/> DEFECTIVE PARTS					
	35. TEST EQUIPMENT <input type="checkbox"/> TEST PROCEDURE <input type="checkbox"/> TEST SET-UP					
	36. MFG. PROCEDURE <input type="checkbox"/> ASSY/FAB ERROR <input type="checkbox"/> WORKMANSHIP					
	37. WIRING ERROR <input type="checkbox"/> ROUGH HANDLING <input type="checkbox"/> WEAR-OUT					
38. FAILURE CLASSIFICATION <input type="checkbox"/> CRITICAL <input type="checkbox"/> MAJOR <input type="checkbox"/> MINOR <input type="checkbox"/> SAFETY						
39. RESPONSIBLE ENGINEER W.M. Randall 2/21 2/10/82						
40. CUSTOMER OR SUPPLIER 5141 2-18-82						

HUGHES

HUGHES AIRCRAFT COMPANY
SPACE AND COMMUNICATIONS GROUP
EL SEGUNDO, CALIFORNIA

SPACE AND COMMUNICATIONS GROUP FAILURE REPORT

S 822

1. PROGRAM NAME AND NUMBER V011 TM		2. GLA	3. MODEL FLIGHT	4. TIME OBSERVED 10:30 am	5. DATE OBSERVED MO 09 DA 08 YR 8
6. HARDWARE LEVEL WHEN FAILURE WAS OBSERVED <input type="checkbox"/> SPACECRAFT <input type="checkbox"/> SYSTEM		<input type="checkbox"/> SUBSYSTEM <input type="checkbox"/> UNIT	<input checked="" type="checkbox"/> ASSEMBLY <input type="checkbox"/> SUBASSEMBLY	<input type="checkbox"/> MODULE <input type="checkbox"/> MICAM	<input type="checkbox"/> CARD <input type="checkbox"/> PART
EQUIPMENT IDENTIFICATION:					
7. SUBSYSTEM		NAME		PART NUMBER	S/N
8. UNIT					
<input checked="" type="checkbox"/> ASSEMBLY <input type="checkbox"/> SUBASSEMBLY		CFPA ASSY		50973	201
10. <input type="checkbox"/> MODULE <input type="checkbox"/> MICAM <input type="checkbox"/> CARD					
11. OTHER					
12. TEST WHEN FAILURE WAS OBSERVED <input type="checkbox"/> DEVELOPMENT <input checked="" type="checkbox"/> IN-PROCESS		<input type="checkbox"/> QUALIFICATION <input type="checkbox"/> ACCEPTANCE	<input type="checkbox"/> INTEGRATION <input type="checkbox"/> SYSTEM	<input type="checkbox"/> LAUNCH OPERATIONS	
13. ENVIRONMENT WHEN FAILURE WAS OBSERVED <input type="checkbox"/> AMBIENT <input type="checkbox"/> EMC/RFI		<input type="checkbox"/> RADIATION <input type="checkbox"/> VIBRATION	<input checked="" type="checkbox"/> TEMP AMB AXIS FOR _____	<input type="checkbox"/> THERMAL VAC _____ HRS AT _____ <input type="checkbox"/> OTHER _____	
14. DESCRIPTION OF FAILURE BAND 5, CH. 10, 12 DIFFERENCE BETWEEN SIGNAL & REFERENCE OFFSET MEASURED $\geq \pm 10$ MV. CH. 10 SIG-REF = 37.5 CH. 12 SIG-REF = 302 MV. DRAIN CURRENTS IN SPEC.					
15. TEST PROCEDURE 16192		PARA 4.2	16. ORIGINATOR C. R. Lane	ORG 2213	DATE 08-05-81
17. CONTIN. SHEET					
18. VERIFICATION AND FAILURE ANALYSIS No abnormalities occurred. Unit was in normal test configuration. Outputs are fed into high impedance circuit, limiting current to other devices.					
19. FOLLOWING REWORK/RETEST REQUIRED <input type="checkbox"/> REWORK/RETEST NOT REQUIRED BECAUSE Repair with Ag spec per MRCO 39323					
19. FAILED ITEM NAME AND PART NUMBER 16-010102 50958					
20. REWORK/RETEST ACTION TAKEN Repair with Ag spec per MRCO 39323. CH 10 and channel defect within Ref 7R 8319. Carry failed test; ref 7R 9443 for failure analysis.					
21. AUTHORITY W. R. [Signature]					
22. CONTIN. SHEET					
23. REWORK/RETEST ACTION TAKEN Repair with Ag spec per MRCO 39323. CH 10 and channel defect within Ref 7R 8319. Carry failed test; ref 7R 9443 for failure analysis.					
24. QA [Signature]					
25. QA [Signature]					
26. LIST ALL PARTS REPLACED					
PART NUMBER	CRT SYM	PART LOT NUMBER	DATE CODE	MANUFACTURER	PROBABLE DEFECT
50958 Bands		95-23167-11-101			
27. Rework by					
ORG		DATE	28. RETESTED BY		DATE
29. CONTIN. SHEET					
30. CAUSE AND CORRECTIVE ACTION Cause is unknown. Possibilities are: detector was opened by high current due to ESD or other current source (possibly defective pull down) or a defect inherent in the detector. (Chad Storr also known to be a hard area to count with T. by)					
31. CONTINUATION SHEET USED					
32. DOCUMENT IMPLEMENTING CORRECTIVE ACTION					
34. BASIC CAUSE OF VERIFIED FAILURE <input type="checkbox"/> DESIGN <input type="checkbox"/> ENVIRONMENTAL <input type="checkbox"/> DEFECTIVE PARTS		<input type="checkbox"/> TEST EQUIPMENT <input type="checkbox"/> TEST PROCEDURE <input type="checkbox"/> TEST SET-UP	<input type="checkbox"/> MFG. PROCEDURE <input type="checkbox"/> ASSY/FAB ERROR <input type="checkbox"/> WORKMANSHIP	<input type="checkbox"/> WIRING ERROR <input type="checkbox"/> ROUGH HANDLING <input type="checkbox"/> WEAR-OUT	
35. FAILURE TYPE <input type="checkbox"/> PRIMARY <input type="checkbox"/> INDUCED		<input type="checkbox"/> UNKNOWN <input type="checkbox"/> NO FAILURE	36. FAILURE CLASSIFICATION <input type="checkbox"/> CRITICAL <input checked="" type="checkbox"/> MAJOR		<input type="checkbox"/> MINOR <input type="checkbox"/> SAFETY
37. RESPONSIBLE ENGINEER [Signature]		ORG 2121	DATE 2/10/82	38. SPACECRAFT SYSTEM ENGINEER [Signature]	
39. RELIABILITY [Signature]		ORG 5741	DATE 2-18-82	40. CUSTOMER OR SUPPLIER [Signature]	

011875 SP JAN 80

2/23/82

ORIGINAL PAGE IS
OF POOR QUALITY

HUGHESHUGHES AIRCRAFT COMPANY
SPACE AND COMMUNICATIONS GROUP
EL SEGUNDO, CALIFORNIASPACE AND COMMUNICATIONS GROUP
FAILURE REPORTORIGINAL PAGE IS
OF POOR QUALITY**S 8226**

ORIGINATOR	1. PROGRAM NAME AND NUMBER V011 TM		2. GLA		3. MODEL FLIGHT		4. TIME OBSERVED 10:30am		5. DATE OBSERVED MO 09 DA 08 YR 81	
	6. HARDWARE LEVEL WHEN FAILURE WAS OBSERVED <input type="checkbox"/> SPACECRAFT <input type="checkbox"/> SUBSYSTEM <input checked="" type="checkbox"/> ASSEMBLY <input type="checkbox"/> MODULE <input type="checkbox"/> CARD		<input type="checkbox"/> SYSTEM <input type="checkbox"/> UNIT <input type="checkbox"/> SUBASSEMBLY <input type="checkbox"/> MICAM <input type="checkbox"/> PART							
	EQUIPMENT IDENTIFICATION: NAME PART NUMBER S/N MANUFACTURER									
	7. SUBSYSTEM									
	8. UNIT									
	9. <input checked="" type="checkbox"/> ASSEMBLY <input type="checkbox"/> SUBASSEMBLY CFPA ASSY 50973 201 SBRL									
	10. <input type="checkbox"/> MODULE <input type="checkbox"/> MICAM <input type="checkbox"/> CARD									
	11. OTHER									
	12. TEST WHEN FAILURE WAS OBSERVED <input type="checkbox"/> DEVELOPMENT <input type="checkbox"/> QUALIFICATION <input type="checkbox"/> INTEGRATION <input type="checkbox"/> LAUNCH OPERATIONS <input checked="" type="checkbox"/> IN-PROCESS <input type="checkbox"/> ACCEPTANCE <input type="checkbox"/> SYSTEM									
	13. ENVIRONMENT WHEN FAILURE WAS OBSERVED <input type="checkbox"/> AMBIENT <input type="checkbox"/> RADIATION <input checked="" type="checkbox"/> TEMP. AMP. <input type="checkbox"/> THERMAL VAC. HRS. AT <input type="checkbox"/> EMC/RF <input type="checkbox"/> VIBRATION <input type="checkbox"/> AXIS FOR MIN TYPE <input type="checkbox"/> OTHER									
ENGINEERING EVALUATION	14. DESCRIPTION OF FAILURE BAND 5, CH. 10, 12 DIFFERENCE BETWEEN SIGNAL AND REFERENCE OFFSET MEASURED ≥ 10 mV. CH. 10 SIG-REF = 375 mV CH. 12 SIG-REF = 362 mV. DRAIN CURRENT: IN SPEC.									
	15. TEST PROCEDURE 16192 PARA 4.2 16. ORIGINATOR C. R. Lane ORG 2213 DATE 08-05-81 17. CONTINUATION SHEET USED <input type="checkbox"/>									
	18. VERIFICATION AND FAILURE ANALYSIS No overstress occurred. Unit was in normal test configuration. Outputs are fed into high impedance circuit, limiting current to other devices.									
	19. FOLLOWING REWORK/RETEST REQUIRED <input type="checkbox"/> REWORK/RETEST NOT REQUIRED BECAUSE Repair with Ag comp per MRCO 393239									
	20. AUTHORIZED BY [Signature] ORG 2213 DATE 8/9/81 21. CONTINUATION SHEET USED <input type="checkbox"/>									
	22. Rework/Retest Action Taken Repaired with Ag comp per MRCO 393239. Ch 10 and channel detector within spec. 72 235. Array failed during ref 38 9443 per failure analysis.									
	23. LIST ALL PARTS REPLACED PART NUMBER CKT SYM PART LOT NUMBER DATE CODE MANUFACTURER PROBABLE DEFECT ANALYSIS NUMBER									
	50958 Bands 906-3311A 11-101									
	24. Rework By ORG DATE 25. Retested By ORG DATE 26. CONTINUATION SHEET USED <input type="checkbox"/>									
	ENGINEERING/RELIABILITY	27. CAUSE AND CORRECTIVE ACTION Cause is unknown. Possibilities are: detector trace was opened by large current due to ESD or other current source (possibly detector pull tester) or a defect inherent in the detector. Check Si ox step. Reason to be a hard area to coat with Ti.								
28. DOCUMENT IMPLEMENTING CORRECTIVE ACTION										
29. BASIC CAUSE OF VERIFIED FAILURE <input type="checkbox"/> DESIGN <input type="checkbox"/> ENVIRONMENTAL <input type="checkbox"/> DEFECTIVE PARTS <input type="checkbox"/> TEST EQUIPMENT <input type="checkbox"/> TEST PROCEDURE <input type="checkbox"/> TEST SET-UP <input type="checkbox"/> MFG. PROCEDURE <input type="checkbox"/> ASSY/FAB ERROR <input type="checkbox"/> WORKMANSHIP <input type="checkbox"/> WIRING ERROR <input type="checkbox"/> ROUGH HANDLING <input type="checkbox"/> WEAR-OUT										
30. FAILURE TYPE <input type="checkbox"/> PRIMARY <input type="checkbox"/> INDUCED <input checked="" type="checkbox"/> UNKNOWN <input type="checkbox"/> NO FAILURE										
31. RESPONSE ENGINEER [Signature] ORG 2121 DATE 2/10/82 32. FAILURE CLASSIFICATION <input checked="" type="checkbox"/> CRITICAL <input type="checkbox"/> MAJOR <input type="checkbox"/> MINOR <input type="checkbox"/> SAFETY										
33. RELIABILITY [Signature] ORG 3841 DATE 2-19-82 34. CUSTOMER OR SUPPLIER [Signature] ORG 22-41 DATE 2/22/82										
35. CONTINUATION SHEET USED <input type="checkbox"/>										
36. FRB CLOSURE										
37. UNKNOWN DEFECT CODE										
38. [Signature] 2/22/82										

HUGHESHUGHES AIRCRAFT COMPANY
SPACE AND COMMUNICATIONS GROUP
EL SEGUNDO, CALIFORNIASPACE AND COMMUNICATIONS GROUP
FAILURE REPORTOper 300 MRCO 393239R / Suppl. 7
oper # 316**S** 8319

ORIGINATOR	1. PROGRAM NAME AND NUMBER V011 TM		2. GLA	3. MODEL FLIGHT	4. TIME OBSERVED 11am	5. DATE OBSERVED MO 09 DA 19 YR 8
	6. HARDWARE LEVEL WHEN FAILURE WAS OBSERVED <input type="checkbox"/> SPACECRAFT <input type="checkbox"/> SYSTEM		<input type="checkbox"/> SUBSYSTEM <input type="checkbox"/> UNIT	<input type="checkbox"/> ASSEMBLY <input checked="" type="checkbox"/> SUBASSEMBLY	<input type="checkbox"/> MODULE <input type="checkbox"/> MACAM	<input type="checkbox"/> CARD <input type="checkbox"/> PART
	EQUIPMENT IDENTIFICATION:					
	7. SUBSYSTEM		NAME		PART NUMBER	S/N
	8. UNIT					
	9. <input type="checkbox"/> ASSEMBLY <input checked="" type="checkbox"/> SUBASSEMBLY		CFPA		50973	201
	10. <input type="checkbox"/> MODULE <input type="checkbox"/> MACAM <input type="checkbox"/> CARD					
	11. OTHER					
	12. TEST WHEN FAILURE WAS OBSERVED <input type="checkbox"/> DEVELOPMENT <input checked="" type="checkbox"/> IN-PROCESS		<input type="checkbox"/> QUALIFICATION <input type="checkbox"/> ACCEPTANCE	<input type="checkbox"/> INTEGRATION <input type="checkbox"/> SYSTEM	<input type="checkbox"/> LAUNCH OPERATIONS	
	13. ENVIRONMENT WHEN FAILURE WAS OBSERVED <input type="checkbox"/> AMBIENT <input type="checkbox"/> EMC/RF		<input type="checkbox"/> RADIATION <input type="checkbox"/> VIBRATION	<input checked="" type="checkbox"/> TEMP 95. K AXIS FOR	<input type="checkbox"/> THERMAL VAC	HRS AT
14. DESCRIPTION OF FAILURE CH. 10 EXHIBITS NO RESPONSE TO INJECTED SIGNAL CH. 12 RESPONSE TO INJECTED SIGNAL TOO HIGH 158m Band 5						
ENGINEERING EVALUATION	15. TEST PROCEDURE 16192		16. PARA 4.6	17. ORIGINATOR C.R. Lane	18. ORG 2213	19. DATE 09-19-81
	20. VERIFICATION AND FAILURE ANALYSIS NO OVERSTRESS OBSERVED. UNIT WAS IN NORMAL TEST CONFIGURATION. OUTPUT IS FED THROUGH 100M IMPEDANCE OPEN. LIMITING CURRENT TO OTHER DEVICES.					
	21. FOLLOWING REWORK/RETEST REQUIRED <input checked="" type="checkbox"/> REWORK/RETEST NOT REQUIRED REASON Ch. 10 - 109 allowed use of this device with Ch. 10 - 109. Ch. 12 - 109 allowed use of this device with Ch. 10 - 109. Ch. 12 - 109 allowed use of this device with Ch. 10 - 109.					
	22. REWORK/RETEST ACTION TAKEN Ref 7R 8443. Ch. 12 was repaired with Ag epoxy and tested good. Ref to FR 8443 for failure analysis.					
	23. LIST ALL PARTS REPLACED					
	PART NUMBER	CKT SYM	PART LOT NUMBER	DATE CODE	MANUFACTURER	PROBABLE DEFECT
	5098 Band 5		906-33164-11-101			
	24. Rework by					
	25. Cause and corrective action Ch. 10 was probably damaged during rework of open per MRCO 393239. Ref 7R 8226 Ch. 12 was open due to inadequate Ag epoxy repair.					
	ENGINEERING/RELIABILITY	26. DOCUMENT IMPLEMENTING CORRECTIVE ACTION				
27. BASIC CAUSE OF VERIFIED FAILURE <input type="checkbox"/> DESIGN <input type="checkbox"/> ENVIRONMENTAL <input type="checkbox"/> DEFECTIVE PARTS						
28. FAILURE TYPE <input type="checkbox"/> PRIMARY <input type="checkbox"/> INDUCED <input checked="" type="checkbox"/> UNKNOWN <input type="checkbox"/> NO FAILURE						
29. RESPONSIBLE ENGINEER W. H. H. H.						
30. RELIABILITY 5141						
31. CONTINUATION <input type="checkbox"/> SHEET USED						
32. CONTINUATION <input type="checkbox"/> SHEET USED						
33. FRD CLOSURE						
34. BASIC CAUSE OF VERIFIED FAILURE <input type="checkbox"/> DESIGN <input type="checkbox"/> ENVIRONMENTAL <input type="checkbox"/> DEFECTIVE PARTS						
35. FAILURE CLASSIFICATION <input type="checkbox"/> CRITICAL <input type="checkbox"/> MAJOR <input type="checkbox"/> MINOR <input type="checkbox"/> SAFETY						
36. FAILURE ORIGIN <input type="checkbox"/> DESIGN <input type="checkbox"/> MFG. PROCEDURE <input type="checkbox"/> ASSY/FAB ERROR <input type="checkbox"/> WORKMANSHIP						
37. FAILURE ORIGIN <input type="checkbox"/> DESIGN <input type="checkbox"/> MFG. PROCEDURE <input type="checkbox"/> ASSY/FAB ERROR <input type="checkbox"/> WORKMANSHIP						
38. FAILURE ORIGIN <input type="checkbox"/> DESIGN <input type="checkbox"/> MFG. PROCEDURE <input type="checkbox"/> ASSY/FAB ERROR <input type="checkbox"/> WORKMANSHIP						
39. FAILURE ORIGIN <input type="checkbox"/> DESIGN <input type="checkbox"/> MFG. PROCEDURE <input type="checkbox"/> ASSY/FAB ERROR <input type="checkbox"/> WORKMANSHIP						
40. FAILURE ORIGIN <input type="checkbox"/> DESIGN <input type="checkbox"/> MFG. PROCEDURE <input type="checkbox"/> ASSY/FAB ERROR <input type="checkbox"/> WORKMANSHIP						

HUGHESHUGHES AIRCRAFT COMPANY
SPACE AND COMMUNICATIONS GROUP
EL SEGUNDO, CALIFORNIA

50973 TEST AHR, ORIGINATOR # 800

ORIGINAL PAGE IS
OF POOR QUALITYSPACE AND COMMUNICATIONS GROUP
FAILURE REPORT**S 8340**

ORIGINATOR	1. PROGRAM NAME AND NUMBER V411 TM		2. GLA		3. MODEL FLIGHT		4. TIME OBSERVED 5: PM		5. DATE OBSERVED MO 10 DA 22 YR 81	
	6. HARDWARE LEVEL WHEN FAILURE WAS OBSERVED <input type="checkbox"/> SPACECRAFT <input type="checkbox"/> SUBSYSTEM <input type="checkbox"/> ASSEMBLY <input type="checkbox"/> MODULE <input type="checkbox"/> CARD		<input type="checkbox"/> SYSTEM <input type="checkbox"/> UNIT <input checked="" type="checkbox"/> SUBASSEMBLY <input type="checkbox"/> MICAM <input type="checkbox"/> PART							
	EQUIPMENT IDENTIFICATION:									
	7. SUBSYSTEM		NAME		PART NUMBER		S/N		MANUFACTURER	
ENGINEERING EVALUATION	8. UNIT									
	9. <input type="checkbox"/> ASSEMBLY <input checked="" type="checkbox"/> SUBASSEMBLY		CFPA		50973		201		SBRC	
	10. <input type="checkbox"/> MODULE <input type="checkbox"/> MICAM <input type="checkbox"/> CARD		Test AHR							
	11. OTHER		BAND 7							
	12. TEST WHEN FAILURE WAS OBSERVED <input type="checkbox"/> DEVELOPMENT <input checked="" type="checkbox"/> IN-PROCESS <input type="checkbox"/> QUALIFICATION <input type="checkbox"/> ACCEPTANCE <input type="checkbox"/> INTEGRATION <input type="checkbox"/> SYSTEM <input type="checkbox"/> LAUNCH OPERATIONS									
	13. ENVIRONMENT WHEN FAILURE WAS OBSERVED <input type="checkbox"/> AMBIENT <input type="checkbox"/> EMC/RFI <input type="checkbox"/> RADIATION <input type="checkbox"/> VIBRATION <input checked="" type="checkbox"/> TEMP 91.5 <input type="checkbox"/> THERMAL VAC <input type="checkbox"/> HRS AT <input type="checkbox"/> OTHER									
	14. DESCRIPTION OF FAILURE BAND 7, CH 8 and 16 unable to set bias adjust per 16192 para 4.10. CH 8 read \approx 4 volts, CH 16 read \approx 8.9 volts. Both should be 5.0V.									
	15. TEST PROCEDURE 16192		PARA 4.10		16. ORIGINATOR J. L. Anderson		ORG 2213		DATE 22 OCT 81	
	17. CONTINUATION SHEET USED <input type="checkbox"/>									
	MANUFACTURING AND TEST	18. VERIFICATION AND FAILURE ANALYSIS No adjustment required. Device was in that configuration. B. 9V appeared at PIN 6 of A HA 2304. This device can withstand a differential input of \pm 18.0 volts. Voltage was seen on TREAD BOARD.								
19. FAILED ITEM NAME AND PART NUMBER 50958 and 16192										
20. FOLLOWING REWORK/RETEST REQUIRED <input type="checkbox"/> REWORK/RETEST NOT REQUIRED BECAUSE Replaced detector per supplement 88										
21. AUTHORITY J. L. Anderson										
22. REWORK/RETEST ACTION TAKEN Detector later failed; ref 72 8443										
23. LIST ALL PARTS REPLACED										
PART NUMBER		CKT SYM	PART LOT NUMBER	DATE CODE	MANUFACTURER	PROBABLE DEFECT	ANALYSIS NUMBER			
50958/Band 7			906-3316A-13-162							
27. REWORK BY										
28. RETESTED BY										
ENGINEERING/RELIABILITY	29. CAUSE AND CORRECTIVE ACTION Unknown. Best possibility is that wind-up pull-down was at fault. The pull-down was later found to be defective and had 4V on the pull-down. This detector was sent to TSD for failure analysis and results were negative. Ref TSD Report 76-1P-42									
	30. FRB CLOSURE									
	31. CONTINUATION SHEET USED <input type="checkbox"/>									
	32. DOCUMENT IMPLEMENTING CORRECTIVE ACTION									
	34. BASIC CAUSE OF VERIFIED FAILURE <input type="checkbox"/> DESIGN <input type="checkbox"/> ENVIRONMENTAL <input type="checkbox"/> DEFECTIVE PARTS		<input type="checkbox"/> TEST EQUIPMENT <input type="checkbox"/> TEST PROCEDURE <input type="checkbox"/> TEST SET-UP		<input type="checkbox"/> MFG. PROCEDURE <input type="checkbox"/> ASSY/FAB ERROR <input type="checkbox"/> WORKMANSHIP		<input type="checkbox"/> WIRING ERROR <input type="checkbox"/> ROUGH HANDLING <input type="checkbox"/> WEAR-OUT		35. UNKNOWN DEFECT CODE	
	35. FAILURE TYPE <input type="checkbox"/> PRIMARY <input type="checkbox"/> INDUCED <input checked="" type="checkbox"/> UNKNOWN <input type="checkbox"/> NO FAILURE				36. FAILURE CLASSIFICATION <input type="checkbox"/> CRITICAL <input type="checkbox"/> MAJOR <input type="checkbox"/> MINOR <input type="checkbox"/> SAFETY					
	37. RESPONSIBLE ENGINEER J. L. Anderson		ORG 2213		DATE 2/10/82		38. SPACECRAFT/SYSTEM ENGINEER J. L. Anderson		ORG 22-41	
	39. FAILURE 51-41		ORG 2-18-82		DATE 2/22/82		CUSTOMER OR SUPPLIER P. 5		DATE 2/22/82	

HUGHESHUGHES AIRCRAFT COMPANY
SPACE AND COMMUNICATIONS GROUP
EL SEGUNDO, CALIFORNIASPACE AND COMMUNICATIONS GROUP
FAILURE REPORT**S** 8394

1. PROGRAM NAME AND NUMBER THIRPAC MAPPER FL1162		2. GLA	3. MODEL F 1	4. TIME OBSERVED 11:00 AM	5. DATE OBSERVED MO 2 DA 26 YR 8
9. HARDWARE LEVEL WHEN FAILURE WAS OBSERVED <input type="checkbox"/> SPACECRAFT <input type="checkbox"/> SYSTEM		<input type="checkbox"/> SUBSYSTEM <input type="checkbox"/> UNIT	<input type="checkbox"/> ASSEMBLY <input type="checkbox"/> SUBASSEMBLY	<input type="checkbox"/> MODULE <input type="checkbox"/> MICAM	<input type="checkbox"/> CARD <input type="checkbox"/> PART
EQUIPMENT IDENTIFICATION:					
7. SUBSYSTEM		NAME		PART NUMBER	S/N
8. UNIT					
9. <input checked="" type="checkbox"/> ASSEMBLY <input type="checkbox"/> SUBASSEMBLY		50973		201	5B2C
10. <input type="checkbox"/> MODULE <input type="checkbox"/> MICAM <input type="checkbox"/> CARD					
11. OTHER					
12. TEST WHEN FAILURE WAS OBSERVED <input type="checkbox"/> DEVELOPMENT <input type="checkbox"/> IN-PROCESS		<input type="checkbox"/> QUALIFICATION <input type="checkbox"/> ACCEPTANCE	<input type="checkbox"/> INTEGRATION <input type="checkbox"/> SYSTEM	<input type="checkbox"/> LAUNCH OPERATIONS	
13. ENVIRONMENT WHEN FAILURE WAS OBSERVED <input type="checkbox"/> AMBIENT <input type="checkbox"/> EMC/RF		<input type="checkbox"/> RADIATION <input type="checkbox"/> VIBRATION	<input type="checkbox"/> TEMP AXIS FOR	<input type="checkbox"/> THERMAL VAC MRS AT <input type="checkbox"/> OTHER	
14. DESCRIPTION OF FAILURE Electrical shorts between FFW cables and radiative cooler structure observed during trial fire of CFDA in cooler.					
15. TEST PROCEDURE		PARA	16. ORIGINATOR D. J. ...	ORG 22-31	DATE 2-26-82
17. CONTINUATION SHEET USED					
18. VERIFICATION AND FAILURE ANALYSIS Practically, check wiring schematics did not show any electrical components.					
19. FAILED ITEM NAME AND PART NUMBER					
20. FOLLOW-UP REWORK/RETEST REQUIRED <input type="checkbox"/> REWORK/RETEST NOT REQUIRED BECAUSE Rework per 504173 and test for electrical insulation.					
21. AUTHORIZATION D. J. ...					
22. REWORK/RETEST ACTION TAKEN Reworked to 504173 and electrical insulation tested good.					
23. CONTINUATION SHEET USED					
24. CONTINUATION SHEET USED					
25. CONTINUATION SHEET USED					
26. CONTINUATION SHEET USED					
27. CONTINUATION SHEET USED					
28. CONTINUATION SHEET USED					
29. CONTINUATION SHEET USED					
30. CONTINUATION SHEET USED					
31. CONTINUATION SHEET USED					
32. CONTINUATION SHEET USED					
33. CONTINUATION SHEET USED					
34. CONTINUATION SHEET USED					
35. CONTINUATION SHEET USED					
36. CONTINUATION SHEET USED					
37. CONTINUATION SHEET USED					
38. CONTINUATION SHEET USED					
39. CONTINUATION SHEET USED					
40. CONTINUATION SHEET USED					
41. CONTINUATION SHEET USED					
42. CONTINUATION SHEET USED					
43. CONTINUATION SHEET USED					
44. CONTINUATION SHEET USED					
45. CONTINUATION SHEET USED					
46. CONTINUATION SHEET USED					
47. CONTINUATION SHEET USED					
48. CONTINUATION SHEET USED					
49. CONTINUATION SHEET USED					
50. CONTINUATION SHEET USED					
51. CONTINUATION SHEET USED					
52. CONTINUATION SHEET USED					
53. CONTINUATION SHEET USED					
54. CONTINUATION SHEET USED					
55. CONTINUATION SHEET USED					
56. CONTINUATION SHEET USED					
57. CONTINUATION SHEET USED					
58. CONTINUATION SHEET USED					
59. CONTINUATION SHEET USED					
60. CONTINUATION SHEET USED					
61. CONTINUATION SHEET USED					
62. CONTINUATION SHEET USED					
63. CONTINUATION SHEET USED					
64. CONTINUATION SHEET USED					
65. CONTINUATION SHEET USED					
66. CONTINUATION SHEET USED					
67. CONTINUATION SHEET USED					
68. CONTINUATION SHEET USED					
69. CONTINUATION SHEET USED					
70. CONTINUATION SHEET USED					
71. CONTINUATION SHEET USED					
72. CONTINUATION SHEET USED					
73. CONTINUATION SHEET USED					
74. CONTINUATION SHEET USED					
75. CONTINUATION SHEET USED					
76. CONTINUATION SHEET USED					
77. CONTINUATION SHEET USED					
78. CONTINUATION SHEET USED					
79. CONTINUATION SHEET USED					
80. CONTINUATION SHEET USED					
81. CONTINUATION SHEET USED					
82. CONTINUATION SHEET USED					
83. CONTINUATION SHEET USED					
84. CONTINUATION SHEET USED					
85. CONTINUATION SHEET USED					
86. CONTINUATION SHEET USED					
87. CONTINUATION SHEET USED					
88. CONTINUATION SHEET USED					
89. CONTINUATION SHEET USED					
90. CONTINUATION SHEET USED					
91. CONTINUATION SHEET USED					
92. CONTINUATION SHEET USED					
93. CONTINUATION SHEET USED					
94. CONTINUATION SHEET USED					
95. CONTINUATION SHEET USED					
96. CONTINUATION SHEET USED					
97. CONTINUATION SHEET USED					
98. CONTINUATION SHEET USED					
99. CONTINUATION SHEET USED					
100. CONTINUATION SHEET USED					

HUGHESHUGHES AIRCRAFT COMPANY
SPACE AND COMMUNICATIONS GROUP
EL SEGUNDO, CALIFORNIAAHR SUPP#5-50973
CP#245SPACE AND COMMUNICATIONS GROUP
FAILURE REPORTORIGINAL PAGE IS
OF POOR QUALITY**S 8438**

ORIGINATOR	1. PROGRAM NAME AND NUMBER TM VOL PL 1162	2. GLA	3. MODEL FLIGHT	4. TIME OBSERVED 3:30 PM	5. DATE OBSERVED MO 6 DA 24 YR 81
	6. HARDWARE LEVEL WHEN FAILURE WAS OBSERVED <input type="checkbox"/> SPACECRAFT <input type="checkbox"/> SYSTEM	<input type="checkbox"/> SUBSYSTEM <input type="checkbox"/> UNIT	<input checked="" type="checkbox"/> ASSEMBLY <input type="checkbox"/> SUBASSEMBLY	<input type="checkbox"/> MODULE <input type="checkbox"/> MICAM	<input type="checkbox"/> CARD <input type="checkbox"/> PART
	EQUIPMENT IDENTIFICATION:				
	7. SUBSYSTEM				
	8. UNIT				
	9. <input checked="" type="checkbox"/> ASSEMBLY <input type="checkbox"/> SUBASSEMBLY CAD FPA ASSY				
	10. <input type="checkbox"/> MODULE <input type="checkbox"/> MICAM <input type="checkbox"/> CARD				
	11. OTHER				
	12. TEST WHEN FAILURE WAS OBSERVED <input type="checkbox"/> DEVELOPMENT <input type="checkbox"/> QUALIFICATION <input type="checkbox"/> INTEGRATION <input type="checkbox"/> LAUNCH OPERATIONS <input checked="" type="checkbox"/> IN-PROCESS <input type="checkbox"/> ACCEPTANCE <input type="checkbox"/> SYSTEM				
	13. ENVIRONMENT WHEN FAILURE WAS OBSERVED <input type="checkbox"/> AMBIENT <input type="checkbox"/> RADIATION <input checked="" type="checkbox"/> TEMP 91.5 °K <input type="checkbox"/> THERMAL VAC <input type="checkbox"/> HRS AT <input type="checkbox"/> OTHER <input type="checkbox"/> EMC/RF <input type="checkbox"/> VIBRATION <input type="checkbox"/> AXIS FOR <input type="checkbox"/> MIN TYPE				
14. DESCRIPTION OF FAILURE BAND 5: CH. 310 & 12 EXHIBIT EXCESSIVELY HIGH OUTPUT DURING INJECTED SIGNAL TEST, INDICATIVE OF DETACHED DETECTOR ELEMENTS.					
ENGINEERING EVALUATION	15. TEST PROCEDURE 16192				
	16. VERIFICATION AND FAILURE ANALYSIS Spag was accidentally dropped on the Band 5 detector while mounting the Band 7 detector on the FPA. The tube leads were damaged during cleanup of the spag; resulting in open traces. No other components were damaged or a failure.				
	17. CONTINUATION SHEET USED <input type="checkbox"/>				
	18. FOLLOWING REWORK/RETEST REQUIRED <input type="checkbox"/>				
	19. REWORK/RETEST NOT REQUIRED BECAUSE Repair and test per MRCCO 393216R				
	20. AUTHORIZATION [Signature] 1122 DATE				
	21. REWORK/RETEST ACTION TAKEN Repaired and test per MRCCO 393216R				
	22. CONTINUATION SHEET USED <input type="checkbox"/>				
	23. LIST ALL PARTS REPLACED				
	24. REWORK BY ORG DATE				
MANUFACTURING AND TEST	25. RETESTED BY ORG DATE				
	26. CAUSE AND CORRECTIVE ACTION Spag was accidentally dropped on the Band 5 detector while mounting the Band 7 detector on the FPA. The tube leads were damaged during cleanup of the spag; resulting in open traces. The open traces were repaired using conductive spag per MRCCO 393216R. Repair 07/02-81 authorized repair.				
	27. CONTINUATION SHEET USED <input type="checkbox"/>				
	28. DOCUMENT IMPLEMENTING CORRECTIVE ACTION				
	29. BASIC CAUSE OF VERIFIED FAILURE <input type="checkbox"/> DESIGN <input type="checkbox"/> ENVIRONMENTAL <input type="checkbox"/> DEFECTIVE PARTS				
	30. TEST EQUIPMENT <input type="checkbox"/> TEST PROCEDURE <input type="checkbox"/> TEST SET-UP				
	31. MFG. PROCEDURE <input type="checkbox"/> ASSY/FAB ERROR <input type="checkbox"/> WORKMANSHIP				
	32. WRING ERROR <input type="checkbox"/> ROUGH HANDLING <input type="checkbox"/> WEAR-OUT				
	33. UNKNOWN <input type="checkbox"/> DEFECT CODE				
	34. FAILURE TYPE <input type="checkbox"/> PRIMARY <input type="checkbox"/> INDUCED				
ENGINEERING/RELIABILITY	35. REPAIRABLE ENGINEER [Signature] 1122 DATE				
	36. SPACECRAFT SYSTEMS ENGINEER [Signature] 2261 DATE				
	37. RELIABILITY [Signature] 314 DATE				
	38. CUSTOMER OR SUPPLIER [Signature] 2261 DATE				
	39. FBG CLOSURE [Signature] 8/6/81				
	40. CONTINUATION SHEET USED <input type="checkbox"/>				
	41. BASIC CAUSE OF VERIFIED FAILURE <input type="checkbox"/> DESIGN <input type="checkbox"/> ENVIRONMENTAL <input type="checkbox"/> DEFECTIVE PARTS				
	42. TEST EQUIPMENT <input type="checkbox"/> TEST PROCEDURE <input type="checkbox"/> TEST SET-UP				
	43. MFG. PROCEDURE <input type="checkbox"/> ASSY/FAB ERROR <input type="checkbox"/> WORKMANSHIP				
	44. WRING ERROR <input type="checkbox"/> ROUGH HANDLING <input type="checkbox"/> WEAR-OUT				
45. UNKNOWN <input type="checkbox"/> DEFECT CODE					

ORIGINAL PAGE IS
OF POOR QUALITY

Program Instruction 010

58438

REQUEST FOR DEVIATION/WAIVER

(SEE MIL-STD-460 ON 401 FOR INSTRUCTIONS)

DATE PREPARED

PROGRAMMING ACTIVITY NO.

1. ORIGINATOR NAME AND ADDRESS David M. Randall SBRC, 75 Curumar Dr. Colaca, Ca. 97117				2. <input type="checkbox"/> DEVIATION <input checked="" type="checkbox"/> WAIVER			
				3. <input checked="" type="checkbox"/> MINOR <input type="checkbox"/> MAJOR <input type="checkbox"/> CRITICAL			
4. DESIGNATION FOR DEVIATION/WAIVER				5. BASE LINE AFFECTED			
6. MODEL/TYPE P	7. MFR. CODE 11323	8. SYS. DESIG.	9. REVISION NO.	10. PLANT TIGER	11. ALSO CATED	12. PRODU UCT	13. OTHER SYSTEM COMPO NENTS AFFECTED
14. SPECIFICATIONS AFFECTED-TEST PLAN				15. DRAWINGS AFFECTED			
16. SYSTEM				17. MFR. CODE 11323			
18. ITEM				19. NUMBER 50973			
20. TEST PLAN				21. REV. B			
22. TITLE OF DEVIATION/WAIVER Conductive Epoxy Repair of InSb Detector Traces				23. CONTRACT NO. & LINE ITEM NAS 5-24200			
24. CONTINUATION TYPE-REPAIR/REWORK Radiometer				25. CLASSIFICATION OF DEFECT			
26. DEFECT NO. 11				27. DEFECT CLASSIFICATION <input checked="" type="checkbox"/> MINOR <input type="checkbox"/> MAJOR <input type="checkbox"/> CRITICAL			
28. DEFECT NO. ON THIS DESIGN 50973				29. DEFECT NO. ON THIS DESIGN 201			
30. DEFECT NO. ON THIS DESIGN 1				31. DEFECT NO. ON THIS DESIGN 1			
32. DEFECT NO. ON THIS DESIGN 1				33. DEFECT NO. ON THIS DESIGN 1			
34. DEFECT NO. ON THIS DESIGN 1				35. DEFECT NO. ON THIS DESIGN 1			
36. DEFECT NO. ON THIS DESIGN 1				37. DEFECT NO. ON THIS DESIGN 1			
38. DEFECT NO. ON THIS DESIGN 1				39. DEFECT NO. ON THIS DESIGN 1			
39. DEFECT NO. ON THIS DESIGN 1				40. DEFECT NO. ON THIS DESIGN 1			
40. DEFECT NO. ON THIS DESIGN 1				41. DEFECT NO. ON THIS DESIGN 1			
41. DEFECT NO. ON THIS DESIGN 1				42. DEFECT NO. ON THIS DESIGN 1			
42. DEFECT NO. ON THIS DESIGN 1				43. DEFECT NO. ON THIS DESIGN 1			
43. DEFECT NO. ON THIS DESIGN 1				44. DEFECT NO. ON THIS DESIGN 1			
44. DEFECT NO. ON THIS DESIGN 1				45. DEFECT NO. ON THIS DESIGN 1			
45. DEFECT NO. ON THIS DESIGN 1				46. DEFECT NO. ON THIS DESIGN 1			
46. DEFECT NO. ON THIS DESIGN 1				47. DEFECT NO. ON THIS DESIGN 1			
47. DEFECT NO. ON THIS DESIGN 1				48. DEFECT NO. ON THIS DESIGN 1			
48. DEFECT NO. ON THIS DESIGN 1				49. DEFECT NO. ON THIS DESIGN 1			
49. DEFECT NO. ON THIS DESIGN 1				50. DEFECT NO. ON THIS DESIGN 1			
50. DEFECT NO. ON THIS DESIGN 1				51. DEFECT NO. ON THIS DESIGN 1			
51. DEFECT NO. ON THIS DESIGN 1				52. DEFECT NO. ON THIS DESIGN 1			
52. DEFECT NO. ON THIS DESIGN 1				53. DEFECT NO. ON THIS DESIGN 1			
53. DEFECT NO. ON THIS DESIGN 1				54. DEFECT NO. ON THIS DESIGN 1			
54. DEFECT NO. ON THIS DESIGN 1				55. DEFECT NO. ON THIS DESIGN 1			
55. DEFECT NO. ON THIS DESIGN 1				56. DEFECT NO. ON THIS DESIGN 1			
56. DEFECT NO. ON THIS DESIGN 1				57. DEFECT NO. ON THIS DESIGN 1			
57. DEFECT NO. ON THIS DESIGN 1				58. DEFECT NO. ON THIS DESIGN 1			
58. DEFECT NO. ON THIS DESIGN 1				59. DEFECT NO. ON THIS DESIGN 1			
59. DEFECT NO. ON THIS DESIGN 1				60. DEFECT NO. ON THIS DESIGN 1			
60. DEFECT NO. ON THIS DESIGN 1				61. DEFECT NO. ON THIS DESIGN 1			
61. DEFECT NO. ON THIS DESIGN 1				62. DEFECT NO. ON THIS DESIGN 1			
62. DEFECT NO. ON THIS DESIGN 1				63. DEFECT NO. ON THIS DESIGN 1			
63. DEFECT NO. ON THIS DESIGN 1				64. DEFECT NO. ON THIS DESIGN 1			
64. DEFECT NO. ON THIS DESIGN 1				65. DEFECT NO. ON THIS DESIGN 1			
65. DEFECT NO. ON THIS DESIGN 1				66. DEFECT NO. ON THIS DESIGN 1			
66. DEFECT NO. ON THIS DESIGN 1				67. DEFECT NO. ON THIS DESIGN 1			
67. DEFECT NO. ON THIS DESIGN 1				68. DEFECT NO. ON THIS DESIGN 1			
68. DEFECT NO. ON THIS DESIGN 1				69. DEFECT NO. ON THIS DESIGN 1			
69. DEFECT NO. ON THIS DESIGN 1				70. DEFECT NO. ON THIS DESIGN 1			
70. DEFECT NO. ON THIS DESIGN 1				71. DEFECT NO. ON THIS DESIGN 1			
71. DEFECT NO. ON THIS DESIGN 1				72. DEFECT NO. ON THIS DESIGN 1			
72. DEFECT NO. ON THIS DESIGN 1				73. DEFECT NO. ON THIS DESIGN 1			
73. DEFECT NO. ON THIS DESIGN 1				74. DEFECT NO. ON THIS DESIGN 1			
74. DEFECT NO. ON THIS DESIGN 1				75. DEFECT NO. ON THIS DESIGN 1			
75. DEFECT NO. ON THIS DESIGN 1				76. DEFECT NO. ON THIS DESIGN 1			
76. DEFECT NO. ON THIS DESIGN 1				77. DEFECT NO. ON THIS DESIGN 1			
77. DEFECT NO. ON THIS DESIGN 1				78. DEFECT NO. ON THIS DESIGN 1			
78. DEFECT NO. ON THIS DESIGN 1				79. DEFECT NO. ON THIS DESIGN 1			
79. DEFECT NO. ON THIS DESIGN 1				80. DEFECT NO. ON THIS DESIGN 1			
80. DEFECT NO. ON THIS DESIGN 1				81. DEFECT NO. ON THIS DESIGN 1			
81. DEFECT NO. ON THIS DESIGN 1				82. DEFECT NO. ON THIS DESIGN 1			
82. DEFECT NO. ON THIS DESIGN 1				83. DEFECT NO. ON THIS DESIGN 1			
83. DEFECT NO. ON THIS DESIGN 1				84. DEFECT NO. ON THIS DESIGN 1			
84. DEFECT NO. ON THIS DESIGN 1				85. DEFECT NO. ON THIS DESIGN 1			
85. DEFECT NO. ON THIS DESIGN 1				86. DEFECT NO. ON THIS DESIGN 1			
86. DEFECT NO. ON THIS DESIGN 1				87. DEFECT NO. ON THIS DESIGN 1			
87. DEFECT NO. ON THIS DESIGN 1				88. DEFECT NO. ON THIS DESIGN 1			
88. DEFECT NO. ON THIS DESIGN 1				89. DEFECT NO. ON THIS DESIGN 1			
89. DEFECT NO. ON THIS DESIGN 1				90. DEFECT NO. ON THIS DESIGN 1			
90. DEFECT NO. ON THIS DESIGN 1				91. DEFECT NO. ON THIS DESIGN 1			
91. DEFECT NO. ON THIS DESIGN 1				92. DEFECT NO. ON THIS DESIGN 1			
92. DEFECT NO. ON THIS DESIGN 1				93. DEFECT NO. ON THIS DESIGN 1			
93. DEFECT NO. ON THIS DESIGN 1				94. DEFECT NO. ON THIS DESIGN 1			
94. DEFECT NO. ON THIS DESIGN 1				95. DEFECT NO. ON THIS DESIGN 1			
95. DEFECT NO. ON THIS DESIGN 1				96. DEFECT NO. ON THIS DESIGN 1			
96. DEFECT NO. ON THIS DESIGN 1				97. DEFECT NO. ON THIS DESIGN 1			
97. DEFECT NO. ON THIS DESIGN 1				98. DEFECT NO. ON THIS DESIGN 1			
98. DEFECT NO. ON THIS DESIGN 1				99. DEFECT NO. ON THIS DESIGN 1			
99. DEFECT NO. ON THIS DESIGN 1				100. DEFECT NO. ON THIS DESIGN 1			

11. DESCRIPTION OF DEVIATION/WAIVER

2216 Epoxy was accidentally dropped onto the Band 5 detector while mounting the Band 7 detector and subsequent cleaning caused open traces on Channels 10 & 12. Silver epoxy was successfully used to repair these channels. Since it is impossible to determine if any damage was incurred on other channels during the cleaning operation that may result in open traces in the future, this waiver requests permission to use silver epoxy to ensure the continuity of all the Band 5 detector traces.

This repair is ideal for InSb detectors since the junction impedance is high (80 megohms) any series impedance caused by use of silver epoxy is easily tolerated. Series impedances of 10K ohms would not have any effect on performance and impedances using silver epoxy will be less than 10 ohms. See attachment A for explanation.

12. REPAIR FOR DEVIATION/WAIVER (Conductive epoxy will be applied to Band 7 detector traces also to further assurance that continuity will be maintained across thick SiO₂.)

The FPA has had several detector changes and the risk of losing the entire FPA by changing this detector is approximately 50%. If the FPA were lost the cost to the program would be in excess of \$500,000.00 and the delivery schedule would be set back 6 months.

13. SIGNATURE OF ORIGINATOR David M. Randall		14. SIGNATURE OF APPROVER J. L. Enright	
15. TITLE OF ORIGINATOR SYS ENGR		16. TITLE OF APPROVER Major - System Engineering Major/Critical - Program Manager	
17. PRODUCTION EFFECTIVITY OF DESIGN NUMBER 003		18. APPROVAL/DISAPPROVAL <input checked="" type="checkbox"/> APPROVED <input type="checkbox"/> DISAPPROVED	
19. SIGNATURE OF APPROVER J. L. Enright		20. SIGNATURE OF APPROVER J. L. Enright	
21. DATE OF APPROVAL 1/24/81		22. DATE OF APPROVAL 1/24/81	
23. DOCUMENT ACTIVITY LANDSAT-D INSTRUMENT M.P.		24. DOCUMENT ACTIVITY LANDSAT-D INSTRUMENT M.P.	
25. DD FORM 1694		26. DD FORM 1694	

HUGHESHUGHES AIRCRAFT COMPANY
SPACE AND COMMUNICATIONS GROUP
EL SEGUNDO, CALIFORNIASPACE AND COMMUNICATIONS GROUP
FAILURE REPORTORIGINAL PAGE IS
OF POOR QUALITY
S 8443

Supp 8 opn 2515/RS NEMR 360075 \$ MRCO STA 720

1. PROGRAM NAME AND NUMBER VO11 T.M.		2. GLA	3. MODEL FLIGHT	4. TIME OBSERVED 9:00 P.M.	5. DATE OBSERVED MO NOV, DA 23, YR 1981
6. HARDWARE LEVEL WHEN FAILURE WAS OBSERVED <input type="checkbox"/> SPACECRAFT <input type="checkbox"/> SYSTEM <input type="checkbox"/> SUBSYSTEM <input type="checkbox"/> UNIT <input checked="" type="checkbox"/> ASSEMBLY <input type="checkbox"/> SUBASSEMBLY <input type="checkbox"/> MODULE <input type="checkbox"/> MICAM <input type="checkbox"/> CARD <input type="checkbox"/> PART					
EQUIPMENT IDENTIFICATION:					
7. SUBSYSTEM		NAME		PART NUMBER	S/N
8. UNIT					
9. <input checked="" type="checkbox"/> ASSEMBLY <input type="checkbox"/> SUBASSEMBLY		CFPA		50973	201
10. <input type="checkbox"/> MODULE <input type="checkbox"/> MICAM <input type="checkbox"/> CARD					SBRC
11. OTHER					
12. TEST WHEN FAILURE WAS OBSERVED <input type="checkbox"/> DEVELOPMENT <input checked="" type="checkbox"/> IN-PROCESS <input type="checkbox"/> QUALIFICATION <input type="checkbox"/> ACCEPTANCE <input type="checkbox"/> INTEGRATION <input type="checkbox"/> SYSTEM <input type="checkbox"/> LAUNCH OPERATIONS					
13. ENVIRONMENT WHEN FAILURE WAS OBSERVED <input type="checkbox"/> AMBIENT <input type="checkbox"/> EMC/RFI <input type="checkbox"/> RADIATION <input type="checkbox"/> VIBRATION <input checked="" type="checkbox"/> TEMP 92.2 <input type="checkbox"/> THERMAL VAC <input type="checkbox"/> HRS AT <input type="checkbox"/> OTHER					
14. DESCRIPTION OF FAILURE		BAND 5 CH. 12 10MHz RESPONSE IS 19.4mV OPEN DET. BAND 7 CH. 2, 4, 6, RESPONSE IS 19.4mV OPEN DETECTORS " " CH. 1, 5, 8 NO RESPONSE TO SHORTED DETECTORS			
15. TEST PROCEDURE		16. ORIGINATOR	17. CONTINUATION SHEET USED		
16192		4.6 M.C. DAVISON, JR.	2213	4/24/81	
18. VERIFICATION AND FAILURE ANALYSIS NO OVERSTRESS OCCURRED. UNIT WAS IN NORMAL TEST CONFIGURATION. OUTPUTS ARE FED INTO VERY HIGH IMPEDANCE CIRCUIT THAT LIMITS CURRENT TO FOLLOWING CIRCUITRY					
19. FOLLOWING REWORK/RETEST REQUIRED <input type="checkbox"/> REWORK/RETEST NOT REQUIRED BECAUSE Rework to replace assembly per Supplement #10					
20. AUTHORIZATION [Signature] ORG 212 DATE 1/24/81					
21. REWORK/RETEST ACTION TAKEN Amplifier replaced per measurement #10. Bands 5 tested good. Band 7 failed. Rf 72 8230.					
22. CONTINUATION SHEET USED <input checked="" type="checkbox"/>					
23. LIST ALL PARTS REPLACED					
PART NUMBER	CXT SYM	PART LOT NUMBER	DATE CODE	MANUFACTURER	PROBABLE DEFECT
Band 5 50958		906-3316A-11-101			
Band 7 50958		906-3316A-13-2			
24. Rework BY ORG DATE 25. RETESTED BY ORG DATE					
26. CONTINUATION SHEET USED <input type="checkbox"/>					
27. CAUSE AND CORRECTIVE ACTION Band 5 Ch12 was due to a failure of Hg epoxy rework, done per MRCO 393239. Rf 72 8226. Band 7 failure was confirmed to be due to discharge of electric current. Ch 24 & 6 had TiAu traces blown open. The wirebond pull tester was found to be defective and allowing 4V to be applied to detector. Pull tester was replaced.					
28. FRB CLOSURE [Signature] 2/22/82					
29. BASIC CAUSE OF VERIFIED FAILURE <input type="checkbox"/> DESIGN <input type="checkbox"/> ENVIRONMENTAL <input type="checkbox"/> DEFECTIVE PARTS <input checked="" type="checkbox"/> TEST EQUIPMENT <input type="checkbox"/> TEST PROCEDURE <input type="checkbox"/> TEST SET-UP <input type="checkbox"/> MFG. PROCEDURE <input type="checkbox"/> ASSY/FAB ERROR <input type="checkbox"/> WORKMANSHIP <input type="checkbox"/> WIRING ERROR <input type="checkbox"/> ROUGH HANDLING <input type="checkbox"/> WEAR-OUT					
30. FAILURE TYPE <input type="checkbox"/> UNKNOWN <input type="checkbox"/> NO FAILURE <input type="checkbox"/> CRITICAL <input checked="" type="checkbox"/> MAJOR <input type="checkbox"/> MINOR <input type="checkbox"/> SAFETY					
31. RESPONSIBLE ENGINEER [Signature] ORG 212 DATE 2/10/82					
32. RELIABILITY [Signature] ORG 51 41 DATE 2-18-82					
33. FAILURE CLASSIFICATION [Signature] ORG 22-41 DATE 2/22/82					
34. CUSTOMER OR SUPPLIER [Signature] ORG 51 41 DATE 2/15/82					

HUGHES

HUGHES AIRCRAFT COMPANY
SPACE AND COMMUNICATIONS GROUP
EL SEGUNDO, CALIFORNIA

SPACE AND COMMUNICATIONS GROUP

FAILURE REPORT
CONTINUATION SHEET

FR SERIAL NO.

58443

CONTINUATION SHEET LETTER

A

ADDITIONAL FR
CONTINUATION
SHEET(S) USED

*LABEL FIRST CONTINUATION SHEET USED 'A', SECOND '3', AND SO ON

IDENTIFY ENTRIES BY REFERENCING FR BLOCK NUMBER IN COLUMN, DATE EACH ENTRY.

30 SEM PHOTOS SHOW CH 2, 4, & 6 HAVE OPENS. THESE
OPENS HAVE A METAL SPLATTER ADJACENT TO THE
SPACE, INDICATING AN OVERHEATING (PROBABLY DUE TO
OVERVOLTAGE) AND FLOW OF THE DISPLACED METAL FROM
THE CONDUCTIVE TRACE. IT IS ASSUMED THAT CHANNEL
1, 5, & 8 WERE SHORTED BY THE SAME MECHANISM, BUT
THAT THE DURATION OF THE APPLIED POWER, OR ITS
AMPLITUDE WERE NOT SUFFICIENT TO CAUSE AN OPEN
IN THE LEADS. BANDS 5 & 7 DETECTORS HAVE BEEN
FORWARDED TO GSEC FOR THEIR USE.

ORIGINAL PAGE IS
OF POOR QUALITY

ORIGINAL PAGE IS
OF POOR QUALITY

2.7

SECTION ~~2.7~~
RADIATIVE COOLER

ORIGINAL PAGE IS
OF POOR QUALITY

Section 2.7.1

Radiative Cooler

Performance Data

Radiative cooler performance data is included in
Appendix F (Vol. IV, Part F)

2.7.2

ORIGINAL PAGE IS
OF POOR QUALITY

2.7.2

Acceptance Data

2.7.2.1

ORIGINAL PAGE IS
OF POOR QUALITY

2.7.2.1

Configuration Lists

C-3

AS-BUILT CONFIGURATION LIST

Sheet 1 of 3

P/N 51200 S/N 003

COOLER ASSY, RADIATIVE (A3A1)

IND LVL	PART NO.	NOMENCLATURE	CURRENT REVISION	ACCEPT. REVISION	AS-BUILT REVISION	SERIAL NUMBER
---------	----------	--------------	------------------	------------------	-------------------	---------------

3	51200	COOLER ASSY, RADIATIVE (A3A1)	E 3922A 4201A 4216A 4269A SB-W032 W144 W147 W149 W151 A	E 3922A 4201A 4216A 4269A SB-W032 W144 W147 W149 W151 A	E 3922A 4201A 4216A 4269A SB-W032 W144 W147 W149 W151 A	003
4	16174	INSP, CLEANING, & HAND RAD COOLER COMPONENTS & SUB ASSY - REQ. FOR				
4	16181	INSULATION, ALUMINIZED MYLAR APPLICATION OF	A	A	A	
4	16183	BONDING, THERMALLY CONDUCTIVE, RAD COOLER, PROCESS	A *(N)7522	A	A	
4	16188	THERMAL VACUUM ACCEPTANCE TEST-RAD COOLER PROCEDURE	B	B	B	
4	16189	WORKMANSHIP VIBRATION	A 4152A	A 4152A	A 4152A	
4	16469	CRIMPING 922426 CONTACTS	A	A	A	

ORIGINAL PAGE IS
OF POOR QUALITY

*N = Non-Mandatory

Sheet 2 of 3
P/N 51200
S/N 003

IND LVL	PART NO.	NOMENCLATURE	CURRENT REVISION	ACCEPT. REVISION	AS-BUILT REVISION	SERIAL NUMBER
4	50973	CFP/COOLER CABLE	B 2870A 3895A 4173A SB-D004 W102-R1 W109 W111 W134 W135	B 2870A 3895A 4173A SB-D004 W102-R1 W109 W111 W134 W135	B 2870A 3895A 4173A SB-D004 W102-R1 W109 W111 W134 W135	201
4	51167	COVER ASSY-COLD STAGE	A	A	A	301
4	51168	COVER ASSY, AMBIENT	A	A	A	301
4	51169	HOUSING ASSY, COLD STAGE	C 3921A 3926A	C 3921A 3926A	C 3921A 3926A	301
4	51208	COVER ASSY, INTERM STAGE	A	A	A	301
4	51210	DISC BARRIER	B	B	B	
4	51211	CLAMP, BARRIER DISC	C	C	C	
4	51310	STRUCTURE ASSY	B 2904A 3970A	B 2904A 3970A	B 2904A 3970A	301
4	51486	PLATE, APERTURE	D	D	D	

ORIGINAL PAGE IS
OF POOR QUALITY

Sheet 3 of 3
P/N 51200
S/N 003

THD LVL	PART NO.	NOMENCLATURE	CURRENT REVISION	ACCEPY. REVISION	AS-BUILT REVISION	SERIAL NUMBER
4	51488-1	STRIP, COVER	B	B	B	
4	51488-2	STRIP, COVER	B	B	B	
4	51491	WASHER, FLAT	A	A	A	
4	52709	BLK ASSY, THERMISTOR	B	B	B	301 & 302
4	52711	BLK ASSY, THERMISTOR	B	B	B	301 & 302

ORIGINAL PAGE IS
OF POOR QUALITY

W.D. Adams 4-26-82

W. D. Adams, Quality

R.A. Groves 4/26/82

R. A. Groves, CDMO

2.7.2.2

ORIGINAL PAGE IS
OF POOR QUALITY

Listing of Liens

RADIATIVE COOLER

P/N 51200

FLIGHT

ORIGINAL PAGE IS
OF POOR QUALITY

Failure Reports Number

<u>Open</u>	<u>Closed</u>
S8136	S8106 S8117 S8118 S8124 S8180 S8370

Deviation

Waivers

	W-144 W-147 W-149 W-151
--	----------------------------------

RADIATIVE COOLER

ORIGINAL PAGE IS
OF POOR QUALITY

P/N 51200

FLIGHT

PROTOFLIGHT

ENGINEER

Failure Report
No.

Failure Report
No.

Failure Report
No.

Open	Closed	Open	Closed	Open	Closed
S8136	S8106 S8117 S8118 S8124 S8180 S8370		F2670 F2689 F2704 F5186		F0531 F0523

ORIGINAL PAGE IS
OF POOR QUALITY

U. 124

Program Instruction 010

REQUEST FOR DEVIATION/WAIVER
(SEE MIL-STD-46 OR 48 FOR INSTRUCTIONS)

DATE PREPARED

23 March 1982

PROCURING ACTIVITY NO.

1. ORIGINATOR NAME AND ADDRESS

Santa Barbara Research Center
75 Coronar Drive, Goleta, CA 93117

2. ☐ DEVIATION ☒ WAIVER
3. ☒ MINOR ☐ MAJOR ☐ CRITICAL

4. DESIGNATION FOR DEVIATION/WAIVER

a. MODEL/TYPE Flight b. MFR. CODE 11323 c. SYS. DESIG. TM d. DEV/WAIVER NO. W-144

5. BASE LINE AFFECTED

☒ FUNCTIONAL ☐ ALLOCATED ☐ PRODUCT ☐ YES ☒ NO

6. OTHER SYSTEMS/CONFIGURATIONS ITEMS AFFECTED

7. SPECIFICATIONS AFFECTED-TEST PLAN

a. SYSTEM b. ITEM 11323 c. SPEC./DOC. NO. 16192 d. REV. E

8. DRAWINGS AFFECTED

9. TITLE OF DEVIATION/WAIVER

Deviation from radiative cooler test plan

10. CONTRACT NO. & LINE ITEM

NAS-5 2400

11. DESCRIPTION OF THE DEVIATION/WAIVER

Radiative cooler

12. CD NO. 13. SUBJECT NO. 14. DEFECT CLASSIFICATION
☒ MINOR ☐ MAJOR ☐ CRITICAL

15. NAME OF PART OR LARGEST ASSEMBLY AFFECTED

Radiative cooler

16. PART NO. OR TYPE DESIGNATION

51200-E

17. LOT NO.

N/A

18. QTY

1

19. REQUIRES DEVIATION/WAIVER

☐ YES ☒ NO

20. EFFECT ON COST/PRICE

none

21. EFFECT ON DELIVERY SCHEDULE

2 days

22. EFFECT ON INTEGRATED LOGISTIC SUPPORT, INTERFACE, ETC.

none

23. DESCRIPTION OF DEVIATION/WAIVER

The following deletions from the Rad Cooler bench test cooler tests following integration of the CFPA were made

1. Band 6 ohmic check per 16192 para. 4.5.
2. Band 6 blackbody acceptance tests per 16192 para. 4.17. Quartz halogen source used instead of blackbody.
3. Verification of CFPA/Rad Cooler thermal conductance per 16191 para 3.4.5 g thru m.

All the above tests will be conducted following vibration testing of the Rad Cooler per AHR without change.

24. REASON FOR DEVIATION/WAIVER

- 1, 2 Erroneous interpretation of E.O. 4152A.
3. Unnecessary duplication of test data.

25. PRODUCTION EFFECTIVITY BY SERIAL NUMBER

51065 SN 003 ONLY

26. SUBMITTING ACTIVITY AUTHORIZING SIGNATURE

[Signature]

3/23/82

Minor - System Engineer
Major/Critical - Program Manager

27. APPROVAL/DISAPPROVAL

☐ APPROVAL RECOMMENDED

☒ APPROVED

☐ DISAPPROVED

28. GOVERNMENT ACTIVITY

NASA GSEL

SIGNATURE

[Signature]

DATE

3/26/82

DD FORM 1694

Program Instruction 010

ORIGINAL PAGE IS
OF POOR QUALITY

REQUEST FOR DEVIATION/WAIVER
(SEE MIL-STD-460 OR -461 FOR INSTRUCTIONS)

DATE PREPARED

PROCESSING ACTIVITY NO.

1. ORIGINATOR NAME AND ADDRESS SANTA BARBARA RESEARCH CENTER 75 Coromar Drive, Goleta, CA 93117				2. <input type="checkbox"/> DEVIATION <input checked="" type="checkbox"/> WAIVER	
				3. <input checked="" type="checkbox"/> MINOR <input type="checkbox"/> MAJOR <input type="checkbox"/> CRITICAL	
4. DESIGNATION FOR DEVIATION/WAIVER					
a. MODEL/TYPE Flight 1	b. WFR CODE 11323	c. SYS. DESIG. TM	d. DEV/WAIVER NO. W147	5. BASE LINE AFFECTED <input checked="" type="checkbox"/> FUNCTIONAL <input type="checkbox"/> ALLOCATED <input type="checkbox"/> PRODUCT	
6. SPECIFICATIONS AFFECTED-TEST PLAN				7. OTHER SYSTEMS/CONFIGURATION ITEMS AFFECTED <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO	
8. SYSTEMS AFFECTED				9. DRAWINGS AFFECTED	
a. SYSTEM	b. WFR CODE	c. SPEC./DOC. NO.	d. SCR	e. WFR CODE	f. NUMBER
1. YES	11323	16188	Rev B		
10. TEST PLAN				11. CONTRACT NO. & LINE ITEM NAS-S 24200	
12. TITLE OF DEVIATION/WAIVER Deviation from radiative cooler test plan					
13. IDENTIFICATION TYPE AND RELATURE Radiative Cooler					
14. NAME OF PART OR LOGICALLY IDENTIFIED AFFECTED Radiative Cooler		15. PART NO. OR TYPE DESIGN 51200-E		16. LOT NO. N/A	
17. EFFECT ON COST/PRICE Reduce test effort by one day.		18. EFFECT ON DELIVERY SCHEDULE 1 day		19. DEFECT CLASSIFICATION <input checked="" type="checkbox"/> MINOR <input type="checkbox"/> MAJOR <input type="checkbox"/> CRITICAL	
20. EFFECT ON INTEGRATED LOGISTIC SUPPORT, INTERFACE, ETC. None					
21. DESCRIPTION OF DEVIATION/WAIVER Shorten thermal-vacuum chamber/space background simulator pre-test 60°C bakeout from 72 hours to 40 hours. (16188 para 4.2.4)					

22. REAS FOR DEVIATION/WAIVER

To reduce cost - high vacuum (3×10^{-6} Torr) achieved after 40 hour bakeout.

23. PRODUCTION EFFECTIVITY BY SERIAL NUMBER 51065 SN 003 ONLY		24. APPROVAL OF DEVIATION/WAIVER Minor - System Engineering Major/Critical - Program Manager	
25. APPROVAL OF DEVIATION/WAIVER APPROVAL RECOMMENDED		26. APPROVAL OF DEVIATION/WAIVER APPROVED	
27. APPROVAL OF DEVIATION/WAIVER DISAPPROVED		28. APPROVAL OF DEVIATION/WAIVER DISAPPROVED	
29. APPROVAL OF DEVIATION/WAIVER NACA CSEC		30. APPROVAL OF DEVIATION/WAIVER 3/26/82	
31. APPROVAL OF DEVIATION/WAIVER DD FORM 1694		32. APPROVAL OF DEVIATION/WAIVER 3/26/82	

Program Instruction 010

ORIGINAL PAGE IS
OF POOR QUALITY

REQUEST FOR DEVIATION/WAIVER
(SEE MIL-STD-469 OR MIL-PCB INSTRUCTIONS)

DATE PREPARED

PROCURING ACTIVITY NO. **H**

1. ORIGINATOR NAME AND ADDRESS Santa Barbara Research Center 75 Coromar Drive, Goleta, CA 93117				2. <input type="checkbox"/> DEVIATION <input checked="" type="checkbox"/> WAIVER	
4. DESIGNATION FOR DEVIATION/WAIVER				5. BASE LINE AFFECTED	
6. MODEL/TYPE Flight 1	8. MFR. CODE 11323	9. SYS. DESIG. TM	4. DEV/WAIVER NO. W149	<input checked="" type="checkbox"/> FUNC. TYPICAL <input type="checkbox"/> ALLO. CATED <input type="checkbox"/> PROD. UCT	6. OTHER SYSTEMS/COMP/IGL-RATION ITEMS AFFECTED <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO
7. SPECIFICATIONS AFFECTED-TEST PLAN				8. DRAWINGS AFFECTED	
MFR. CODE		SPEC./DOC. NO.		REV.	
6. SYSTEM		8. ITEM		51200	
6. TEST PLAN		8. TEST PLAN		E	
9. TITLE OF DEVIATION/WAIVER Waiver from radiative cooler circuit diagram.				10. CONTRACT NO. & LINE ITEM NAS 5-24200	

11. CONFIGURATION ITEM IDENTIFICATION Radiative Cooler		12. CD NO.		13. DEFECT NO.		14. DEFECT CLASSIFICATION <input type="checkbox"/> MINOR <input checked="" type="checkbox"/> MAJOR <input type="checkbox"/> CRITICAL	
15. NAME OF PART OR LATEST ASSEMBLY AFFECTED Radiative Cooler		16. PART NO. OR TYPE DESIGN 51200-E		17. LOT NO. N/A		18. QTY 1	
19. EFFECT ON COST/PRICE None		20. EFFECT ON DELIVERY SCHEDULE None if implemented		21. EFFECT ON INTEGRATED LOGISTIC SUPPORT, INTERFAC, ETC. None		22. EFFECT ON QUALITY ASSURANCE None	

23. DESCRIPTION OF DEVIATION/WAIVER
Use as-is the following circuit discrepancy:
Cooler intermediate stage platinum resistance temp sensor circuit at connector W3P4 pin 13 to pin 14 shows open, resulting in the loss of one lead in a redundant two-lead sensor hookup. P/N 51394 has a crack in the solder pad where it joins the trace lead. Will incorporate EO 4269A (spot bonding) to prevent propagation of crack. Redundant lead has adequate pad-to-solder connection to insure a reliable circuit.

24. NEED FOR DEVIATION/WAIVER
Risk of repair or replacement not warranted - redundant lead maintains circuit operational.

25. PRODUCTION EFFECTIVITY BY SERIAL NUMBER 51065 SN 003 ONLY		26. SUBMITTING ACTIVITY AUTHORIZING SIGNATURE <i>[Signature]</i> 4/16/82		27. APPROVAL/DISAPPROVAL <input checked="" type="checkbox"/> APPROVED <input type="checkbox"/> DISAPPROVED	
28. GOVERNMENT ACTIVITY LANDSAT-D PROJECT		29. SIGNATURE <i>[Signature]</i> 4/16/82		30. DATE 4-16-82	

DD FORM 1694

ORIGINAL PAGE IS
OF POOR QUALITY

REQUEST FOR DEVIATION/WAIVER
(SEE MIL-STD-460 OR 481 FOR INSTRUCTIONS)

DATE PREPARED

4/8/82

PROCURING ACTIVITY NO.

1. ORIGINATOR NAME AND ADDRESS Terry Cafferty SBRC, 75 Coronar Dr., Goleta, CA 93117				2. <input type="checkbox"/> DEVIATION <input checked="" type="checkbox"/> WAIVER	
3. <input checked="" type="checkbox"/> MINOR <input type="checkbox"/> MAJOR <input type="checkbox"/> CRITICAL				4. OTHER SYSTEMS/CONFIGURATION ITEMS AFFECTED	
5. DESIGNATION FOR DEVIATION/WAIVER				6. BASE LINE AFFECTED	
a. MODEL TYPE b. MFR. CODE c. SYS. DESIG. d. DEV/WAIVER NO. W-151				e. <input checked="" type="checkbox"/> FUNCTIONAL <input type="checkbox"/> ALLOCATED <input type="checkbox"/> PRODUCTION <input checked="" type="checkbox"/> YES <input type="checkbox"/> NO	
7. SPECIFICATIONS AFFECTED-TEST PLAN				8. DRAWINGS AFFECTED	
a. SYSTEM b. ITEM c. TEST PLAN 11323 16188 REV B				d. MFR. CODE e. SPEC./DOC. NO. f. SCH g. MFR. CODE h. NUMBER i. REV. j. MFR. NO.	
9. TITLE OF DEVIATION/WAIVER Permission to shorten temperature control tests				10. CONTRACT NO. & LINE ITEM NAS5-24200	
11. CONFIGURATION ITEM NUMBER/LAYER Radiative Cooler				12. CD NO. NA	
13. NAME OF PART OR LOGIST ASSEMBLY AFFECTED Radiative Cooler				14. DEFECT NO. NA	
15. PART NO. OR TYPE DESIGNATION 51200-E				16. DEFECT CLASSIFICATION <input type="checkbox"/> MINOR <input type="checkbox"/> MAJOR <input type="checkbox"/> CRITICAL	
17. LOT NO. NA				18. LOT QTY 1	
19. EFFECT ON COST/PRICE \$1500 if not approved				20. EFFECT ON DELIVERY SCHEDULE 8 Hours	
21. EFFECT ON INTEGRATED LOGISTIC SUPPORT, INTERFACE, ETC. None				22. REQUIREMENTS DEVIATION/WAIVER <input checked="" type="checkbox"/> YES <input type="checkbox"/> NO	
23. DESCRIPTION OF DEVIATION/WAIVER Long term stability tests are specified for the primary CSPA temperature control system at 90, 95, and 105K. The requirement is $\pm 0.1K$ over an 8 hour period at each setpoint. No temperature change is discernible in the control diode voltage readings at 95K, and only 0.04K change is observed for the 105K setpoint. It is requested that the 8-hour requirement be shortened to 4 hours. It is also requested that the outgas control test be shortened from 24 hours to the minimum time necessary to demonstrate outgas system functionality.					
24. NEED FOR DEVIATION/WAIVER This waiver would provide schedule relief which could be of value in troubleshooting noise and offset anomalies observed in several channels of Bards 5 and 7 during thermal/vacuum testing of the radiative cooler.					

25. PRODUCTION EFFECTIVITY BY SERIAL NUMBER 51065 SERNO 003 ONLY		26. SUBMITTING ACTIVITY AUTHORIZING SIGNATURE J. K. Engel 4/12/82		27. APPROVAL/DISAPPROVAL <input type="checkbox"/> APPROVAL RECOMMENDED <input checked="" type="checkbox"/> APPROVED <input type="checkbox"/> DISAPPROVED	
28. GOVERNMENT ACTIVITY 11525 5-5-82		29. SIGNATURE K. R. Britt		30. DATE 4-14-82	
DD FORM 1694					

HUGHESHUGHES AIRCRAFT COMPANY
SPACE AND COMMUNICATIONS GROUP
EL SEGUNDO, CALIFORNIA

SPACE AND COMMUNICATIONS GROUP

FAILURE REPORTORIGINAL PAGE IS
OF POOR QUALITY**S 8118**

ORIGINATOR	1. PROGRAM NAME AND NUMBER TM PL 1162		2. GLA		3. MODEL FLIGHT		4. TIME OBSERVED 9:00 AM		5. DATE OBSERVED MO 4 DA 27 YR 82	
	6. HARDWARE LEVEL WHEN FAILURE WAS OBSERVED <input type="checkbox"/> SPACECRAFT <input type="checkbox"/> SYSTEM		<input type="checkbox"/> SUBSYSTEM <input type="checkbox"/> UNIT		<input type="checkbox"/> ASSEMBLY <input type="checkbox"/> SUBASSEMBLY		<input type="checkbox"/> MODULE <input type="checkbox"/> MICAM		<input type="checkbox"/> CARD <input type="checkbox"/> PART	
	EQUIPMENT IDENTIFICATION:									
	7. SUBSYSTEM		NAME		PART NUMBER		C/N		MANUFACTURER	
	8. UNIT				51200		002		SBRC	
	9. <input type="checkbox"/> ASSEMBLY <input type="checkbox"/> SUBASSEMBLY									
	10. <input type="checkbox"/> MODULE <input type="checkbox"/> MICAM <input checked="" type="checkbox"/> CARD				50942		003		SBRC	
	11. OTHER									
	12. TEST WHEN FAILURE WAS OBSERVED <input type="checkbox"/> DEVELOPMENT <input type="checkbox"/> IN-PROCESS		<input type="checkbox"/> QUALIFICATION <input checked="" type="checkbox"/> ACCEPTANCE		<input type="checkbox"/> INTEGRATION <input type="checkbox"/> SYSTEM		<input type="checkbox"/> LAUNCH OPERATIONS			
	13. ENVIRONMENT WHEN FAILURE WAS OBSERVED <input type="checkbox"/> AMBIENT <input type="checkbox"/> EMC/RFI		<input type="checkbox"/> RADIATION <input type="checkbox"/> VIBRATION		<input type="checkbox"/> TEMP AXIS FOR		<input checked="" type="checkbox"/> THERMAL VAC HRS AT		<input type="checkbox"/> OTHER	
14. DESCRIPTION OF FAILURE Cold stage outgas temperature controller unable to achieve 20°C setpoint temp. while radiating to simulated space background.										
15. TEST PROCEDURE STR F010 16188										
16. VERIFICATION AND FAILURE ANALYSIS No failure - PRT temp. control sensor achieved 20°C set point, but CPGA diode was steady-state at -3°C, due to steady-state thermal gradient in cold stage structure, as verified by analysis.										
17. CONTINUATION SHEET USED <input type="checkbox"/>										
18. ORIGINATOR 12 Hughes										
19. FAILED ITEM NAME AND PART NUMBER None										
20. <input type="checkbox"/> FOLLOWING REWORK/RETEST REQUIRED <input checked="" type="checkbox"/> REWORK/RETEST NOT REQUIRED BECAUSE No failure, normal operation.										
21. AUTHORIZATION										
22. CONTINUATION SHEET USED <input type="checkbox"/>										
23. REWORK/RETEST ACTION TAKEN None										
24. QA Rework										
25. QA Retest										
26. LIST ALL PARTS REPLACED										
27. Rework by										
28. RETESTED BY										
29. CONTINUATION SHEET USED <input type="checkbox"/>										
30. CAUSE AND CORRECTIVE ACTION Test Engineer believed temp. gradient should be less than measured, however analysis shows temp. gradient to be real. (Refer to Continuation Sheet)										
31. FRG CLOSURE										
32. CONTINUATION SHEET USED <input type="checkbox"/>										
33. DOCUMENT IMPLEMENTING CORRECTIVE ACTION										
34. BASIC CAUSE OF VERIFIED FAILURE <input type="checkbox"/> DESIGN <input type="checkbox"/> ENVIRONMENTAL <input type="checkbox"/> DEFECTIVE PARTS										
35. TEST EQUIPMENT <input type="checkbox"/> TEST PROCEDURE <input type="checkbox"/> TEST SET-UP										
36. MFG. PROCEDURE <input type="checkbox"/> ASSY/FAB ERROR <input type="checkbox"/> WORKMANSHIP										
37. WIRING ERROR <input type="checkbox"/> ROUGH HANDLING <input type="checkbox"/> WEAR-OUT										
38. UNKNOWN										
39. DEFECT CODE										
40. FAILURE TYPE <input type="checkbox"/> PRIMARY <input type="checkbox"/> INDUCED										
41. UNKNOWN										
42. FAILURE CLASSIFICATION <input type="checkbox"/> CRITICAL <input type="checkbox"/> MAJOR <input type="checkbox"/> MINOR <input type="checkbox"/> SAFETY										
43. RESPONSIBLE ENGINEER [Signature]										
44. DATE 4-29-82										
45. SPACECRAFT SYSTEM ENGINEER [Signature]										
46. DATE 5/5/82										
47. CUSTOMER OR SUPPLIER [Signature]										
48. DATE 5/1/82										

HUGHES

HUGHES AIRCRAFT COMPANY
SPACE AND COMMUNICATIONS GROUP
EL SEGUNDO, CALIFORNIA

SPACE AND COMMUNICATIONS GROUP

FAILURE REPORT
CONTINUATION SHEET

FR SERIAL NO.

S8118

CONTINUATION SHEET LE TER

*LABEL FIRST CONTINUATION SHEET USED 'A', SECOND 'B', AND SO ON

IDENTIFY ENTRIES BY REFERENCING FR BLOCK NUMBER IN COLUMN. DATE EACH ENTRY.

ADDITIONAL FR
CONTINUATION
SHEET(S) USED



30 A thermal analysis of the Cold Stage Heater and the Cold Stage Radiator was performed. The results are as follows:

1. Heater and Sensor show the following heating dynamics: (Temp. vs. Time)

Time zero - Temperature of Cold Stage was ~~-156.2~~ -156.2°C
(start)

5700 seconds later - Temperature of Cold Stage was -20.3°C .

2. Cold Stage Radiator shows the following heating dynamics: (Temp. vs. time)

Time zero - Temperature of Cold Stage Radiator was -156.5°C

8700 seconds later - Temperature of Cold Stage Radiator was -4.9°C

Note: Cold Focal Plane is Heat-Sink to the Cold Stage Radiator and is essentially the same temperature as the radiator.

[Signature]

ORIGINAL PAGE IS
OF POOR QUALITY

SECTION 2.8
RADIATIVE COOLER DOOR ASSEMBLY

ORIGINAL PAGE IS
OF POOR QUALITY

2.8.1

2.8.1 Radiative Cooler Door Assembly

2.8.1.1

No performance data was taken at the subsystem level on this subsystem.

ORIGINAL PAGE IS
OF POOR QUALITY

2.8.2

2.3.2

Acceptance Data

2.8.2.1

ORIGINAL PAGE IS
OF POOR QUALITY

2.8.2.1

Configuration Lists

Configuration listing for the Radiative Cooler Door
is included in Section 2.7, Radiative Cooler

2.8.2.2

ORIGINAL PAGE IS
OF POOR QUALITY

Listing of Liens

RADIATIVE COOLER DOOR ASSEMBLY

ORIGINAL PAGE IS
OF POOR QUALITY

P/N 51740

FLIGHT

Failure Reports Number	
Open	Closed
	-
	S8143
	S8145
S8149	S8150

Deviation	Waivers
	W-156

ORIGINAL PAGE IS
OF POOR QUALITY

RADIATIVE COOLER DOOR ASSY.

P/N 51740

FLIGHT
Failure Report
No.

PROTOFLIGHT
Failure Report
No.

ENGINEER
Failure Report
No.

Open	Closed	Open	Closed	Open	Closed
S8149	S8143 S8145 S8150		F1741 F2694 F2766 F5177		F0507 F0512 F0517 F0518 F0523 F0528 F0594 F2753 S8098

HUGHESHUGHES AIRCRAFT COMPANY
SPACE AND COMMUNICATIONS GROUP
EL SEGUNDO, CALIFORNIA

SPACE AND COMMUNICATIONS GROUP

FAILURE REPORTORIGINAL PAGE IS
OF POOR QUALITY**S 8145**

1. PROGRAM NAME AND NUMBER TM 1162		2. GLA		3. MODEL FLIGHT 003		4. TIME OBSERVED 3 PM		5. DATE OBSERVED MO 6 DA 9 YR 82	
6. HARDWARE LEVEL WHEN FAILURE WAS OBSERVED <input type="checkbox"/> SPACECRAFT <input type="checkbox"/> SYSTEM		<input type="checkbox"/> SUBSYSTEM <input type="checkbox"/> UNIT		<input type="checkbox"/> ASSEMBLY <input checked="" type="checkbox"/> SUBASSEMBLY		<input type="checkbox"/> MODULE <input type="checkbox"/> MICAM		<input type="checkbox"/> CARD <input type="checkbox"/> PART	
EQUIPMENT IDENTIFICATION:									
7. SUBSYSTEM		NAME		PART NUMBER		S/N		MANUFACTURER	
8. UNIT									
9. <input type="checkbox"/> ASSEMBLY <input checked="" type="checkbox"/> SUBASSEMBLY		DOOR ASSY, INLER		51740		003		58RC	
10. <input type="checkbox"/> MODULE <input type="checkbox"/> MICAM <input type="checkbox"/> CARD									
11. OTHER									
12. TEST WHEN FAILURE WAS OBSERVED <input type="checkbox"/> DEVELOPMENT <input checked="" type="checkbox"/> IN-PROCESS		<input type="checkbox"/> QUALIFICATION <input type="checkbox"/> ACCEPTANCE		<input type="checkbox"/> INTEGRATION <input type="checkbox"/> SYSTEM		<input type="checkbox"/> LAUNCH OPERATIONS			
13. ENVIRONMENT WHEN FAILURE WAS OBSERVED <input checked="" type="checkbox"/> AMBIENT <input type="checkbox"/> EMC/RFI		<input type="checkbox"/> RADIATION <input type="checkbox"/> VIBRATION		<input type="checkbox"/> TEMP AXIS FOR		<input type="checkbox"/> THERMAL VAC MIN TYPE		HAS AT <input type="checkbox"/> OTHER	
14. DESCRIPTION OF FAILURE OUTGAS POSITION CANNOT BE ADJUSTED TO MEET PARA 3.2.4.4 SPEC 18012 REV C.									
15. TEST PROCEDURE 18012		P/PRA 3.2.4.4		16. ORIGINATOR D. DASCOMB		ORG		DATE 6/9/82	
17. CONTINUATION <input type="checkbox"/> SHEET USED									
18. VERIFICATION AND FAILURE ANALYSIS									
19. FAILED ITEM NAME AND PART NUMBER									
20. <input checked="" type="checkbox"/> FOLLOWING REWORK/RETEST REQUIRED <input type="checkbox"/> REWORK/RETEST NOT REQUIRED BECAUSE See DWG. 58337 Sht 2, Zone 4 D/E. Reduce switch override time duration at U13-5 from "1.5 SEC" to "APPROX 0.2 SEC" (actually came out 0.65 SEC). See EO 4457A. Now door doesn't open too far past outgas spec'd position.									
21. AUTHORIZATION Current									
22. REWORK/RETEST ACTION TAKEN Changed R5B from 1.2 M to 470K									
23. QA Rework									
24. QA RETEST									
25. LIST ALL PARTS REPLACED									
PART NUMBER		CKT SYM		PART LOT NUMBER		DATE CODE		MANUFACTURER	
908661-137								N/A	
26. PROBABLE DEFECT N/A									
27. ANALYSIS NUMBER									
27. REWORK BY McBannon		ORG 72-73		DATE 6/15/82		28. REQUESTED BY L. Simon		ORG 22-13	
29. CAUSE AND CORRECTIVE ACTION DURATION OF SIGNAL TO OPEN DOOR TO OUT GAS POSITION WAS TOO LONG. EO 4457 A CHANGED RESISTOR VALUE IN TIMING CIRCUIT TO MATCH MOTOR SPEED AND GEARING/BACKLASH CHARACTERISTICS.								DATE 6/17/82	
30. CONTINUATION <input type="checkbox"/> SHEET USED									
31. FRB CLOSURE									
32. DOCUMENT IMPLEMENTING CORRECTIVE ACTION EO 4457 A EFFECTIVITY 1/003 TO 505.									
33. BASIC CAUSE OF VERIFIED FAILURE <input checked="" type="checkbox"/> DESIGN <input type="checkbox"/> ENVIRONMENTAL <input type="checkbox"/> DEFECTIVE PARTS		<input type="checkbox"/> TEST EQUIPMENT <input type="checkbox"/> TEST PROCEDURE <input type="checkbox"/> TEST SET-UP		<input type="checkbox"/> MFG. PROCEDURE <input type="checkbox"/> ASSY/FAB ERROR <input type="checkbox"/> WORKMANSHIP		<input type="checkbox"/> WIRING ERROR <input type="checkbox"/> ROUGH HANDLING <input type="checkbox"/> WEAR-OUT		<input type="checkbox"/> UNKNOWN	
34. FAILURE TYPE <input checked="" type="checkbox"/> PRIMARY <input type="checkbox"/> INDUCED		<input type="checkbox"/> UNKNOWN <input type="checkbox"/> NO FAILURE		35. FAILURE CLASSIFICATION <input type="checkbox"/> CRITICAL <input type="checkbox"/> MAJOR		<input checked="" type="checkbox"/> MINOR <input type="checkbox"/> SAFETY		DEFECT CODE	
36. RESPONSIBLE ENGINEER Current		ORG 51 41		DATE 6-17-82		37. SPACECRAFT SYSTEM ENGINEER 6-17-82		DATE 6/17/82	
38. RELIABILITY 1.0		ORG 51 41		DATE 6-17-82		39. CUSTOMER OR SUPPLIER 6/17/82		DATE 6/17/82	

ORIGINAL PAGE IS
OF POOR QUALITY


58145

[SERC] ENGINEERING ORDER / REVISION NOTICE		NO. 445	
CODE 102MT 11323		SHEET 1 OF 1	
DRAWING TITLE ELECTRONIC DIAGRAM, MOTOR DRIVE, COOLER DOOR (A9)		DRAWING NUMBER 50933 (D)	
PROJECT NUMBER PL 1162	ITEM DISPOSITION REWORK <input type="checkbox"/> ITEMS CONFORM <input type="checkbox"/> NO ITEMS MADE <input type="checkbox"/> REJECT <input type="checkbox"/> USE <input type="checkbox"/> NOT APPLICABLE <input checked="" type="checkbox"/>	CLASS CHANGE <input type="checkbox"/> I <input checked="" type="checkbox"/> A <input type="checkbox"/> B	DRAWING TYPE <input type="checkbox"/> A <input checked="" type="checkbox"/> B
EFFECTIVITY S1065 SER NO. 003 & SUBQ		AUTHORIZING ECR NUMBER TM 2737/02	
DESCRIPTION OF CHANGE			
<p>1) ON F/D, SH 2, ZONE 4 E CHANGED VALUE R5B IS: 470K WAS: 1.2 M</p> <p>2) CHANGED SWITCH OVERRIDE IS: APPROX .5 SEC WAS: 1.5 SEC</p>			
* NOTE AND/OR ITEM NUMBER TO BE ASSIGNED STATUS THIS CORPORATION.			
PREPARED BY J PRINCE	DATE 82-6-10	QUALITY APPROVAL <i>[Signature]</i> NO	DATE 6-11-82
CHECKED BY 7. B. H. 12	DATE 10. 20. 82	MANUFACTURING APPROVAL <i>[Signature]</i> DO	DATE 6-11-82
ECR / RSA APPROVAL <i>[Signature]</i>	DATE 6/11/82	PROJECT APPROVAL <i>[Signature]</i>	DATE 6-11-82
		RELEASED BY A <i>[Signature]</i> DATE 82-6-11	
		INCORPORATED BY <i>[Signature]</i> DATE	
		DO NOT USE THIS PRINT	
		DRAWING REV. LETTER	

HUGHESHUGHES AIRCRAFT COMPANY
SPACE AND COMMUNICATIONS GROUP
EL SEGUNDO, CALIFORNIASPACE AND COMMUNICATIONS GROUP
FAILURE REPORTORIGINAL PAGE IS
OF POOR QUALITY**S** 8150

ORIGINATOR	1. PROGRAM NAME AND NUMBER THEMATIC MAPPER HS23A	2. GLA	3. MODEL F1	4. TIME OBSERVED 1100	5. DATE OBSERVED MO 7 DA 1 YR 82	
	6. HARDWARE LEVEL WHEN FAILURE WAS OBSERVED <input type="checkbox"/> SPACECRAFT <input type="checkbox"/> SYSTEM <input type="checkbox"/> SUBSYSTEM <input type="checkbox"/> UNIT <input checked="" type="checkbox"/> ASSEMBLY <input type="checkbox"/> SUBASSEMBLY <input type="checkbox"/> MODULE <input type="checkbox"/> MICAM <input type="checkbox"/> CARD <input type="checkbox"/> PART					
	EQUIPMENT IDENTIFICATION: NAME PART NUMBER S/N MANUFACTURER					
	7. SUBSYSTEM					
	8. URGY					
	9. <input checked="" type="checkbox"/> ASSEMBLY <input type="checkbox"/> SUBASSEMBLY RC DOOR ASSY S1740-1 003					
	10. <input type="checkbox"/> MODULE <input type="checkbox"/> MICAM <input type="checkbox"/> CARD					
	11. OTHER					
	12. TEST WHEN FAILURE WAS OBSERVED <input type="checkbox"/> DEVELOPMENT <input type="checkbox"/> QUALIFICATION <input type="checkbox"/> INTEGRATION <input type="checkbox"/> LAUNCH OPERATIONS <input type="checkbox"/> IN-PROCESS <input type="checkbox"/> ACCEPTANCE <input type="checkbox"/> SYSTEM <input checked="" type="checkbox"/> STR FO14					
	13. ENVIRONMENT WHEN FAILURE WAS OBSERVED <input type="checkbox"/> AMBIENT <input type="checkbox"/> RADIATION <input type="checkbox"/> TEMP <input type="checkbox"/> THERMAL VAC MRS AT <input type="checkbox"/> EMC/RF <input checked="" type="checkbox"/> VIBRATION X AXIS FOR JEN TYPE RANDOM <input type="checkbox"/> OTHER					
ENGINEERING EVALUATION	14. DESCRIPTION OF FAILURE ITEM 63, SHC SCREEN, WAS NOTICABLY LOOSE AFTER X-AXIS VIBRATION, 2 PL. THESE SCREENS FASTEN THE ELECTROMAGNET BRACKET TO THE DOOR ASSY. THERE ARE ALSO 4 OTHER FASTENERS FOR THESE BRACKETS					
	15. TEST PROCEDURE STR FO14 2000 FINCHER 2235 1 JUL 82 <input type="checkbox"/> CONTINUATION SHEET USED					
	16. VERIFICATION AND FAILURE ANALYSIS THESE SCREENS AND 1 OTHER WERE FOUND TO BE LOOSE. THIS WAS PROBABLY DUE TO INSUFFICIENT TORQUE BEFORE VIBRATION, OR AN INEFFECTIVE LOCKING DEVICE ON THE SCREENS					
	19. FAILED ITEM NAME AND PART NUMBER					
	20. <input checked="" type="checkbox"/> FOLLOWING REWORK/RETEST REQUIRED <input type="checkbox"/> REWORK/RETEST NOT REQUIRED BECAUSE CONTINUE VIBRATION TEST TO COMPLETION. TEST DOOR PER SUPP 9 OF AHR 51740 (10 CYCLES). REWORK RETORQUE ALL FASTENERS ON ASSY AND NOTE LOOSE ITEMS. SPOT BAND HEADS TO PREVENT ROTATION					
	21. AUTHORIZATION AL. [Signature] 1000 DATE <input type="checkbox"/> CONTINUATION SHEET USED					
	22. REWORK/RETEST ACTION TAKEN STR FO14 COMPLETED. AHR 51740 SUPP 9 COMPLETED. FASTENERS RETORQUED AND SPOTBANDS. SEE E.O. 45284 THIS E.O. ADA SPOTBAND TO PREVENT LOOSENING.					
	23. QA REWORK					
	24. QA RETEST					
	25. LIST ALL PARTS REPLACED PART NUMBER CKT SYM PART LOT NUMBER DATE CODE MANUFACTURER PROBABLE DEFECT ANALYSIS NUMBER SCB0016-159 MS15795-B03					
MANUFACTURING AND TEST	27. REWORK BY ORG DATE 28. RETESTED BY ORG DATE 29. CONTINUATION SHEET USED					
	30. CAUSE AND CORRECTIVE ACTION CAUSED BY INEFFECTIVE LOCKING OF SCREENS. CORRECTED BY SPOTBANDING SCREENS AFTER FOLLOWING TO PREVENT LOOSENING. WASHER WERE CHANGED FROM SMALL PATTERN TO LARGE PATTERN TO INCREASE RIGIDITY.					
	31. FRG CLOSURE					
	32. DOCUMENT IMPLEMENTING CORRECTIVE ACTION E.O. 45284-EFFECTIVITY 51,003 SUBSQ					
	33. BASIC CAUSE OF VERIFIED FAILURE <input checked="" type="checkbox"/> DESIGN <input type="checkbox"/> TEST EQUIPMENT <input type="checkbox"/> MFG. PROCEDURE <input type="checkbox"/> WIRING ERROR <input type="checkbox"/> UNKNOWN <input type="checkbox"/> DEFECT CODE <input type="checkbox"/> ENVIRONMENTAL <input type="checkbox"/> TEST PROCEDURE <input type="checkbox"/> ASSY/FAB ERROR <input type="checkbox"/> ROUGH HANDLING <input type="checkbox"/> DEFECTIVE PARTS <input type="checkbox"/> TEST SET-UP <input type="checkbox"/> WORKMANSHIP <input type="checkbox"/> WEAR-OUT					
	34. FAILURE TYPE <input checked="" type="checkbox"/> PRIMARY <input type="checkbox"/> UNKNOWN <input type="checkbox"/> NO FAILURE <input type="checkbox"/> CRITICAL <input type="checkbox"/> MINOR <input type="checkbox"/> INDUCED <input type="checkbox"/> CLASSIFICATION <input type="checkbox"/> MAJOR <input type="checkbox"/> SAFETY					
	35. RESPONSIBLE ENGINEER W. [Signature] 22-35 7-13-82 36. SPACECRAFT SYSTEM ENGINEER 7-2-41 7-12-82					
	37. RECALLABILITY 31-41 7-13-82 38. CUSTOMER OR SUPPLIER					
	39. [Signature]					
	40. [Signature]					

50150



ENGINEERING CHANGE REQUEST

SHEET 1 OF 1

NO. TM2749/21

DRAWING TITLE RADIATIVE COOLER DOOR ASSY		DRAWING NUMBER 51740		REV E
CLASS CHANGE <input type="checkbox"/> I <input checked="" type="checkbox"/> BA	DRAWING TYPE <input type="checkbox"/> A <input checked="" type="checkbox"/> B	PRIORITY OF CHANGE <input type="checkbox"/> emergency <input checked="" type="checkbox"/> urgent <input type="checkbox"/> routine		PROJECT NUMBER 1162
OTHER AFFECTED ENGINEERING DOCUMENTS NONE				
REASON CHANGE NEEDED (EXPLAIN IN FULL) A FEW SCREWS LOOSENED DURING VIBRATION BUT DID NOT AFFECT THE DOOR FUNCTION OR PERFORMANCE. THIS CHANGE INSTALLS OVERSIZE WASHERS AND SPOT BONDS SCREWS TO PREVENT FUTURE PROBLEMS.				
NATURE OF PROBLEM AND/OR REQUIRED CHANGE SEE EO 4528A ORIGINAL PAGE IS OF POOR QUALITY				
<i>Let's fix FRP. 7-9-82</i>				
REQUESTED BY FINCHER	DATE 7 JUL 82	APPROVAL <i>[Signature]</i>	DATE 7/8/82	VELLUM ISSUE APPROVED BY
END REVIEWER <i>[Signature]</i>	DATE 7-9-82	APPROVAL <i>[Signature]</i>	DATE 7/9/82	ACTION TAKEN
EFFECTIVE ENGS SN003 & SUBS		APPROVAL <i>[Signature]</i>	DATE 7/8/82	E.O. 4528A DWG. REV.
ITEM DISPOSITION REWORK <input type="checkbox"/> ITEMS CONFORM <input type="checkbox"/> NO ITEMS MADE <input checked="" type="checkbox"/> REJECT <input type="checkbox"/> USE <input type="checkbox"/> NOT APPLICABLE <input type="checkbox"/>		APPROVAL <i>[Signature]</i>	DATE 7/8/82	INCOPI BY MC Fincher
		APPROVAL <i>[Signature]</i>	DATE 7/8/82	CHECKED BY <i>[Signature]</i>
		APPROVAL <i>[Signature]</i>	DATE 7/13/82	DATE 8 JUL 82
				MRS REQ —

MECH

SEBRC
 6000 10000 10000

ENGINEERING ORDER / ~~REVISION NOTICE~~

NO. 4528A

SHEET 1 OF 11

DRAWING TITLE RADIATIVE COOLER DOOR ASSY		DRAWING NUMBER 51740-E	
PROJECT NUMBER 1162	ITEM DISPOSITION NETWORK <input type="checkbox"/> ITEMS CONFORM <input type="checkbox"/> NO ITEMS MADE <input checked="" type="checkbox"/> REJECT <input type="checkbox"/> USE <input type="checkbox"/> NOT APPLICABLE <input type="checkbox"/>	CLASS CHANGE <input type="checkbox"/> I <input checked="" type="checkbox"/> A	DRAWING TYPE <input type="checkbox"/> A <input checked="" type="checkbox"/> B
EFFECTIVITY 51065 SN 003 18 SUBSQ		AUTHORIZING ECR NUMBER TM2749/01	

DESCRIPTION OF CHANGE

- 1) LM, ADDED ITEM * 1

6	-		MS1579S-804	WASHER, FLAT (1.25 IN DIA I.D.)	* 1
---	---	--	-------------	---------------------------------	-----

- 2) LM, QTY REQD

ITEM 73

IS:

17	6Z
----	----

WAS:

23	6Z
----	----

-1 BSC -1 BSC

- 3) ADDED NOTE

✱Z

AFTER FINAL ADJUSTMENT, SPOT BOND INDICATED

THREADED ITEM TO PREVENT ROTATION PER SP 80060-I-A-2.

* NOTE AND/OR ITEM NUMBER TO BE ASSIGNED AT TIME OF INCORPORATION.

PREPARED BY FINCHER	DATE 7 JUL 82	QUALITY APPROVAL <i>[Signature]</i>	DATE 7/8/82	RELEASED BY	DATE
CHECKED BY <i>[Signature]</i>	DATE 8 JUL 82	MANUFACTURING APPROVAL <i>[Signature]</i>	DATE 7/8/82	INCORPORATED BY	DATE
REA/ RSA APPROVAL <i>[Signature]</i>	DATE 8 JUL 82	PROJECT APPROVAL <i>[Signature]</i>	DATE 7/8/82	DRAWING REV LETTER <u> </u>	

58150



ENGINEERING ORDER / ~~REVISION NOTICE~~ NO. 452

SHEET 2

DRAWING TITLE


RADIATIVE COOLER DOOR ASSY

DRAWING NUMBER


51740

DESCRIPTION OF CHANGE

4) SH 2, ZN D7, ADDED CALLOUT




5) SH 2, ZN D7, ADDED CALLOUT



6) SH 2, ZN B7, ADDED CALLOUT



7) SH 2, ZN B7, ADDED CALLOUT



58150

ENGINEERING ORDER / ~~REVISION NOTICE~~

NO. 4528A

SHEET 3

DRAWING TITLE



RADIATIVE COOLER DOOR ASSY

DRAWING NUMBER



51740

DESCRIPTION OF CHANGE



8) SH 2, ZN A5, ADDED CALLOUT

ORIGINAL PAGE IS
OF POOR QUALITYWAS

9) SH 2, ZN D4, ADDED CALLOUT

WAS

10) SH 2, ZN D5, ADDED CALLOUT

ISWAS

58150

ENGINEERING ORDER / ~~REVISION NOTICE~~

NO. 4528 A

SHEET 4

DRAWING TITLE



RADIATIVE COOLER DOOR ASSY

DRAWING NUMBER



51740

DESCRIPTION OF CHANGE



11) SH 2, ZN D5, ADDED CALLOUT





12) SH 3, ZN D7, ADDED CALLOUT

ORIGINAL PAGE IS
OF POOR QUALITY

13) SH 3, ZN A7, ADDED CALLOUT



14) SH 3, ZN B6, ADDED CALLOUT



58150



ENGINEERING ORDER / ~~REVISION NOTICE~~

NO. 4528A

SHEET 5

DRAWING TITLE

RADIATIVE COOLER DOOR ASSY



DRAWING NUMBER

51740



DESCRIPTION OF CHANGE

ORIGINAL PAGE IS
OF POOR QUALITY



15) SH 3, ZN BS, ADDED CALLOUT





16) SH 3, ZN AS, ADDED CALLOUT




17) SH 3, ZN A4, ADDED CALLOUT



18) SH 3, ZN B2, ADDED CALLOUT



58150

ENGINEERING ORDER / ~~REVISION NOTICE~~

NO. 4528

SHEET 6

DRAWING TITLE


RADIATIVE COOLER DOOR ASSY

DRAWING NUMBER


51790

DESCRIPTION OF CHANGE


19) SH 4, ZN E6, ADDED CALLOUT, CHANGED CALLOUT



20) SH 4, ZN E7, ADDED CALLOUT



21) SH 4, ZN D7, ADDED CALLOUT

ORIGINAL PAGE IS
OF POOR QUALITY

58150



ENGINEERING ORDER / REVISION NOTICE

SHEET 7

NO. 4528A

DRAWING TITLE



RADIATIVE COOLER DOOR ASSY

DRAWING NUMBER



51740

DESCRIPTION OF CHANGE



22) SH 4, ZN A6, ADDED CALLOUT, CHANGED CALLOUT

ORIGINAL PAGE IS
OF POOR QUALITY

23) SH 5, ZN E3, ADDED CALLOUT

WAS

24) SH 5, ZN D7, ADDED CALLOUT

WAS

ORIGINAL PAGE IS
OF POOR QUALITY

S8150



ENGINEERING ORDER / ~~REVISION NOTICE~~

NO. 4528

SHEET 8

DRAWING TITLE RADIATIVE COOLER DOOR ASSY


DRAWING NUMBER

51740


DESCRIPTION OF CHANGE

25) SH 5, ZN C7, ADDED CALLOUT

IS




WAS




26) SH 5, ZN B7, ADDED CALLOUT

IS




WAS




27) SH 5, ZN B4, ADDED CALLOUT


IS



WAS



58150



ENGINEERING ORDER / REVISION NOTICE

NO. 4528A

SHEET 9

DRAWING TITLE



RADIATIVE COOLER DOOR ASSY

DRAWING NUMBER



51740

DESCRIPTION OF CHANGE



28) SHS, ZN B3, ADDED CALLOUT

ORIGINAL PAGE IS
OF POOR QUALITY

29) SHS, ZN C3, ADDED CALLOUT



30) SHS, ZN C2, ADDED CALLOUT



58150



ENGINEERING ORDER / ~~REVISION NOTICE~~

NO. 4528A

SHEET 10

DRAWING TITLE



RADIATIVE COOLER DOOR ASSY

DRAWING NUMBER

51740



DESCRIPTION OF CHANGE

31) SH 6, ZN AS, ADDED CALLOUT




ORIGINAL PAGE IS
OF POOR QUALITY

32) SH 6, ZN B3, ADDED CALLOUT



33) SH 6, ZN T3, ADDED CALLOUT



SB150



ENGINEERING ORDER / REVISION NOTICE

NO. 4528A

SHEET 11



DRAWING TITLE **RADIATIVE COOLER DOOR ASSY**

DRAWING NUMBER
51740



DESCRIPTION OF CHANGE

34) SH6, ZN F3, ADDED CALLOUT



ORIGINAL PAGE IS
OF POOR QUALITY





35) SH6, ZN C1, ADDED CALLOUT, CHANGED CALLOUT



36) SH7, ZN F6, ADDED CALLOUT



37) SH7, ZN C4, ADDED CALLOUT



58150

SB 0295C JAN 81

133HS 2nd 5

ORIGINAL PAGE IS
OF POOR QUALITY

58150

ASSEMBLY HISTORY RECORD CONTINUATION SHEET				SHEET 2 OF 3	
PART NUMBER		SERIAL OR LOT NUMBER	ASSEMBLY NAME	CONTINUATION OF:	
51740-1		003	DOOR ASSEMBLY, RADIATIVE COOLER	AHR DATED	AHR SUPPLEMENT NO. 10
OPER NO.	S/C NO.	INSTRUCTIONS		PERFORMED BY	
				OPER	DATE
17600	22-72	KIT NEW PART PER SUPPLEMENT NO. 6 ABCTR.			7/9/82
17700	51-41	Q.A. INSPECT KIT ABOVE.			7/9/82
17800	22-74	REPLACE WASHERS, ITEM 73, WITH NEW WASHERS, ITEM *1, PER E.O.			7/9/82
		4528A, SIX PLACES SHOWN IN SHEET 4, ZONE E-6, SHEET 4, ZONE A-6,			
		AND SHEET 6, ZONE C-1. TORQUE SCREWS TO 5.5 IN-LBS PER SPEC			
		16357, REV B, PARA 3.1.1 AND PARA 3.1.1.4.			
17900	51-41	Q.A. INSPECT ABOVE AND WITNESS TORQUE.			7/9/82

ORIGINAL PAGE IS
OF POOR QUALITY

58150

ASSEMBLY HISTORY RECORD CONTINUATION SHEET				SHEET 3 OF 3	
PART NUMBER		SERIAL OR LOT NUMBER	ASSEMBLY NAME	CONTINUATION OF: AHR DATED AHR SUPPLEMENT NO. 10	
51740-1		003	DOOR ASSEMBLY, RADIATIVE COOLER		
OPER NO.	S/C NO.	INSTRUCTIONS		PERFORMED BY OPER INSP DATE	
				REMARKS	
18000	22-74	BOND SCREWS PER NOTE #2 OF E.O. 4528A. ROOM TEMPERATURE CURE.		7/9/82 ALL EXCEPT LAST TWO	
		BOND SCREWS AS FOLLOWS:			
				MIX NO. 5403	
		LOCATION	ITEM NO.	QTY.	
		SHEET 2	ZONE D7 65	4	✓
		2	D7 59	8	✓
		2	B7 64	9	✓
		2	B7 60	6	✓
		2	A5 62	4	✓
		2	D4 59	4	✓
		2	D5 58	2	✓
		2	D5 59	3	✓
		SHEET 3	D7 59	4	✓
		3	A7 58	2	✓
		3	B6 59	3	✓
		3	B5 66	78	✓
		3	A5 59	42	✓
		3	A4 67	42	✓

SHEET 4 OF 1

ASSEMBLY HISTORY RECORD CONTINUATION SHEET

PART NUMBER		SERIAL OR LOT NUMBER	ASSEMBLY NAME		CONTINUATION OF:		
51740-1		003	DOOR ASSEMBLY, RADIATIVE COOLER		AHR DATED AHR SUPPLEMENT NO. 10		
OPER NO.	S/C NO.	INSTRUCTIONS			PERFORMED BY		REMARKS
		LOCATION	ITEM NO.	QTY.	OPER	INSP	DATE
18000		SHEET 3	ZONE B2 66	2			MIX NO. 5403
		4	E6 59	2			
		4	E7 59	6			
		4	D7 59	19			
		4	A6 59	2			
		SHEET 5,	ZONE E3 59	2			
		5	D7 60	9			
		5	C7 61	3			
		5	B7 62	4			
		5	B4 59	2			
		5	B3 57	2			
		5	C3 58	2			
		5	C2 94	3			
		SHEET 6	ZONE A5 62	4			
		6	B3 60	6			
		6	D3 64	9			
		6	F3 59	11			
		6	C1 41	2			

ORIGINAL PAGE IS
OF POOR QUALITY

58150

[SBC]

ASSEMBLY HISTORY RECORD CONTINUATION SHEET

SHEET 5 OF 5

PART NUMBER		SERIAL OR LOT NUMBER		ASSEMBLY NAME		CONTINUATION OF:	
51740-1		003		DOOR ASSEMBLY, RADIATIVE COOLER		AHR DATED AHR SUPPLEMENT NO. 10	
OPER. NO.	S/C NO.	INSTRUCTIONS		PERFORMED BY		REMARKS	
		LOCATION	ITEM NO.	QTY.	OPER	INSP	DATE
18000	CONT.	SHEET 7	ZONE F6 98	2	Bundy		2/14/82
		7	C4 59	4			
18100	51-41	Q.A. INSPECT THE ABOVE OPERATION.			(180)		3/14/82
18200	51-41	Q.A. REVIEW THIS SUPPLEMENT AHR FOR COMPLETENESS AND ROUTE TO PROJECT QUALITY FILES. THIS AHR, WHEN APPROVED, COMPLETES THE COOLER DOOR ASSEMBLY.					

ORIGINAL PAGE IS
OF POOR QUALITY

58150

三三三

1 1 0 1 133HS
5-

PART NUMBER 51740-1	SERIAL OR LOT NUMBER 003	DRAWING NO. 51740	DRAWING REVISION E	CSA SOURCE CODE 22-35	SUPPLEMENT NO. 6 1D ABCTR DATED 15 Apr. 80
PURPOSE OF SUPPLEMENT - INCORPORATES NEW ASSY DRAWING REVISION <input type="checkbox"/> OR EO's <input type="checkbox"/> ; REWORK <input type="checkbox"/> ; OTHER <input type="checkbox"/> . EXPLAIN:			APPLICABLE EO 4528A	PREPARED BY D. Dascomb	SUPPLEMENT RELEASE DATE 9 July 1982
				QUALITY APPROVAL <i>[Signature]</i> 7-9-82	NOTE TO PRODUCTION - UPON RECEIPT, ENTER SUPPLEMENT NO. AND RECEIPT DATE ON FRONT SHEET OF ABCTR. INITIAL THE ENTRY.

NOTES: THIS SUPPLEMENT ABCTR IS TO INCORPORATE CHANGES PER E.O. 4528A.

[illegible]

ORIGINAL PAGE IS
OF POOR QUALITY

58150

ORIGINAL PAGE IS
OF POOR QUALITY

SECTION 2.9
TOP OPTICAL ASSEMBLY

ORIGINAL PAGE IS
OF POOR QUALITY

2.9.1

2.9.1 Top Optical Assembly

2.9.1.1

No performance data was taken at the subsystem level on this subsystem.

2.9.2

ORIGINAL PAGE IS
OF POOR QUALITY

2.9.2

Acceptance Data

2.9.2.1

ORIGINAL PAGE IS
OF POOR QUALITY

2.9.2.1
Configuration Lists

AS-BUILT CONFIGURATION LIST

OPTICAL ASSEMBLY
52532 S/N 003

TRD LVL	PART NO.	NOMENCLATURE	CURRENT REVISION	ACCEPT. REVISION	AS-BUILT REVISION	SERIAL NUMBER
2	52532	OPTICAL ASSY - TM	F 3174A 4100A 4187A 4266A 4488A 4559A D-154 W-148 4656A	F 3174A 4100A 4187A 4266A 4488A 4559A D-154 W-148 4656A	F 3174A 4100A 4187A 4266A 4488A 4559A D-154 W-148 4656A	003
3	TP-32015-501	PRIME FOCAL PLANE COARSE FOCUS & FINE FOCUS TEST PROCEDURE 1A01R	G 4165A 4181A 4206A	G 4165A 4181A 4206A	G 4165A 4181A 4206A	
3	TP-32015-503	COLD FOCAL PLANE COARSE FOCUS AND CFPA TO PFPA ALIGN CHECK TEST PROCEDURE 1A03R	D	D	D	
3	TP-32015-504	COLD FOCAL PLANE FINE FOCUS AND PRELIM BAND REGISTRATION - CFPA TO PFPA ALIGN TEST PROCEDURE 1A04R	C	C	C	
3	TP-32015-608	TM MVNG, HANDLING & TRANSPORTATION	A	A	A	

ORIGINAL PAGE IS
OF POOR QUALITY

TRD LVL	PART NO.	NOMENCLATURE	CURRENT REVISION	ACCEPT. REVISION	AS-BUILT REVISION	SERIAL NUMBER
3	16357	PROCEDURE FOR GENERAL MECHANICAL ASSY OF THE TM	B	B	B	
3	16800	WORKMANSHIP SHAKEDOWN TEST PLAN AFT, OPTICS	A 4194A	A 4194A	A 4194A	
3	50844	RADIATION COOLER ADA	D	D	D	
3	50980	MODULE ASSY, PREAMP	E 2953A 4177A	E 2953A 4177A	E 2953A 4177A	201
3	51200	RAD COOLER ASSY	E 3922A 4201A 4216A 4269A SB-W032 W144 W147 W149 W151	E 3922A 4201A 4216A 4269A SB-W032 W144 W147 W149 W151	E 3922A 4201A 4216A 4269A SB-W032 W144 W147 W149 W151	003
3	51337	TELESCOPE ASSY	D 3866A 3917A *N2072A W129 W136	D 3866A 3917A	D 3866A 3917A	002
3	51512	AFT OPTICS	D 3646A 3896A 3925A 3959A 4134A	D 3646A 3896A 3925A 3959A 4134A	D 3646A 3896A 3925A 3959A 4134A	003

ORIGINAL PAGE IS
OF POOR QUALITY

*N=Other "Non Mandatory" Change.

IND LVL	PART NO.	NOMENCLATURE	CURRENT REVISION	ACCEPT. REVISION	AS-BUILT REVISION	SERIAL NUMBER
3	523532-097 -098 -099	SHIM	F 3174A 4100A 4187A 4266A 4490A 4488A	F 3174A 4100A 4187A 4266A 4490A 4488A	F 3174A 4100A 4187A 4266A 4490A 4488A	
3	52534	RELAY OPTICS ASSY	D 1145A 4097A	D 1145A 4097A	D 1145A 4097A	003
3	52787-001	CABLE HARNESS-PREAMP	C 3702A	C 3702A	C 3702A	201
3	52787-002	CABLE HARNESS-PREAMP	C 3702A	C 3702A	C 3702A	202
3	52787-003	CABLE HARNESS-PREAMP	C 3702A	C 3702A	C 3702A	203
3	52787-004	CABLE HARNESS-PREAMP	C 3702A	C 3702A	C 3702A	204
3	52788-001	CABLE HARNESS-PREAMP	C 3703A	C 3703A	C 3703A	202
3	52788-002	CABLE HARNESS-PREAMP	C 3703A	C 3703A	C 3703A	203
3	52788-003	CABLE HARNESS-PREAMP	C 3703A	C 3703A	C 3703A	203
3	52788-004	CABLE HARNESS-PREAMP	C 3703A	C 3703A	C 3703A	204
3	52884	CLAMP, STRAIN RELIEF	B 3252A	B 3252A	B 3252A	

ORIGINAL PAGE IS
OF POOR QUALITY

TRD LVL	PART NO.	NOMENCLATURE	CURRENT REVISION	ACCEPT. REVISION	AS-BUILT REVISION	SERIAL NUMBER
3	53650	CABLE ASSY, INCHWORM	B 2887A 3728A 9273A	B 2887A 3728A 9273A	B 2887A 3728A 9273A	101
3	53697-001	TUBE CUPPORT-OPTICAL	A	A	A	
3	53697-002	TUBE SUPPORT-OPTICAL	A	A	A	
3	53700	RETAINER BEARING	A	A	A	
3	53701	PLATE MTG RIGHT	B	A 2380A	A 2380A	
3	53702	PLATE MTG LEFT	B	A 2381A	A 2381A	
3	53703	PLATE MTG RIGHT	B	A 2382A	A 2382A	
3	53704	PLATE MTG LEFT	B	A 2383A	A 2383A	
3	53705-001	HSG BEARING, OPT	A	A	A	
3	53705-002	HSG BEARING	A	A	A	
3	53706	CONNECTOR TUBE	A	A	A	
3	53707	COLLAR SUPPORT	A	A	A	
3	53752	RETAINER, MODULE-IPS	A 2278A 3433A	A 2278A 3433A	A 2278A 3433A	
3	54245	HSG BEARING	A	A	A	
3	54561	GROUND WIRE, RAD COOLER	A	A	A	201 202
3	53865	CABLE ROUTING & CLAMPING DIAGRAM	A 3322A	A 3322A	A 3322A	

ORIGINAL PAGE IS
OF POOR QUALITY

2.9.2.2

ORIGINAL PAGE IS
OF POOR QUALITY

Listing of Liens

TOP OPTICAL ASSEMBLY

P/N 52532

FLIGHT

ORIGINAL PAGE IS
OF POOR QUALITY

Failure Reports Numbers

Open	Closed
	F1764 S8361 S8405

Deviations

Waivers

D-154 D-156	W-145
----------------	-------

TOP OPTICAL ASSY.

ORIGINAL PAGE IS
OF POOR QUALITY

P/N 52532

FLIGHT
Failure Report
No.

PROTOFLIGHT
Failure Report
No.

ENGINEER
Failure Report
No.

Open	Closed	Open	Closed	Open	Closed
	F1764 S8371 S8405		F0571 F1739 F2635 F2647 F2725 S8085 S8089 S8097		F0525 F0529 S8007

26 May 1982

1. ORIGIN Santa Barbara Research Center 75 Coronado Drive, Goleta, CA 93117				2. <input checked="" type="checkbox"/> DEVIATION <input type="checkbox"/> WAIVER	
				3. <input checked="" type="checkbox"/> MINOR <input type="checkbox"/> MAJOR <input type="checkbox"/> CRITICAL	
4. DESIGNATION FOR DEVIATION/WAIVER MODEL/TYPE: Flight-1 S. SPC. CODE: 11323 O. SYS. DESIG. TM A. DEV/WAIVER NO. D-154				5. BASE LINE AFFECTED <input checked="" type="checkbox"/> FUNCTIONAL <input type="checkbox"/> ALLOCATED <input type="checkbox"/> PRODUCE	
				6. OTHER SYSTEMS/CONFIGURATION ITEMS AFFECTED F. YES <input type="checkbox"/> H. NO <input checked="" type="checkbox"/>	
7. SPECIFICATIONS AFFECTED-TEST PLAN				8. DRAWINGS AFFECTED	
MFR. CODE		SPEC./DOC. NO.		MFR. CODE	
6. SYSTEM				NUMBER	
6. ITEM				REV.	
6. TEST PLAN		11323 TP32015-514		NOR. NO.	
9. TITLE OF DEVIATION/WAIVER Use Optional AC07 Test Configuration for AC07 Testing				10. CONTRACT NO. & LINE ITEM NAS5-24200	
11. CONFIGURATION ITEM NOMENCLATURE Thematic Mapper Assembly				CLASSIFICATION OF DEFECT 12. CD NO. 13. DEFECT NO. 14. DEFECT CLASSIFICATION <input checked="" type="checkbox"/> MINOR <input type="checkbox"/> MAJOR <input type="checkbox"/> CRITICAL	
15. NAME OF PART OR LATEST ASSEMBLY AFFECTED Optical Assembly		16. PART NO. OR TYPE DESIGN 52532		17. LOT NO. N/A	
				18. QTY 1	
19. EFFECT ON COST/PRICE Reduces test effort by 2 to 3 days		20. EFFECT ON DELIVERY SCHEDULE		21. RECURRING DEVIATION/WAIVER <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO	
22. EFFECT ON INTEGRATED LOGISTIC SUPPORT, INTERFACE, ETC.					

EXT: 615:

78

DESCRIPTION OF DEVIATION/WAIVER: ~~HS 236~~ IA04 Configuration Options
Accept the attached HS236-8004 memo as sufficient test--configuration modification description.

Relevant IA04 References:

1. D-151 Deviation prepared 11 May 1982.
2. HS236-7989 memo dated 11 May 1982.

ORIGINAL PAGE IS
OF POOR QUALITY

REASON FOR DEVIATION/WAIVER

The optical AC07 test configuration, delineated in the attached memo, will facilitate the transition from presently occurring IA04 testing to AC07 by allowing use of the IA04 configuration to the maximum extent possible. In addition, it will permit computer control of TM turn-on functions and thermal shutdown enablement.

REASON FOR DEVIATION/WAIVER		RE: <i>5/20/82</i>	
REQ: <i>9/2/82</i> SYS ENGR: <i>W. J. ...</i>		QA: <i>W. J. ...</i>	
PRODUCTION EFFECTIVITY BY SERIAL NUMBER		PE: <i>George B. ...</i>	
SERIAL NO 3 ONLY			
MITTING AUTHORITY AUTHORIZING SIGNATURE <i>W. J. ...</i>		TITLE: Minor - System Engineering Major/Critical - Program Manager	
27. APPROVAL/DISAPPROVAL			
<input type="checkbox"/> APPROVAL RECOMMENDED		<input checked="" type="checkbox"/> APPROVED <input type="checkbox"/> DISAPPROVED	
PRESENT ACTIVITY 95A GPEC		SIGNATURE: <i>George B. ...</i> DATE: <i>6/4/82</i>	
DOW 1694			

ORIGINAL PAGE IS
OF POOR QUALITY

SANTA BARBARA RESEARCH CENTER
A Subsidiary of Hughes Aircraft Company
INTERNAL MEMORANDUM

TO: G. S. Plevs CC: Distribution

DATE: 820527
REF: HS236-8004

SUBJECT: AC07 Optional Test Configuration--
Bands 1-5, 7 Testing

FROM: J. C. Campbell

BLDG: B11 MAIL STA. 78
EXT: 6131

REFERENCE: HS236-7989 IA04 Configuration Options

INTRODUCTION:

This memo describes a possible optional test configuration, TM to BTCE, that can be used for Bands 1-5, 7 testing during the AC07 test phase to support the presently defined AC07 data collection and also to provide the TM instrument with computer controlled power turn on and thermal shutdown capability. This configuration is based on reference memo HS236-7989 and is presented here in terms of existing configuration drawings and test procedures to the extent possible.

TEST CONFIGURATION

1. Configure TM & BTCE per drawing 3533100-300-2, but with the following possible exceptions:

FUNCTION	REQUIREMENT	DWG ZONE	CABLE#
X-Y ALIGN MONTR	NOT USED	B-19	W-109
VIDEO MONITOR	DON'T CARE	E-3	W2114-2
HDRR	DON'T CARE	F-10	(see DWG)
DEMUX	DON'T CARE	G-7	(see DWG)
TM MUX TST PTS	NOT USED	G-15	VERIFY DISCONN. W5002& W5003

ORIGINAL PAGE IS
OF POOR QUALITY

2. Then refer to phase-I DWG 3533100-300-1, and make the following connections or changes:

FUNCTION	REQUIREMENT	DWG ZONE	CABLE or CONN#
B1 AOTS VIDEO	CONNECT	E/F-17	WTC30& 35
B2 AOTS VIDEO	CONNECT	E/F-17	WTC31& 36
B3 AOTS VIDEO	CONNECT	E/F-17	WTC32& 37
B4 AOTS VIDEO	CONNECT	E/F-17	WTC33& 38
B5 AOTS VIDEO	CONNECT	E/F-17	WTC-41
B7 AOTS VIDEO	CONNECT	E/F-17	WTC-42
AOTS DC RESTR	1 CONNECTION	E/F-15	W5050 to J410
AOTS TLMY	NOT USED	E/G-15	W5050(J102, J105, & J400)
AOTS VID OUT	CONNECT	F-15/17	W5035& W5036
AOTS IW COUNT	DON'T CARE	G-16	AOTS CONN B5-J5
DC RESTORE	CONNECT	E-19	W-139

3. Provide the following functions according to test procedure number TP32015-514:

- a) Install the SMACC per Appendix U: connect SMACC or SAMLOCK Drawer to penetration-plate connector P-10 via adapter cable # W3071. Ground the SMACC dc power return to the Collimator Ground Bus.
- b) Implement "Shutter Aside" via Appendix S, Method 3 at TM connector P45.

4. Install the BTC and CFPA Temp Sensor Converter per Appendix V of TP32015-504.

5. Bring TMT software up using TLMY stream #2.

TM COMMANDS REQUIRED:

Power the following TM functions ON:

TM-COMMANDS (ALL BANDS)

TM:001; PS1 ON
~~TM:004; Thermal Shutdown Enabled~~
 TM:009; SWE 1 ON / 2 OFF
 TM:005; MUX ON (PS1)
 TM:007; TLMY Scaling ON

The choice of this configuration is optional and is to be used at the Test Director's discretion. If its use fails to support the test adequately then the configuration shall be per phase - I DWG 3533100-300-1 as originally specified by TP32015-514.

ORIGINAL PAGE IS
OF POOR QUALITY

Program Instruction 010

REQUEST FOR DEVIATION/WAIVER
(SEE MIL-STD-440 OR 481 FOR INSTRUCTIONS)

DATE PREPARED

3-25-82

PROPOSING ACTIVITY NO.

1. ORIGINATOR NAME AND ADDRESS

Santa Barbara Research Center
75 Conamar Drive, Goleta, CA 93117

1. ☐ DEVIATION ☒ WAIVER
2. ☒ MINOR ☐ MAJOR ☐ CRITICAL

4. DESIGNATION FOR DEVIATION/WAIVER

5. MODEL/TYPE
FLIGHT

6. MFR. CODE
11323

7. SYS. DESIG.
TM

8. DEVIATION NO.
W145

3. BASE LINE AFFECTED

☒ FUNCTIONAL ☐ ALLOCATED ☐ PRODUCT

9. OTHER SYSTEMS/CONFIGURATION ITEMS AFFECTED

☐ YES ☒ NO

SPECIFICATIONS AFFECTED-TEST PLAN

6. SYSTEM

7. ITEM

8. TEST PLAN

8. DRAWINGS AFFECTED

9. MFR. CODE

10. DRAWING NO.

11. REV.

12. MFR. NO.

9. TITLE OF DEVIATION/WAIVER
Waiver: from IA01R test procedure

10. CONTRACT NO. & LINE ITEM
NAS-5 2400

11. SUBSTITUTION TYPE OBSERVATIONS

Optical Assembly

12. DEF. NO.

13. SURVEY NO.

14. DEFECT CLASSIFICATION
☒ MINOR ☐ MAJOR ☐ CRITICAL

15. NAME OF PART IN LOWEST ASSEMBLY AFFECTED
Optical Assembly

16. PART NO. OR TYPE DESIGNATION
52532-D

17. LOT NO.
N/A

18. QTY
1

19. REASONING DEVIATION/WAIVER
☐ YES ☒ NO

20. EFFECT ON COST/PRICE
None

21. EFFECT ON DELIVERY SCHEDULE
None

22. EFFECT ON INTEGRATED LOGISTIC SUPPORT, INTERFACE, ETC.
None

23. DESCRIPTION OF DEVIATION/WAIVER

Delete the Fine Focus (post-shimming) Test of Band 1,
in Paragraph 5.5 of TP 32015-501(G) test procedure, for
flight model only.

24. REASON FOR DEVIATION/WAIVER

1. Test equipment problem with collecting Band 1 video data.
2. Sufficient MIF focus data has been obtained from video collects of Bands 2,3 & 4.
3. To preclude schedule delay in starting next systems test, IA06R.

REQ BY *[Signature]* SYS ENGR *[Signature]*

25. PRODUCTION EFFECTIVITY BY SERIAL NUMBER

51065 SN C03 ONLY

26. SUBMITTER'S SIGNATURE
[Signature] 3/25/82

Minor - System Engineering
Major/Critical - Program Manager

27. APPROVAL, DISAPPROVAL

☐ APPROVAL RECORDED

☒ APPROVED

☐ DISAPPROVED

28. APPROVING ACTIVITY

NAS-5 GPEC

SIGNATURE

[Signature]

DATE

3-26/82

DD FORM 1694

OF POOR QUALITY

50984 job into 50980 job into 52532 optical assembly

HUGHES

HUGHES AIRCRAFT COMPANY

SPACE AND COMMUNICATION GROUP
FAILURE REPORT

F 1764

1. PROGRAM NAME AND NUMBER TM HS236		2. GLA	3. MODEL PLT	4. TIME OBSERVED	5. DATE OBSERVED 49 17 80
6. HARDWARE LEVEL WHEN FAILURE WAS OBSERVED <input type="checkbox"/> SPACECRAFT <input type="checkbox"/> SUBSYSTEM <input type="checkbox"/> ASSEMBLY <input type="checkbox"/> MODULE <input checked="" type="checkbox"/> CARD		<input type="checkbox"/> SYSTEM <input type="checkbox"/> UNIT <input type="checkbox"/> SUBASSEMBLY <input type="checkbox"/> MICAM <input type="checkbox"/> PART			
EQUIPMENT IDENTIFICATION:					
7. SUBSYSTEM		NAME		PART NUMBER	S/N
8. UNIT					
9. <input type="checkbox"/> ASSEMBLY <input type="checkbox"/> SUBASSEMBLY					
10. <input type="checkbox"/> MODULE <input type="checkbox"/> MICAM <input checked="" type="checkbox"/> CARD		BAND 6 PRE AMP		50984	101
11. OTHER					SBAC
12. TEST WHEN FAILURE WAS OBSERVED <input type="checkbox"/> DEVELOPMENT <input checked="" type="checkbox"/> PRODUCTION <input type="checkbox"/> QUALIFICATION <input type="checkbox"/> ACCEPTANCE <input type="checkbox"/> INTEGRATION <input type="checkbox"/> SYSTEM <input type="checkbox"/> LAUNCH OPERATIONS					
13. ENVIRONMENT WHEN FAILURE WAS OBSERVED <input checked="" type="checkbox"/> AMBIENT <input type="checkbox"/> RADIATION <input type="checkbox"/> TEMPERATURE <input type="checkbox"/> THERMAL VAC <input type="checkbox"/> VIBRATION <input type="checkbox"/> AXIS FOR <input type="checkbox"/> TYPE <input type="checkbox"/> OTHER					
14. DESCRIPTION OF FAILURE CH4 -12VDC SHORTED TO GROUND					
15. TEST PROCEDURE 16378					
16. VERIFICATION AND FAILURE ANALYSIS CUT & JUMPED W/ W/ER W-033 (EO 9532) WAS NOT INCORPORATED PRIOR TO APPLICATION OF POWER. THIS FAILURE QUALIFIES FOR F767. STRESS ANALYSIS SHOWS NO PARTS OTHER THAN THOSE REPLACED WERE OVERSTRESSED. SEE HS 7274.		18. ORIGINATOR Stonaker		17. CONTINUATION SHEET USED 12313 422-80	
20. FOLLOWING REWORK/RETEST REQUIRED Q2-4 AND R6-4 REQUIRED REPLACEMENT WITH NEW FLIGHT COMPONENTS. THE SAME STRESS ANALYSIS FOR 94301 (REF: MAND HS236 6707) APPLIES TO THIS FAILURE. (COPY ATTACHED)					
21. REWORK/RETEST ACTION TAKEN Replaced to EO 9532 (4-18-80) RETESTED OK (5-11-80)		22. AUTHORIZATION Old looking		19. PAILED ITEM NAME AND PART NUMBER	23. CONTINUATION SHEET USED 122-17 15-22-80
24. LIST ALL PARTS REPLACED					
PART NUMBER	QTY SYN	PART LOT NO.	DATE CODE	MFR	PROBABLE DEFECT
27. REWORK BY ORG		DATE	28. RETESTED BY ORG	DATE	29. CONTINUATION SHEET USED
30. CAUSE AND CORRECTIVE ACTION Design Error Design changed per EO 9532					
31. REFER TO CONTINUATION SHEET FOR CAUSE AND CORRECTIVE ACTION.					
32. DOCUMENT IMPLEMENTING CORRECTIVE ACTION EO 9532 - EFFECTIVITY IS 5/10/80					
34. BASIC CAUSE OF VERIFIED FAILURE <input checked="" type="checkbox"/> DESIGN <input type="checkbox"/> ENVIRONMENTAL <input type="checkbox"/> DEFECTIVE PARTS		<input type="checkbox"/> TEST EQUIP <input type="checkbox"/> TEST PROC. <input checked="" type="checkbox"/> TEST SET-UP		<input type="checkbox"/> MFG. PROCEDURE <input type="checkbox"/> ASSEMBLY ERROR <input type="checkbox"/> WORKMANSHIP	
35. FAILURE TYPE <input checked="" type="checkbox"/> PRIMARY <input type="checkbox"/> INDUCED <input type="checkbox"/> UNKNOWN		<input type="checkbox"/> NO FAILURE		36. FAILURE CLASSIFICATION <input type="checkbox"/> CRITICAL <input type="checkbox"/> MAJOR <input type="checkbox"/> MINOR	
37. RESPONSIBLE ENGINEER W. H. K. [Signature]		38. SPACECRAFT SYSTEM ENGINEER W. H. K. [Signature]		39. CUSTOMER OR SUPPLIER 12/10/81	
39. RELIABILITY 514		DATE 9-10-80		DATE 9/10/80	

HUGHES

HUGHES AIRCRAFT COMPANY
SPACE AND COMMUNICATIONS GROUP
EL SEGUNDO, CALIFORNIA

SPACE AND COMMUNICATIONS GROUP

**FAILURE REPORT
CONTINUATION SHEET**

FR SERIAL NO.

F 1714

CONTINUATION SHEET LETTER

*LABEL FIRST CONTINUATION SHEET USED 'A', SECOND 'B', AND SO ON

☐ IDENTIFY ENTRIES BY REFERENCING FR BLOCK NUMBER IN COLUMN, DATE EACH ENTRY.

ADDITIONAL FR
CONTINUATION
SHEET(S) USED ☐

30 THE TEST ENGINEER MISTAKENLY TESTED FLIGHT PWR
ATT. 5/N 101. HADSHOULD HAVE TESTED PROTOFLIGHT PWR
ATT. 5/N 201 WHICH HAD E.O. 9532 INCORPORATED.
AT THE TIME 5/N 101 WAS TESTED E.O. 9532 HAD NOT
BEEN INCORPORATED INTO THE BOARD, THEREFORE IT FAILED.

Shannon 12/7/81

C/A: DUE TO THIS MISTAKE PLUS OTHER SIMILAR MISTAKES
THE RESPONSIBLE TEST ENGINEER HAS BEEN TERMINATED

Shannon 12/7/81

2.10

ORIGINAL PAGE IS
OF POOR QUALITY

SECTION 2.10
TELESCOPE ASSEMBLY

2.10.1

ORIGINAL PAGE IS
OF POOR QUALITY

2.10.1 Telescope Assembly

2.10.1.1

No performance data was taken at the subsystem level on this
subsystem.

2.10.2

ORIGINAL PAGE IS
OF POOR QUALITY

2.10.2

Acceptance Data

ORIGINAL PAGE IS
OF POOR QUALITY

2.10.2.1

2.10.2.1

Configuration Lists

AS-BUILT CONFIGURATION LIST

TELESCOPE ASSY

P/N 51337, S/N 002, FLIGHT

IND LVL	PART NO.	NOMENCLATURE	CURRENT REVISION	ACCEPT. REVISION	AS-BUILT REVISION	SERIAL NUMBER
	51337	TELESCOPE ASSY	D + 3866A 3917A W-129 W-136	D + 3866A 3917A W-129 W-136	D + 3866A 3917A W-129 W-136	002
	50825-101	PRIMARY MIRROR	D + 3865A W-095 W-137	D + 3865A W-095 W-137	D + 3865A W-095 W-137	001
	50825-102	SECONDARY MIRROR	D + 3865A W-137	D + 3865A W-137	D + 3865A W-137	001
	50842	TELESCOPE HOUSING OPTICAL METERING	G	G	G	
	52753	THERMISTOR BLOCK ASSY	D + 3794A	D + 3794A	D + 3794A	304
	52958	THERMISTOR BLOCK ASSY	C + 3795A D-138	C + 3795A D-138	C + 3795A D-138	101 102 103
	52447	PLATE, SUPPORT	D	D	D	002
	52448	BLOCK, ADJUSTING	D	D	D	
	52449	ANGLE	A	A	A	
	52451	SCREW, SWIVEL	A	A	A	
	52452	PIN, INDEX	A	A	A	
	52453	CYLINDER, SPRING	A	A	A	
	52454	NUT, SWIVEL	A	A	A	
	52455	WASHER, SPECIAL	A	A	A	
	52456	BRACKET, PIVOT	A	A	A	

ORIGINAL PAGE IS
OF POOR QUALITY

P/N 51337

IND LVL	PART NO.	NOMENCLATURE	CURRENT REVISION	ACCEPT. REVISION	AS-BUILT REVISION	SERIAL NUMBER
2	52457	PLUNGER, SPRING	A	A	A	
2	52458	BLOCK, PRESSURE	A	A	A	
2	52459	BLOCK, ADJUSTING	B	B	B	
2	52460	CUSHION, ADJUSTER	A	A	A	
2	52461	SCREW, ADJUSTING	A	A	A	
2	52463	CLIP, LOCATING	A	A	A	
2	52464	WASHER, SPECIAL	A	A	A	
2	52516	BAFFLE, SECONDARY MIRROR	C	C	C	001
2	52860 -1&-2	PLUG, MIRROR MOUNT	A	A	A	
2	53514	MASK, PRIMARY MIRROR	B	B	B	
2	53696	BAFFLE, TELESCOPE HOUSING	A	A	A	
2	51335-1	THERMISTOR, PRECISION (SCD)	D	D	D	138
2	51808	TERMINAL, INSUL, PRESS MOUNT	B	B	B	

ORIGINAL PAGE IS
OF POOR QUALITY

MD Cullen 1-18-82
R.L. Dick (17)

R.L. Dick
Quality Assurance

E. J. Vergara 2-11-82
E.J. Vergara
Configuration/Data Management

2.10.2.2

ORIGINAL PAGE IS
OF POOR QUALITY

Listing of Liens

ORIGINAL PAGE IS
OF POOR QUALITY

TELESCOPE ASSEMBLY

P/N 51337

FLIGHT

Failure Reports Number

<u>Open</u>	<u>Closed</u>
	F0530 F0552 F0591 F1742 S8084

Deviations

Waivers

D-136	W-129 W-136 W-137
-------	-------------------------

ORIGINAL PAGE IS
OF POOR QUALITY

TELESCOPE ASSEMBLY

P/N 51337

FLIGHT
Failure Report
No.

PROTOFLIGHT
Failure Report
No.

ENGINEER
Failure Report
No.

Open	Closed	Open	Closed	Open	Closed
	F0530 F0552 F0591 F1742 S8084		F1765 S8006		F0513

Program Instruction 010

ORIGINAL PAGE IS
OF POOR QUALITY

REQUEST FOR DEVIATION/WAIVER
(SEE MIL-STD-460 OR 481 FOR INSTRUCTIONS)

DATE PREPARED
1-20-82

PROCURING ACTIVITY NO.

1. ORIGINATOR NAME AND ADDRESS Santa Barbara Research Center 75 Coromar Dr. Goleta, Ca. 93117				2. <input checked="" type="checkbox"/> DEVIATION <input type="checkbox"/> WAIVER	
				3. <input checked="" type="checkbox"/> MINOR <input type="checkbox"/> MAJOR <input type="checkbox"/> CRITICAL	
4. DESIGNATION FOR DEVIATION/WAIVER					
a. MODEL/TYPE F-1	b. MFR. CODE 11323	c. SYS. DESIG. TM	d. DEV/WAIVER CO. D-138	5. BASE LINE AFFECTED <input type="checkbox"/> FUNCTIONAL <input type="checkbox"/> ALLOCATED <input checked="" type="checkbox"/> PRODUCTION	
				6. OTHER SYSTEMS/CONFIGURATION ITEMS AFFECTED <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO	
7. SPECIFICATIONS AFFECTED-TEST PLAN					
a. SYSTEM		b. ITEM		8. DRAWINGS AFFECTED	
9. TITLE OF DEVIATION/WAIVER Documentation Deficiency of Telescope Thermistors				10. CONTRACT NO. & LINE ITEM NAS5-24200	
11. CONFIGURATION ITEM NOMENCLATURE Thematic Mapper Assy				12. CD NO. II	
				13. DEFECT NO.	
				14. DEFECT CLASSIFICATION <input checked="" type="checkbox"/> MINOR <input type="checkbox"/> MAJOR <input type="checkbox"/> CRITICAL	
15. NAME OF PART OR LOWEST ASSEMBLY AFFECTED Thermistor Block Assy		16. PART NO. OR TYPE DESIGN 52958-C		17. LOT NO.	
				18. QTY 3	
				19. RECURRING DEVIATION/WAIVER <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO	
20. EFFECT ON COST/PRICE No Effect				21. EFFECT ON DELIVERY SCHEDULE 8 weeks if not approved.	
22. EFFECT ON INTEGRATED LOGISTIC SUPPORT, INTERFACE, ETC. No Effect					
23. DESCRIPTION OF DEVIATION/WAIVER The Assembly History Record (AHR) for the installation of three Thermistor Block Assemblies (P/N 52958) into the Telescope Assembly cannot be located.					

24. NEED FOR DEVIATION/WAIVER

Sufficient documentation is available to insure flight quality of assembled thermistors (MR# 117487). In addition, Revision "C" status of P/N 52958 was confirmed on each of three assemblies by resistance measurements and visual inspection.

25. PRODUCTION EFFECTIVITY BY SERIAL NUMBER 51065 SN 003 ONLY		RE <u>Planned 1/21/82</u>	
		QA <u>WOL 2-582</u>	
		PE <u>WOL 2-582</u>	
26. SUBMITTING ACTIVITY AUTHORIZING SIGNATURE <u>L. L. Ennis</u>		TITLE Minor - System Engineering Major/Critical - Program Manager	
27. APPROVAL/DISAPPROVAL			
a. <input type="checkbox"/> APPROVAL RECOMMENDED		b. <input checked="" type="checkbox"/> APPROVED <input type="checkbox"/> DISAPPROVED	
c. GOVERNMENT ACTIVITY NASA GSFC		SIGNATURE <u>George B. Ennis</u> DATE 3/11/82	
DD FORM 1694			

ORIGINAL FROM IS
OF PCOR QUALITY

Program Instruction 010

REQUEST FOR DEVIATION/WAIVER
(SEE MIL-STD-449 OR -82 FOR INSTRUCTIONS)

DATE PREPARED
1-8-82

PROCESSING ACTIVITY NO.

1. ORIGINATOR NAME AND ADDRESS SANTA BARBARA RESEARCH CENTER 75 COROMAR DR. Goleta, CA 93117				2. <input type="checkbox"/> DEVIATION <input type="checkbox"/> WAIVER 3. <input checked="" type="checkbox"/> MINOR <input type="checkbox"/> MAJOR <input type="checkbox"/> CRITICAL			
4. DESIGNATION FOR DEVIATION/WAIVER				5. CASE LINE AFFECTED			
6. MODEL/TYPE F1	7. MFR. CODE 11323	8. SYS. DESIG. TM	9. DEV/WAIVER NO. W-129	<input type="checkbox"/> FUNC. TYPICAL	<input type="checkbox"/> ALLO. CATED	<input type="checkbox"/> PROD. UCT	10. OTHER SYSTEMS/CONFIGURATION ITEMS AFFECTED <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO
7. SPECIFICATIONS AFFECTED-TEST PLAN				8. DRAWINGS AFFECTED			
MFR. CODE SPEC./DOC. NO. SCR				MFR. CODE NUMBER REV. MFR. NO.			
9. SYSTEM				11323 51337 D			
10. TEST PLAN							
11. TITLE OF DEVIATION/WAIVER TELESCOPE HOUSING BLACK PAINT FLAKING				12. CONTRACT NO. & LINE ITEM NASS-24200			
13. CONFIGURATION ITEM NOMENCLATURE THEMATIC MAPPER ASSY				14. DEFECT CLASSIFICATION <input checked="" type="checkbox"/> MINOR <input type="checkbox"/> MAJOR <input type="checkbox"/> CRITICAL			
15. NAME OF PART OR LARGEST ASSEMBLY AFFECTED TELESCOPE ASSY				16. PROV. NO. OR TYPE DESIGN 51337-D	17. LOT NO.	18. QTY -1-	19. REQUIRING DEVIATION/WAIVER <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO
20. EFFECT ON COST/PRICE				21. EFFECT ON DELIVERY SCHEDULE 3 weeks if disapproved			
22. EFFECT ON INTEGRATED LOGISTIC SUPPORT, INTERFACE, ETC.							

23. DESCRIPTION OF DEVIATION/WAIVER

As a result of extensive handling and rework of Telescope Housing, several areas on the aluminum and Invar flanges have experienced black paint flaking (or chipping). All loose paint on invar parts and all exposed paint on aluminum flange has been removed per MRCO 294836R. Poor adhesion of the black optical paint to these aluminum and Invar parts in the Telescope Housing has resulted in general delamination of the paint during tape testing.

24. REAS FOR DEVIATION/WAIVER

Repainting exposed surfaces is impractical and not recommended as considerable disassembly would be required to avoid possible contamination of optical surfaces. Surface of aluminum flange can be left without finish since the telescope's graphite epoxy structure already requires a low humidity environment, by design less than 50% relative humidity. No operations will occur which would cause direct exposure to moisture. Invar surfaces left unpainted will cause neither optical nor corrosion problems.

REA W. Balch STS ENGR

QA M. G. King
PE David A. Wilson

25. PRODUCTION EFFECTIVITY BY SERIAL NUMBER
51065 SN 003 ONLY

CMDR E. J. J. J.

26. SIGNATURE OF AUTHORIZING OFFICIAL
J. L. Enright 12 Jan 82
Minor - System Engineering
Major/Critical - Program Manager

27. APPROVAL/DISAPPROVAL

☐ APPROVAL RECOMMENDED ☒ APPROVED ☐ DISAPPROVED

28. SIGNATURE OF ACTIVITY
11000 OFFICE George P. Lutz 1/12/82

DD FORM 1694

HUGHES

NONCONFORMING MATERIAL REPORT (NCMR)

 NO. 207000
 DATE 1-4-82
 PAGE 1 OF 1

PROGRAM ID T 11 K 412 7 PPG

PART NO.	51337 REV D	B/N	002	ENG. CHANGES	NOMENCLATURE
WORK ORDER DOC NO.	LOT SIZE	QTY. SUSP.	1	SUSPENDED IN	TELESCOPE
SUPPLIER	DIV. OR LOCATION	SUPPLIER CODE	5-D, P. C.	P.O. NO.	REF. DOCUMENTS
					AMRS 51337 ORANGE 710
					ITEM NO.
					R.R. NO.

ITEM NO.	QTY INSP.	QTY SUSP.	DESCRIPTION OF NONCONFORMANCE	RESP. DEPT.	PRIOR OCCUR.	M.A. LEVEL	COD
1	1	1	EXCESSIVE PAINT PER ALUMINUM AND INDOOR FRAME				
2	1	1	ADDITIONAL PAINT NEEDED TO COVER ALL SURFACES ON OUTSIDE MOUNTING				

ORIGINATOR	DATE	QUALITY	INSTRUCTIONS	ENGINEERING	DATE
R. L. Davis	1-4-82	100%	REMOVE LOOSE PAINT AS REQD FROM TELESCOPE TO MAINFRAME BOLT CIRCUMFER MRCO. (4 THRU 11-UP)	W. Babin	1-5-82
1. E			REMOVE LOOSE PAINT AS REQD FROM ROB MOUNTING PADS PER MRCO, AND		
2. B			USE AS IS (O.K. PER TELECON WITH M. WEISS ON 1-5-82)		

ENGINEERING	DATE	QUALITY	CUSTOMER	DATE
W. Babin	1-5-82	100%	V. J. Jellor	1-5-82
ITEM NO.	CAUSE OF NONCONFORMANCE	RESULTS OF CORRECTIVE ACTION INVESTIGATION	CORRECTIVE ACTION	DATE
12	EXCESSIVE REWORK (DAMAGED PRIMARY MIRROR) AND HANDLING TELESCOPE ASSY TO OPEN MOUNTING HOLES	THIS WAS AN ISOLATED INSTANCE OF FLAKING PAINT DUE TO USUALLY ROUGH ATTEMPTED REPAIR, AND WILL NOT BE REPEATED IN THE FUTURE		

SIGNATURE	DATE	SIGNATURE	DATE
W. Babin	1/5/82	S. H. Babin	1-5-82
RESPONSIBILITY	DEBIT VENDOR	DISP CODE	VENDOR PACKING SHEET
QTY. INSP.	QTY. SUSP.	QTY. R.T.V.	QTY. SCRAP
YES	NO	YES	NO
QTY. INSP.	QTY. SUSP.	QTY. R.T.V.	QTY. SCRAP
YES	NO	YES	NO
QTY. INSP.	QTY. SUSP.	QTY. R.T.V.	QTY. SCRAP
YES	NO	YES	NO

ORIGINAL PAGE 13 OF FOUR QUALITY

ORIGINAL PAGE IS
OF POOR QUALITY

MATERIAL REVIEW
CONTROL ORDER

MRCO

2	9	4	8	3	6	R
W	/	A	V	4	1	2

PART NO. 51337 REVISION D

PART NAME TELESCOPE ASSY

QUANTITY 1 SIN 002

ROUTE TO: DON DASCOMB

P.O. MASTER CLEARED

	OPR NO.	INSTRUCTIONS	DATE	QTY ACC	QTY SUS	INSP OPER	COMMENTS
12-74	10	COVER SCAN MIRROR END OF TELESCOPE ASSY WITH A FLUENT APPROVED PLASTIC AND INSTALL & CLEAN DRY NITROGEN PURGE SYSTEM TO PROTECT MIRRORS FROM CONTAMINATION DURING PAINT REPAIR WORK.					
5-74	20	AECA TO BE NOTIFIED P.A. INSPECT PURGE ASSEMBLY AND PERFORM TAPE TEST IN AREA OF SCRATCHES					NOTIFY NASA OF TAPE TEST RESULT
2-74	30	MECHANICALLY REMOVE ALL LOOSE PARTICLES OF PAINT IN AREA OF SCRATCHES ON THE MOUNTING RING FOR THE AET OPTICS BULK- HEAD (AOB INSIDE HOUSING)					USE VACUUM TUBE & VERIFY NO PAINT IS PEELING
LAST		RETURN THIS CARD TO MATERIAL REVIEW FOR RECORD CLEARANCE					
OPR							

SB 0344-B-1 FEB 78

QA APPROVAL

S.H. Bandy

DATE

1-5-82

ENG APPROVAL

N. Balin

DATE

1-5-82

J.F.

ORIGINAL PAGE IS
OF POOR QUALITY

MATERIAL REVIEW
CONTROL ORDER

M R C O 2 9 4 8 3 6 R
W / A V 4 1 2

CONTINUATION SHEET

PAGE 2 OF 2

	OPR NO.	INSTRUCTIONS	DATE	QTY ACC	QTY SUS	INSP OPER	COMMENTS
22-74	40	MECHANICALLY REMOVE ALL LOOSE PAINT PARTICLES ON THE OUTSIDE SURFACE OF THE TELESCOPE MOUNTING RINGS (ALUM & INVAR).					USE VACUUM TUBE & VERIFY NO PAINT IS PEELING
51-41	50	Q.A. INSPECT ABOVE TWO OPR.					
22-74	60	TOUCH UP CHROMATE CONVERSION COAT (ALODINE) ALUM TELESCOPE MOUNTING RING PER NOTE 11 OF DRAWING 50842 REV G.					
51-41	70	AFQA AND SBRO Q.A. INSPECT ABOVE OPR. AND PERFORM TAPE TEST ON PAINT ACROSS ALLOINED AREAS.					
22-74	80	REMOVE N ₂ PURGE INSTALLED IN OPR 10.					
LAST		RETURN THIS CARD TO MATERIAL REVIEW FOR RECORD CLEARANCE.					
OPR							

SB 0344-B-1 FEB 78

Program Instruction 010

ORIGINAL PAGE IS
OF POOR QUALITYREQUEST FOR DEVIATION/WAIVER
(SEE MIL-STD-883C OR 883 FOR INSTRUCTIONS)

DATE PREPARED

2-17-82

PROCURING ACTIVITY NO.

1. ORIGINATOR NAME AND ADDRESS SANTA BARBARA RESEARCH CENTER 75 COROMAR DR. GOLETA, CAL. 93117				2. <input type="checkbox"/> DEVIATION <input checked="" type="checkbox"/> WAIVER	
4. DESIGNATION FOR DEVIATION/WAIVER				3. <input checked="" type="checkbox"/> MINOR <input type="checkbox"/> MAJOR <input type="checkbox"/> CRITICAL	
6. MODEL/TYPE F-1	8. MFR. CODE 11323	9. SYS. DESIG. HS236	4. DEV/WAIVER NO. W-136	5. BASE LINE AFFECTED <input type="checkbox"/> FUND. TYPICAL <input type="checkbox"/> ALLO- CATED <input checked="" type="checkbox"/> PROD. UCT	6. OTHER SYSTEMS/CONFIGU- RATION ITEMS AFFECTED <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO
7. SPECIFICATIONS AFFECTED-TEST PLAN				8. DRAWINGS AFFECTED	
a. SYSTEM b. ITEM c. TEST PLAN				a. MFR. CODE b. NUMBER c. REV. d. NOR. NO.	
9. TITLE OF DEVIATION/WAIVER Low Value for Telescope MTF				10. CONTRACT NO. & LINE ITEM NAS 5-24200	
11. CONFIGURATION ITEM NOMENCLATURE Thematic Mapper Assy				12. CD NO. II	
13. NAME OF PART OR LOWEST ASSEMBLY AFFECTED Telescope Assy				14. DEFECT CLASSIFICATION <input checked="" type="checkbox"/> MINOR <input type="checkbox"/> MAJOR <input type="checkbox"/> CRITICAL	
15. PART NO. OR TYPE DESIG. 51337-D				16. QTY -1-	
17. LOT NO.				18. RECURRING DEVIATION/WAIVER <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO	
19. EFFECT ON COST/PRICE None				20. EFFECT ON DELIVERY SCHEDULE -2 months min. if not approved	
21. EFFECT ON INTEGRATED LOGISTIC SUPPORT, INTERFACE, ETC. None					
22. DESCRIPTION OF DEVIATION/WAIVER Telescope single pass MTF is computed to be 0.87 along track and 0.88 cross track at a system frequency of 11,765 cycles/radian. TP32015-612 requirement is 0.85 along track and 0.90 cross track. Subsequent analysis indicates that computed F-1 MTF is adequate to produce a predicted system level SWR which will meet system requirements of ≥ 0.35 at 11,750 cycles/radian with margin. (Ref. HS236-7831 J.B. Young to J. Engel, Summary of MTF Performance for FMI Telescope, dated 9 February 1982.)					
23. NEED FOR DEVIATION/WAIVER This waiver is needed to avoid costly and time consuming rework which would have catastrophic impact on the entire Thematic Mapper program. The out-of-spec condition cannot be improved significantly without replacing the telescope optical system and/or reworking the Main Frame mounting surfaces. This would involve a minimum of 2 months delay and at least \$100,000 additional costs.					
24. REA <u>W. Belink</u> SYS ENGR <u>J.B. Young</u>					
25. PRODUCTION EFFECTIVITY BY SERIAL NUMBER 51065 SN 003 ONLY					
26. SUBMITTING ACTIVITY AUTHORIZING SIGNATURE <u>J. Engel</u> 2/18/82					
27. APPROVAL/DISAPPROVAL a. <input type="checkbox"/> APPROVAL RECOMMENDED b. <input checked="" type="checkbox"/> APPROVED <input type="checkbox"/> DISAPPROVED					
c. GOVERNMENT ACTIVITY NA-7 R/F-1					
SIGNATURE <u>James R. Lott</u> 2/18/82					
DD FORM 1694					

ORIGINAL PAGE IS
OF POOR QUALITY

Program Instruction 010

REQUEST FOR DEVIATION/WAIVER
(SEE MIL-STD-480 OR 481 FOR INSTRUCTIONS)

DATE PREPARED

19 February 1982

PROCURING ACTIVITY NO.

1100

1. ORIGINATOR NAME AND ADDRESS Santa Barbara Research Center, 75 Coromar Drive, Goleta, CA 93017				2. <input type="checkbox"/> DEVIATION <input checked="" type="checkbox"/> WAIVER	
				3. <input checked="" type="checkbox"/> MINOR <input type="checkbox"/> MAJOR <input type="checkbox"/> CRITICAL	
4. DESIGNATION FOR DEVIATION/WAIVER				5. BASE LINE AFFECTED	
6. MODEL/TYPE F-1	8. MFR. CODE 11323	7. SYS. DESIG. TM	4. DEV/WAIVER NO. W-137	<input type="checkbox"/> FUNC. TIONAL <input type="checkbox"/> ALLO- CATED <input type="checkbox"/> PROD- UCT	9. OTHER SYSTEMS/CONFIG- URATION ITEMS AFFECTED <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO
7. SPECIFICATIONS AFFECTED-TEST PLAN				8. DRAWINGS AFFECTED	
MFR. CODE SPEC./DOC. NO. SON				MFR. CODE NUMBER REV. NOR. NO.	
6. SYSTEM				11323 50825 D	
6. ITEM					
6. TEST PLAN					
9. TITLE OF DEVIATION/WAIVER Reflectance of Telescope Optics				10. CONTRACT NO. & LINE ITEM NAS5-24200 Data Item 32	
11. CONFIGURATION ITEM NOMENCLATURE Radiometer, Thematic Mapper				12. CD NO. II	
13. NAME OF PART OR LOWEST ASSEMBLY AFFECTED Telescope System				14. DEFECT CLASSIFICATION <input checked="" type="checkbox"/> MINOR <input type="checkbox"/> MAJOR <input type="checkbox"/> CRITICAL	
15. PART NO. OR TYPE DESIG. 50825				16. QTY 1	
17. LOT NO.				18. REQUIRING DEVIATION/WAIVER <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO	
19. EFFECT ON COST/PRICE None				20. EFFECT ON DELIVERY SCHEDULE None, if approved	
21. EFFECT ON INTEGRATED LOGISTIC SUPPORT, INTERFACE, ETC. None					

23. DESCRIPTION OF DEVIATION/WAIVER The measured reflectance on the delivered optical elements is lower than specified. The scattering from the surface is greater than allowed in the specification. It is requested that the Telescope system be used in its existing condition.

(Ref: NCMR #280985)

24. NEED FOR DEVIATION/WAIVER Technical details in HS 236-6160 and HS 236-6165 show that the telescope is usable in present condition. Rework would create extensive schedule delays. Analysis indicates no evidence of system performance degradation below system specification.

25. PRODUCTION EFFECTIVITY BY SERIAL NUMBER Serial No. 002		26. SIGNATURE W. Balinski		27. APPROVAL/DISAPPROVAL Minor - System Engineering Major/Critical - Program Manager	
28. GOVERNMENT ACTIVITY NASA GSFC		29. SIGNATURE George B. Britt		30. DATE 2/19/82	
DD FORM 1694					

ORIGINAL PAGE IS
OF POOR QUALITY



SPACE AND COMMUNICATION GROUP
FAILURE REPORT

F 0530

1. PROGRAM NAME AND NUMBER THEMATIC MAPPER		2. CLA LA	3. MODEL DP	4. TIME OBSERVED 1700	5. DATE OBSERVED 5 MO 3 DA 80
6. HARDWARE LEVEL WHEN FAILURE WAS OBSERVED <input type="checkbox"/> SPACECRAFT <input type="checkbox"/> SYSTEM <input type="checkbox"/> SUBSYSTEM <input type="checkbox"/> UNIT <input type="checkbox"/> ASSEMBLY <input type="checkbox"/> DISASSEMBLY <input type="checkbox"/> MODULE <input type="checkbox"/> MICAM <input type="checkbox"/> CARD <input type="checkbox"/> PART					
EQUIPMENT IDENTIFICATION:					
7. SUBSYSTEM TELESCOPE / MAIN FRAME		PART NUMBER 50823/51337/5002		S/N 002	
8. UNIT C				MANUFACTURER SARC	
9. <input checked="" type="checkbox"/> ASSEMBLY <input type="checkbox"/> DISASSEMBLY					
10. <input type="checkbox"/> MODULE <input type="checkbox"/> MICAM <input type="checkbox"/> CARD					
11. OTHER					
12. TEST WHEN FAILURE WAS OBSERVED <input type="checkbox"/> DEVELOPMENT <input type="checkbox"/> UN-PROCESSED <input type="checkbox"/> QUALIFICATION <input type="checkbox"/> ACCEPTANCE <input checked="" type="checkbox"/> INTEGRATION <input type="checkbox"/> SYSTEM <input type="checkbox"/> LAUNCH OPERATIONS					
13. ENVIRONMENT WHEN FAILURE WAS OBSERVED <input checked="" type="checkbox"/> AMBIENT <input type="checkbox"/> RADIATION <input type="checkbox"/> TEMPERATURE <input type="checkbox"/> THERMAL VAC <input type="checkbox"/> MISC. AT <input type="checkbox"/> OTHER <input type="checkbox"/> ELEC/RFI <input type="checkbox"/> VIBRATION <input type="checkbox"/> AXIS FOR <input type="checkbox"/> MIN TYPE					
14. DESCRIPTION OF FAILURE MTE TEST INDICATES THAT PRIMARY MIRROR WAS DISTORTED. TELESCOPE WAS MATED TO MAIN FRAME. CROSS BACK AND ALONG FOCAL PLANES OFFSET 0.009 INCH FROM EACH OTHER.					
15. TEST PROCEDURE TP32015-612.4.3		16. ORIGINATOR TDW/ISE		17. DATE 5/5/80	
18. VERIFICATION AND FAILURE ANALYSIS IT IS SUSPECTED THAT THE FIT OF THE TELESCOPE BODY TO THE MAIN FRAME MAY CONTRIBUTE TO THE DISTORTION. FITTED ASSEMBLIES WILL BE BONDED WITH TELESCOPE INSTALLED IN THE MAIN FRAME.					
19. FOLLOWING REWORK/RETEST REQUIRED REWORK/RETEST NOT REQUIRED (CHECK) SYSTEMS EVALUATION OF THE DISTORTION INDICATES THAT IT IS ACCEPTABLE AND WITHIN TESTED REQUIREMENTS. REFER TO HQ 236-7831 J. R. Young to J. ENEELY SUMMARY OF MTE PERFORMANCE FOR TELESCOPE. (COPY ATTACHED)					
20. REWORK/RETEST ACTION TAKEN NO REWORK REQD. FINAL MTE TESTS SHOW THAT MIRROR PERFORMANCE IS ACCEPTABLE FOR USE (REF W-136)		21. AUTHORIZATION [Signature]		22. DATE 10-19-81	
23. LIST ALL PARTS REPLACED					
24. CAUSE AND CORRECTIVE ACTION CAUSE: OUT-OF-FLATNESS CONDITION (LESS THAN 0.001 INCH) BETWEEN TELESCOPE MOUNTING FLANGE AND MAIN FRAME MOUNTING SURFACE. CORRECTING ACTION: ASSEMBLY TECHNIQUE HAS BEEN CHANGED TO BOND THE MIRROR AFTER THE TELESCOPE HAS BEEN BOLTED TO ITS INTERFACE. THIS TECHNIQUE WAS SUCCESSFULLY USED FOR THE PROTOFLIGHT ASSEMBLY. [Signature] 10-19-81					
25. DOCUMENT IMPLEMENTING CORRECTIVE ACTION AHR 51337 (RELEASE DATE: 12/5/80)					
26. BASIC CAUSE OF VERIFIED FAILURE <input type="checkbox"/> DESIGN <input type="checkbox"/> TEST EQUIP. <input checked="" type="checkbox"/> MFG. PROCEDURE <input type="checkbox"/> WIRING ERROR <input type="checkbox"/> UNKNOWN <input type="checkbox"/> ENVIRONMENTAL <input type="checkbox"/> TEST PROC. <input type="checkbox"/> ASBY/FAB ERROR <input type="checkbox"/> ROUGH HANDLING <input type="checkbox"/> DEFECT CODE <input type="checkbox"/> OBSOLETE PARTS <input type="checkbox"/> TEST SET-UP <input type="checkbox"/> WORKMANSHIP <input type="checkbox"/> WEAR-OUT					
27. FAILURE TYPE <input checked="" type="checkbox"/> PRIMARY <input type="checkbox"/> INDUCED <input type="checkbox"/> UNKNOWN <input type="checkbox"/> NO FAILURE					
28. FAILURE CLASSIFICATION <input type="checkbox"/> CRITICAL <input checked="" type="checkbox"/> MINOR <input type="checkbox"/> MAJOR <input type="checkbox"/> SAFETY					
29. RESPONSIBLE ENGINEER [Signature]		30. SPACECRAFT SYSTEM ENGR. [Signature]		31. DATE 12-61 8110	
32. RELIABILITY Q. Huber		33. CUSTOMER OR SUPPLIER [Signature]		34. DATE 51-11 9-9-81	

ORIGINAL PAGE IS
OF POOR QUALITY

HUGHES

HUGHES AIRCRAFT COMPANY

SPACE AND COMMUNICATION GROUP
FAILURE REPORT

F 0552

1. PROGRAM NAME AND NUMBER TM PL1162		2. QLA	3. MODEL FLT	4. TIME OBSERVED 6 AM	5. DATE OBSERVED 07 26 82
6. HARDWARE LEVEL WHEN FAILURE WAS OBSERVED <input type="checkbox"/> SPACECRAFT <input type="checkbox"/> SYSTEM <input type="checkbox"/> SUBSYSTEM <input type="checkbox"/> UNIT <input checked="" type="checkbox"/> ASSEMBLY <input type="checkbox"/> DISASSEMBLY <input type="checkbox"/> MODULE <input type="checkbox"/> MICAS <input type="checkbox"/> CARD <input type="checkbox"/> PART					
EQUIPMENT IDENTIFICATION:					
7. SUBSYSTEM		NAME		PART NUMBER	S/N
8. UNIT					
9. ASSEMBLY <input checked="" type="checkbox"/> ASSEMBLY <input type="checkbox"/> SUBASSEMBLY		Telescope/Main Frame		51337	002
10. MODULE <input type="checkbox"/> MODULE <input type="checkbox"/> MICAS <input type="checkbox"/> CARD					SRRC
11. OTHER					
12. TEST WHEN FAILURE WAS OBSERVED <input type="checkbox"/> DEVELOPMENT <input type="checkbox"/> IN-PROGRESS <input type="checkbox"/> QUALIFICATION <input type="checkbox"/> ACCEPTANCE <input type="checkbox"/> INTEGRATION <input type="checkbox"/> SYSTEM <input type="checkbox"/> LAUNCH OPERATIONS					
13. ENVIRONMENT WHEN FAILURE WAS OBSERVED <input checked="" type="checkbox"/> AMBIENT <input type="checkbox"/> RADIATION <input type="checkbox"/> TEMPERATURE <input type="checkbox"/> VIBRATION <input type="checkbox"/> THERMAL VAC <input type="checkbox"/> MSL AT <input type="checkbox"/> OTHER		0.88			
14. DESCRIPTION OF FAILURE Telescope single pass MTF is 0.84 along track and 0.88 cross track. (Measurements made at system frequency of 11.765 cycles/radian.) Specification (TP) requirement is 0.85 along track and 0.90 cross track.					
15. TEST PROCEDURE TP32015-612-1 3.2		16. ORIGINATOR J. Campbell		17. DATE 12-22-82	18. CONTINUATION SHEET USED
19. VERIFICATION AND FAILURE ANALYSIS Remeasurements and subsequent analysis indicates that measured Flight Model MTF is adequate to produce a predicted system level SWR which will meet system requirements of ≥ 0.35 at 11.750 cycles/radian with a margin.					
20. FOLLOWING REWORK/RETEST REQUIRED REWORK/RETEST NOT REQUIRED BECAUSE Refer to attached HS236-7831-J.B. Young to J. Engel, Summary of MTF Performance for FMI Telescope, dated 9 February 1982. Present MTF is ACCEPTED PER 11.765 cycles/radian.					
21. AUTHORIZATION J. Campbell		12-22-82		22. CONTINUATION SHEET USED	
23. REWORK/RETEST ACTION TAKEN None - MTF is acceptable per 11.765 cycles/radian.		24. QA REVIEW		25. QA RETEST	
26. LIST ALL PARTS REPLACED					
27. REWORK BY					
28. CAUSE AND CORRECTIVE ACTION SPECIFICATION REQUIREMENTS WERE HIGHER THAN REQUIRED FOR OPERATION WITHIN SYSTEM SPECIFICATIONS. CC 4131-4 MTF 0.84 PER WAIVER W 136 J.C.					
29. DOCUMENT IDENTIFYING CORRECTIVE ACTION CC 4131-4					
30. BASIC CAUSE OF VERIFIED FAILURE <input type="checkbox"/> DESIGN <input type="checkbox"/> ENVIRONMENTAL <input type="checkbox"/> DEFECTIVE PARTS <input type="checkbox"/> TEST EQUIP. <input checked="" type="checkbox"/> TEST PROC. <input type="checkbox"/> TEST SET-UP <input type="checkbox"/> MFG. PROCEDURE <input type="checkbox"/> ASSY/PKG ERROR <input type="checkbox"/> WORK MISMATCH <input type="checkbox"/> WRITING ERROR <input type="checkbox"/> POOR HANDLING <input type="checkbox"/> WELD-OUT <input type="checkbox"/> UNKNOWN <input type="checkbox"/> DEFECT CODE					
31. FAILURE TYPE <input type="checkbox"/> PRIMARY <input type="checkbox"/> INDUCED <input type="checkbox"/> UNUSUAL <input type="checkbox"/> NO FAILURE					
32. FAILURE CLASSIFICATION <input type="checkbox"/> CRITICAL <input type="checkbox"/> MAJOR <input type="checkbox"/> MINOR <input type="checkbox"/> SAFETY					
33. RESPONSIBLE J. Campbell 12-23-82 12-15-82 12-15-82 12-19-82					

Program Instruction 010

ORIGINAL PAGE IS 552
OF POOR QUALITYREQUEST FOR DEVIATION/WAIVER
(SEE MIL-STD-460 OR 481 FOR INSTRUCTIONS)

DATE PREPARED

2-17-82

PROCURING ACTIVITY NO.

1. ORIGINATOR NAME AND ADDRESS SANTA BARBARA RESEARCH CENTER 75 COROMAR DR. GOLETA, CAL. 93117				2. <input type="checkbox"/> DEVIATION <input checked="" type="checkbox"/> WAIVER	
4. DESIGNATION FOR DEVIATION/WAIVER				3. <input checked="" type="checkbox"/> MINOR <input type="checkbox"/> MAJOR <input type="checkbox"/> CRITICAL	
6. MODEL/TYPE F-1	5. MFR. CODE 11323	7. SYS. DESIG. HS236	8. DEV/WAIVER NO. W-136	9. OTHER SYSTEMS/CONFIGURATION ITEMS AFFECTED <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO	
7. SPECIFICATIONS AFFECTED-TEST PLAN				10. DRAWINGS AFFECTED	
a. SYSTEM TP32015-612				b. DRAWING NO. 51337	
c. TEST PLAN				d. REV. D	
9. TITLE OF DEVIATION/WAIVER Low Value for Telescope MTF				10. CONTRACT NO. & LINE ITEM NAS 5-24200	
11. CONFIGURATION ITEM NOMENCLATURE Thematic Mapper Assy				12. CD NO. II	
13. NAME OF PART OR LOWEST ASSEMBLY AFFECTED Telescope Assy				14. DEFECT CLASSIFICATION <input checked="" type="checkbox"/> MINOR <input type="checkbox"/> MAJOR <input type="checkbox"/> CRITICAL	
15. PART NO. OR TYPE DESIG. 51337-D				16. QTY -1-	
17. EFFECT ON COST/PRICE None				18. RECURRING DEVIATION/WAIVER <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO	
19. EFFECT ON DELIVERY SCHEDULE 2 months min. if not approved.				20. EFFECT ON INTEGRATED LOGISTIC SUPPORT, INTERFACE, ETC. None	
21. DESCRIPTION OF DEVIATION/WAIVER Telescope single pass MTF is computed to be 0.87 along track and 0.88 cross track at a system frequency of 11,765 cycles/radian. TP32015-612 requirement is 0.85 along track and 0.90 cross track. Subsequent analysis indicates that computed F-1 MTF is adequate to produce a predicted system level SWR which will meet system requirements of ≥ 0.35 at 11,750 cycles/radian with margin. (Ref. HS236-7831 J.B. Young to J. Engel, Summary of MTF Performance for FMI Telescope, dated 9 February 1982.)					

24. NEED FOR DEVIATION/WAIVER

This waiver is needed to avoid costly and time consuming rework which would have catastrophic impact on the entire Thematic Mapper program. The out-of-spec condition cannot be improved significantly without replacing the telescope optical system and/or reworking the Main Frame mounting surfaces. This would involve a minimum of 2 months delay and at least \$100,000 additional costs.

REA W. Belinski SYS ENGR J.B. Young RE J. Engel 2/18/82
QA W. Belinski 2/18/82
PE J. Engel

25. PRODUCTION EFFECTIVITY BY SERIAL NUMBER
51065 SN 003 ONLY

26. SUBMITTING ACTIVITY AUTHORIZING SIGNATURE <u>J. Engel</u> 2/18/82		TITLE Minor - System Engineering Major/Critical - Program Manager	
27. APPROVAL/DISAPPROVAL <input type="checkbox"/> APPROVAL RECOMMENDED		<input checked="" type="checkbox"/> APPROVED <input type="checkbox"/> DISAPPROVED	
28. GOVERNMENT ACTIVITY NASA GSFC		SIGNATURE <u>Robert R. Britt</u> 2/18/82	

DD FORM 1694

ORIGINAL PAGE IS
OF POOR QUALITY

SANTA BARBARA RESEARCH CENTER
A Subsidiary of Hughes Aircraft Company
INTERNAL MEMORANDUM

f552

TO: J. Engel

CC: L. Candell
R. Thomsen

DATE: 9 February 1982

REF: HS236-7831
2221-506

SUBJECT: Summary of MTF Performance
for FMI Telescope

ORIGINAL PAGE IS
OF POOR QUALITY

FROM: J. E. Young

BLIND: B11 MAIL STA. 78
EXT. 6180


Introduction

During the measurement of TM flight model (FMI) telescope EFL/MTF performance it was noted that its MTF was lower than the TM Protoflight (PFM). The MTF values for the spatial frequency of 11,750 cycles/radian were 0.86 (subsequently revised to 0.88) and 0.94 for FMI and PFM, respectively. Failure report, F0552 was initiated. Additional MTF measurements were then completed using special test request, STR #F1-001. The purpose of the additional measurements and associated analyses were to assess whether TM FMI sensor would pass the square wave response (SWR) of ≥ 0.35 @ 11,750 cycles/radian in the final thermal vacuum (T/V) performance tests.

Discussion

The measurement of MTF at the telescope level is accomplished in a double pass mode, see TP 32015-612 for a detailed description. The measured MTF in double pass must be converted to single pass MTF. Figure 1 conceptually illustrates the relationship between MTF_{DP} (double pass), MTF_{SP} (single pass), and MTF_{DL} (diffraction limited).

Figure 1. Relationship of MTF vs Spatial Frequency between Double Pass, Single Pass and Diffraction Limited Performance



F552

J. Engel

-2-

9 February 1982
HS236-7831
2221-506

Summary of MTF Performance for FM-1 Telescope

The expression used to calculate f_{sp} is

$$f_{sp} = \left(\left[2 \left(f_{DP}^2 - f_{DL}^2 \right)^{-1/2} - 1 \right] f_{DL} \right)^{-1/2} \quad (1)$$

where f_{DP} is a measured parameter and f_{DL} is approximated by

$$f_{DL} = 310.56 (1 - \text{MTF}) \quad \text{for } \text{MTF} > 0.60 \quad (2)$$

and spatial frequency is in units of kilocycles per radian.

Table I is a tabulation of the f_{sp} vs MTF. Equation (1) was used to convert double pass to single pass values except for the MTF listed for a spatial frequency of 11.75 K cycles/radian. These values were obtained by linear interpolation from adjacent points. The tabulated data includes Y (along scan) and X (cross scan) axes. Peripheral data is given, such as: time, Z axis location, and field angle. The last column notes the telescope configuration, principally, the telescope/mainframe interface bolt torque status.

It should be noted that FM-1 telescope optical system has appreciable astigmatism, even though the data tabulated in Table I shows very little. This is due to the astigmatism axis being about 30 degrees to the Y axis.

The TM PFM data has been used in an attempt to extrapolate whether the TM FM-1 performance will pass the specification of $\text{SWR} > 0.35$ @ 11.75 K cycles/radian. In an attempt to gain confidence in our extrapolation methodology the following PFM data was used.

In January 1981 PFM measurements were made during IA01 and IA02 in an attempt to understand the "measured low MTF values". The results of the associated analyses will be listed and their composite values compared with measured system level PFM MTF performance. All values are for a spatial frequency of 11.75 K cycles/radian.

Table 1. TM Flight Model (FM-1) Computed Single Pass Function of Spatial Frequency vs MTF.

F552

ORIGINAL PAGE IS OF POOR QUALITY	Y Axis		X Axis		Comments
	SP K Cycles Rad	MTF	SP K Cycles Rad	MTF	
TP32015-612 25 Jan 82 22:57:12 (Y Axis) 22:57:12 (X Axis) Z = 0.0000 inch On Axis	11.28 11.75 15.23 23.05 29.46 39.36	0.889 0.881 0.822 0.681 0.564 0.383	11.33 11.75 15.29 21.13 29.55 39.61	0.882 0.874 0.808 0.650 0.523 0.357	Telescope/Mainframe interface bolts torqued
TP32015-612 26 Jan 82 05:10:01 (Y Axis) 06:30:52 (X Axis) Z = 0.0000 inch On Axis	11.15 11.75 15.11 22.91 29.32 39.18	0.902 0.893 0.843 0.719 0.614 0.457	11.34 11.75 15.29 21.12 29.54 39.42	0.881 0.873 0.807 0.651 0.524 0.351	Telescope/Mainframe interface bolts torqued
TP32015-612 26 Jan 82 22:58:09 (Y Axis) 22:58:09 (X Axis) Z = -0.010 inch On Axis	11.23 11.75 15.18 22.98 29.38 39.27	0.895 0.887 0.831 0.701 0.594 0.425	11.15 11.75 15.13 22.98 29.41 39.28	0.902 0.893 0.840 0.701 0.586 0.420	Telescope/Mainframe interface bolts torqued
TP32015-612 27 Jan 82 01:30:16 (Y Axis) 01:30:16 (X Axis) Z = -0.010 On Axis	11.12 11.75 15.12 23.01 29.45 39.21	0.905 0.895 0.841 0.694 0.571 0.397	11.17 11.75 15.16 23.03 29.46 39.35	0.900 0.890 0.834 0.688 0.567 0.388	Telescope/Mainframe interface bolts torqued
STR # F1-002 30 Jan 82 18:51:38 (Y Axis) 18:51:39 (X Axis) Z = 0.000 On Axis	10.99 11.75 14.96 22.76 29.16 39.03	0.914 0.904 0.861 0.749 0.655 0.504	10.95 11.750 14.95 22.81 29.24 39.11	0.916 0.905 0.862 0.741 0.635 0.481	Telescope/Mainframe interface bolts "loose"
STR # F1-002 31 Jan 82 00:45:11 (Y Axis) 00:45:11 (X Axis) Z = 0.005 inch On Axis	11.21 11.75 15.15 22.96 29.37 39.25	0.897 0.889 0.836 0.708 0.599 0.431	11.39 11.75 15.34 23.19 29.61 39.47	0.873 0.886 0.792 0.619 0.455 0.321	Telescope rotated = 1/3 deg CCW as viewed from behind primary mirror Telescope/ Mainframe interface bolts torqued. See AHRS Suppl #3 to 51337. Suppl. dated 1/28/82
STR # F1-002 1 Feb 82 11:46:54 (Y Axis) 11:46:54 (X Axis) Z = 0.000 inch On Axis	10.88 11.75 14.33 22.55 28.85 38.56	0.920 0.910 0.871 0.780 0.705 0.596	10.84 11.75 14.33 22.66 29.02 38.80	0.922 0.911 0.873 0.766 0.680 0.554	Telescope rotated = 1/3 CW back to ori- ginal position Telescope/Mainframe interface bolts torque & then 12 loosened.
STR # F1-002 1 Feb 82 14:24:47 (Y Axis) 14:24:47 (X Axis) Z = -0.010 On Axis	10.84 11.75 14.35 22.75 29.15 39.5	0.922 0.910 0.871 0.757 0.657 0.497	10.70 11.75 14.69 22.47 28.84 38.63	0.923 0.915 0.883 0.789 0.708 0.535	Same as previous configuration except that only 10 bolts are loosened

Table 1. TM Flight Model (FM-1) Computed Single Pass Function of Spatial Frequency vs MTF - continued.

FS5

ORIGINAL PAGE IS OF POOR QUALITY	Y Axis		X Axis		Comments
	f _{SP} Cycles Rad	MTF	f _{SP} Cycles Rad	MTF	
STR # F1-002	10.53	0.934	10.99	0.914	10 bolts loose
1 Feb 82	11.75	0.921	11.75	0.904	
16:45:58 (Y Axis)	14.51	0.893	14.97	0.860	
16:45:58 (X Axis)	22.29	0.806	22.30	0.743	
Z = -0.005	29.54	0.742	29.17	0.651	
On Axis	38.11	0.650	38.94	0.524	81 pt. KER
STR # F1-002	11.13	0.904	11.05	0.910	Telescope/Mainframe interface bolts retorqued
2 Feb 82	11.75	0.895	11.75	0.900	
10:51:35 (Y Axis)	15.09	0.845	15.05	0.850	
10:51:35 (X Axis)	22.93	0.715	22.93	0.715	
Z = -0.005 inch	29.36	0.600	29.36	0.601	
On Axis	39.27	0.423	39.23	0.438	KER 41 pts $\delta X = \delta Y = 0.0002$
STR # F1-002	11.10	0.906	11.26	0.891	Telescope/Mainframe interface bolts torqued
2 Feb 82	11.75	0.897	11.75	0.882	
15:34:26 (Y Axis)	15.06	0.849	15.23	0.821	
15:34:26 (X Axis)	22.87	0.728	23.07	0.672	
Z = -0.004 inch	23.19	0.621	29.49	0.552	
Z = -0.004 inch	39.19	0.453	39.35	0.390	KER - 81 pts $\delta X = \delta Y = 0.001$
STR # F1-002	11.10	0.906	11.09	0.907	Telescope/Mainframe interface bolts torqued
2 Feb 82	11.75	0.897	11.75	0.897	
17:08:50 (Y Axis)	15.06	0.849	15.07	0.848	
17:08:50 (X Axis)	22.89	0.724	22.91	0.719	
Z = -0.010 inch	29.42	0.613	29.33	0.610	
+4 mr. Field Angle			39.22	0.445	KER - 81 pts $\delta X = \delta Y = 0.0001$
STR # F1-002	11.31	0.885	11.36	0.878	Telescope/Mainframe interface bolts torqued
2 Feb 82	11.75	0.877	11.75	0.870	
18:14:55 (Y Axis)	15.25	0.817	15.31	0.801	
18:14:55 (X Axis)	23.05	0.600	23.16	0.635	
Z = -0.010 inch	29.44	0.574	29.58	0.505	
-4 mr. Field Angle	39.28	0.421	39.44	0.338	KER 81 pts $\delta X = \delta Y = 0.0001$

Computer Single Pass Function of
Spatial Frequency vs MTF - continued.

F552

ORIGINAL PAGE IS OF POOR QUALITY	Y Axis		Y Axis		Comments
	f_{sp} K Cycles Rad	MTF	f_{sp} K Cycles Rad	MTF	
STR # F1-002 1 Feb 82 16:45:58 (Y Axis) 16:45:58 (X Axis) Z = -0.005 On Axis	10.53 11.75 14.51 22.29 38.54 38.11	0.934 0.921 0.893 0.806 0.742 0.650	10.99 11.75 14.99 22.30 29.17 38.94	0.914 0.904 0.860 0.743 0.651 0.524	10 bolts loosened 81 pt. KER
STR # F1-002 2 Feb 82 10:51:35 (Y Axis) 10:51:35 (X Axis) Z = -0.005 inch On Axis	11.13 11.75 15.09 22.93 29.36 39.27	0.904 0.895 0.845 0.715 0.600 0.423	11.05 11.75 15.05 22.93 29.36 39.22	0.910 0.900 0.850 0.715 0.601 0.438	Telescope/Mainframe interface bolts retorqued KER 41 pts $\delta X = \delta Y = 0.0002$ inch
STR # F1-002 2 Feb 82 15:34:26 (Y Axis) 15:34:26 (X Axis) Z = -0.004 inch Z = -0.004 inch	11.10 11.75 15.06 22.87 23.19 39.19	0.906 0.897 0.849 0.728 0.621 0.453	11.26 11.75 15.23 23.07 29.49 39.35	0.891 0.882 0.821 0.672 0.552 0.390	Telescope/Mainframe interface bolts torqued KER - 81 pts $\delta X = \delta Y = 0.001$ inch
STR # F1-002 2 Feb 82 17:08:50 (Y Axis) 17:08:50 (X Axis) Z = -0.010 inch +4 mr. Field Angle	11.10 11.75 15.06 22.89 29.32 39.22	0.906 0.897 0.849 0.724 0.613 0.445	11.09 11.75 15.07 22.91 29.33 39.22	0.907 0.897 0.848 0.719 0.610 0.445	Telescope/Mainframe interface bolts torqued KER - 81 pts $\delta X = \delta Y = 0.0001$ inch
STR # F1-002 2 Feb 82 18:14:55 (Y Axis) 18:14:55 (X Axis) Z = -0.010 inch -4 mr. Field Angle	11.11 11.75 15.25 23.05 29.44 39.28	0.885 0.877 0.817 0.600 0.574 0.421	11.36 11.75 15.31 23.16 29.58 39.44	0.878 0.870 0.801 0.635 0.505 0.338	Telescope/Mainframe interface bolts torqued KER 81 pts $\delta X = \delta Y = 0.0001$ inch

Table II. Protoflight Model (PFM) MTF Components @ 11.75 K Cycles/

#	Component	MTF	Location of Referenced Data Technical Journal
1	Telescope	0.94	TM XXX1 (K1588) pg.
2	AOB Induced Degradation	0.94 to 0.89	TM XXX1 (K1588) pg. 103
3	SMA	0.90 to 0.88	TM XXX1 (K1588) pg. 99
4	Electrical Filtering	0.70	ORIGINAL PAGE IS OF POOR QUALITY
5	IGFOV	0.63	

The total MTF is obtained by

$$MTF_T = MTF_1 \times MTF_2 \times MTF_3 \times MTF_4 \times MTF_5 \quad (3)$$

and an approximation for SWR is given by

$$SWR_T = (4/\pi) MTF_T \quad (4)$$

Table III is a tabulation of the results.

Table III. Composite MTF and Extrapolated SWR

	MTF _T	SWR _T
Minimum Value	0.325	0.413
Maximum Value	0.351	0.447

Table IV is a tabulation of PFM SWR measured in T/V tests during September 1981. A more complete set of values is given in HS236-7680

Table IV. PFM T/V SWR Measured Performed

Band	SWR (15 September 1981)		
	Channel		Average
	High	Low	
1	0.471	0.434	0.456
2	0.463	0.410	0.438
3	0.432	0.389	0.407
4	0.455	0.398	0.433
5	0.439	0.394	0.416
7	0.447	0.404	0.435

The correlation between predicted SWR (Table III) and measured SWR (Table IV) is better than I had expected due to the approximation methods used to obtain the predicted values. Nevertheless, it gives a degree of credence to the analytical approximations used.

ORIGINAL PAGE IS
OF POOR QUALITY

F552

Using some of the same approximation methods the FM-1 system performance is predicted by

$$SWR_{FM1} = SWR_{PFM} (MTF_{FM1} / MTF_{PFM})_{\text{Telescope}} \quad (5)$$

where

$$0.88 \leq MTF_{FM1}(\text{telescope}) \leq 0.90$$

using the smaller value of 0.88, Table V is generated.

Table V. Predicted FM1 System Level SWR Performance Based Upon FM1 and PFM Telescope MTF Differences and PFM (September 1981) SWR Performance.

Band	Predicted FM1 SWR (0.88/0.94) SWR_{PFM}
1	0.427
2	0.410
3	0.381
4	0.405
5	0.389
7	0.407

Data Location

Test information is located in TM System Test Log Book F1. Data was recorded on history tape per Table VI.

Table VI. History Tapes - Recorded Data

Time (1982)	History Tape #
1/25	D 03000
1/26-1/27	D 03002
1/29-2/1	D 03003
2/1 -2/2	D 03004
2/2 -2/3	D 03005

Additional information on the test is available in HS236-7837, 2221-508, TM F1 EFL/MTF Test Report.

ORIGINAL PAGE IS
OF POOR QUALITY

F552
9 February 1982
HS236-7831
2221-506

J. Engel

-7-

Summary of MTF Performance for FMI Telescope

Conclusion

As seen above the FMI predicted SWR system performance meets the TM specification of $SWR \leq 0.35$ at 11,750 cycles/radian with margin. It has been noted that our analytical methods are not exact. However, there was good correlation between predicted values and actual measured PFM SWR (September 1981) performance. As an aside there is no question of the adequacy of FMI cross scan (X axis) SWR performance. Since there is no appreciable electrical filtering component in this direction, the system cross scan SWR should be > 0.50 .

Thus it is recommended that failure report F0552 be closed based upon the data and conclusions presented above.

J. B. Young
James B. Young

ORIGINAL PAGE IS
OF POOR QUALITY

HUGHES

HUGHES AIRCRAFT COMPANY

SPACE AND COMMUNICATION GROUP
FAILURE REPORT

F 0591

1. PROGRAM NAME AND NUMBER THEMATIC WITNESS PL 1162		2. QLA	3. MODEL FLT	4. TIME OBSERVED	5. DATE OBSERVED 11-7-79
6. HARDWARE LEVEL WHEN FAILURE WAS OBSERVED <input type="checkbox"/> SPACECRAFT <input type="checkbox"/> SUBSYSTEM <input type="checkbox"/> ASSEMBLY <input type="checkbox"/> MODULE <input type="checkbox"/> CARD <input type="checkbox"/> SYSTEM <input type="checkbox"/> UNIT <input type="checkbox"/> SUBASSEMBLY <input type="checkbox"/> MICAM <input checked="" type="checkbox"/> PART					
EQUIPMENT IDENTIFICATION					
7. SUBSYSTEM		NAME		PART NUMBER	S/N
8. UNIT					
9. <input type="checkbox"/> ASSEMBLY <input type="checkbox"/> SUBASSEMBLY					
10. <input type="checkbox"/> MODULE <input type="checkbox"/> MICAM <input type="checkbox"/> CARD					
11. OTHER WITNESS SAMPLE FOR TELES COATING		50025		3	DENTON
12. TEST WHEN FAILURE WAS OBSERVED <input type="checkbox"/> DEVELOPMENT <input type="checkbox"/> IN-PROGRESS <input checked="" type="checkbox"/> QUALIFICATION <input type="checkbox"/> ACCEPTANCE <input type="checkbox"/> INTEGRATION <input type="checkbox"/> SYSTEM <input type="checkbox"/> LAUNCH OPERATIONS					
13. ENVIRONMENT WHEN FAILURE WAS OBSERVED <input type="checkbox"/> AMBIENT <input type="checkbox"/> RADIATION <input type="checkbox"/> TEMPERATURE <input type="checkbox"/> THERMAL VAC <input type="checkbox"/> HRS. AT <input type="checkbox"/> OTHER <input type="checkbox"/> EMC/RFI <input type="checkbox"/> VIBRATION <input type="checkbox"/> AXIS FOR <input type="checkbox"/> MIN TYPE					
14. DESCRIPTION OF FAILURE COATING WITNESS SAMPLE FAILED SCOTCH TAPE TEST AFTER HUMIDITY TEST AT SBRC.					
15. TEST PROCEDURE Rel Temp Pwr		16. ORIGINATOR CLINE	17. CONTINUATION SHEET USED 22-21	18. DATE 11-7-79	
19. VERIFICATION AND FAILURE ANALYSIS					
20. FOLLOWING REWORK/RETEST REQUIRED REWORK/RETEST NOT REQUIRED BECAUSE OUT OF 8 COATING WITNESS SAMPLES TESTED 3 SHOWED MINOR ADHESION FAILURE WHICH ARE ATTRIBUTABLE TO INSUFFICIENT CLEANING.					
21. AUTHORIZATION					
22. REWORK/RETEST ACTION TAKEN SATISFACTORY					
23. LIST ALL PARTS REPLACED					
24. CAUSE AND CORRECTIVE ACTION 1) INSPECTION / TEST INSTRUCTION AND REPORT USED FOR SOURCE CHANGED TO IMPOSE INSPECTION OF PARTS AND WITNESS SAMPLES, PRIOR TO COATING, FOR CONTAMINATION 2) PWG 50825 NOTE 10 CHANGED HUMIDITY REQUIREMENTS FROM 24 HOURS AT 50°C WITH 95% RELATIVE HUMIDITY TO 24 HOURS AT FROM 45 TO 50°C WITH 90 TO 95% RELATIVE HUMIDITY.					
25. DOCUMENT IMPLEMENTING CORRECTIVE ACTION PEY. D OF DRAWING 50825. EFFECTIVITY 5/1 002 & 5/1 003					
26. BASIC CAUSE OF VERIFIED FAILURE <input checked="" type="checkbox"/> DESIGN <input type="checkbox"/> TEST EQUIP. <input type="checkbox"/> MFG. PROCEDURE <input type="checkbox"/> WIRING ERROR <input type="checkbox"/> UNKNOWN <input type="checkbox"/> ENVIRONMENTAL <input type="checkbox"/> TEST PROC. <input type="checkbox"/> ASSEMBLY ERROR <input type="checkbox"/> ROUGH HANDLING <input type="checkbox"/> DEFECT CODE <input type="checkbox"/> DEFECTIVE PARTS <input type="checkbox"/> TEST SET-UP <input type="checkbox"/> WORKMANSHIP <input type="checkbox"/> WEAR-OUT					
27. FAILURE TYPE <input checked="" type="checkbox"/> PRIMARY <input type="checkbox"/> UNKNOWN <input type="checkbox"/> NO FAILURE <input type="checkbox"/> INDUCED					
28. FAILURE CLASSIFICATION <input type="checkbox"/> CRITICAL <input type="checkbox"/> MINOR <input checked="" type="checkbox"/> SAFETY					
29. RESPONSIBLE ENGINEER [Signature]		30. SPACECRAFT SYSTEM ENGR. [Signature]	31. DATE 11-11-81	32. DATE 11-10-79	33. DATE 11-10-79
34. RELIABILITY [Signature]		35. CUSTOMER OR SUPPLIER [Signature]	36. DATE 11-10-79	37. DATE 11-10-79	38. DATE 11-10-79

HUGHES

HUGHES AIRCRAFT COMPANY

SPACE AND COMMUNICATION GROUP
EQUIPMENT CHECKOUT
FAILURE REPORT
CONTINUATION SHEETORIGINAL PAGE IS
OF POOR QUALITYP0591
FR SERIAL NO.CONT. SHEET
LETTER*

*LABEL FIRST CONTINUATION SHEET USED 'A', SECOND 'B', AND SO ON

IDENTIFY ENTRIES BY REFERENCING FR BLOCK NUMBER IN COLUMN, DATE EACH ENTRY.

ADDITIONAL FR
CONTINUATION
SHEET(S) USED

30	Witness samples failed when tested to drawing 50825 Rev. C. Rev. C of drawing 50825 required the witness samples to be tested at 50°C and 95% relative humidity. There were no tolerances for temperature or humidity specified on Rev. C of drawing 50825. Therefore, the witness samples were tested above design limits. Witness samples from the same lot were tested to Rev. D of drawing 50825 and passed.
----	--

Johnson 10/21/81

11873 SC JUNE 78

HUGHES

HUGHES AIRCRAFT COMPANY

SPACE AND COMMUNICATION GROUP
EQUIPMENT CHECKOUT
FAILURE REPORT
CONTINUATION SHEET

ORIGINAL PAGE IS
OF POOR QUALITY

F1742
FR SERIAL NO.

CONT. SHEET
LETTER*

* LABEL FIRST CONTINUATION SHEET USED 'A', SECOND 'B', AND SO ON

IDENTIFY ENTRIES BY REFERENCING FR BLOCK NUMBER IN COLUMN, DATE EACH ENTRY.

ADDITIONAL F
CONTINUATION
SHEET(S) USED

30 Board authority. A copy of NCMR 280985 is attached.

CHES

PROGRAM ID *W-5-15* NONCONFORMING MATERIAL REPORT (NCMR)

051902

NO. DATE PAGE 1 OF 1

PROGRAM ID *W-5-15* NONCONFORMING MATERIAL REPORT (NCMR)

ORDER DOC NO.	50825B	LOT SIZE	001	QTY. SUSP.	1	SUSPENDED IN	50825B	HARDWARE I.D. NO.		REF. DOCUMENTS	10092	ITEM NO.	7	P.O. NO.	511393-1	S.R. NO.	
---------------	--------	----------	-----	------------	---	--------------	--------	-------------------	--	----------------	-------	----------	---	----------	----------	----------	--

QTY. SUSP.	1	QTY. SUSP.	1	QTY. SUSP.	1	QTY. SUSP.	1	QTY. SUSP.	1	QTY. SUSP.	1	QTY. SUSP.	1	QTY. SUSP.	1	QTY. SUSP.	1
DISP. CODE		DISP. CODE		DISP. CODE		DISP. CODE		DISP. CODE		DISP. CODE		DISP. CODE		DISP. CODE		DISP. CODE	
DATE	1-3-79	DATE	1-3-79	DATE	1-3-79	DATE	1-3-79	DATE	1-3-79	DATE	1-3-79	DATE	1-3-79	DATE	1-3-79	DATE	1-3-79

DESCRIPTION OF NONCONFORMANCE	DESCRIPTION OF NONCONFORMANCE	DESCRIPTION OF NONCONFORMANCE	DESCRIPTION OF NONCONFORMANCE	DESCRIPTION OF NONCONFORMANCE	DESCRIPTION OF NONCONFORMANCE	DESCRIPTION OF NONCONFORMANCE	DESCRIPTION OF NONCONFORMANCE	DESCRIPTION OF NONCONFORMANCE	DESCRIPTION OF NONCONFORMANCE	DESCRIPTION OF NONCONFORMANCE	DESCRIPTION OF NONCONFORMANCE	DESCRIPTION OF NONCONFORMANCE	DESCRIPTION OF NONCONFORMANCE	DESCRIPTION OF NONCONFORMANCE	DESCRIPTION OF NONCONFORMANCE	DESCRIPTION OF NONCONFORMANCE	DESCRIPTION OF NONCONFORMANCE
-------------------------------	-------------------------------	-------------------------------	-------------------------------	-------------------------------	-------------------------------	-------------------------------	-------------------------------	-------------------------------	-------------------------------	-------------------------------	-------------------------------	-------------------------------	-------------------------------	-------------------------------	-------------------------------	-------------------------------	-------------------------------

CAUSE OF NONCONFORMANCE	CAUSE OF NONCONFORMANCE	CAUSE OF NONCONFORMANCE	CAUSE OF NONCONFORMANCE	CAUSE OF NONCONFORMANCE	CAUSE OF NONCONFORMANCE	CAUSE OF NONCONFORMANCE	CAUSE OF NONCONFORMANCE	CAUSE OF NONCONFORMANCE	CAUSE OF NONCONFORMANCE	CAUSE OF NONCONFORMANCE	CAUSE OF NONCONFORMANCE	CAUSE OF NONCONFORMANCE	CAUSE OF NONCONFORMANCE	CAUSE OF NONCONFORMANCE	CAUSE OF NONCONFORMANCE	CAUSE OF NONCONFORMANCE	CAUSE OF NONCONFORMANCE
-------------------------	-------------------------	-------------------------	-------------------------	-------------------------	-------------------------	-------------------------	-------------------------	-------------------------	-------------------------	-------------------------	-------------------------	-------------------------	-------------------------	-------------------------	-------------------------	-------------------------	-------------------------

RESULTS OF CORRECTIVE ACTION INVESTIGATION	RESULTS OF CORRECTIVE ACTION INVESTIGATION	RESULTS OF CORRECTIVE ACTION INVESTIGATION	RESULTS OF CORRECTIVE ACTION INVESTIGATION	RESULTS OF CORRECTIVE ACTION INVESTIGATION	RESULTS OF CORRECTIVE ACTION INVESTIGATION	RESULTS OF CORRECTIVE ACTION INVESTIGATION	RESULTS OF CORRECTIVE ACTION INVESTIGATION	RESULTS OF CORRECTIVE ACTION INVESTIGATION	RESULTS OF CORRECTIVE ACTION INVESTIGATION	RESULTS OF CORRECTIVE ACTION INVESTIGATION	RESULTS OF CORRECTIVE ACTION INVESTIGATION	RESULTS OF CORRECTIVE ACTION INVESTIGATION	RESULTS OF CORRECTIVE ACTION INVESTIGATION	RESULTS OF CORRECTIVE ACTION INVESTIGATION	RESULTS OF CORRECTIVE ACTION INVESTIGATION	RESULTS OF CORRECTIVE ACTION INVESTIGATION	RESULTS OF CORRECTIVE ACTION INVESTIGATION
--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--

SIGNATURE	SIGNATURE	SIGNATURE	SIGNATURE	SIGNATURE	SIGNATURE	SIGNATURE	SIGNATURE	SIGNATURE	SIGNATURE	SIGNATURE	SIGNATURE	SIGNATURE	SIGNATURE	SIGNATURE	SIGNATURE	SIGNATURE	SIGNATURE
-----------	-----------	-----------	-----------	-----------	-----------	-----------	-----------	-----------	-----------	-----------	-----------	-----------	-----------	-----------	-----------	-----------	-----------

ORIGINAL PAGE IS OF POOR QUALITY

F1742

FAILURE REPORT

011873 SC JAN 60

11/30/81

**END
DATE
FILMED**

AUG 5 1983